

INS. CASE OWNER:

CC 4, QBE 180 22328, K #31/1

LKK IDAC

Surveyor:

Kye

ASSIGNMENT

DOI:

14/12/18

Date/Time:

10/12/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SPJ 9245T

Claim No.:

VCO12126

Name of Insured:

Yuen Sh. mm

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

Place of Accident:

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Yuen Chey Wah

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: % Final? Yes / No

SDW 5090M



INSRS:

WSP:

Tel:

Liability:

RMKS:

Wan Teong



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

22/12
CPC

SDW 5090M - X;
SPJ 9245T, 251800180 22328 / U6013 : 009. 6/12/18

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 14/12/2019

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

14/12/18 Spoke to OI, confirmed BOLA 27, OI now ended TP informed TP claim and HEP issue OI agree to settle and aware HEP will be attached. Sent letter to OI.

15/12/18 File pass to type mandate

9/1/2020 File pass to MK to close.

C - Assignment paper should be LOU instead of LOR.

PRELIMINARY ADVICE

Date/Time:

14/12/2018

Sent By:

HMK

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

45

SS 2,900

(6 days)

Reduction:

63%

Email Call

FINAL SETTLEMENT

Date/Time:

4/1/19

Confirm with:

Wendy

Email Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

USE (4/1/19)

SS 3,103.00

Loss of Benefit (LOB):

LOU

SS 360.00

(6 days)

x \$60

OI now ended TP

Loss of Use (LOU):

SS

-

(5 - x - days)

Loss of Income (LOI):

SS

-

(5 - x - days)

COPY SENT 10/1/2020

LOR only LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search:

SS

7.45

Medical:

SS

-

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS

-

(e.g. Tow/Independent)

2) Report Format:

TP

Legal Cost:

SS

-

3) Survey fee:

\$400

Total:

SS

3,470.45

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email Call

Payee 1:

SS

3,470.45

Name 1:

KIAN TEONG AUTO CENTRE

Payee 2 (Strike if N/A):

SS

Name 2:

Payee 3 (Strike if N/A):

SS

Name 3:

Kf

KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08
Sin Ming AutoCare Singapore 575721
Tel No. : 64556268 Fax No. : 64555166
E-Mail : info@ktauto.com.sg
Website : www.ktauto.com.sg
Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

EQ INSURANCE COMPANY LIMITED
22 GEMMILL LANE
069257

Attention : Motor Claim Department

*Not Authorized
11 Rmp @ 2900k
Resurvey After Paint
6das*

Estimate : ES000474

Date : 28/11/2018
Vehicle Num. : 0
Make/Model :
Chassis/Eng# :
Accident Date : 28/11/2018
Claim No. :
Reference : SDW5090M
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	REAR BUMPER UNIT	577.80	
3.	LH	REAR BUMPER REINFORCEMENT		
4.	LH	REAR BUMPER SIDE BRACKET		
5.	1	REAR BUMPER REFLECTOR	86.20	
6.	1	REAR TAIL LAMP - LH	409.60	
7.	1	REAR TAIL LAMP BRACKET		
8.	1	REAR TAIL LAMP PANEL		
9.	LOGO	REAR BOOTH LID		
10.	1	REAR BOOTH LID EMBLEM		
		REAR FENDER - LH		

Bu	887.60	✓
NSP	795.00	X
D/S	68.00	✓
CM	295.00	✓
B2	589.50	✓
MS	58.00	✓
R	495.00	X
R	1,160.00	✓
RA	68.50	✓
R	785.00	X
<hr/>		
	5,201.60	

List Total S\$:

258

1.	1	NETT ITEMS :		
2.	1	REAR REVERSE SENSOR		
3.	1	WINDSCREEN SEALANT		
		PRIVTE HIRE DECAL		

RA	220.00	X
RA	35.00	✓
RA	40.00	X
<hr/>		
	295.00	

Nett Total S\$:

LABOUR :	
LABOUR FEES:	
TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS	980.00
TO KNOCK AND RE-ALIGN ALL DAMAGED PARTS	1,150.00
TO REMOVE AND CHANGE ALL DAMAGED PARTS	
TO REMOVE AND REFIT REAR WINDSCREEN TO FACILATE REPAIR	160.00
TO CHECK ALL LIGHTING WIRING	120.00
TO CHECK REVERSE SENSOR AND CAMERA WIRING	

Labour Total S\$:

2,410.00

E. & O.E.

Total S\$: 7,906.60

for KIAN TEONG AUTO CENTRE

Please do not hesitate to contact us at the above number if there is any other further quire.
We thank you for your kind attention. Your prompt reply is greatly appreciated.

- UJK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08
 Sin Ming AutoCare Singapore 57521
 Tel No. : 64556268 Fax No. : 64555166
 E-Mail : info@ktauto.com.sg
 Website : www.ktauto.com.sg
 Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

EQ INSURANCE COMPANY LIMITED
 22 GEMMILL LANE
 069257

Attention : Motor Claim Department

Estimate : ES000474

Date : 28/11/2018
 Vehicle Num. : 0
 Make/Model :
 Chassis/Eng# :
 Accident Date : 28/11/2018
 Claim No. :
 Reference : SDW5090M
 Policy No. :

*Not Notified
 1/1 Rep &?
 Purway Abu Pain
 6das*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- LIST ITEMS :
- 1 REAR BUMPER UNIT
 - 1 REAR BUMPER REINFORCEMENT
 - LH REAR BUMPER SIDE BRACKET
 - LH REAR BUMPER REFLECTOR
 - 1 REAR TAIL LAMP - LH
 - 1 REAR TAIL LAMP BRACKET
 - 1 REAR TAIL LAMP PANEL
 - 1 REAR BOOTH LID
 - LOGO REAR BOOTH LID EMBLEM
 - 1 REAR FENDER - LH

List Total S\$:

- NETT ITEMS :
- 1 REAR REVERSE SENSOR
 - 1 WINDSCREEN SEALANT
 - 1 PRIVATE HIRE DECAL

Nett Total S\$:

LABOUR :

LABOUR FEES:

- TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS
- TO KNOCK AND RE-ALIGN ALL DAMAGED PARTS
- TO REMOVE AND CHANGE ALL DAMAGED PARTS
- TO REMOVE AND REFIT REAR WINDSCREEN TO FACILATE REPAR
- TO CHECK ALL LIGHTING WIRING
- TO CHECK REVERSE SENSOR AND CAMERA WIRING

Labour Total S\$:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

258

*Bu 887.60 ✓
 NSP 795.00 X
 D11 68.00 ✓
 CM 295.00 ✓
 BU 589.50 ✓
 N13 58.00 ✓
 495.00 ✓
 1,160.00 ✓
 68.50 ✓
 785.00 X
 5,201.60*

*220.00 ?
 35.00 ✓
 40.00 X
 295.00*

*800 980.00
 1,150.00 800
 160.00 1200
 120.00 700
 2,410.00*

E. & O.E. Total S\$: 7,906.60

for KIAN TEONG AUTO CENTRE

Please do not hesitate to contact us at the above number if there is any other further quire.
 We thank you for your kind attention. Your prompt reply is greatly appreciated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC4/QBE18022328/Kfa3

Date: 14/12/2018

The Motor Claims Department
M/s QBE INSURANCE (SINGAPORE) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SDW 5090M


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11/12/2018 at the premises of M/s Kian Teong Auto Centre - Sin Ming and have the following to report:-

Workshop Estimate Amount	: S\$	<u>7,906.60</u>	(est.)
Revised Estimate Amount	: S\$	<u>4,169.95</u>	(est.)
"Check" Items Amount	: S\$	<u>591.25</u>	(est.)
Total (Including Check Items)	: S\$	<u>4,761.20</u>	(est.)
Market Value	: S\$	<u>-</u>	(est.)
LTA Reimbursement Value	: S\$	<u>-</u>	(est.)
Nett Value	: S\$	<u>-</u>	(est.)

Description of Damage:

The vehicle sustained damages at the Rear N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Catherine Chong (LKK Auto)

From: info@ktauto.com.sg
Sent: Monday, 10 December, 2018 11:24 AM
To: joyce.foo@qbe.com; assignments@lkkauto.com
Subject: Re: FW: Accident report_SDW5090M - Pre-repair arrangement
Attachments: image001.png; gia.PDF

Dear Joyce,

We are please to get LKK Auto Consultants Pte Ltd to survey and finalise the mentioned claim. Kindly advice liability ASAP.

Yours faithfully
Wendy Siew
On and behalf of
Kian Teong Auto Centre
176 Sin Ming Drive
Sin Ming autocare #01-08
Singapore 575721
Tel: 65 64556268
Fax: 65 64555166
HP: 91786498
Website: www.ktauto.com.sg

*10.12.2018 @ 1:10pm
Wendy with not in*

From: Joyce Foo <joyce.foo@qbe.com>
Sent: 12/10/18 11:19 AM
To: "info@ktauto.com.sg" <info@ktauto.com.sg>
Subject: FW: Accident report_SDW5090M - Pre-repair arrangement
undefinedundefinedundefined

WITHOUT PREJUDICE

Our ref: V0016400

Dear Sirs/Madam

We refer to the above captioned matter.

We intent to conduct a full survey of the damage to your client's vehicle. We propose to use one of the motor surveyors named in the attached list:

COMPANY
Appraisal Associates Pte Ltd
Automobile Inspection Services
KM Auto Assessors Pte Ltd
LKK Auto Consultants Pte Ltd
Infiniti Appraisal Service
Priority Services
Quantum Risk Management (S) Pte Ltd


Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors.

Thanks & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com

Visit us on the web at www.qbe.com.sg



From: Info SINGAPORE
Sent: Monday, 10 December 2018 10:52 AM
To: Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>; Jenny Toh <jenny.toh@qbe.com>; Joyce Foo <joyce.foo@qbe.com>
Subject: FW: Accident report_SDW5090M - Pre-repair arrangement

Hi All

Attached for your attention.

Regards

Grace Wong

From: info@ktauto.com.sg <info@ktauto.com.sg>
Sent: Saturday, 8 December 2018 11:14 AM

To: QBE Asia P&I <qbeasiapni@qbe.com>; Info SINGAPORE <info.sing@qbe.com>

Subject: Accident report_SDW5090M - Pre-repair arrangement

Dear Sirs,

Kindly please assist to arrange for a pre-repair survey for the above mentioned vehicle, vehicle already in workshop awaiting for repair. Please find attached GIA for your kind reference. Your insured vehicle number SKJ9245T. Direct settlement is our priority, assuring you our best attention at all times.

Yours faithfully

Wendy Siew

On and behalf of

Kian Teong Auto Centre

176 Sin Ming Drive

Sin Ming autocare #01-08

Singapore 575721

Tel: 65 64556268

Fax: 65 64555166

HP: 91786498

Website: www.ktauto.com.sg

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Mei Kwan (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Wednesday, 19 December, 2018 12:01 PM
To: joyce.foo@qbe.com
Cc: Admin A; CS A Team; Admin A; Poh Kin (LKKAuto)
Subject: RE: FW: Accident report_SDW5090M - Pre-repair arrangement
Attachments: TP ESTIMATE - MARKED.pdf; Preliminary Advice.pdf

Categories: HMK

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

QBE ref: VC012126
LKK REF: CC4/QBE18022328/Kfa3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SDW 5090M

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Please take note that the case handler in-charge is Poh Kin and he can be contacted at DID: 6841 2132.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 10 December, 2018 1:12 PM
To: joyce.foo@qbe.com; assignments <assignments@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: FW: Accident report_SDW5090M - Pre-repair arrangement

Dear Joyce,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Thanks & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com

Visit us on the web at www.qbe.com.sg

From: Info SINGAPORE
Sent: Monday, 10 December 2018 10:52 AM
To: Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>; Jenny Toh <jenny.toh@qbe.com>; Joyce Foo <joyce.foo@qbe.com>
Subject: FW: Accident report_SDW5090M - Pre-repair arrangement

Hi All

Attached for your attention.

Regards

Grace Wong

From: info@ktauto.com.sg <info@ktauto.com.sg>
Sent: Saturday, 8 December 2018 11:14 AM
To: QBE Asia P&I <qbeasiapni@qbe.com>; Info SINGAPORE <info.sing@qbe.com>
Subject: Accident report_SDW5090M - Pre-repair arrangement

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 15 October 2019 6:00 PM
To: Janice Goh Siew Geok; Jenny Toh
Cc: Admin A
Subject: Mandate Request - ACCIDENT INVOLVING VEHICLES SDW 5090M (TP) & SKJ 9245T (OI-QBE) on 06/12/2018
Attachments: DS Supporting docs.pdf; LKK Adjustment Report.pdf; LKK Inspection Report.pdf; LKK Reinspection Photos (2).pdf; LKK Reinspection Photos.pdf; LKK Survey Photos.pdf

YOUR REF – V0016400
LKK REF - CC4/QBE18022328/Kka3q2

=====

Dear Sir/Madam,

ACCIDENT INVOLVING VEHICLES SDW 5090M (TP) & SKJ 9245T (OI-QBE) on 06/12/2018

We refer to the above matter.

This is a head to rear end collision.

We had informed to the Insured company of the TP claim and NCD issues and they agreed to let Insurance handle.

In view of the above, we are of the view that BOLA 27 is applicable.

Summary to offer to repairer **KIAN TEONG AUTO CENTRE** is as follows:

	TP CLAIMED	REVISED - TO OFFER
Cost of Repair (w/GST)	\$ 8,460.06	\$ 3,103.00
Loss of Use (\$60 x 6 days)	\$ 360.00	\$ 360.00(\$60 x 6 days)
LTA Search Fee	\$ 7.49	\$ 7.45
TOTAL	\$ 8,827.55	\$ 3,470.45

Breakdown of days is as follows:

*6 days recommendation for repair

Relevant supporting claim documents are attached herewith for your perusal and reference.

For your approval and/or further instructions please.

Thank you.

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Khanchna (LKK Auto)

From: info@ktauto.com.sg
Sent: Friday, 8 November 2019 12:46 PM
To: Khanchna (LKK Auto)
Cc: Admin A
Subject: Re: MVA BETWEEN SDW 5090M & SKJ 9245T ON 06/12/2018

Thank you for your reply, please help close case as per your mentioned and let me know documents required.

Yours faithfully
Wendy Siew
On and behalf of
Kian Teong Auto Centre
176 Sin Ming Drive
Sin Ming autocare #01-08
Singapore 575721
Tel: 65 64556268
Fax: 65 64555186
HP: 91786498

From: "Khanchna (LKK Auto)" <khanchna@lkkauto.com>
Sent: 11/7/19 11:53 AM
To: "info@ktauto.com.sg" <info@ktauto.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: MVA BETWEEN SDW 5090M & SKJ 9245T ON 06/12/2018

Without Prejudice
(save as to costs)

Dear Sirs/Mdm.

We refer to the above matter and your e-mail below.

For amicable settlement on a without prejudice basis, we propose settlement as follows:

1. Cost of Repair (w/GST)	\$ 3,103.00
2. Loss of Use (14 days x \$60)	\$ 360.00
3. LTA/ GIA Search Fee	\$ 7.45
Total	\$ 3,470.45

Please confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC4/QBE18022328/Kka3q2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 13-01-2020



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKJ 9245T	Veh. Inspected	SDW 5090M
Policy No.	8-V0016400-MVA	Coverage (\$)	0.00
Claim No.	VC012126	Excess (\$)	0.00
Assign From	JOYCE	Assign Date	10/12/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH (A)	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	ZNE100368312	Colour	METALLIC DARK BLUE
Odometer	203280	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MICHELIN	2 mm
L/H Front Tyre	195/65 R15	MICHELIN	2 mm
R/H Rear Tyre	195/65 R15	MICHELIN	2 mm
L/H Rear Tyre	195/65 R15	MICHELIN	2 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/12/2018	Inspection Date	11/12/2018
Survey held at	KIAN TEONG AUTO CENTRE BLK 176 SIN MING DRIVE #01-08 SIN MING CARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDW 5090M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER UNIT	BUCKLED	887.60	577.80
1	REAR BUMPER REINFORCEMENT	NO SUCH PARTS	795.00	-
1	LH REAR BUMPER SIDE BRACKET	DISTORTED	68.00	68.00
1	LH REAR BUMPER REFLECTOR	CRACKED	295.00	86.20
1	REAR TAIL LAMP-LH	BROKEN	589.50	409.00
1	REAR TAIL LAMP BRACKET	MISSING	58.00	58.00
1	REAR TAIL LAMP PANEL	TO REPAIR SEE LABOUR	495.00	-
1	REAR BOOTH LID	BENT	1,160.00	1,160.00
1	LOGO REAR BOOTH LID EMBLEM	NECESSARY	68.50	68.50
1	REAR FENDER -LH	TO REPAIR SEE LABOUR	785.00	-
	LESS 25% DISCOUNT		-	-606.88
			5,201.60	1,820.62
SPECIAL NETT ITEMS				
1	REAR REVERSE SENSOR (SN)	SERVICEABLE	220.00	-
1	WINDSCREEN SEALANT (SN)	NECESSARY	35.00	35.00
1	PRIVTE HIRE DECAL (SN)	NOT NECESSARY	40.00	-
			295.00	35.00
LABOUR				
	TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS.		980.00	800.00
	TO KNOCK AND RE-ALIGN ALL DAMAGED PARTS.TO REMOVE AND CHANGE ALL DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR TAIL LAMP PANEL AND REAR FENDER -LH .		1,150.00	800.00
	TO REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAR.		160.00	120.00
	TO CHECK ALL LIGHTING WIRING .TO CHECK REVERSE SENSOR AND CAMERA WIRING.		120.00	70.00
			2,410.00	1,790.00
GRAND TOTAL			7,906.60	3,645.62

Report Ref No. CC4/QBE18022328/Kka3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,900.00
---	--	--	----------

Report Ref No. CC4/QBE18022328/Kka3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.