

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 11th December 2018

To : LKK

Attn : Bryan

Tel :

By Fax:

VEHICLE NO : FBM 2982K

Yamaha 150 Sniper

ACCIDENT DATE: 4/12/2018

Description	Qty	Quotation \$
1 Balancer <i>Cut</i>	2	90.00 ✓
2 Handle Bar <i>HL</i>	1	105.00 ✗
3 Mirror <i>HL</i>	1 set	96.00 ✗
4 Brake Lever <i>Cut</i>	1	58.00 ✓
5 Front RH Body Fairing <i>Cut</i>	1	205.00 ✓
6 Front RH Signal <i>Cut</i>	1	55.00 ✓
7 Rear RH Tail Fairing <i>HL</i>	1	185.00 ✗
8 Brake Pedal <i>BT</i>	1	65.00 ✓
9 Exhaust Guard <i>Cut</i>	1	105.00 ✓
10 Exhaust Cover End <i>Cut</i>	1	85.00 ✓
11 Front Cover Guard <i>Cut broken</i>	1	95.00 ✓
12 Fork Tube RH <i>Down</i>	1	180.00 ✓

Sub-Total	1,324.00
Less 10%	132.40
Sub-Total	1,191.60

VEHICLE NO : FBM 2982K

Yamaha 150 Sniper

Nett items

1	Towing fees	50.00 30/-
2	Remove & replace necessary parts, align & etc	250.00 180/-
3	Remove and replace fork tube & fork oil	120.00 80/-
4	Supply Body Sticker	160.00 120/-
5	Re-press front Rim	80.00 50/-
6	Rear Carrier Box-SHAD SH 39	250.00 40/-

Sub-Total

910.00

Nett Total

2,101.60

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you

SG 98 MOTOR PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10/12/2018 @ 1300hrs

Not Authorised

1/Small

4 days.
Ryan

LKK Auto