

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61
Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : AXA INSURANCE SINGAPORE PTE LTD

PARTICULARS OF CLAIM			
Claim Type:	OD	Ref. No:	YTKB/OD/1812/007
Policy No:	GA206078/1	Date of Loss:	08/12/2018
Vehicle Reg. No.:	SJY4688P	Driveable?	yes
Driver Age:		Third Party Vehicle No.:	LAMP POST
Any Injuries?	no	Contact No:	
Insured/Claimant:	CHAN CHEE CHONG GEOFFREY (ZHENG ZHIZHONG)	Driver:	TAN SEOK TIANG ANNE

Make/Model:	Honda, Vezel - RU1	Vehicle Reg. Date:	25 May 2017
Vehicle Colour:	WHITE	Engine Number:	L15B4407854
Chassis No:	RU11207857	Odometer:	
Total Loss?	YES	Est. Duration of Repair(Day)	25

Description of Accident/loss	HIT ONTO LAMPPOST
Remarks:	
Present Location:	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS	Amount
Parts	34,761.10
Miscellaneous Items	127.60
Labour	5,030.00
Paintwork Labour	1,845.00
Towing	150.00
Gross Total(\$\$):	41,913.70
GST 7.00%(\$\$):	2,933.96
Nett Amount(\$\$):	44,847.66

This claim is handled by: Shaun Toh L M

LKK Auto Consultants hence notify the Repairer of the following:

- Third survey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*Not Allowed
Lump
Excess \$300
12/12/18
maybe TOTAL LOSS
2018.*

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	BONNET <i>Buc</i>	0.00	280.00	+10.00	308.00
2	1	BONNET HINGE LH <i>Bent</i>	0.00	32.00	+10.00	35.20
3	1	BONNET HINGE RH <i>Bent</i>	0.00	32.00	+10.00	35.20
4	1	BONNET INSULATOR <i>Torn</i>	0.00	85.00	+10.00	93.50
5	1	BONNET LOCK <i>twi</i>	0.00	70.00	+10.00	77.00
6	1	BONNET RUBBER <i>new</i>	0.00	18.00	+10.00	19.80
7	1	ENGINE CROSSMEMBER <i>no/bent</i>	0.00	700.00	+10.00	770.00
8	1	FRONT BUMPER <i>D.5</i>	0.00	230.00	+10.00	253.00
9	1	FRONT BUMPER BRACKET LH <i>Bent</i>	0.00	28.00	+10.00	30.80
10	1	FRONT BUMPER BRACKET RH <i>Bent</i>	0.00	28.00	+10.00	30.80
11	1	FRONT BUMPER CENTRE AIR GRILLE <i>Torn</i>	0.00	70.00	+10.00	77.00
12	1	FRONT BUMPER CENTRE LOWER GRILLE <i>Torn</i>	0.00	155.00	+10.00	170.50
13	1	FRONT BUMPER FOG LAMP GARNISH LH <i>twi</i>	0.00	28.00	+10.00	30.80
14	1	FRONT BUMPER FOG LAMP GARNISH RH	0.00	28.00	+10.00	30.80
15	1	FRONT BUMPER FOG LAMP LH <i>one</i>	0.00	165.00	+10.00	181.50
16	1	FRONT BUMPER FOG LAMP RH	0.00	165.00	+10.00	181.50
17	1	FRONT BUMPER LOWER COVER <i>Torn</i>	0.00	130.00	+10.00	143.00
18	1	FRONT BUMPER LOWER RUBBER <i>D.5</i>	0.00	70.00	+10.00	77.00
19	1	FRONT BUMPER REINFORCEMENT <i>D.5</i>	0.00	210.00	+10.00	231.00
20	1	FRONT BUMPER SIDE RETAINER LH <i>Bent</i>	0.00	15.00	+10.00	16.50
21	1	FRONT BUMPER SIDE RETAINER RH <i>Bent</i>	0.00	15.00	+10.00	16.50
22	1	FRONT BUMPER TOW COVER <i>Torn</i>	0.00	12.00	+10.00	13.20
23	1	FRONT GRILLE BASE <i>3.20</i>	0.00	200.00	+10.00	220.00
24	1	FRONT GRILLE TOP BRACKET <i>one</i>	0.00	42.00	+10.00	46.20
25	1	FRONT HEADLAMP LOWER BRACKET LH <i>one</i>	0.00	35.00	+10.00	38.50
26	1	FRONT HEADLAMP LOWER BRACKET RH <i>one</i>	0.00	35.00	+10.00	38.50
27	1	AIR CON CONDENSER <i>D.5</i>	0.00	310.00	+10.00	341.00
28	1	AIR CON CONDENSER AIR GUIDE LH <i>Torn</i>	0.00	35.00	+10.00	38.50
29	1	FRONT AIR INTAKE DUCT <i>one</i>	0.00	45.00	+10.00	49.50
30	1	FRONT AIR INTAKE JOINT PIPE <i>twi</i>	0.00	55.00	+10.00	60.50
31	1	RADIATOR <i>D.5</i>	0.00	240.00	+10.00	264.00
32	1	RADIATOR FAN COWLING <i>one</i>	0.00	80.00	+10.00	88.00
33	1	FRONT FENDER INNER SHIELD LH <i>Torn</i>	0.00	85.00	+10.00	93.50
34	1	FRONT FENDER LH <i>Bent/Buc</i>	0.00	270.00	+10.00	297.00
35	1	FRONT FENDER RH <i>Bent/Buc</i>	0.00	270.00	+10.00	297.00
36	1	FRONT FENDER WHEEL ARCH GARNISH LH <i>Torn</i>	0.00	110.00	+10.00	121.00
37	1	FRONT FENDER WHEEL ARCH GARNISH RH <i>one</i>	0.00	100.00	+10.00	110.00
38	1	AUTO TRANSMISSION GEARBOX <i>one IP 10,000</i>	20.00	12,000.00	+10.00	13,200.00
39	1	FRT SHOCK ABSORBER LH	0.00	220.00	+10.00	242.00
40	1	FRT LOWER ARM LH <i>Bent</i>	0.00	200.00	+10.00	220.00
41	1	FRT KNUCKLE LH <i>Bent</i>	0.00	195.00	+10.00	214.50
42	1	FRONT WHEEL HUB LH <i>Bent</i>	0.00	140.00	+10.00	154.00
43	1	DASHBOARD <i>Torn</i>	0.00	550.00	+10.00	605.00
44	1	PASSENGER AIR BAG <i>Acting</i>	0.00	1,100.00	+10.00	1,210.00
45	1	FRONT SEAT BELT LH <i>Acting</i>	0.00	480.00	+10.00	528.00
46	1	FRONT SEAT BELT RH <i>Acting</i>	0.00	480.00	+10.00	528.00
47	1	AIR BAG ECU <i>Acting</i>	0.00	850.00	+10.00	935.00
48	1	FRONT SUPPORT PANEL <i>Bent/twi</i>	0.00	370.00	+10.00	407.00
49	1	FRONT SUPPORT PANEL TOP GARNISH <i>Torn</i>	0.00	55.00	+10.00	60.50
50	1	FRONT HORN LH <i>one</i>	0.00	38.00	+10.00	41.80
51	1	FRONT CHASSIS MEMBER LH <i>one</i>	0.00	550.00	+10.00	605.00
52	2	FRONT CHASSIS FRAME <i>one</i>	0.00	0.00	+10.00	0.00
53	1	ENGINE MOUNTING LH	0.00	200.00	+10.00	220.00

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
54	1	ENGINE MOUNTING RH	0.00	140.00	+10.00	154.00
55	1	ENGINE MOUNTING REAR	0.00	110.00	+10.00	121.00
56	1	FRONT DRIVESHAFT LH <i>B/A</i>	0.00	650.00	+10.00	715.00
57	1	POWER STEERING RACK	0.00	850.00	+10.00	935.00
58	1	FRONT STABILIZER LINK LH <i>twi</i>	0.00	50.00	+10.00	55.00
59	1	FRONT TIE ROD END LH	0.00	60.00	+10.00	66.00
60	1	FRONT DRAG LINK LH	0.00	65.00	+10.00	71.50
61	1	FRONT HEADLAMP WIRE HARNESS SET	0.00	2,800.00	+10.00	3,080.00
62	1	BATTERY <i>B/A</i>	0.00	160.00	+10.00	176.00
63	1	ENGINE ECU	0.00	2,100.00	+10.00	2,310.00
64	1	FUSE BOX TOP COVER	0.00	90.00	+10.00	99.00
65	1	FUSE BOX BOTTOM COVER	0.00	120.00	+10.00	132.00
66	1	FUSE BOX CENTRE MAIN	0.00	550.00	+10.00	605.00
67	1	FRONT CTBA CONTROL BOX <i>Daye/twi</i>	0.00	700.00	+10.00	770.00
68	1	FRONT WIPER PANEL GARNISH <i>cu</i>	0.00	210.00	+10.00	231.00
69	1	FRONT TYRE LH <i>pan LP180</i>	0.00	220.00	+10.00	242.00
70	1	FRONT WHEEL RIM LH <i>M</i>	0.00	220.00	+10.00	242.00
71	1	AIR CON DISCHARGE PIPE	0.00	150.00	+10.00	165.00
72	1	AIR CON SUCTION PIPE	0.00	140.00	+10.00	154.00
73	1	AIR CON LIQUID PIPE	0.00	125.00	+10.00	137.50
74	1	FRONT WIPER GARNISH END LH <i>twi</i>	0.00	20.00	+10.00	22.00
75	1	FRONT WIPER GARNISH END RH <i>twi</i>	0.00	20.00	+10.00	22.00
76	1	FRONT WHEEL HUB BEARING LH <i>nu</i>	0.00	45.00	+10.00	49.50
77	1	FRONT WINDSCREEN GLASS MOULDING LH <i>nu</i>	0.00	15.00	+10.00	16.50
78	1	FRONT WINDSCREEN GLASS MOULDING RH <i>nu</i>	0.00	15.00	+10.00	16.50
79	1	FRONT WINDSCREEN GLASS MOULDING TOP <i>nu</i>	0.00	30.00	+10.00	33.00
80	1	FRONT WINDSCREEN GLASS MOULDING LOWER <i>nu</i>	0.00	40.00	+10.00	44.00

front windscreen *310 ✓* **Total Parts (\$\$)** 34,761.10
Driver air bag *Activat ✓*

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT WINDSCREEN GLASS SEALANT <i>nu</i>	0.00	24.00	+10.00	26.40 ✓
2	1	FRONT SUPPORT PANEL TOP GARNISH CLIPS <i>nu</i>	0.00	12.00	+10.00	13.20 ✓
3	1	FRONT BUMPER CLIPS <i>nu</i>	0.00	20.00	+10.00	22.00 ✓
4	1	FRONT FENDER INNER SHIELD CLIPS <i>nu</i>	0.00	30.00	+10.00	33.00 ✓
5	1	BONNET INSULATOR CLIP <i>nu</i>	0.00	30.00	+10.00	33.00 ✓
Sub Total (\$\$)						127.60

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Do Up Interior Cleaning and Chemical Wash.	250.00	250.00	0.00	250.00
2	1	To Dismantle & Refit Front Dashboard & related wire harness & related parts.	350.00	350.00	0.00	350.00
3	1	To Computer Reset and Re-program all fault code.	350.00	350.00	0.00	350.00
4	1	To Dismantle and Refit Engine, Gearbox.	750.00	750.00	0.00	750.00
5	1	To Dismantle and Refit Front Undercarriage.	220.00	220.00	0.00	220.00
6	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace	30.00	30.00	0.00	30.00

17 *take phd*
260
300
350?

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
Damaged Parts.						
7	1	To Conduct Computer Wheel Alignment.	80.00	80.00	0.00	80.00 ✓
8	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	3,000.00	3,000.00	0.00	3,000.00 1400
Gross Labour Cost (\$\$)						5,030.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00	45.00 ✓
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	1,800.00	1,800.00	0.00	1,800.00 900
Gross Labour Cost (\$\$)						1,845.00

< END OF ESTIMATES >