



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2016 HONDA VEZEL 1.5 (SJY4688P)
Date of Loss	8 December 2018
Time of Loss	5.30
Loss Description	SJY4688P (INSD) COLLIDED INTO PROPERTY
Comment	<input type="text"/>

Workshop Details

Total Rebate Amount	<input type="text" value="53416"/>
Nett Loss Amount	\$18,584.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	<input type="text" value="95"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SJY4688P

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

25/05/2017



Mileage

0

Age of Vehicle

1

Driver Details

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2016	2016
Make	HONDA	HONDA
Model	VEZEL 1.5	VEZEL 1.5X CVT

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	TAN SEOK TIANG ANNE	
Date of Birth	15 December 1965	dd/mm/yy
Age	53	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No	RU11207857	<input type="text" value="RU11207857"/>
Engine No	L15B4407854	<input type="text" value="L15B4407854"/>
Engine Capacity		<input type="text" value="1496"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="72000"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	11	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date	1 January 2008	<input type="text" value="dd/mm/yy"/> 
License Expiration Date		<input type="text" value="dd/mm/yy"/> 
Address	BLK 237 PASIR RIS ST 21 #02-15, 510237, Singapore	<input type="text" value=""/>
Address type	Personal Correspondence	<input type="text" value=""/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Female	<input type="text"/>
Marital status	Unknown	<input type="text"/>
Identification #	S1708021J	<input type="text"/>



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

12/12/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

300

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

215/60R16

Rear Tyre Size

215/60R16

Front left side

DUNLOP7mm

Rear left side

DUNLOP7mm

Front right side

DUNLOP7mm

Rear right side

DUNLOP7mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Part Supplied by AXA

Yes No



SERVICE REQUESTS

MESSAGES

CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		1	1			BONNET (WCP) (10%)			Buckled	308				308	Reviewing	
<input type="checkbox"/>		2	1			BONNET HINGE LH (WCP) (10%)			Bent	35.2				35.2	Reviewing	
<input type="checkbox"/>		3	1			BONNET HINGE RH (WCP) (10%)			Bent	35.2				35.2	Reviewing	
<input type="checkbox"/>		4	1			BONNET INSULATOR (WCP) (10%)			Damaged	93.5				93.5	Reviewing	
<input type="checkbox"/>		5	1			BONNET LOCK (WCP) (10%)			Twisted	77				77	Reviewing	
<input type="checkbox"/>		6	1			BONNET RUBBER (WCP) (10%)			Necessary	19.8				19.8	Reviewing	
<input type="checkbox"/>		7	1			ENGINE CROSSMEMBER (WCP) (10%)			Dented	770				770	Reviewing	
<input type="checkbox"/>		8	1			FRONT BUMPER (WCP) (10%)			Damaged	253				253	Reviewing	
<input type="checkbox"/>		9	1			FRONT BUMPER BRACKET LH (WCP) (10%)			Bent	30.8				30.8	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		10	1			FRONT BUMPER BRACKET RH (WCP) (10%)			Bent	30.8				30.8	Reviewing	
<input type="checkbox"/>		11	1			FRONT BUMPER CENTRE AIR GRILLE (WCP) (10%)			Damaged	77				77	Reviewing	
<input type="checkbox"/>		12	1			FRONT BUMPER CENTRE LOWER GRILLE (WCP) (10%)			Damaged	170.5				170.5	Reviewing	
<input type="checkbox"/>		13	1			FRONT BUMPER FOG LAMP GARNISH LH (WCP) (10%)			Twisted	30.8				30.8	Reviewing	
<input type="checkbox"/>		14	1			FRONT BUMPER FOG LAMP GARNISH RH			Serviceable	0	0	0	0	0	Deny	
<input type="checkbox"/>		15	1			FRONT BUMPER FOG LAMP LH (WCP) (10%)			Cracked	181.5				181.5	Reviewing	
<input type="checkbox"/>		16	1			FRONT BUMPER FOG LAMP RH			Serviceable	0	0	0	0	0	Deny	
<input type="checkbox"/>		17	1			FRONT BUMPER LOWER COVER (WCP) (10%)			Damaged	143				143	Reviewing	
<input type="checkbox"/>		18	1			FRONT BUMPER LOWER RUBBER (WCP) (10%)			Damaged	77				77	Reviewing	
<input type="checkbox"/>		19	1			FRONT BUMPER REINFORCEMENT (WCP) (10%)			Damaged	231				231	Reviewing	
<input type="checkbox"/>		20	1			FRONT BUMPER SIDE RETAINER LH (WCP) (10%)			Bent	16.5				16.5	Reviewing	

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	21	1			FRONT BUMPER SIDE RETAINER RH (WCP) (10%)			Bent	16.5				16.5	Reviewing	
	22	1			FRONT BUMPER TOW COVER (WCP) (10%)			Damaged	13.2				13.2	Reviewing	
	23	1			FRONT GRILLE BASE (WCP) (10%)			Broken	220				220	Reviewing	
	24	1			FRONT GRILLE TOP BRACKET (WCP) (10%)			Cracked	46.2				46.2	Reviewing	
	25	1			FRONT HEADLAMP LOWER BRACKET LH (WCP) (10%)			Cracked	38.5				38.5	Reviewing	
	26	1			FRONT HEADLAMP LOWER BRACKET RH (WCP) (10%)			Cracked	38.5				38.5	Reviewing	
	27	1			AIR CON CONDENSER (WCP) (10%)			Damaged	341				341	Reviewing	
	28	1			AIR CON CONDENSER AIR GUIDE LH (WCP) (10%)			Damaged	38.5				38.5	Reviewing	
	29	1			FRONT AIR INTAKE DUCT (WCP) (10%)			Cracked	49.5				49.5	Reviewing	
	30	1			FRONT AIR INTAKE JOINT PIPE (WCP) (10%)			Twisted	60.5				60.5	Reviewing	
	31	1			RADIATOR (WCP) (10%)			Damaged	264				264	Reviewing	

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	32	1			RADIATOR FAN COWLING (WCP) (10%)			Cracked	88				88	Reviewing	
	33	1			FRONT FENDER INNER SHIELD LH (WCP) (10%)			Damaged	93.5				93.5	Reviewing	
	34	1			FRONT FENDER LH (WCP) (10%)			Buckled	297				297	Reviewing	
	35	1			FRONT FENDER RH (WCP) (10%)			Buckled	297				297	Reviewing	
	36	1			FRONT FENDER WHEEL ARCH GARNISH LH (WCP) (10%)			Damaged	121				121	Reviewing	
	37	1			FRONT FENDER WHEEL ARCH GARNISH RH			Serviceable	0	0	0	0	0	Deny	
	38	1			FRT SHOCK ABSORBER LH (WCP) (10%)			Bent	242				242	Reviewing	
	39	1			FRT LOWER ARM LH (WCP) (10%)			Bent	220				220	Reviewing	
	40	1			FRT KNUCKLE LH (WCP) (10%)			Bent	214.5				214.5	Reviewing	
	41	1			FRONT WHEEL HUB LH (WCP) (10%)			Bent	154				154	Reviewing	
	42	1			DASHBOARD (WCP) (10%)			Damaged	605				605	Reviewing	
	43	1			PASSENGER AIR BAG (WCP) (10%)			Activated	1210				1210	Reviewing	

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	44	1			FRONT SEAT BELT LH (WCP) (10%)			Activated	528				528	Reviewing	
	45	1			FRONT SEAT BELT RH (WCP) (10%)			Activated	528				528	Reviewing	
	46	1			AIR BAG ECU (WCP) (10%)			Activated	935				935	Reviewing	
	47	1			FRONT SUPPORT PANEL (WCP) (10%)			Twisted	407				407	Reviewing	
	48	1			FRONT SUPPORT PANEL TOP GARNISH (WCP) (10%)			Damaged	60.5				60.5	Reviewing	
	49	1			FRONT HORN LH (WCP) (10%)			Cracked	41.8				41.8	Reviewing	
	50	1			FRONT CHASSIS MEMBER LH			Repair	0	0	0	0	0	Deny	
	51	2			FRONT CHASSIS FRAME			Repair	0	0	0	0	0	Deny	
	52	1			ENGINE MOUNTING LH (WCP) (10%)			Damaged	220				220	Reviewing	
	53	1			ENGINE MOUNTING RH (WCP) (10%)			Damaged	154				154	Reviewing	
	54	1			ENGINE MOUNTING REAR			Serviceable	0	0	0	0	0	Deny	
	55	1			FRONT DRIVESHAFT LH (WCP) (10%)			Broken	715				715	Reviewing	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		56	1			POWER STEERING RACK			Serviceable	0	0	0	0	0	Deny	
		57	1			FRONT STABILIZER LINK LH (WCP) (10%)			Twisted	55				55	Reviewing	
		58	1			FRONT TIR ROD END LH			Serviceable	0	0	0	0	0	Deny	
		59	1			FRONT DRAG LINK LH			Serviceable	0	0	0	0	0	Deny	
		60	1			SET FRONT HEADLAMP WIRE HARNESS			Repair	0	0	0	0	0	Deny	
		61	1			ENGINE ECU			Serviceable	0	0	0	0	0	Deny	
		62	1			FUSE BOX TOP COVER			Serviceable	0	0	0	0	0	Deny	
		63	1			FUSE BOX BOTTOM COVER			Serviceable	0	0	0	0	0	Deny	
		64	1			FUSE BOX CENTRE MAN			Serviceable	0	0	0	0	0	Deny	
		65	1			FRONT CTBA CONTROL BOX (WCP) (10%)			Damaged	770				770	Reviewing	
		66	1			FRONT WIPER PANEL GARNISH (WCP) (10%)			Cut	231				231	Reviewing	
		67	1			FRONT WHEEL RIM LH (WCP) (10%)			Dented	242				242	Reviewing	
		68	1			AIR CON DISCHARGE PIPE			Serviceable	0	0	0	0	0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		69	1			AIR CON SUCTION PIPE			Serviceable	0	0	0	0	0	Deny	
		70	1			AIR CON LIQUID PIPE			Serviceable	0	0	0	0	0	Deny	
		71	1			FRONT WIPER GARNISH END LH (WCP) (COST PLUS 10%)			Twisted	22				22	Reviewing	
		72	1			FRONT WIPER GARNISH END RH (WCP) (10%)			Twisted	22				22	Reviewing	
		73	1			FRONT WHEEL HUB BEARING LH (WCP) (10%)			Necessary	49.5				49.5	Reviewing	
		74	1			FRONT WINDSCREEN GLASS MOULDING LH (WCP) (10%)			Necessary	16.5				16.5	Reviewing	
		75	1			FRONT WINDSCREEN GLASS MOULDING RH (WCP) (10%)			Necessary	16.5				16.5	Reviewing	
		76	1			FRONT WINDSCREEN GLASS MOULDING TOP (WCP) (10%)			Necessary	33				33	Reviewing	
		77	1			FRONT WINDSCREEN GLASS MOULDING LOWER (WCP) (10%)			Necessary	44				44	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	78	1			FRONT WINDSCREEN GLASS SEALANT (WCP) (COST PLUS 10%)			Necessary	26.4				26.4	Reviewing	
	79	1			FRONT SUPPORT PANEL TOP GARNISH CLIPS (WCP) (COST PLUS 10%)			Necessary	13.2				13.2	Reviewing	
	80	1			FRONT BUMPER CLIPS (WCP) (COST PLUS 10%)			Necessary	22				22	Reviewing	
	81	1			FRONT FENDER INNER SHIELD CLIPS (WCP) (COST PLUS 10%)			Necessary	33				33	Reviewing	
	82	1			BONNET INSULATOR CLIP (WCP) (COST PLUS 10%)			Necessary	33				33	Reviewing	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		TO DO UP INTERIOR CLEANING AND CHEMICAL WASH	0	0	0	Deny		
	2		TO DISMANTLE & REFIT FRONT DASHBOARD & RELATED WIRE HARNESS & RELATED PARTS	260	0	0	Reviewing		
	3		TO COMPUTER RESET AND RE-PROGRAM ALL FAULT CODE	300	0	0	Reviewing		
	4		TO DISMANTLE AND REFIT ENGINE, GEARBOX	350	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		5		TO DISMANTLE AND REFIT FRONT UNDERCARRIAGE	220	0	0	Reviewing		
		6		TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS	30	0	0	Reviewing		
		7		TO CONDUCT COMPUTER WHEEL ALIGNMENT	80	0	0	Reviewing		
		8		TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	1400	0	0	Reviewing		
		9		TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	0	0	0	Deny		
		10		TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	900	0	0	Reviewing		
		11		TOWING	150	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
 	1	DAYS OF REPAIR : 20 DAYS	Reviewing			
 	2	AUTO TRANSMISSION GEARBOX (LOCAL REPAIR)	Reviewing	7500	CRACKED	
 	3	BATTERY	Reviewing	80	BROKEN	
 	4	FRONT TYRE LH (LOCAL REPAIR) (\$180.00) (70%)	Reviewing	126	PUNCTURED	

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
 	5	FRONT WINDSCREEN GLASS (WCP) (COST PLUS 10%)	Reviewing	880	CRACKED (SUPPLEMENTARY)	
 	6	DRIVER AIRBAG (WCP) (COST PLUS 10%)	Reviewing	1155	ACTIVATED (SUPPLEMENTARY)	
 	7	HEADLAMP LH (WCP) (COST PLUS 10%)	Reviewing	495	BROKEN (SUPPLEMENTARY)	
 	8	AIR CLEANER BOX (WCP) (COST PLUS 10%)	Reviewing	225.5	BROKEN (SUPPLEMENTARY)	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$26,318.90

Claim Amount

\$26,318.90

CATEGORY

ESTIMATE

REVISED AMOUNT

Spare Parts

\$12,467.40

\$12,467.40

Labour

\$3,690.00

\$3,690.00

Miscellaneous

\$10,461.50

\$10,461.50

Excess

-\$300.00

-\$300.00

[Submit for Review](#)



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	FINAL LUMP SUM	Reviewing	20000		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$19,700.00

Claim Amount

\$19,700.00

CATEGORY

ESTIMATE

REVISED AMOUNT

Miscellaneous

\$20,000.00

\$20,000.00

Excess

-\$300.00

-\$300.00

[Submit for Review](#)