



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



(tp)

AXA INSURANCE PTE LTD		NAME : Mr Tan Ying Chuin		WIP : 30168	
8 SHENTON WAY		ADDRESS : Blk 2C Hong San Walk		EXCESS :	
#24-01 AXA TOWER		#09-07 PALM GARDENS		DATE: 11-Dec-18	
SINGAPORE 068811		Singapore 689049			
ATTN : MOTOR CLAIMS		TEL : 97387566			
FAX :					
VEH NO :	SFC5712J	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	JM6CC1071G0110254	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	BIANTE	DATE REG.:	27-Feb-17	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	REAR BUMPER	1	MC275-50-221FBB	\$ 1,114.70
2	RETAINER RHS	1	MC273-50-2H1C	\$ 46.40
3	STRIPE LHS, REAR BUMPER	1	MC467-50-888	\$ 81.90
4	STRIPE CENTER, REAR BUMPER	1	MC467-50-879	\$ 123.90
5	STRIPE RHS, REAR BUMPER	1	MC467-50-878	\$ 81.90
6	REFLECTOR RHS	1	MC273-51-5L0A	\$ 118.50
7	CAP DRIP LHS	1	MC275-50-5A1BBB	\$ 3.30
8	CAP DRIP RHS	1	MC273-50-5A1BBB	\$ 3.30
9	TAPE PROTECTOR, REAR BUMPER	2	MG043-62-864A	\$ 6.60
10	GROMMET, REAR BUMPER	2	MB01W-51-142B	\$ 6.00
11	PIN LOCATOR, REAR BUMPER	2	MGJ6B-50-1K5	\$ 8.00
12	GROMMET, REAR BUMPER	2	MBP4K-50-ES1	\$ 8.80
13	RIVET, REAR BUMPER	2	MA001-50-7C1	\$ 7.20
14	ANTENNA, KEYLESS	1	MC277-67-6N0	\$ 253.10
15	REAR END PANEL	1	MC273-70-750B	\$ 288.70
16	TRIM, END PANEL	1	MC273-68-89XA56	\$ 116.40
17	TRIM RHS, BOOTSIDE	1	MC273-68-850D56	\$ 602.50
18	TAILGATE	1	MC2Y3-62-02XF	\$ 1,618.70
19	WEATHERSTRIP, TAILGATE	1	MC273-62-761B	\$ 207.90
20	TRIM LOWER, TAILGATE	1	MC273-68-960E56	\$ 406.00
21	FASTENER, TAILGATE	3	MB467-68-AC3 34	\$ 15.90
22	FASTENER, TAILGATE	3	MB467-68-AC3 02	\$ 11.10
23	RECESS, TAILGATE	1	MGJ6A-68-966 56	\$ 22.30
24	LOCK, TAILGATE	1	MC273-62-310	\$ 252.00
25	STRIKER, LOCK	1	MD350-62-361D	\$ 27.20
26	ORNAMENT, SKYACTIVE	1	MC603-51-771A	\$ 111.50
27	FASTENER, REAR WINDSCREEN	4	MD204-50-896A	\$ 10.40
28	SPACER, REAR WINDSCREEN	5	MGJ6A-50-897	\$ 60.50
29	FASTENER, REAR WINDSCREEN	2	MC273-50-896	\$ 15.60

30	PIN STUD, REAR WINDSCREEN		1	MG21E-63-938B		\$	10.50
	TOTAL PARTS					\$	5,640.80
	LESS 10%					\$	564.08
	TOTAL PARTS COST					\$	5,076.72
Labour Description							
1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR END PANEL AND TAILGATE. TO REPAIR REAR FLOOR PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.				\$	4,620.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR FLOOR PANEL, REAR END PANEL AND TAILGATE.				\$	2,520.00
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.			NETT	\$	560.00
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.			NETT	\$	120.00
5	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.			NETT	\$	330.00
6	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.				\$	660.00
7	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.				\$	660.00
8	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.			NETT	\$	70.00
9	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.				\$	990.00
10	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING				\$	350.00
11	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.				\$	250.00
12	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.				\$	250.00
13	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.				\$	350.00
14	MZ-BR-SUNDRI	SUNDRIES.			NETT	\$	100.00
				TOTAL LABOUR	\$	-	\$ 11,830.00
				TOTAL PARTS	\$	-	\$ 5,076.72
				TOTAL	\$	-	\$ 16,906.72
				LESS EXCESS	\$	-	\$ -
				TOTAL AFTER EXCESS	\$	-	
				GST 7%	\$	-	\$ -
				GRAND TOTAL	\$	-	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature