

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

12 DEC 2018

E S T I M A T E

Estimate No. : b1 49419
Date Estimated : 12/12/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Yap Pek Lan
240 Tampines Street 21
#09-465

Singapore 520240

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ1610B	5G66470	28/06/2017	X1 sDrive20i	0

DESCRIPTIONVALUE

To replace rear bumper panel & all attachments cause by accident.

850 1,700.00

Painting on rear bumper upper

934 1,038.00

To check electrical wiring systems at the rear section for proper function.

150. 177.00

Sundries.

2 80.00

Total Labour 1: **2,995.00**DESCRIPTIONQTYPRICVALUE

REAR LH BUMPER MOUNT

1

160.55

160.55

REAR RH BUMPER MOUNT

1

160.55

160.55

RR BUMPER CARRIER

1

468.30

468.30

MOUNTING SMART OPENER

1

45.30

45.30

REAR TRIM UNDERRIDE PROTECTION (X L

1

102.30

102.30

RR BUMPER LH CORNER MOUNTING

1

141.90

141.90

RR BUMPER RH CORNER MOUNTING

1

141.90

141.90

REAR BUMPER PANEL PRIMED

1

741.55

741.55

REAR BUMPER MIDDLE TRIM PANEL (PDC)

1

233.60

233.60

REAR BUMPER BOTTOM TRIM PANEL (LINE

1

222.45

222.45

REAR BUMPER TOWING EYE COVER

1

36.60

36.60

DECOUPING RING PDC TORQUE CONVERTER

4

5.05

20.20

Total Parts : **2,475.20**



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 49419**
Date Estimated : **12/12/2018**
Prepared By : **Kevin Leong Wai Kit**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ1610B	5G66470	28/06/2017	X1 sDrive20i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 28/1/19 e 1115 Claim No. _____

Date & Time 28/1/19 e 1115 Excess S\$ _____

Surveyor's Name Tan Jiah Sign Tan Jiah

Surveyor's Tel 97495449 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail tanjiah@lkkauto.com

No. of Working Days Recommend 03 days

LKK Auto Consultants Hence notify the Repairer of the following

- To resurvey before after survey
- To display damaged parts
- Parts prices are subject to change
- Third party surveys on a TV at Prejudice
- No illegal modifications is allowed
- Supplementary items must be approved
- is subject to final approval from LKK Auto Consultants

Acknowledged by Repairer

Signature:

Date:

B.S. 225/50R18

Labour 1	:	2,995.00
Parts	:	2,475.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	382.91
Grand Total	:	5,853.11

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **