

REPAIR ESTIMATE*

DATE 7/12/2018 10:59

MODEL : HYUNDAI IONIQ

MODEL	: HYUNDAI IONIQ		Qty	Parts Description/ Labour	Type	Unit Price	Amount
				Rear Bumper			\$ 459.40
				Rear Bumper Reinforcement Bracket (LH/RH)		\$ 138.10	\$ 276.20
				SUB TOTAL			\$ 735.60
				LESS 20%			\$ 147.12
				DISCOUNTED TOTAL			\$ 588.48
				Rear Bumper Rubber Mat			\$ 50.00
				Labour Charge			
				Panel Beating			\$ 400.00
				Spray Painting Charge			\$ 300.00
				Wiring Charge			\$ 30.00
				Remove/Refix Reverse Sensor			\$ 120.00
				TOTAL LABOUR			\$ 850.00
				ESTIMATE TOTAL			\$ 1,488.48
				<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary claim(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>			