



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SLM7071M

Lee Wen Yan

63 Hillview Crescent  
Singapore 669464

Vehicle & Document Information  
WIP No 29282  
Reg No/Reg Date SLM7071M / 07/04/2017  
Date In/Mileage / 0  
Chassis No WDD2050402R262555  
Engine No 27491030887415  
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A  
Colour/Trim 029 988 Diamond Sil/ 041 118 ARTICOLther

| Account No | Terms  | Date/Time Printed | CSE | Operator         |
|------------|--------|-------------------|-----|------------------|
| WCV29627   | CRDVCH | 11/12/2018/ 11:09 | K0  | 301 / Kerlyn Ong |

| Description of Goods / Services  | Qty  | Unit Price | Disc% | Amount      |
|--|------|------------|-------|-------------|
| Z REQUEST<br>Customer Request<br>M BPNSUN<br>POLICY NO/ACC DATE : // 10/12/2018<br>DRIVE IN/EXCESS : 11/12/2018 // FBL1594J - EQ<br>DATE IN/DATE SURVEY:<br>BY/AUTHORIZED ON : |      |            |       |             |
| A BPILAB<br>DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.   |      |            |       | 960 1920.00 |
| A BPIRES<br>RESPRAY REAR BUMPER  |      |            |       | 600 960.00  |
| A BPILAB<br>USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT   |      |            | 0.10  | 380.00      |
| A BPILAB<br>CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT  |      |            |       | 120.00      |
| M REAR BUMPER cat  | 1.00 | 1559.46    | 00.00 | 1559.46     |
| M LH/ REAR BUMPER BRACKET  | 1.00 | 29.98      | 00.00 | 29.98       |
| M RH/ REAR BUMPER BRACKET  | 1.00 | 29.98      | 00.00 | 29.98       |
| M COVER BUMPER AREA  | 1.00 | 100.55     | 00.00 | 100.55      |
| M RH/ BASIC MOUNTING FOR BUMPER  | 1.00 | 51.97      | 00.00 | 51.97       |
| M RH/ REAR BUMPER SIDE STABILITY   | 1.00 | 49.72      | 00.00 | 49.72       |
| M RH/ REAR LAMP COMBINATION CRA  | 1.00 | 679.52     | 00.00 | 679.52      |

Kerlyn Ong Kai Li  
DID : 6771 4420 HP : 9186 5113  
Email : kerlyn.ong@cyclecarriage.com.sg  
Cycle & Carriage Industries Pte Ltd  
Customer Service Centre - Pandan Loop

Confirmed & accepted by

Authorized signatory and company stamp

|  |                          |
|--|--------------------------|
| LKK Auto Consultants hence notify the Repairer of the following:                                   |                          |
| • To resurvey before/after spray painting  |                          |
| • To display damaged part(s) during resurvey   |                          |
| • Parts prices are subject to confirmation   |                          |
| • Third party survey is on a "Without Prejudice" basis   |                          |
| • No illegal modification(s) is allowed  |                          |
| • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company |                          |
| Acknowledged by Repairer   | Nett 5,881.18            |
| Signature:   | 7% GST on 5881.18 411.68 |
| Date:  | Total Payable 6,292.86   |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg