

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5823T

AAD1812-082

*Not Authored
Resurvey B4 paint*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD 5823T
JTDKB3FU103076873
TOYOTA
PRIUS
8.12.2018
FWD

| PART | | LIST | |
|------|---|--------|-------------------------|
| 1 | 1 REAR BUMPER | \$ | <i>Buc 1th</i> 458.60 ✓ |
| 2 | 1 REAR BUMPER RE-INFORCEMENT | \$ | 318.80 ? |
| 3 | 1 REAR BUMPER TOWING COVER | \$ | <i>Sn</i> 14.70 X |
| 4 | 1 REAR BUMPER UNDER COVER (BLACK) | \$ | <i>Buc 1th</i> 552.60 ✓ |
| 5 | 1 REAR BUMPER SIDE RETAINER LH | \$ | <i>Sn</i> 112.70 |
| 6 | 1 REAR BUMPER SIDE RETAINER RH | \$ | <i>Sn</i> 112.70 |
| 7 | 1 REAR TAILGATE | \$ | <i>Sn</i> 1,547.27 |
| 8 | 1 REAR TAILGATE OUTER GARNISH | \$ | <i>Sn</i> 905.10 |
| 9 | 1 COVER, REAR COMBINATION LAMP, RH | \$ | <i>Sn</i> 54.70 |
| 10 | 1 COVER, REAR COMBINATION LAMP, RH | \$ | <i>Sn</i> 54.70 |
| 11 | 1 GARNISH, BACK DOOR SIDE, LH | \$ | <i>Sn</i> 93.60 |
| 12 | 1 GARNISH, BACK DOOR SIDE, RH | \$ | <i>Sn</i> 93.60 |
| 13 | 1 MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH | \$ | <i>Sn</i> 55.40 |
| 14 | 1 MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH | \$ | <i>Sn</i> 55.40 |
| 15 | 1 BOARD ASSY, BACK DOOR TRIM | \$ | <i>Sn</i> 254.40 |
| 16 | 1 PANEL ASSY, BACK DOOR TRIM, UPPER | \$ | <i>Sn</i> 51.20 |
| 17 | 1 REAR TAILGATE WEATHERSTRIP | \$ | <i>Sn</i> 365.20 |
| 18 | 1 REAR END PANEL | \$ | <i>Sn</i> 602.10 |
| 19 | 1 TAILLAMP LOWER RH | \$ | <i>Sn</i> 548.40 |
| 20 | 1 TAILLAMP UPPER RH | \$ | <i>Sn</i> 557.90 |
| 21 | 1 REAR BUMPER SIDE RH | \$ | <i>Sn</i> 232.00 |
| 22 | 1 REAR BUMPER SIDE LH | \$ | <i>Sn</i> 232.00 |
| | | \$ | 7,273.07 |
| | | 25% \$ | 1,818.27 |
| | | \$ | 5,454.80 |

Trans-cab Auto Services Pte Ltd

AAD1812-082

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5823T

Special Nett

| | | | |
|--|----|-------------|-------|
| 1 1SET PARKING AID | \$ | Shot 700.00 | 2000n |
| 2 1SET REAR BUMPER CLIP | \$ | na 22.00 | — |
| 3 2 REAR WINDSCREEN SELANT | \$ | na 80.00 | } X |
| 4 1 WINDSCREEN MOULDING | \$ | na 100.00 | |
| 5 1 REAR WINDSCREEN INNER SPONGE SEAL | \$ | na 100.00 | |
| 6 1 REAR TAILGATE TOYOTA LOGO | \$ | na 47.00 | |
| 7 1 REAR TAILGATE WORDING 'PRIUS' | \$ | na 52.90 | |
| 8 1 REAR TAILGATE WORDING 'HYBRID' | \$ | na 53.50 | |
| 9 1 REAR TAILGATE STICKER 'TRANS-CAB' | \$ | na 80.00 | |
| 10 1 REAR TAILGATE STICKER '6555-3333' | \$ | na 80.00 | |
| 11 1 REAR BUMPER PROTECTOR | \$ | nsp 100.00 | |

TOTAL \$ 1,315.40

TOTAL PARTS \$ 6,770.20

LABOUR

| | | | |
|---|----|-----------|------|
| Putty And Spray Painting Of The Affected Portion. | \$ | 4,500.00 | 2200 |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 4,500.00 | 2000 |
| To Rust-Proofing Of The Affected Areas. | \$ | na 170.00 | X |
| To reinstall rear bumper parking sensor. | \$ | 170.00 | 500 |
| To transfer of Tailgate fittings, attachments and perform water seepage test. | \$ | na 170.00 | X |
| To transfer of Rear Bumper fittings, attachments and perform water seepage test. | \$ | na 170.00 | X |
| To repair and realign rear exhaust pipe. | \$ | na 170.00 | X |

Trans-cab Auto Services Pte Ltd

AAD1812-082

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5823T

| | | |
|--|-----------|--------------------|
| To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe. | \$ | <i>na</i> 170.00 X |
| To transfer of rear end panel fittings, attachment and perform water seepage test. | \$ | <i>na</i> 170.00 X |
| To transfer of rear windscreen fittings and conduct water seepage test. | \$ | <i>na</i> 170.00 X |
| To check steering geometry and computer wheel alignment | \$ | <i>na</i> 220.00 X |
| TOTAL | \$ | 10,580.00 |
| Over All Total | \$ | 22,805.01 |

(PART-BY-PART) Repair Days

15 days

2 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: