

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

TAX INVOICE

AIG Asia Pacific Insurance Pte. Ltd
78 SHENTON WAY
#07-16
SINGAPORE 079120

GST Ref. No: 20-0000274-Z

Vehicle No: SBY8030E
Chasis No: W0VZRHNY0JS046076
Engine No: 10XTA40923936

Invoice No: CGI-ASC-19IR00672G

Invoice Date: 03-May-19

DESCRIPTION	AMOUNT	SGD
-------------	--------	-----

Parts

No.	Qty.	Description	Price (SGD)
<u>1</u>	1	LHR Taillamp	\$ 520.00
<u>2</u>	1	LHR Bumper Upper	\$ 754.00
<u>3</u>	1	LHR Bumper Reflector	\$ 73.00
<u>4</u>	1	Rear Bumper Lower(Black)	\$ 1,888.00
<u>5</u>	1	Rear Bumper Sill Plate	\$ 442.00
<u>6</u>	1	Rear Bumper Reinforcement Bar	\$ 781.00
<u>7</u>	1	Rear Tailgate	\$ 2,742.00
<u>8</u>	1	Rear Tailgate Windscreen with Windscreen Moulding	\$ 924.00
<u>9</u>	1	LHR Tailgate Lamp	\$ 545.00
<u>10</u>	1	Opel Logo	\$ 132.00
<u>11</u>	1	Grandland X Lettering	\$ 204.00
<u>12</u>	1	Turbo Lettering	\$ 110.00
<u>13</u>	1	Rear Tailgate Inner Trim Board	\$ 580.00
<u>14</u>	1	Rear Bumper Centre Bracket, Guide	\$ 310.00
<u>15</u>	1	LHR Bumper Bracket, Guide	\$ 227.00
<u>16</u>	1	RHR Bumper Bracket, Guide	\$ 227.00
<u>17</u>	1	LHR Lower Bumper Bracket	\$ 107.00
<u>18</u>	1	RHR Lower Bumper Bracket	\$ 107.00

Supplementary

No.	Qty.	Description	Price (SGD)
<u>19</u>	4	RR Bumper Reverse Sensor Holder	\$ 160.00
<u>20</u>	1	LHR Tailgate Damper LH	\$ 1,850.00

Total: \$ 12,683.00
Less 10%: \$ 1,268.30

Parts Total : \$ 11,414.70

Labour

No. Description Price (SGD)

Rear portion

<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 per day)	\$ 1,950.00
<u>2</u>	Carry out spray painting on accident affected area (\$550 per panel)	\$ 1,650.00
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
<u>4</u>	To remove and refix reverse sensor and conduct test	\$ 60.00
<u>5</u>	To remove and refix reverse camera and conduct test	\$ 60.00
<u>6</u>	To conduct transfer of parts from old tailgate to new tailgate	\$ 250.00
<u>7</u>	To remove and refix rear tail gate windscreen	\$ 130.00

Labour Total : \$ 4,130.00

Other

No. Other Description Price (SGD)


<u>1</u>	<u>6</u>	LHR Fender Liner clips	\$ 39.00
<u>2</u>	<u>20</u>	LHR Bumper Upper clips	\$ 65.00
<u>3</u>	<u>10</u>	Rear Tailgate Inner Trim Clips	\$ 65.00
<u>4</u>	<u>1</u>	Tailgate windscreen sealant	\$ 60.00
<u>5</u>	<u>1</u>	Tailgate windscreen solar film	\$ 250.00

Other Total : \$ 479.00

Total : \$ 16,023.70

GST (7%) \$ 1,121.66

Grand Total: \$ 17,145.36

Yours Faithfully

Suhaimi Ong

Suhaimi Ong

Service Advisor

Tel: 68441985 Fax: 68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1ST Autoworks Pte Ltd".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.