## PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

11-Dec-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6841 P

1 pc	Front n/s fender	\$	384.00
1 pc	Front n/s fender inner shield ×	\$	120.00
1 pc	Front n/s wheel cover	\$	116.00
1 pc	Front bumper	\$	531.00
1 pc	Front bumper emblem	\$	44.00
1 pc	Front bumper lip ?	\$	52.00
2 pcs	Front bumper o/s & o/s side retainer @ \$16.00 Als ? o/s ×	\$	32.00
2 pcs	Front bumper o/s & o/s upper bracket @ \$16.00 ^/s ?	\$	32.00
2 pcs	Front bumper o/s & o/s support bracket @ \$16.00 مراء ک ماری ×	\$	32.00
1 pc	n/s headlamp	\$	1,028.00
1 pc	Front bumper n/s fog lamp cover 🔀	\$	66.00
1 pc	Front bumper n/s protector X	\$	51.00
		\$	2,488.00
	less 10%	\$	248.80
		\$	2,239.20
S/NETT			
1 pc	Front bumper clips	\$	48.00
1 pc	Front n/s head lamp lower clip	\$	6.00
1 pc	Front n/s head lamp lower clip / Front n/s head lamp side clip / Front n/s fender inner shield clips X	\$	3.00
1 set	Front n/s fender inner shield clips X	\$	28.00
	1/ 12/12/18 1600 L		
	Sunday	•	50.00
	Sundry 3 by	\$	30.00 10
	To check for wiring and to focus head lamps	,\$	40.00 20
	To check wheel alignment Affer Report plan	\$	80.00 ×
	To labour charge for dismantle and renew the accident	-	400
	damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	2	
	resnape and adjust of the same, etc.	\$	600.00
	To putty and spray painting on front bumper, front n/sore after stray	1	1.1
	To putty and spray painting on front bumpbe, front place after surely because fender  To resure a damaged partis, during sesure y  To display damaged partis, during sesure y  To display damaged partis, during sesure y  Parts prices are subject to contirmation	asis\$	400.00 3 60
	• Parts prices and is on a -Without		1 2
	To apply rustproofing on the repaired and replaced panels n(s) is allow and no illegal modified must be resurveyed an No illegal modified must be resurveyed and	n \$	
	To resurvey damaged partis, dirth.  To display dama	\$	3,574.20
	( ALL THE REPAIR COSTS ARE SUBJECTED TO GST Pepairer		
	A CKNOWICE		_