

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

11-Dec-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6841 P

1 pc	Front n/s fender	— <i>dent</i>	\$	384.00
1 pc	Front n/s fender inner shield	<i>X su</i>	\$	120.00
1 pc	Front n/s wheel cover	<i>X repair</i>	\$	116.00
1 pc	Front bumper	— <i>dent</i>	\$	531.00
1 pc	Front bumper emblem	— <i>dent</i>	\$	44.00
1 pc	Front bumper lip	<i>X su</i>	\$	52.00
2 pcs	Front bumper o/s & o/s side retainer @ \$16.00	<i>n/s X o/s X</i>	\$	32.00
2 pcs	Front bumper o/s & o/s upper bracket @ \$16.00	<i>n/s X o/s X</i>	\$	32.00
2 pcs	Front bumper o/s & o/s support bracket @ \$16.00	<i>n/s X o/s X</i>	\$	32.00
1 pc	n/s headlamp	— <i>hazard</i>	\$	1,028.00
1 pc	Front bumper n/s fog lamp cover	<i>X su</i>	\$	66.00
1 pc	Front bumper n/s protector	<i>X su</i>	\$	51.00
			\$	2,488.00
			less 10%	\$ 248.80
			\$	2,239.20

S/NETT

1 pc	Front bumper clips	— <i>acc</i>	\$	48.00
1 pc	Front n/s head lamp lower clip	— <i>acc</i>	\$	6.00
1 pc	Front n/s head lamp side clip	— <i>acc</i>	\$	3.00
1 set	Front n/s fender inner shield clips	<i>X am</i>	\$	28.00
				<i>1600 L</i>
Sundry				<i>3 hrs</i>
To check for wiring and to focus head lamps				<i>45</i>
To check wheel alignment				<i>Adm Repair photo</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.				<i>400</i>
				<i>600.00</i>
To putty and spray painting on front bumper, front n/s fender				<i>400.00</i>
To apply rustproofing on the repaired and replaced panels				<i>80.00</i>
				<i>30</i>
				<i>3,574.20</i>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

17/12/18
about 45 \$ 2100 / 3 hrs

LKK Auto Consultancy

Repairer of title for: []

- To resurvey the repaired parts during resurvey
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by: []

at: []