

ASS. REC. BY:

REF

CS/CTI18022384/Upd3/

Special Instruction:

Surveyor
Meinen

Maras

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

CTI

Date/Time:

12/12/18 @ 3:20pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XE1812G

Insured:

XD7119R

at Workshop m/s

Yew Tee Automobile

Tel:

62882081

of

39 woodlands close # 01-12

Policy No:

DMCVSN1757101801

Claim No:

9NM18D05694C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/12/18

CA / REV / REP. / REV 24 HRS

kup

13/12/18

H.O.D. Endorsement:

Date/Time:

3:55pm @ 12/12/18

Person Contacted:

Vinnie

Vehicle

☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	XE1812G - X
	XD7119R - CC6/CTI18013744/Upb3s2
	DOA: 27/07/2018

REF: CTE

ASSIGNMENT

From: Date: 13/12/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

XE 1812G

at Workshop no:

Yew Tee Automobile

of

39 woodlands close # 01-12

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

90

IDAC Accident Report:

Consistent? : Yes or No

G/A / PR Seen

Consistent? : Yes or No

Est. Repairs:

8

days

Res.:

Yes or No

Lump Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS 'up

LTA 14867

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

XE1812G

Veh Reg:

616

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA/

Make:

IVECO TRAKKER

CC 12882

Colour:

yellow

AC

Insured / Std / NI / NA

Sp Reading:

193316

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WJME2N5540C281847

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

385/65R22.5

R:

315/60R22.5 Mirage

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

roadwiny

Front

Rear

R/Bal:

4

mm

R/Bal:

5/5

5/5

mm

L/Bal:

4

mm

L/Bal:

5/5

5/5

mm

D.O.A:

5/12/18

D.O.A:

13/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Rep 12k. 7yrs. bal.

27/12/19

H/S \$18,600 confirmed with sky (Ref 8 29420.50, 61%)

RECEIVED 01 MAR 2019

Date/Time, File Path for

☐

Prel. Report

11/01/20 Final Report

☐

Final Report

Date/Time, File Path for

Days Of Repair:

8

Resurvey No. of Trip:

2

Survey Fee:

Transportation

1 Photos

1 Videos

TOTAL

Report Format:

MED-TP

Lump Sum / I.D. (\$) :

18600

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Week-end (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2018		12 Dec 2018 15:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAT HONG CONSTRUCTION & TRANSPORT PTE. LTD., Co. Reg. No.: 200613703C		
Main Claimant:	ORIENT NATURAL RESOURCES PTE LTD, Co. Reg. No.: 201015702G		
Vehicle Reg. No.:	XE1812G	Date of Loss:	05/12/2018 08:00 - :59
Claim Type:	TP / SNM18D05694C02	Policy/Cover Note No.:	DMCVSN17S7101801 (Comprehensive)
Vehicle Reg. No. (Insured):	XD7119R	Policy No. (Claimant):	VFX/P1931543
		Excess:	S\$0.00
Repairer:	Yew Tee Automobile Tech Pte Ltd (Woodlands) 39 Woodlands Close #01-12, Mega@Woodlands, 737856 Woodlands - Tel: 62562533		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/12/2018]		
Driver/Custodian (Insured):	YU HONG QUAN (47 / Male), NRIC: G6196196N, Tel: +6590536792		
Adj Asg. Remarks:	EST \$49,147.78 , ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/12/2018 14:20
Date Of Accident	05/12/2018 08:30
Exact Location Of Accident	18 SELETAR NORTH LINK
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	XE1812G
Insured/Policyholder	
Name Of Registered Owner	ORIENT NATURAL RESOURCES PTE LTD
Co Reg No	201015702G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65086998
Vehicle Particulars	
Manufacturer	IVECO
Model	TRAKKER AUTO AT260T41 (MY2013, EURO V)
Exact Purpose for which vehicle was being used at time of accident	WORK USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VFX/P1931543
Cover Note Number	
Driver	
Name of Driver	LI SHIYU
Passport No/FIN	G5425710X
Date Of Birth	26/05/1986
Occupation	OUTDOOR
Date Of Driving Pass	01/06/2013
Driving Experience	5 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83532670
Fax Number	
Contact Number	
Email Address	NOEMAIL

Sell your car by **BIDDING**
Highest price or your money-back!

[Click to find out more](#)

[f Connect with Facebook](#)

[HOME](#)

[NEW CARS](#)

[USED CARS](#)

[COMMERCIAL VEH](#)

[RENTAL CARS](#)

[SELL CARS](#)

[MOTOR DIRECT](#)

[Home](#) > [Used Commercial Veh](#) > [Iveco Search Results](#)

IVECO SEARCH RESULTS (2 listings)

Sort By [Recommended](#)

15 results/page

Iveco Stralis



Transmission: Auto
Engine Cap : 10,308 cc
Reg Date : 31-Jul-2013
(4yrs 7mths COE left)

Mileage : -
Fuel Type : Diesel
Depreciation : \$12,710 / year

\$58,800
AVAILABLE

Call To Make Appointment To View.

Posted On 10 October 2018

Tags: [Iveco Stralis Car](#), [2013 Iveco Stralis Car](#), [Stralis Car](#), [Used Iveco Car](#)



Iveco Stralis



Transmission: Auto
Engine Cap : 10,308 cc
Reg Date : 23-Mar-2012
(3yrs 3mths COE left)

Mileage : -
Fuel Type : Diesel
Depreciation : \$12,170 / year

\$39,800
AVAILABLE

Do Not Miss This Rare Opportunity To Own This Machine At An Amazing Price.
Get Ahead Of The Queue To Confirm This Wonderful Deal Today! Call Our
Friendly Sales Personnel For An Appointment To View Now.

Posted On 10 October 2018

Tags: [Iveco Stralis Car](#), [2012 Iveco Stralis Car](#), [Stralis Car](#), [Used Iveco Car](#)



Sort By [Recommended](#)

15 results/page

USED VEHICLE SEARCH

Category

Transmission

Min Price

Min Depreciation

From Reg Year



ADVICE

Many drivers have heard of these fuel-saving tips but do they really work?



LIFESTYLE

Bell & Ross launches R.S.18 Collection



ADVICE

Six reasons why you should never upsize your wheels



New Cars

[BMW cars](#)
[Audi cars](#)
[Volkswagen cars](#)
[Mercedes Benz Cars](#)
[Toyota Cars](#)
[Honda Cars](#)

Used Cars

[Toyota Cars](#)
[Honda Cars](#)
[BMW Cars](#)
[Hyundai Cars](#)
[Nissan Cars](#)
[Mercedes Benz Cars](#)

Car Rental and Leasing

[Passenger Car Rental](#)
[Passenger Car Leasing](#)
[Car Sharing](#)
[Commercial Vehicle Leasing](#)
[Chauffeur & Limousine Service](#)
[Wedding Car Rental](#)

Motoring Directory

[Servicing and Repair](#)
[Car Grooming](#)
[Car Audio and Entertainment](#)
[Tyres Rims and Batteries](#)
[Spray Painting and Body Repair](#)
[Accident Claims and Repair](#)

Articles

[Car Reviews](#)
[Motoring News](#)
[Motoring Guides](#)
[COE](#)
[Car Park Rates](#)
[Sell Cars](#)

Car Forum

[Car Club](#)
[Motor Insurance](#)
[Car Discussion](#)
[Forum Discussi](#)
[Car Accessories](#)
[Car Blog](#)

Affiliates:



[About Us](#) | [Contact Us](#) | [Advertise With Us](#) | [Terms & Conditions](#) | [Privacy Policy](#) | [Personal Data P](#)

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5702G
Vehicle Details	
Vehicle No.:	XE1812G
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Dec 2018
Vehicle Make:	IVECO
Vehicle Model:	TRAKKER AUTO AT260T41 (MY2013, EURO V)
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	F3BE3681DS451219464
Chassis No.:	WJME2NSS40C281847
Maximum Power Output:	-
Open Market Value:	\$129,358.00
Original Registration Date:	08 Jun 2016
First Registration Date:	08 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$6,468.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 Jun 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$19,872.00
COE Rebate Amount:	\$14,867.00
Total Rebate Amount:	\$14,867.00

The information contained herein is correct as at 14 Dec 2018

OK



鐘摩多拖車服務
TENG MOTOR TOWING SERVICE

TENG MOTOR TOWING SERVICE

Blk 5, 395-E/F, Yew Tee Industrial Estate

Woodlands Road, Singapore 677987

Tel: 6769 7777 • 6769 6666 Fax: 6763 2376

Reg. No. 218618/ODW

INVOICE

№ 7469

M/S Cash

Date: 31/12/2018

[illegible]

TOTALS

240

lived by _____

Issued by

Received by

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

ON BEHALF OF OWNER :

Policy Particulars: - THIRD PARTY DAMAGED CLAIM

Insured veh.	XE1812G	Excess.	NIL
Policy No.	VFX/P1931543	Coverage.	Comprehensive
Claiming Against.	XD7119R	CHINA TAIPING	
Insured Under.	AXA		

Vehicle Particulars & Condition

Make & Model	Iveco Trakker
Engine No.	F3BE3681DS451219464
Chassis No.	WJME2NSS40C281847
Odometer	
Engine CC.	
Year Of Reg.	2016
Colour.	ORANGE
Parf/COE Rebate.	

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

Front portion damaged.

General Information

Accident Date. 5/12/2018
Survey held at

Yew Tee Automobile Tech Pte Ltd
MEGA@Woodlands, 39 Woodlands Close #01-12, Singapore 737856

Remarks

KINDLY LET US HAVE THE LIABILITY SOON.

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: Days

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

ON BEHALF OF OWNER :

Policy Particulars: - THIRD PARTY DAMAGED CLAIM

Insured veh.	XE1812G	Excess.	NIL
Policy No.	VFX/P1931543	Coverage.	Comprehensive
Claiming Against.	XD7119R	CHINA TAIPING	
Insured Under.	AXA		

Vehicle Particulars & Condition

Make & Model	Iveco Trakker
Engine No.	F3BE3681DS451219464
Chassis No.	WJME2NSS40C281847
Odometer	
Engine CC.	
Year Of Reg.	2016
Colour.	ORANGE
Parf/COE Rebate.	

Conditions Of Tyres

	Size	Make
R/H Front Tyre		
L/H Front Tyre		
R/H Rear Tyre		
L/H Rear Tyre		

Description Of Damages

Front portion damaged.

General Information

Accident Date. 5/12/2018
Survey held at

Yew Tee Automobile Tech Pte Ltd

MEGA@Woodlands, 39 Woodlands Close #01-12, Singapore 737856

Remarks

KINDLY LET US HAVE THE LIABILITY SOON.

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: Days

YTC Auto Consultants hence notify the Repairer of the following:

- To survey bilinear spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- This survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Allowed
LH
2/4 ~~18,600~~
8 day.
13/1/18
The photo above

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

Qty.	Description Of Parts	Pricing
1	Front bumper centre <i>nc</i>	\$ 4,200.00 <i>X</i>
1	Front panel <i>one</i>	\$ 8,200.00 <i>6179.21</i>
1	Front panel damper LH <i>buy</i>	\$ 130.00 <i>—</i>
1	Front panel damper RH <i>buy</i>	\$ 130.00 <i>—</i>
1	Front panel logo <i>nc</i>	\$ 300.00 <i>15.55</i>
1	Front panel garnish <i>one</i>	\$ 850.00 <i>—</i>
1	Front panel garnish grille <i>one</i>	\$ 280.00 <i>—</i>
1	Front panel garnish outer handle LH <i>cm</i>	\$ 150.00 <i>—</i>
1	Front panel garnish outer handle RH <i>buy</i>	\$ 150.00 <i>—</i>
2	Front panel hinges <i>buy</i>	\$ 200.00 <i>—</i>
2	Front panel inner bracket <i>buy</i>	\$ 220.00 <i>—</i>
1	Front corner panel RH <i>buy</i>	\$ 3,800.00 <i>2950.87</i>
1	Front top side mirror LH <i>buy</i>	\$ 1,900.00 <i>1471.68</i>
1	Front condenser <i>buy/pur</i>	\$ 3,400.00 <i>2507.72</i>
1	Front clutch pump c/w pipes <i>buy</i>	\$ 1,100.00 <i>—</i>
1	Front clutch pump inner brake panel <i>one</i>	\$ 4,400.00 <i>2594.13</i>
1	Front door LH <i>nc</i>	Rpr <i>X</i>
1	Front door RH <i>nc</i>	Rpr <i>X</i>
1	Front door pillar LH <i>nc</i>	\$ 1,900.00 <i>X</i>
1	Front door pillar RH <i>nc</i>	\$ 1,900.00 <i>X</i>
1	Front door top hinges RH <i>buy</i>	\$ 280.00 <i>—</i>
1	Front door bottom hinges RH <i>buy</i>	\$ 280.00 <i>—</i>
1	Front door top hinges LH <i>11</i>	\$ 280.00 <i>X</i>
1	Front door bottom hinges LH <i>11</i>	\$ 280.00 <i>X</i>
1	Front door lock RH <i>buy/nc</i>	\$ 660.00 <i>450.00</i>
1	Front door lock catch RH <i>11</i>	\$ 100.00 <i>X</i>
1	Front door lock LH <i>11</i>	\$ 660.00 <i>X</i>
1	Front door lock catch LH <i>11</i>	\$ 100.00 <i>X</i>
1	Front dashboard <i>11</i>	\$ 5,500.00 <i>X</i>
		List \$ 41,350.00
		Less 5% \$ 2,067.50
		Total \$ 39,282.50 <i>2001861</i>
1	Front panel advertisement <i>nc</i>	\$ 250.00 <i>200</i>
		S/N \$ 250.00

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

Qty.	Description Of Parts	Pricing
LABOUR		
	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 100.00 50
	To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts.	\$ 150.00 80
	Towing charges.	\$ 300.00 120
	To Dismantle & Refit Front Dashboard & related wire harness & related parts.	11 \$ 350.00 x
	To Pressure Test Air Con Condenser and Radiator For Leakage.	\$ 120.00 100
	To Transfer Door x 2.	\$ 200.00 50
	To Remove & Refit air-con compressor, air-con motor, condenser, pipes & vacuum, including refilling of gas.	\$ 180.00 x
	To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.	\$ 3,000.00 2000
	To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.	\$ 2,000.00 1000
	LABOUR	\$ 6,400.00 3600
	Sub Total.	\$ 45,932.50
	7% GST	\$ 3,215.28
	Grand Total	\$ 49,147.78

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.

21670.74
17336

49070.50

YEW TEE AUTOMOBILE TECH PTE LTD

HQ: BLK 6 WOODLANDS ROAD 399F YEW TEE IND EST S(678006)

TEL: 6765 3373 / 6762 2081 / 6764 9042 FAX: 6760 4895

EMAIL: utauto@singnet.com.sg

Branch: Synergy@KB, 25 Kaki Bukit Road 4 #01-61 S(417800)

Tel: 6702 3113 (3Lines) Fax: 6702 3773

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

<u>Qty.</u>	<u>Description Of Parts</u>	<u>Pricing</u>
1	Front panel inner grille <i>one 320.</i>	\$ 580.00 —
1	Front panel damper top bracket RH <i>11</i>	\$ 250.00 <i>X</i>
1	Front panel damper bottom bracket RH <i>bel</i>	\$ 460.00 <i>X</i>
1	Front intercooler outer garnish <i>one</i>	\$ 620.00 —
1	Front air con condenser pipe <i>bel</i>	\$ 410.00 —
	List	\$ 2,320.00
	Less 10%	\$ 232.00
	<i>②</i> Total	\$ 2,088.00

21888.61
107
19699.74
3600.00
23299.74
18639.79

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2018		12 Dec 2018 15:20 Edit Adj Rpt	S\$18,600.00 Edit Estimates	S\$18,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAT HONG CONSTRUCTION & TRANSPORT PTE. LTD., Co. Reg. No.: 200613703C								
Main Claimant:	ORIENT NATURAL RESOURCES PTE LTD, Co. Reg. No.: 201015702G								
Vehicle Reg. No.:	XE1812G	Date of Loss:	05/12/2018 08:00 - :59 [29 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D05694C02	Policy/Cover Note No.:	DMCVSN17S7101801 (Comprehensive)						
Vehicle Reg. No. (Insured):	XD7119R	Policy No. (Claimant):	VFX/P1931543						
		Excess:	S\$0.00						
Repairer:	Yew Tee Automobile Tech Pte Ltd (Woodlands) 39 Woodlands Close #01-12, Mega@Woodlands, 737856 Woodlands - Tel: 62562533								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 21/12/2018]								
Driver/Custodian (Insured):	YU HONG QUAN (47 / Male), NRIC: G6196196N, Tel: +6590536792 Email: NOEMAIL								
Adj Asg. Remarks:	EST \$49,147.78 , ASSIGN MARCUS CHUA AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XE1812G (SNM18D05694C02)
[XD7119R]

TP

ORIENT NATURAL RESOURCES PTE LTD

Dec 5 2018 8:00AM

[TAT HONG CONSTRUCTION & TRANSPORT PTE. LTD.]

Yew Tee Automobile Tech Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)			Thumbnail		Print			
1	07/12/18 14:39	Accident Statement			1		Load HTML			
Photos/Images							3 per page		☒	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)			Thumbnail		Print			
1	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
2	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
3	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
4	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
5	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
6	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
7	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
8	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
9	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
10	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
11	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
12	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
13	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
14	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
15	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
16	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
17	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
18	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
19	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
20	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
21	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
22	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
23	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
24	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	
25	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]			1		Load JPG		☒	

Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
26	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
27	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
28	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
29	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
30	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
31	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
32	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
33	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
34	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
35	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
36	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
37	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
38	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
39	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
40	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
41	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
42	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
43	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
44	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
45	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
46	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
47	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
48	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
49	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
50	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
51	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
52	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
53	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
54	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
55	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
56	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
57	07/12/18 14:33	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/03/19 11:47	General View	 Load JPG	☒
2	01/03/19 11:47	General View	 Load JPG	☒
3	01/03/19 11:47	General View	 Load JPG	☒
4	01/03/19 11:47	General View	 Load JPG	☒
5	01/03/19 11:47	General View	 Load JPG	☒
6	01/03/19 11:47	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
7	01/03/19 11:47	General View	 Load JPG	☒
8	01/03/19 11:47	General View	 Load JPG	☒
9	01/03/19 11:47	General View	 Load JPG	☒
10	01/03/19 11:47	General View	 Load JPG	☒
11	01/03/19 11:47	General View	 Load JPG	☒
12	01/03/19 11:47	General View	 Load JPG	☒
13	01/03/19 11:47	General View	 Load JPG	☒
14	01/03/19 11:47	General View	 Load JPG	☒
15	01/03/19 11:47	General View	 Load JPG	☒
16	01/03/19 11:47	General View	 Load JPG	☒
17	01/03/19 11:47	General View	 Load JPG	☒
18	01/03/19 11:47	General View	 Load JPG	☒
19	01/03/19 11:47	General View	 Load JPG	☒
20	01/03/19 11:47	General View	 Load JPG	☒
21	01/03/19 11:47	General View	 Load JPG	☒
22	01/03/19 11:47	General View	 Load JPG	☒
23	01/03/19 11:47	General View	 Load JPG	☒
24	01/03/19 11:47	General View	 Load JPG	☒
25	01/03/19 11:47	General View	 Load JPG	☒
26	01/03/19 11:47	Chassis Number	 Load JPG	☒
27	01/03/19 11:47	General View	 Load JPG	☒
28	01/03/19 11:47	General View	 Load JPG	☒
29	01/03/19 11:47	General View	 Load JPG	☒
30	01/03/19 11:47	General View	 Load JPG	☒
31	01/03/19 11:47	General View	 Load JPG	☒
32	01/03/19 11:47	General View	 Load JPG	☒
33	01/03/19 11:47	General View	 Load JPG	☒
34	01/03/19 11:47	General View	 Load JPG	☒
35	01/03/19 11:47	General View	 Load JPG	☒
36	01/03/19 11:47	General View	 Load JPG	☒
37	01/03/19 11:47	General View	 Load JPG	☒
38	01/03/19 11:47	General View	 Load JPG	☒
39	01/03/19 11:47	General View	 Load JPG	☒
40	01/03/19 11:47	General View	 Load JPG	☒
41	01/03/19 11:47	General View	 Load JPG	☒
42	01/03/19 11:47	General View	 Load JPG	☒
43	01/03/19 11:47	General View	 Load JPG	☒
44	01/03/19 11:47	General View	 Load JPG	☒
45	01/03/19 11:47	General View	 Load JPG	☒
46	01/03/19 11:47	General View	 Load JPG	☒
47	01/03/19 11:47	General View	 Load JPG	☒
48	01/03/19 11:47	General View	 Load JPG	☒
49	01/03/19 11:47	General View	 Load JPG	☒
50	01/03/19 11:47	General View	 Load JPG	☒
51	01/03/19 11:47	General View	 Load JPG	☒
52	01/03/19 11:47	General View	 Load JPG	☒
53	01/03/19 11:47	General View	 Load JPG	☒
54	01/03/19 11:47	General View	 Load JPG	☒
55	01/03/19 11:47	General View	 Load JPG	☒
56	01/03/19 11:47	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
57	01/03/19 11:47	General View	 Load JPG	☒
58	01/03/19 11:47	General View	 Load JPG	☒
59	01/03/19 11:47	General View	 Load JPG	☒
60	01/03/19 11:47	General View	 Load JPG	☒
61	01/03/19 11:47	General View	 Load JPG	☒
62	01/03/19 11:47	General View	 Load JPG	☒
63	01/03/19 11:47	General View	 Load JPG	☒
64	01/03/19 11:47	General View	 Load JPG	☒
65	01/03/19 11:47	General View	 Load JPG	☒
66	01/03/19 11:47	General View	 Load JPG	☒
67	01/03/19 11:47	General View	 Load JPG	☒
68	01/03/19 11:47	General View	 Load JPG	☒
69	01/03/19 11:47	General View	 Load JPG	☒
70	01/03/19 11:47	General View	 Load JPG	☒
71	01/03/19 11:47	General View	 Load JPG	☒
72	01/03/19 11:47	General View	 Load JPG	☒
73	01/03/19 11:47	General View	 Load JPG	☒
74	01/03/19 11:47	General View	 Load JPG	☒
75	01/03/19 11:47	General View	 Load JPG	☒
76	01/03/19 11:47	General View	 Load JPG	☒
77	01/03/19 11:47	General View	 Load JPG	☒
78	01/03/19 11:47	General View	 Load JPG	☒
79	01/03/19 11:47	General View	 Load JPG	☒
80	01/03/19 11:47	General View	 Load JPG	☒
81	01/03/19 11:47	General View	 Load JPG	☒
82	01/03/19 11:47	General View	 Load JPG	☒
83	01/03/19 11:47	General View	 Load JPG	☒
84	01/03/19 11:47	General View	 Load JPG	☒
85	01/03/19 11:47	General View	 Load JPG	☒
86	01/03/19 11:47	General View	 Load JPG	☒
87	01/03/19 11:47	General View	 Load JPG	☒
88	01/03/19 11:47	General View	 Load JPG	☒
89	01/03/19 11:47	General View	 Load JPG	☒
90	01/03/19 11:47	General View	 Load JPG	☒
91	01/03/19 11:47	General View	 Load JPG	☒
92	01/03/19 11:47	General View	 Load JPG	☒
93	01/03/19 11:47	General View	 Load JPG	☒
94	01/03/19 11:47	General View	 Load JPG	☒
95	01/03/19 11:47	General View	 Load JPG	☒
96	01/03/19 11:47	General View	 Load JPG	☒
97	01/03/19 11:47	General View	 Load JPG	☒
98	01/03/19 11:47	General View	 Load JPG	☒
99	01/03/19 11:47	General View	 Load JPG	☒
100	01/03/19 11:47	General View	 Load JPG	☒
101	01/03/19 11:47	General View	 Load JPG	☒
102	01/03/19 11:47	General View	 Load JPG	☒
103	01/03/19 11:47	General View	 Load JPG	☒
104	01/03/19 11:47	General View	 Load JPG	☒
105	01/03/19 11:47	General View	 Load JPG	☒
106	01/03/19 11:47	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
107	01/03/19 11:47	General View	 Load JPG	☒
108	01/03/19 11:47	General View	 Load JPG	☒
109	01/03/19 11:47	General View	 Load JPG	☒
110	01/03/19 11:47	General View	 Load JPG	☒
111	01/03/19 11:47	General View	 Load JPG	☒
112	01/03/19 11:47	General View	 Load JPG	☒
113	01/03/19 11:47	General View	 Load JPG	☒
114	01/03/19 11:47	General View	 Load JPG	☒
115	01/03/19 11:47	General View	 Load JPG	☒
116	01/03/19 11:47	General View	 Load JPG	☒
117	01/03/19 11:47	General View	 Load JPG	☒
118	01/03/19 11:47	General View	 Load JPG	☒
119	01/03/19 11:47	General View	 Load JPG	☒
120	01/03/19 11:47	General View	 Load JPG	☒
121	01/03/19 11:47	General View	 Load JPG	☒
122	01/03/19 11:47	General View	 Load JPG	☒
123	01/03/19 11:47	General View	 Load JPG	☒
124	01/03/19 11:47	General View	 Load JPG	☒
125	01/03/19 11:47	General View	 Load JPG	☒
126	01/03/19 11:47	General View	 Load JPG	☒
127	01/03/19 11:47	General View	 Load JPG	☒
128	01/03/19 11:47	General View	 Load JPG	☒
129	01/03/19 11:47	General View	 Load JPG	☒
130	01/03/19 11:47	General View	 Load JPG	☒
131	01/03/19 11:47	General View	 Load JPG	☒
132	01/03/19 11:47	General View	 Load JPG	☒
133	01/03/19 11:47	General View	 Load JPG	☒
134	01/03/19 11:47	General View	 Load JPG	☒
135	01/03/19 11:47	General View	 Load JPG	☒
136	01/03/19 11:47	General View	 Load JPG	☒
137	01/03/19 11:47	General View	 Load JPG	☒
138	01/03/19 11:47	General View	 Load JPG	☒
139	01/03/19 11:47	General View	 Load JPG	☒
140	01/03/19 11:47	General View	 Load JPG	☒
141	01/03/19 11:47	General View	 Load JPG	☒
142	01/03/19 11:47	General View	 Load JPG	☒
143	01/03/19 11:47	General View	 Load JPG	☒
144	01/03/19 11:47	Odometer Reading	 Load JPG	☒
145	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
146	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
147	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
148	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
149	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
150	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
151	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
152	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
153	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
154	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
155	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
156	01/03/19 11:49	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
157	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
158	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
159	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
160	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
161	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
162	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
163	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
164	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
165	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
166	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
167	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
168	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
169	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
170	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
171	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
172	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
173	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
174	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
175	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
176	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
177	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
178	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
179	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
180	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
181	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
182	01/03/19 11:49	Reinspection Photo	 Load JPG	☒
183	01/03/19 11:50	Reinspection Photo	 Load JPG	☒
184	01/03/19 11:50	Reinspection Photo	 Load JPG	☒
185	01/03/19 11:50	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/12/18 15:20	REPAIR EST	 Load PDF	
2	12/12/18 15:20	TP GIA	 Load PDF	
3	12/12/18 15:20	OI GIA	 Load PDF	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
1	07/12/18 14:31	Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	07/12/18 14:31	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/03/19 09:31	SUPPLEMENTARY PART	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
1	07/12/18 14:39	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
1	07/12/18 14:33	Accident Photo	 Load JPG	☒
2	07/12/18 14:33	Accident Photo	 Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
				☒
3	07/12/18 14:33	Accident Photo	 Load JPG	☒
4	07/12/18 14:33	Accident Photo	 Load JPG	☒
5	07/12/18 14:33	Accident Photo	 Load JPG	☒
6	07/12/18 14:33	Accident Photo	 Load JPG	☒
7	07/12/18 14:33	Accident Photo	 Load JPG	☒
8	07/12/18 14:33	Accident Photo	 Load JPG	☒
9	07/12/18 14:33	Accident Photo	 Load JPG	☒
10	07/12/18 14:33	Accident Photo	 Load JPG	☒
11	07/12/18 14:33	Accident Photo	 Load JPG	☒
12	07/12/18 14:33	Accident Photo	 Load JPG	☒
13	07/12/18 14:33	Accident Photo	 Load JPG	☒
14	07/12/18 14:33	Accident Photo	 Load JPG	☒
15	07/12/18 14:33	Accident Photo	 Load JPG	☒
16	07/12/18 14:33	Accident Photo	 Load JPG	☒
17	07/12/18 14:33	Accident Photo	 Load JPG	☒
18	07/12/18 14:33	Accident Photo	 Load JPG	☒
19	07/12/18 14:33	Accident Photo	 Load JPG	☒
20	07/12/18 14:33	Accident Photo	 Load JPG	☒
21	07/12/18 14:33	Accident Photo	 Load JPG	☒
22	07/12/18 14:33	Accident Photo	 Load JPG	☒
23	07/12/18 14:33	Accident Photo	 Load JPG	☒
24	07/12/18 14:33	Accident Photo	 Load JPG	☒
25	07/12/18 14:33	Accident Photo	 Load JPG	☒
26	07/12/18 14:33	Accident Photo	 Load JPG	☒
27	07/12/18 14:33	Accident Photo	 Load JPG	☒
28	07/12/18 14:33	Accident Photo	 Load JPG	☒
29	07/12/18 14:33	Accident Photo	 Load JPG	☒
30	07/12/18 14:33	Accident Photo	 Load JPG	☒
31	07/12/18 14:33	Accident Photo	 Load JPG	☒
32	07/12/18 14:33	Accident Photo	 Load JPG	☒
33	07/12/18 14:33	Accident Photo	 Load JPG	☒
34	07/12/18 14:33	Accident Photo	 Load JPG	☒
35	07/12/18 14:33	Accident Photo	 Load JPG	☒
36	07/12/18 14:33	Accident Photo	 Load JPG	☒
37	07/12/18 14:33	Accident Photo	 Load JPG	☒
38	07/12/18 14:33	Accident Photo	 Load JPG	☒
39	07/12/18 14:33	Accident Photo	 Load JPG	☒
40	07/12/18 14:33	Accident Photo	 Load JPG	☒
41	07/12/18 14:33	Accident Photo	 Load JPG	☒
42	07/12/18 14:33	Accident Photo	 Load JPG	☒
43	07/12/18 14:33	Accident Photo	 Load JPG	☒
44	07/12/18 14:33	Accident Photo	 Load JPG	☒
45	07/12/18 14:33	Accident Photo	 Load JPG	☒
46	07/12/18 14:33	Accident Photo	 Load JPG	☒
47	07/12/18 14:33	Accident Photo	 Load JPG	☒
48	07/12/18 14:33	Accident Photo	 Load JPG	☒
49	07/12/18 14:33	Accident Photo	 Load JPG	☒
50	07/12/18 14:33	Accident Photo	 Load JPG	☒
51	07/12/18 14:33	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
52	07/12/18 14:33	Accident Photo	 Load JPG	☒
53	07/12/18 14:33	Accident Photo	 Load JPG	☒
54	07/12/18 14:33	Accident Photo	 Load JPG	☒
55	07/12/18 14:33	Accident Photo	 Load JPG	☒
56	07/12/18 14:33	Accident Photo	 Load JPG	☒
57	07/12/18 14:33	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
1	07/12/18 14:31	Sketch Plan	 Load JPG	☒
2	07/12/18 14:31	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18022384/UQD3Q2

Date: 05/03/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN17S7101801

Claimant Vehicle
No: XE1812G

Insured Vehicle
No: XD7119R

Date of Loss: 05/12/2018

Nature of Claim: TP

Claim
No: SNM18D05694C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XE1812G**
Make & Model: IVECO TRAKKER, 12.9 D AT260T41 (EURO V) (A) Engine No: F3BE3681DS451219464
Reg. Date: 08/06/2016 (Man. Year: 2013) Chassis No: WJME2NSS40C281847
Colour: Yellow Odometer: 193316 km
Engine Capacity: 12882 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 385/65 R22.5 Rear Tyre Size: 315/80 R22.5 (D/D)
Front Left Side: RoadWing 4 mm Rear Left Side: Mirage 5/5/5/5 mm
Front Right Side: RoadWing 4 mm Rear Right Side: Mirage 5/5/5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	41,736.50	19,899.75	21,836.75	52.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,400.00	3,400.00	3,000.00	46.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	48,136.50	23,299.75	24,836.75	51.60
Approved Total (Overridden) (\$\$)		18,600.00		
(\$\$)	48,136.50	18,600.00	29,536.50	61.36
+ GST 7.00/7.00% (\$\$)	3,369.56	1,302.00	2,067.56	61.36
Nett Amount (\$\$)	51,506.06	19,902.00	31,604.06	61.36

INSPECTION

Date of Assignment: 12/12/2018

Date Inspected: 13/12/2018 Inspected At:

Yew Tee Automobile Tech Pte Ltd
(Woodlands)
39 Woodlands Close #01-12,

Mega@Woodlands
Singapore 737856

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 04 Mar 2019)	
Parts:	N/A	IVECO TRAKKER 12.9 D AT260T41 (EURO V) (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE1812G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER CENTRE	Repair	4,200.00 FL	*- FL
2	1		*FRONT PANEL	Cracked	8,200.00 FL	*6,179.21 FL
3	1		*FRONT PANEL DAMPER LH	Bent	130.00 FL	*130.00 FL
4	1		*FRONT PANEL DAMPER RH	Bent	130.00 FL	*130.00 FL
5	1		*FRONT PANEL LOGO	Necessary	300.00 FL	*155.00 FL
6	1		*FRONT PANEL GARNISH	Cracked	850.00 FL	*850.00 FL
7	1		*FRONT PANEL GARNISH GRILLE	Cracked	280.00 FL	*280.00 FL
8	1		*FRONT PANEL GARNISH OUTER HANDLE LH	Cracked	150.00 FL	*150.00 FL
9	1		*FRONT PANEL GARNISH OUTER HANDLE RH	Bent	150.00 FL	*150.00 FL
10	2		*FRONT PANEL HINGES	Twisted	200.00 FL	*200.00 FL
11	2		*FRONT PANEL INNER BRACKET	Bent	220.00 FL	*220.00 FL
12	1		*FRONT CORNER PANEL RH	Broken	3,800.00 FL	*2,950.87 FL
13	1		*FRONT TOP SIDE MIRROR LH	Broken	1,900.00 FL	*1,471.68 FL
14	1		*FRONT CONDENSER	Bent / Punctured	3,400.00 FL	*2,507.72 FL
15	1		*FRONT CLUTCH PUMP C/W PIPES	Damaged / Buckled	1,100.00 FL	*1,100.00 FL
16	1		*FRONT CLUTCH PUMP INNER BRAKE PANEL	Cracked	4,400.00 FL	*2,594.13 FL
17	1		*FRONT DOOR LH (NPA)	Repair	0.00 FL	*- FL
18	1		*FRONT DOOR RH (NPA)	Repair	0.00 FL	*- FL
19	1		*FRONT DOOR PILLAR LH	Repair	1,900.00 FL	*- FL
20	1		*FRONT DOOR PILLAR RH	Repair	1,900.00 FL	*- FL
21	1		*FRONT DOOR TOP HINGES RH	Bent	280.00 FL	*280.00 FL
22	1		*FRONT DOOR BOTTOM HINGES RH	Bent	280.00 FL	*280.00 FL
23	1		*FRONT DOOR TOP HINGES LH	Not Necessary	280.00 FL	*- FL
24	1		*FRONT DOOR BOTTOM HINGES LH	Not Necessary	280.00 FL	*- FL
25	1		*FRONT DOOR LOCK RH	Dented / Twisted	660.00 FL	*450.00 FL
26	1		*FRONT DOOR LOCK CATCH RH	Not Necessary	100.00 FL	*- FL
27	1		*FRONT DOOR LOCK LH	Not Necessary	660.00 FL	*- FL
28	1		*FRONT DOOR LOCK CATCH LH	Not Necessary	100.00 FL	*- FL
29	1		*FRONT DASHBOARD	Not Necessary	5,500.00 FL	*- FL
30	1		*FRONT PANEL ADVERTISEMENT	Necessary	250.00 FS	*200.00 FS
31	1		*FRONT PANEL INNER GRILLE	Cracked	580.00 FL	*320.00 FL
32	1		*FRONT PANEL DAMPER TOP BRACKET RH	Not Necessary	250.00 FL	*- FL
33	1		*FRONT PANEL DAMPER BOTTOM BRACKET RH	Bent	460.00 FL	*460.00 FL
34	1		*FRONT INTERCOOLER OUTER GARNISH	Cracked	620.00 FL	*620.00 FL
35	1		*FRONT AIR CON CONDENSER PIPE	Bent	410.00 FL	*410.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **43,920.00** **22,088.61**
 - List Item Discount on L Items 5.00/10.00% (S\$) **2,183.50** **2,188.86**

Total Parts (S\$) 41,736.50 19,899.75

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANEL FOR RUST PROTECTION	New	100.00	50.00
2	TO DISCONNECT AND RECONNECT ,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS ,REPLACE DAMAGED PARTS	New	150.00	80.00
3	TOWING CHARGES	New	300.00	120.00
4	TO DISMANTLE & REFIT FRONT DASHBOARD & RELATED WIRE HARNESS & RELATED PARTS	New	350.00	0.00
5	TO PRESSURE TEAT AIR CONDENSER AND RADIATOR FOR LOAKAGE) }	New	120.00	100.00
6	TO REMOVE & REFIT AIR-CON COMPRESSOR ,AIR-CON MOTOR,CONDENSER ,PIPES & VACUUM ,INCLUDING REFAILLING OF GAS }	New	180.00	0.00
7	TO TRANSFER DOOR X2	New	200.00	50.00
8	TO REMOVE & REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT,REALIGN & REPAIR INCLUDING CUT & WELD BODY PANELS .TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	3,000.00	2,000.00
9	TO SPRAY PAINTING ON THE REPLACED & REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPERS ,CLEANING & SANDING OF SURFACES ,FINAL POLISING & WAXING ARE ALSO AVAILABLE	New	2,000.00	1,000.00
Gross Labour Cost (S\$)			6,400.00	3,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >