

ASS. REC. BY:

REF:

CS/SPF/18022390/TIVD36

Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Frankie Thay

of

SPF

Date/Time:

12/12/18 @ 2.58pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 41991

Insured:

QX508A

at Workshop m/s

Win Automotive

Tel:

9750 6777

of

Blk 6, Woodlands Rd 399J, Yew Tee Ind.

Policy No:

Claim No:

AEMD/105/009/2018/171

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/11/2018

CA / REV / REP. / REV 24 HRS

Lup

14/12/18 @ 4/6/12pm

H.O.D. Endorsement:

Date/Time:

4:22pm @ 12/12/18

Person Contacted:

Winson

Vehicle IN ☒ OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLN 41991-X

QX508A-X

8/1/19

Taufik informed repairer LS \$4200

TAUFIKH Taufik.

REF: SPF

ASSIGNMENT

From: Date: 14/12/18
 Estimated Cost:
 OI / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLN 4199T
 at Workshop m/s: Win Automotive
 of: Blk 6, Woodlands Rd 399J, Yew
 Insured: Tee Industrial.
 Policy No:
 Claims No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh: After 12pm
 Winson @ 9750 6777

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value:
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res.: Yes or No
 Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up'

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLN 4199T Yr Regn: 3 May 2017
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mercedes E220d c.c. 1950
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 114877 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: WDD2130042A116221
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Modi: Nil / R/Rim / STD A/Rim or
 Tyre Size: F: 225/55 R17
 R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear
R/Bal. 6 mm		R/Bal. 6 mm
L/Bal. 6 mm		L/Bal. 6 mm
D.O.A. 12/11/18		D.O.I. 14/12/18

Survey held at: Win Automotive

Des. of Damages: Frt / Rear / B/S / N/S / U/C / Rooftop or
 Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range \$4000-\$5000 (EST)

RECEIVED 08 JAN 2019

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee: 280

Date/Time, File Return to?

2) 8/1 - typist

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Transportation
) S + RS. \$
) Photos
) Others

Report Format : TP

Lump Sum / I.B.I. (\$) 4200p

TOTAL

280

Niyitha (LKK Auto)

From: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>
Sent: Wednesday, 12 December 2018 2:58 PM
To: Catherine Chong; assignments
Cc: Olivia Lau (LKKAuto)
Subject: RE: AEMD/105/009/2018/171 Pre-Repair Inspection for SLN4199T

Your reference: SLN4199T
Our reference : AEMD/105/009/2018/171

Catherine,
Please conduct a Pre-Repair Inspection for vehicle SLN4199T at Win Automotive Services, blk 6 Woodlands Road 399J Yew Tee Industrial Estate. Singapore 678008
Please contact Mr. Winson Tan at Tel : 67506777 for appointment.

Thanks.

Frankie Thay (Mr)
Safe Driving Manager
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4841 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

**Cheonghoh
Law Corporation**

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 . Singapore 160053
Co. Reg No. 201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply, please quote our Reference Number

Our Ref: LCH.lg/W9WAS-81125.18
Your Ref: QX 508 A

12 December 2018

Singapore Police Force
1 Mount Pleasant Road
Blk 8 Old Police Academy
Singapore 298333
Attn: Frankie

BY FAX ONLY
Fax No: 6474 8484


Dear Sirs

**ACCIDENT INVOLVING VEHICLES NO SLN 4199 T AND QX 508 A ON 12 NOVEMBER 2018 AT/ALONG
CUSCADEN WALK NEAR SEASONS PARK -**

We refer to the above matter.

Kindly inform LKK Auto Consultants Pte Ltd to contact Mr Winson Tan at 6750 6777 from Win Automotive Services, Blk 6 Woodlands Road 399J Yew Tee Industrial Estate, Singapore 678008 for the said survey of SLN 4199 T.

Yours faithfully



Lee Cheong Hoh
CHEONGHOH LAW CORPORATION

cc: client - via fax only (SLN 4199 T)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/11/2018 13:00
Date Of Accident	12/11/2018 22:15
Exact Location Of Accident	ALONG CUSCADEN WALK NEAR SEASONS PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN4199T
Insured/Policyholder	
Name Of Registered Owner	TITANIUM LIMOUSINES PTE. LTD.
Co Reg No	201213055R
Email Address	SHAH@TITANIUMLIMOUSINES.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-90042550

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200D
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5089460350-01
Cover Note Number	

Driver

Name of Driver	SHAFIE BIN PADRI
NRIC No	S1801088G
Date Of Birth	30/07/1967
Occupation	OUTDOOR
Date Of Driving Pass	03/09/2008
Driving Experience	10 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81018256
Fax Number	
Contact Number	
Email Address	SHAH@TITANIUMLIMOUSINES.COM.SG

Address	BLK 701 YISHUN AVENUE 5 #11-320
Postcode	760701
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8529999 - FAX NO: 68522299
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED - 3RD PARTY IN INSURED STATIONARY VEHICLE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX508A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Titanium
LIMOUSINES PTE LTD
CO. REG. NO. 201810058R

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

A. SLN 4199T

Four Seasons
PARK

B. QX 508A

REFER TO POLICE REPORT.

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Common Statement Pg. 1



**SINGAPORE
POLICE FORCE**



T/20181113/2008

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

1 of 3

Report No. T/20181113/2008

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/11/2018 01:00	Vide Report No.: E/20181112/0179	Station Diary No.: 10
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: SHAFIE BIN PADRI			Address: APT BLK 701 YISHUN AVENUE 5 #11-320 SINGAPORE 760701	
ID Type / ID No.: NRIC NO / S1801088G			Contact No.: Home/Office: Mobile: 81018256	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 51	Date of Birth: 30/07/1967	Type of Informant: Driver	
Race: Boyanese			Language: English	Institution / School Name:
Occupation: Chauffeur			Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 12/11/2018 22:15	Type of Location:
Location: Along Road 1 Traveling Toward Road 2 CUSCADEN WALK Near Junction of Four Seasons Park				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX508A	Car					0
SLN4199T	Car	MERCEDES BENZ	E class	Black	Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20181113/2008

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

2 of 3

Report No. T/20181113/2008

CONTINUATION OF REPORT

Brief Details.

On 12/11/2018 at around 2215hrs, I parked my vehicle (SLN4199T) in front Four Seasons Hotel as I was waiting for the time to fetch my VIP client. I then noticed a police car (QX508A) driven by W/Sgt Rachel, making a 3-point turn at the junction in front of Four Seasons Hotel. It was then that I felt an impact on my rear right passenger door and realize that the police car left bumper had grazed my rear right passenger door. I then went out of my vehicle and exchange particulars with the driver. Due to the accident, my vehicle sustained minor scratches on the rear right passenger door. Traffic police was at scene whom advised me to lodged a traffic accident report in ref to E/20181112/0179.

Common Statement Pg. 1



SINGAPORE
POLICE FORCE



T/20181113/2008

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

3 of 3

Report No. T/20181113/2008

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 NU'MAN BIN MOHD NOOR

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

13/11/2018 01:00

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Classification Of Case:

Authentication Stamp

NP168

WIN AUTOMOTIVE SERVICES

Vehicle no. : SLN 4199T
Model : Mercedes e220d

Estimate - Parts(s)

S/N	Qty	Descriptions	Amount
-----	-----	--------------	--------

LIST ITEMS:-

- | | | |
|----|-------|--------------------------------------|
| 1 | 1 pc | RH rear fender |
| 2 | 1 pc | Rear bumper retainer |
| 3 | 1 set | bumper fastener |
| 4 | 1 pc | Rear bumper |
| 5 | 1 pc | RH rear door |
| 6 | 1 pc | RH rear door lock |
| 7 | 1 pc | RH rear door regulator |
| 8 | 1 set | RH rear door inner trimboard clips |
| 9 | 1 pc | RH rear door weatherstrip |
| 10 | 1 pc | RH black sticker |
| 11 | 1 pc | RH door inner trim board |
| 12 | 1 pc | RH rear door checker |
| 13 | 1 pc | RH rear door protector |
| 14 | 1 | RH door outer chrome upper moulding |
| 15 | 1 | RH door outer chrome lower moulding |
| 16 | 1 | Rear door inner black garnish |
| 17 | 1 | Rear door outer centre black garnish |
| 18 | 1 | rear door lock sensor/actuator |
| 19 | 1 | rear door handle |
| 20 | 1 | Rear door outer top moulding |

Less 10%

\$ -
\$ -

\$ -

Special Nett

- | | | | | |
|---|------|-------------------------|----|--------|
| 1 | 1 pc | RH rear tyre | \$ | 280.00 |
| 2 | 1 pc | RH rear rim | \$ | 350.00 |
| 3 | 1 pc | rear windscreen sealant | \$ | 60.00 |

WIN AUTOMOTIVE SERVICES

Vehicle no. : SLN 4199T

Model : MERCEDES E220D

Estimate - Labour(s)

S/N	Qty	Descriptions	Amount
B/F			\$ -

LABOUR & OTHER CHARGES:-

1		To panel beat and renewal of all necessary damaged body parts	\$ 600.00
3		To check wiring and rewire	\$ 60.00
4		To remove and reinstall rear door components	\$ 120.00
5		To remove and reinstall rear undercarriage items for checking	\$ 350.00
6		To perform 4 wheel alignment	\$ 100.00
7		To anti-rust	\$ 100.00
8		To putty and spray-paint of affected areas	\$ 600.00
9		To remove & refix rear windscreen	\$ 150.00
10		to resetting fault code or rear door function	\$ 120.00
			\$ 2,200.00

Grand - Total \$ -

WIN AUTOMOTIVE SERVICES

Vehicle no. : SLN 4199T
Model : Mercedes e220d

Estimate - Parts(s)

S/N	Qty	Descriptions	Amount
-----	-----	--------------	--------

LIST ITEMS:-

1	1 pc	RH rear fender	\$ 2,150.00 Rx
2	1 pc	Rear bumper retainer	\$ 65.00 x u4
3	1 set	bumper fastener	\$ 24.00 x u4
4	1 pc	Rear bumper	\$ 1,950.00 Rx
5	1 pc	RH rear door	\$ 2,185.00 bt
6	1 pc	RH rear door lock	\$ 550.00 x
7	1 pc	RH rear door regulator	\$ 725.00 x gun
8	1 set	RH rear door inner trimboard clips	\$ 22.00 x
9	1 pc	RH rear door weatherstrip	\$ 150 300.00 rec
10	1 pc	RH black sticker	\$ 85.00 rec
11	1 pc	RH door inner trim board	\$ 1,365.00 x gun
12	1 pc	RH rear door checker	\$ 165.00 x
13	1 pc	RH rear door protector	\$ 85.00 x
14	1	RH door outer chrome upper moulding	\$ 172 rec
15	1	RH door outer chrome lower moulding	\$ 105 rec
16	1	Rear door inner black garnish	NIL un
17	1	Rear door outer centre black garnish	NIL un
18	1	rear door lock sensor/acurator	NIL un
19	1	rear door handle	\$ 480 x u4
20	1	Rear door outer top moulding	\$ 225 x u4
21	1	rh side skirt	\$ 700 crs
22	1	rh side skirt rear chorme moulding	\$ 110 aut
23	1	RH rear absorber	\$ 565 x u4
24	1	Rh rear wheel bearing	\$ 255 dis
25	1	Rh rear lower arm	\$ 265 x u4
			\$ 12,548.00
Less 10%			\$ 1,254.80 3677

Special Nett

1	1 pc	RH rear tyre	\$ 280.00 x u4
2	1 pc	RH rear rim	\$ 350.00 aut
3	1 pc	rear windscreen sealant	\$ 60.00 x u4

SN \$350

\$ 11,293.20 3309.3

WIN AUTOMOTIVE SERVICES

Vehicle no. : SLN 4199T
Model : MERCEDES E220D

Estimate - Labour(s)

S/N	Qty	Descriptions	Amount
		B/F	\$ -

LABOUR & OTHER CHARGES:-

1		To panel beat and renewal of all necessary damaged body parts	600. \$ 1,000.00
3		To check wiring and rewire	\$ 60.00 30.
4		To remove and reinstall rear door components	\$ 120.00 60.
5		To remove and reinstall rear undercarriage items for checking	\$ 350.00 100.
6		To perform 4 wheel alignment	\$ 100.00 80.
7		To anti-rust	\$ 100.00 30.
8		To putty and spray-paint of affected areas	\$ 800.00 600.
9		to remove and reinstall fuel tank components	\$ 180.00 X
10		to remove and reinstall rear upholstery components	\$ 100.00 X
11		To remove & refix rear windscreen	\$ 150.00 X
12		to resetting fault code or rear door function	\$ 120.00 80.

Part - 3309.30

SN - 350

Labour - 1580

5239.30

153 4200 *

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15063.30

YEW TEE CAR ALIGNMENT CENTRE
BLK a1 WOODLANDS ROAD 18KM
387-L YEW TEE IND. EST.
SINGAPORE 677956
TEL: 63683231
FAX: 63684366

Customer

Vehicle ident no.
SLN4199T

Repair order no.
R010975

Technician
CHENG

Date
19.12.18

License plate no. First reg. date Model Odometer reading: km/miles
Mercedes-Benz : 213 (E Class Sedan/Wagon 2016-) : 12345
Rear Wheel Drive : with Code 485 (Standard Suspension)
Sedan (W/V)

Complaints or reason for alignment check

			Before	Target Data		Actual
Rear axle	Camber	left		+/-0°30'		-1°17'
		right				-2°39'
		cross		0°00'	+/-0°24'	1°22'
	Toe	left		0°10'	+/-0°09'	0°05'
		right			0°28'	
		total		0°19'	+/-0°09'	0°33'
	Geometrical driving axis			0°00'	+/-0°08'	-0°12'
Front axle	Camber	left		+0°16' -0°28'		-1°13'
		right				-1°17'
		cross		0°00'	+/-0°24'	0°03'
	Caster	left		+/-0°30'		9°01'
		right				9°09'
		cross		0°00'	+/-0°30'	-0°08'
	SAI	left				10°13'
		right				10°24'
		cross		0°00'	-0°10'	
	Track differential angle	left		-1°20'	+/-0°30'	
		right				
	Toe	left		0°09'	+/-0°05'	0°37'
		right				-0°07'
		total		0°18'	+/-0°10'	0°30'
Setback						
Max steering lock	left steer	left				
		right				
	right steer	left				
		right				

YEW TEE CAR ALIGNMENT CENTRE
BLK a1 WOODLANDS ROAD 18KM
387-L YEW TEE IND. EST.
SINGAPORE 677956
TEL: 63683231
FAX: 63684366

Customer

Vehicle ident no.
SLN4199T

Repair order no.
R010976

Technician
CHENG

Date
19.12.18

License plate no. First reg. date Model Odometer reading: km/miles
Mercedes-Benz : 213 (E Class Sedan/Wagon 2016-) : 12345
Rear Wheel Drive : with Code 485 (Standard S

Complaints or reason for alignment check

			Before	Target Data	Actual
Rear axle	Camber	left	-1°14'	+/-0°30'	-1°12'
		right	-1°22'		-1°21'
		cross	0°07'	0°00' +/-0°24'	0°09'
	Toe	left	0°03'	0°10' +/-0°09'	0°10'
		right	0°07'		0°09'
		total	0°10'	0°19' +/-0°09'	0°18'
	Geometrical driving axis		-0°02'	0°00' +/-0°08'	0°00'
Front axle	Camber	left	-1°11'	+0°16' -0°28'	-1°08'
		right	-1°17'		-1°17'
		cross	0°05'	0°00' +/-0°24'	0°09'
	Caster	left	8°54'	+/-0°30'	8°54'
		right	9°03'		9°03'
		cross	-0°09'	0°00' +/-0°30'	-0°09'
	SAI	left	7°41'		7°38'
		right	7°46'		7°47'
		cross	-0°05'	0°00'	-0°09'
	Track differential angle	left		-1°20' +/-0°30'	
		right			
	Toe	left	0°26'	0°09' +/-0°05'	0°08'
		right	0°02'		0°08'
		total	0°28'	0°18' +/-0°10'	0°16'
	Setback				
	Max steering lock	left steer	left		
			right		
		right steer	left		
			right		




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18022390/T1vd3e2	
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 08-01-2019	
ATTN : FRANKIE THAY		Code : SPF	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 508A	Veh. Inspected	SLN 4199T
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/171	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	12/12/2018
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ E220D	c.c	1950
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WDD2130042A116221	Colour	BLACK
Odometer	114877	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55 R17	MICHELIN	6 mm
L/H Front Tyre	225/55 R17	MICHELIN	6 mm
R/H Rear Tyre	225/55 R17	MICHELIN	6 mm
L/H Rear Tyre	225/55 R17	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/11/2018	Inspection Date	14/12/2018
Survey held at	WIN AUTOMOTIVE-BLK 6 WOODLANDS RD 399J		
Repairer	-		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 4199T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RH REAR FENDER	TO REPAIR SEE LABOUR	2,150.00	-
1	REAR BUMPER RETAINER	NOT NECESSARY	65.00	-
1	SET BUMPER FASTENER	NOT NECESSARY	24.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,950.00	-
1	RH REAR DOOR	BENT	2,185.00	2,185.00
1	RH REAR DOOR LOCK	NOT NECESSARY	550.00	-
1	RH REAR DOOR REGULATOR	NOT NECESSARY	725.00	-
1	SET RH REAR DOOR INNER TRIMBOARD CLIPS	NOT NECESSARY	22.00	-
1	RH REAR DOOR WEATHERSTRIP	NECESSARY	300.00	150.00
1	RH BLACK STICKER	NECESSARY	85.00	85.00
1	RH DOOR INNER TRIM BOARD	NOT NECESSARY	1,365.00	-
1	RH REAR DOOR CHECKER	NOT NECESSARY	165.00	-
1	RH REAR DOOR PROTECTOR	NOT NECESSARY	85.00	-
1	RH DOOR OUTER CHROME UPPER MOULDING	NECESSARY	172.00	172.00
1	RH DOOR OUTER CHROME LOWER MOULDING	NECESSARY	105.00	105.00
1	REAR DOOR INNER BLACK GARNISH (NPA)	NOT NECESSARY	-	-
1	REAR DOOR OUTER CENTRE BLACK GARNISH (NPA)	NOT NECESSARY	-	-
1	REAR DOOR LOCK SENSOR / ACURATOR (NPA)	NOT NECESSARY	-	-
1	REAR DOOR HANDLE	NOT NECESSARY	480.00	-
1	REAR DOOR OUTER TOP MOULDING	NOT NECESSARY	225.00	-
1	RH SIDE SKIRT	CRACKED	700.00	700.00
1	RH SIDE SKIRT REAR CHROME MOULDING	CUT	110.00	110.00
1	RH REAR ABSORBER	NOT NECESSARY	565.00	-
1	RH REAR WHEEL BEARING	DISTORTED	255.00	255.00
1	RH REAR LOWER ARM	NOT NECESSARY	265.00	-
	LESS 10% DISCOUNT		-1,254.80	-376.20
			11,293.20	3,385.80
<u>SPECIAL NETT ITEMS</u>				
1	RH REAR TYRE (SN)	NOT NECESSARY	280.00	-
1	RH REAR RIM (SN)	CUT	350.00	350.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
			690.00	350.00

Report Ref No. CS/SPF18022390/T1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS. INCLUSIVE OF THE REPAIR OF RH REAR FENDER AND REAR BUMPER.		1,000.00	600.00
	TO CHECK WIRING AND REWIRE.		60.00	30.00
	TO REMOVE AND REINSTALL REAR DOOR COMPONENTS.		120.00	60.00
	TO REMOVE AND REINSTALL REAR UNDERCARRIAGE ITEMS FOR CHECKING.		350.00	100.00
	TO PERFORM 4 WHEEL ALIGNMENT.		100.00	80.00
	TO ANTI-RUST.		100.00	30.00
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.		800.00	600.00
	TO REMOVE AND REINSTALL FUEL TANK COMPONENTS.		180.00	-
	TO REMOVE AND REINSTALL REAR UPHOLSTERY COMPONENTS.	NOT NECESSARY	100.00	-
	TO REMOVE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO RESETTING FAULT CODE OR REAR DOOR FUNCTION.		120.00	80.00
			3,080.00	1,580.00
	GRAND TOTAL		15,063.20	5,315.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,200.00

Report Ref No. CS/SPF18022390/T1vd3e2

NOTES : THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.