

ASS. REC. BY:

REF: CS/FCI18022399/Ued3ⁿ²

Special Instruction:

Surveyor: Marius ASSIGNMENT (Office)From (Person): Karen tan of FEI Date/Time: 11:29 am @ 12/12/18 ¹²

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFD 7643M Insured: SHB 3706 Yat Workshop m/s Fastech Auto Tel: 6746 5405of 1 Kaki Bukit Ave 6 # 01-46Policy No: _____ Claim No: D1800881SMP8H

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 12/12/2018
(Client's Record)CA / REV / REP. / REV 24 HRS ^(up)

H.O.D. Endorsement: _____

Date/Time: 11:33 am @ 13/12/18 Person Contacted: N/any Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
14/12/18	@ 15:00 p.m. revert pending estimate from repairer to Karen via email.

(08/11/13) wef

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: STQ 7643Mat Workshop m/s A.

of _____

Insured: SMB37064

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 12800

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Date / Time Action / Instruction 13 mth.asky sh. LTA 7780 cost \$52722 10320 pays/ass.17/12/18 confirmed a/s \$4800 with Alan18/12/18 Confirmed Ls \$ 4,800/- @ 4 days with Marcus.(\$14,973.70 Red 76%)MV - \$12,800/- Net - \$5,020/-LTA - \$7,780/-RECEIVED 10 DEC 2018

Date/Time, File Pass to?

1) 18/12/18

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

9x15=135

170+135

50

50

110

515

Report Format :

Lump Sum / I.B.I: (\$ 4,800/- als)Veh No: STQ 7643M Yr Regn: 8/1/05Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAIMake: Honda stream C.C. 1998Colour: white A/C: Insured / Std / NI / NASp. Reading: 167169 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMRN387055200153Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 12/12/18

Survey held at _____

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 12/12/18Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRear
The U/C / Chassis frame / Body Structure affected due to collision.

MOTOR SURVEY ASSIGNMENT

Date	12-12-2018	Our Ref No. D18008815MFSH
Accident Date	12-12-2018	Claim Type. Third Party
Insured Vehicle	SHB3706Y	Third Party Vehicle. SFQ7643M
Survey Location	1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY	
Contact Person.	NANCY LAM	
Contact No.	67465405/ 0	Fax No. 67458520
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FASTECH AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 14 December 2018 3:00 PM
To: 'Karen Tan'; 'CWS Motor Claims'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D18008815MFSH/1

Dear Karen,

Please be informed that we have inspected the vehicle SFQ 7643M on 12/12/2018.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 13 December 2018 11:50 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008815MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 13 December 2018 11:29 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008815MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 0115E

Vehicle Details

Vehicle No.: SFQ7643M
Vehicle to be Exported: No
Intended Deregistration Date: 12 Dec 2018
Vehicle Make: HONDA
Vehicle Model: STREAM 2.0 A
Primary Colour: White
Manufacturing Year: 2004
Engine No.: K20A15500150
Chassis No.: JHMRN38705S200153
Maximum Power Output: 115.0 kW (154 bhp)
Open Market Value: \$25,168.00
Original Registration Date: 08 Jan 2005
First Registration Date: 08 Jan 2005
Transfer Count: 1
Actual ARF Paid: \$27,685.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 07 Jan 2020
COE Category: B - Car (1601cc & above)
COE Period(Years): 5
PQP Paid: \$36,363.00
COE Rebate Amount: \$7,780.00
Total Rebate Amount: \$7,780.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Dec 2018

OK

Date of Accident : 12/12/18 Accident Time: 12.50pm (24-HR-Format)
Accident Place : Along PIE toward cheng
Vehicle No. (Car Plate No.) : SFB 7643M Make/Model: Honda
Insurance Company : Lompax Policy No: _____
Owner or Company Name /IC No. : Mitchell Lee Keng Boon / S7120115E
Owner or Company Contact No. : _____ Owner's Hp 9742 2068 Company Tel _____
DRIVER'S Name / IC No. : as above
DRIVER'S Date Of Birth : 17/6/1971 DRIVER'S License Pass Date 20/12/2017
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: owner
DRIVER'S Address : 32 Segar Road #10-20 S677722
DRIVER'S Contact No./ Alt No. : 1) _____ 2) _____
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
Email Address : _____
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim \ Other Party \ Claim Own Insurance
Number of Passengers (Including Driver): NO
Was there any video Captured by car camera: YES \ NO
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
Any Injury (If YES, Pls state): NO

Other Party Driver's Particular (if any)

Vehicle No: SFB 3706Y
Vehicle Make/Model: _____
Name Driver: Muhammad Azhar
IC No. Driver/Contact: 88000581

Vehicle No: _____
Vehicle Make/Model: _____
Name Driver: _____
IC No. Driver/Contact: _____

* NEW - Passenger's name & gender:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 12/12/18 at 12:50pm, I was driving my vehicle
I'm on stationary portion.
along PIE towards cheng, suddenly vehicle B hit on
my rear portion

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Tax Reg No : 20-0006262-D

not allowed
N/A
d/s = 4800
initial
4 day.

Qty	Particular	SFQ7643M	Amount S\$
<u>List Item:</u>			
1PCS	REAR WINDSCREEN	11	\$1488.10 X
1PCS	REAR WINDSCREEN MOULDING	rec	\$48.50 /
1PCS	TAILGATE	30/500	\$903.20 /
1PCS	TAILGATE 'H' LOGO	11	\$35.00 X
1PCS	TAILGATE 'STREAM' EMBLEM	NZ	\$32.60 X
1PCS	TAILGATE OUTER GARNISH	11	\$184.50 X
1PCS	TAILGATE INNER LOCK	DD/Jm	\$109.50 /
1PCS	TAILGATE INNER TRIM BOARD	de/cne	\$341.50 /
1PCS	TAILGATE INNER TRIM BOARD CLIPS	rec	\$50.00 /
1PCS	TAILGATE INNER TOP SIDE GARNISH	11	\$162.30 X
2PCS	TAILGATE Reflectors @ \$245.10	scr/cna	\$490.20 ✓
1PCS	TAILGATE REAR WIPER ARM	11	\$235.30 X
1PCS	TAILGATE REAR WIPER MOTOR	11	\$488.50 X
1PCS	TAILGATE WEATHERSTRIP	twi	\$116.90 /
1PCS	REAR BUMPER	Dij	\$665.40 /
2PCS	REAR BUMPER SIDE RETAINERS @ \$25.50	Bent	\$51.00 /
2PCS	REAR BUMPER BRACKETS @ \$22.50	Bent	\$45.00 /
1SET	REAR BUMPER CLIPS	rec	\$39.00 /
1PCS	REAR END PANEL	Bent	\$306.10 /
1PCS	REAR END PANEL LOWER MEMBER	NS	\$182.30 X
1PCS	REAR END PANEL TOP GARNISH	twi	\$225.60 ✓
1PCS	REAR FLOOR PANEL	N	\$912.30 X
2PCS	REAR FLOOR PANEL TOP BOARDS @ \$266.50	11	\$533.00 X

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

<u>Qty</u>	<u>Particular</u>	<u>Amount S\$</u>
<u>List Item:</u>		
1PCS	REAR FLOOR PANEL INNER TOP GARNISH	MS \$341.10 x
2PCS	TAILLAMPS @\$338.80	11 \$677.60 x
2PCS	REAR FENDERS @\$891.10	11 \$1782.20 x
2PCS	REAR FENDER INNER TRIM BOARDS @\$395.20	MS 7011 \$790.40 126
1SET	REAR FENDER INNER TRIM BOARD CLIPS	11 \$60.00 —
2PCS	REAR FENDER QUARTER GLASS @\$671.10	11 \$1342.20 x
1PCS	REAR EXHAUST	11 \$689.30 x
2PCS	REAR EXHAUST MOUNTINGS @\$45.00	(202) 11 \$90.00 x
1PCS	REAR SPARE TYRE BRACKET	11 \$285.10 —
List Item Total:		\$13,703.70
		4132.2 3304.76
<u>Special Nett Item:</u>		
1PCS	REAR WINDSCREEN SEALANT	11 \$80.00 40
1SET	REAR REVERSE CAMERA	11 \$500.00 x
1PCS	REAR LICENCE PLATE W/HOLDER	11 \$50.00 x
1SET	REAR FLOOR PANEL INSULATOR	11 \$200.00 x
1PCS	REAR QUARTER GLASS SEALANT N/S	11 \$50.00 x
1SET	REAR REVERSE SENSOR. 4pcs.	shw \$280.00 250
Special Nett Total:		\$1160.00
<u>Labour Charge:</u>		
TO CHECK WIRING.		\$80.00 30
TO DISMANTLE & REPLACING REVERSE SENSOR.		\$80.00 50

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

<u>Qty</u>	<u>Particular</u>	<u>Amount S\$</u>
<u>Labour Charge:</u>		
	TO DISMANTLE & REPLACING REAR WINDSCREEN.	\$150.00 / 20
11	TO DISMANTLE & REPLACING REAR FENDER QUARTER GLASS.	\$150.00 x
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.	\$150.00 80
	TO DISMANTLE & REFIX REAR EXHAUST.	\$100.00 60
	TO TRANSFER TAILGATE MECHANISM.	\$100.00 60
11	TO DISMANTLE & REFIX PETROL TANK.	\$100.00 x
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS.	\$2000.00 800
	TO PUTTY & SPRAY PAINTING.	\$1800.00 1150
	TO SPRAY ANTI RUST PROOFING.	\$200.00 80
	Labour Charge Total:	\$4910.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$19,773.70

LKK Auto Consultants hence notify
the Reparer of the following:

- To resurvey before/after spray painting
- To identify damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and
is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18022399/Usd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-12-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 3706Y	Veh. Inspected	SFQ 7643M	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008815MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	12/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2005	
Chassis No.	JHMRN38705S200153	Colour	WHITE	
Odometer	167169	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/12/2018	Inspection Date	12/12/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFQ 7643M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN	NOT NECESSARY	1,488.10	-
1	REAR WINDSCREEN MOULDING	NECESSARY	48.50	48.50
1	TAILGATE	BADLY DENTED	903.20	903.20
1	TAILGATE "H" LOGO	NOT NECESSARY	35.00	-
1	TAILGATE "STREAM" EMBLEM	NOT FITTED	32.60	-
1	TAILGATE OUTER GARNISH	NOT NECESSARY	184.50	-
1	TAILGATE INNER LOCK	DENTED / JAMMED	109.50	109.50
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	341.50	341.50
1	TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00
1	TAILGATE INNER TOP SIDE GARNISH	NOT NECESSARY	162.30	-
2	TAILGATE REFLECTORS @\$245.10	SCRATCHED / CRACKED	490.20	490.20
1	TAILGATE REAR WIPER ARM	NOT NECESSARY	235.30	-
1	TAILGATE REAR WIPER MOTOR	NOT NECESSARY	488.50	-
1	TAILGATE WEATHERSTRIP	TWISTED	116.90	116.90
1	REAR BUMPER	DISTORTED	665.40	665.40
2	REAR BUMPER SIDE RETAINERS @\$25.50	BENT	51.00	51.00
2	REAR BUMPER BRACKETS @\$22.50	BENT	45.00	45.00
1	SET REAR BUMPER CLIPS	NECESSARY	39.00	39.00
1	REAR END PANEL	BENT	306.10	306.10
1	REAR END PANEL LOWER MEMBER	NO SUCH PARTS	182.30	-
1	REAR END PANEL TOP GARNISH	TWISTED	225.60	225.60
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	912.30	-
2	REAR FLOOR PANEL TOP BOARDS @\$266.50	NOT NECESSARY	533.00	-
1	REAR FLOOR PANEL INNER TOP GARNISH	NO SUCH PARTS	341.10	-
2	TAILLAMPS @\$338.80	NOT NECESSARY	677.60	-
2	REAR FENDERS @\$891.10	TO REPAIR SEE LABOUR	1,782.20	-
2	REAR FENDER INNER TRIM BOARDS @\$395.20	N/S TORN	790.40	395.20
1	SET REAR FENDER INNER TRIM BOARD CLIPS	NECESSARY	60.00	60.00

Report Ref No. CS/FCI18022399/Usd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER QUARTER GLASS @\$671.10	NOT NECESSARY	1,342.20	-
1	REAR EXHAUST	TO REPAIR SEE LABOUR	689.30	-
2	REAR EXHAUST MOUNTINGS @\$45.00	NOT NECESSARY	90.00	-
1	REAR SPARE TYRE BRACKET	BENT	285.10	285.10
	LESS 20% DISCOUNT		-	-826.44
			13,703.70	3,305.76
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	SET REAR REVERSE CAMERA (SN)	NOT FITTED	500.00	-
1	REAR LICENCE PLATE W/HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	200.00	-
1	REAR QUARTER GLASS SEALANT N/S (SN)	NOT NECESSARY	50.00	-
1	SET REAR REVERSE SENSOR-4PCS (SN)	SHORTED	280.00	250.00
			1,160.00	290.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REPLACING REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REPLACING REAR FENDER QUARTER GLASS.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		150.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST.		100.00	60.00
	TO TRANSFER TAILGATE MECHANISM.		100.00	60.00
	TO DISMANTLE & REFIX PETROL TANK.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL,REAR FENDERS AND REAR EXHAUST.		2,000.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,800.00	1,150.00
	TO SPRAY ANTI RUST PROOFING.		200.00	80.00
			4,910.00	2,430.00
	GRAND TOTAL		19,773.70	6,025.76

Report Ref No. CS/FCI18022399/Usd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,800.00
---	--	--	----------

Report Ref No. CS/FCI18022399/Usd3n2

MARKET VALUE: \$12,800.00 (EST)-LTA REIMBURSEMENT VALUE: \$7,780.00=NETT VALUE: \$5,020.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.