

STARTS AUTO ENGINEERING (S) PTE LTD

9A Serangoon North Ave 5, Singapore 554500

Tel: 64857777-102 Fax: 6896-1171

Reg No: 200718625Z

Vehicle No: SGN 1462L
Model: Nissan Murano 2.5
Chassis No: JNITDA25020000647

12th Dec 2018

Guo Qiang
82880282
13/12/18.
4 Days.
lampsum repair.
After repair photos.

ESTIMATE COST OF REPAIRS FOR VEHICLE SGN 1462L

1 pc Rear top control arm / BT
1 pc Rear bottom control arm / BT
1 pc Rear shock absorber /
1 pc Rear shock absorber stopper /
1 pc Rear shock absorber dust cover / } MC
1 pc Rear wheel bearing buh /
1 pc Rear torsion link bar ?
1 pc Rear lower link bar ?
1 pc Rear sport rim / cut
1 pc Rear sport rim cover / cut
1 pc Rear tyre-235/60,R18 / SCR
1 bt Brake fluid / MC
4 wheel alightment /

1 set Rear top control arm bush / } MC
1 set Rear bottom control arm bush / } MC
1 set Rear kuncle hub with bush /
1 set Rear wheel brake caliper assy ?
1 set Rear wheel brake pad / MC

Labour

Towing-from accident sence to office /
To dismantle & fixed above parts /
To realight chassic ?
To spray paint-Rear bumper /
To spray paint-Rear R/H tender /
To spray paint-Rear R/H door /

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: