



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

ATTN: MARCUS CHUA

PAGE 1/1

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

WD: 9 DAYS

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: JHMRC1890HC200810
License No: SLM338R
Mileage: 21807
Engine No: K24W72040268

Document No: SVO18075068
Printed By: JESHURUEBEN
Order Date: 17. December 2018
Order Time: 9:42:58 AM
Service Advisor: RUEBEN THOMAS

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 71840) OWNER: LOH WAI LEONG JEFFREY OWNER INSURER: NTUC INCOME INS ACC DATE: 11/12/2018 SURVEYED BY: MARCUS CHUA (LKK) DATE: 14/12/2018 REF NO: D18008794 MFSH TP INSURER: MS FIRST CAPITAL INSURANCE TP VEH: SHA2136D						
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	18.00	25	27.00	1.89	28.89
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	16.90	25	12.67	0.89	13.56
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.90	25	12.67	0.89	13.56
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90	25	11.70	0.82	12.52
73225-TM8-000	RUBBER AWINDSHIELD DAM	1	3.70	25	2.77	0.19	2.96
73226-SZW-000	DAMPERSTD 5X5	2	8.50	25	12.75	0.89	13.64
76711-T6A-003	CAPPIVOT	1	4.80	25	3.60	0.25	3.85
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
68100-T6A-Q10ZZ	TAILGATE COMP	1	1,070.80	25	803.10	56.22	859.32
74440-T6A-003	WEATHERSTRIPTAILGATE	1	117.40	25	88.05	6.16	94.21
75701-T6A-000	EMBLEMH	1	26.30	25	19.72	1.38	21.10
04715-T6A-900ZZ	FACERR.BUMPER	1	568.30	25	426.22	29.84	456.06
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	19.10	25	14.32	1.00	15.32
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	19.10	25	14.32	1.00	15.32
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
66100-T6A-Q00ZZ	PANEL COMP,REAR	1	460.80	25	345.60	24.19	369.79
84640-T6A-003ZA	LINING ASSYRR.PANEL	1	103.60	25	77.70	5.44	83.14
	SUM PARTS:				2,264.26	158.49	2,422.75
BOSUN	0760 SUNDRIES	1	20.00		20.00	1.40	21.40
BML02I	EXT-YJ INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	80.00		80.00	5.60	85.60
BA02R	EXT-YJ REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	130.00		130.00	9.10	139.10
BOJSE	0760 BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BOBC	0959 BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BP00R	EXT-YBH APPLY BODY UNDERSIDE COATING (N).	1	180.00		180.00	12.60	192.60
BG02D	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN. (N)	1	300.00		300.00	21.00	321.00
BOMISC1	0626 RESET VEHICLE SMART ENTRY SYSTEM (N)	1	320.00		320.00	22.40	342.40



PAGE 2/2
SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	WZF002 / MS FIRST CAPITAL	Document No:	SVO18075068				
Chassis No:	JHMRC1890HC200810	Printed By:	JESHURUEBEN				
License No:	SLM338R	Order Date:	17. December 2018				
Mileage:	21807	Order Time:	9:42:58 AM				
Engine No:	K24W72040268	Service Advisor:	RUEBEN THOMAS				
BOMISC1	EXT-YJ REMOVE, INSTALL & ADJUST REAR VIEW CAMERA (N)	1	320.00	320.00	22.40	342.40	
BMI03D	EXT-YJ REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	280.00	280.00	19.60	299.60	
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	450.00	450.00	31.50	481.50	
BKRP02M	EXT-YJ CUT OFF & RENEW RR PANEL. CUT RR FLOOR ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.	1	2,800.00	2,800.00	196.00	2,996.00	
BP06R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2,300.00	2,300.00	161.00	2,461.00	
				SUM LABOUR:	7,380.00	516.60	7,896.60
				TOTAL SGD	9,644.26	675.09	10,319.35
						Total Payable (SGD)	10,319.35

GST Amount is calculated from individual line(s)



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

Customer : MS FIRST CAPITAL INSURANCE
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLM338R
Chassis No : JHMRC1890HC200810
Model : ODYSSEY 2.4 EXV-S 17YM
Owner's Name : LOH WAI LEONG JEFFREY
Ins Policy No. :
Date of Accident : 11/12/2018

Document No. : SQT19000060 **Page** 1
Date : 4. Jan 2019
Customer No. : WZF002
Svc Advisor : RUEBEN THOMAS
Engine No : K24W72040268
Date | Time : 4. Jan 2019 11:40:04 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	SUPPLEMENTARY PARTS & LABOUR						
84640-T6A-003ZA	LINING ASSYRR.PANEL	1	103.60	25	77.70	5.44	83.14
				Sum Item	77.70	5.44	83.14

Survey By _____
Date & Time _____
Excess _____
Status _____
Signature _____

Total Amount 77.70 5.44 83.14
Total (Inclusive of GST) **83.14**

Printed on 4/1/2019 11:41:29 AM

This is a computer generated invoice. No signature is required.
Part prices are subjected to change without notice.
The above estimated cost of repair do not include any unforeseen damages.
GST Amount is calculated from individual line(s)