

ASS. REC. BY:

REF:

CS/FCI18022426/Ktd32

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time:

12.13pm @ 13/12/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 69004

Insured:

SHC3708L

at Workshop m/s

Hui Yung Motor

Tel:

64515752

of

Blk 176 Sin Ming Drive # 04-02

Policy No:

Claim No:

D18008803MF8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/12/18

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time:

12.22pm @ 13/12/18

Person Contacted:

Bel

Vehicle:

IN OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLX 69004 - X

SHC3708L - CS/FCI16023197/M/qbv2 DOA: 3/12/16

17/12/2018 @ 3:37pm

Revised. preli advise via email.

Lump Sum \$30,000, 14days (Red: 17451.50! 36%)

ASS. REC. BY:

REF: 1021

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$125k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

14/12

File pass to Catherine

RECEIVED 11 JAN 2019

Veh No:

SLX 69000

Yr Regn:

05, 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

M. CLA 180

c.c.

1595

Colour:

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

46311

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD1173422N-463433

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/40 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

11/12/18

D.O.I.

13/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

11/1 Typist

Date/Time, File Return to?

2)



: Prel. Report



: Final Report

Days Of Repair:

14

Resurvey No. of Trip:

2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fixtures

Others

TOTAL

37X15=555

170+555

50

50+50

88

963

Report Format:

TP

Lump Sum / I.B.I. (\$

30,000-

MOTOR SURVEY ASSIGNMENT

Date	12-12-2018	Our Ref No. D18008803MFSH
Accident Date	11-12-2018	Claim Type. Third Party
Insured Vehicle	SHC3708L	Third Party Vehicle. SLX6900U
Survey Location	BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE	
Contact Person.	BEL	
Contact No.	6451 5752/ 0	Fax No. 6451 4658
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUI YANG MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

SGCARMART.COM[Login](#) [Sign up](#)[New Cars](#)[Used Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Insurance](#)[Articles](#)[Forum](#)[Resources](#)



HONDA FIT
FROM '450/MTH

TOYOTA ALTIS
FROM '520/MTH

HONDA CIVIC
FROM '500/MTH

HONDA STREAM
FROM '530/MTH

COE Renewed Cars

\$0 Down payment

100% Loan Approvals

COSMO

AUTOMOBILES

15-16 Dec @ Downtown East

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)**New 5 Years Coe Renewal Toyota Wish 1.8A**

2.88%p.a Lowest Interest@GV
Cars Financing \$2000
Downpayment Monthly From
\$688
GV Credit Pte Ltd [StarAd](#)



KA-HUP

VALUE FOR MONEY

VALUE FOR TIME

A PEACE OF MIND

HOTLINE: 6741 9997



[View our cars](#)

[Browse by Category](#)[Sort by Date Posted](#)[20 results/page](#)

2 vehicles

CLA-Class CLA180 AMG Line

[Advanced Search](#)[Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	CLA-Class CLA180 AMG Line		Any	Any	2017	Any	Any	Any	Available
	Mercedes-Benz CLA-Class CLA180 AMG Line		\$130,800	\$12,990 /yr	10-Nov-2017	1,595 cc	5,000 km	Luxury	Available
	Graded A by STP								
	Xmas Promo! Best Deal! 1 Owner (Lawyer). Save Up To \$15K! As Good As New! AMG Line High Spec Model! Flexible Loan Up To 90%! Low Interest! Fully Serviced And Maintain By Optima Cars With Warranty Pack...								
	Posted: 30-Oct-2018 Tags: 2017 Mercedes-Benz CLA180, 2017 mercedes-benz cla180, Mercedes-Benz CLA180, mercedes-benz cla180, Mercedes-Benz, CLA180, cla180, Used Mercedes-Benz								
	Mercedes-Benz CLA-Class CLA180 AMG Line		\$113,800	\$11,900 /yr	27-Feb-2017	1,595 cc	24,000 km	Luxury	Available
	Meticulously Maintained By 1 Owner Who Is Relocating. Under Warranty. Selling With 2 Digit Bidded Plate. Trade In Welcome. Please Call To Arrange For Viewing.								
	Posted: 24-Oct-2018 Tags: 2017 Mercedes-Benz CLA180, 2017 mercedes-benz cla180, Mercedes-Benz CLA180, mercedes-benz cla180, Mercedes-Benz, CLA180, cla180, Used Mercedes-Benz								

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view [Expired ads](#)[20 results/page](#)[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used CLA-Class CLA180 AMG Line, CLA-Class CLA180 AMG Line Singapore, used CLA-Class CLA180 AMG Line Singapore, used CLA-Class CLA180 AMG Line, used vehicles Singapore or even buy used CLA-Class CLA180 AMG Line Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

[Compare](#)

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 17 December 2018 3:37 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008801MFSH/1
Attachments: PRELI ADVISED SLX 6900U.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLX 6900U**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 13 December 2018 5:17 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008801MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer arrange on 14/12/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 13 December 2018 4:42 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008801MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008803MFSH

Date: 17/12/2018

Our Ref: CS/FCI18022426/Ktd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLX 6900U

Please be informed that we had conducted the inspection of the abovementioned vehicle 13/12/2018 at the premises of M/s Hui Yang Motor have the following to report: -

Workshop Estimate Amount	: S\$ <u>47,451.00</u>
Revised Estimate Amount	: S\$ <u>23,872.50</u>
"Check" Items Amount	: S\$ <u>2,680.00</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the rear, front portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth
Automotive Assessor

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company
Owner ID: 0561K

Vehicle Details

Vehicle No.: SLX6900U
Vehicle to be Exported: Yes
Intended Deregistration Date: 11 Dec 2018
Vehicle Make: MERCEDES BENZ
Vehicle Model: CLA180 AMG LINE AUTO
Primary Colour: Black
Manufacturing Year: 2016
Engine No.: 27091031178664
Chassis No.: WDD1173422N463433
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$31,890.00
Original Registration Date: 15 May 2017
First Registration Date: 15 May 2017
Transfer Count: 0
Actual ARF Paid: \$31,646.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 14 May 2027
PARF Rebate Amount: \$23,734.00

Intended COE Rebate Details

COE Expiry Date: 14 May 2027
COE Category: A - Car up to 1600cc & 97kW
(130bhp)
COE Period(Years): 10
QP Paid: \$51,106.00
COE Rebate Amount: \$40,884.00
Total Rebate Amount: \$64,618.00

The information contained herein is correct as at 11 Dec 2018

OK

Marked V \$130k

MHYM18160172-01 / Hui Yang Motor Pte Ltd - HQ
 ENTRY DATE & TIME: 12/12/2018 09:31
 SUBMITTED BY: Bel Chew Shu Jing

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/12/2018 09:31
Date Of Accident	11/12/2018 16:30
Exact Location Of Accident	ALONG PIE TOWARDS CHANGI NEAR PAYA LEBAR EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX6900U
Insured/Policyholder	
Name Of Registered Owner	HYMS CAR LEASING PTE LTD
Co Reg No	201320561K
Email Address	HYMS@LIVE.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64515752

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	CLA180 AMG LINE AUTO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999994505
Cover Note Number	

Driver

Name of Driver	FOK KAR LAM
NRIC No	S7870958H
Date Of Birth	02/06/1978
Occupation	OUTDOOR
Date Of Driving Pass	29/06/2002
Driving Experience	16 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81200362
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 116B JALAN TENTERAM
Postcode	322116
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN (PASSENGER)
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	ROCHER N.P.C 11 KAMPONG KAPOR ROAD SINGAPORE 208678
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ATTACHED SKETCH PLAN & POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC3708L
Vehicle Make/Model/Colour	COMFORT BLUE TAXI
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	EE HOE KEE
NRIC/Passport Number	S1327285I
Contact Number	
Address	BLK 602 CHOA CHU KANG ST 62 #08-29
Postcode	680602
Insurance Company Name	MS FIRST CAPITAL INSURANCE LTD
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHB8958D
Vehicle Make/Model/Colour	PREMIER SILVER CAB
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	TAN HUNG KAI
NRIC/Passport Number	S1411168I
Contact Number	
Address	BLK 233 SIMEI ST 4 #07-170
Postcode	520233
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	FOK KAR LAM
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLX6900U
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 116B JALAN TENTERAM
Postcode	322116

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: *Bel*
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

Along P/E towards Chang. Report near Page Index Exit

Veh A-51X 6900U

Veh B - SHC 37082

Yeh C - SHB 89580

$$\boxed{B} \times \boxed{A} \times \boxed{C}$$

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to attached Police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: BET
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



1/20181212/2003

Police Station Of Origin
Rochor N P C
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999

Report No: 1/20181212/2003

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/12/2018 00:32
Vide Report No:
Station Diary No: 5

Informant's Particulars

Name of Informant FOK KAR LAM			Address APT BLK 116B JALAN TENTERAM #11-551 SINGAPORE 322116		
ID Type / ID No. NRIC NO / S7870958H			Contact No. Home/Office Mobile: 87423935		
Nationality SINGAPORE CITIZEN			Email		
Sex Male	Age 40	Date of Birth 02/06/1978	Type of Informant Driver		
Race Chinese			Language		Institution / School Name
Occupation DRIVER			Driving Licence Information Class: 2B 2A 3		Date of Expiry

General Information of the Accident

Type of Accident Non-Injury	Drink Drive No	Date/Time of Accident 11/12/2018 16:30	Type of Location Straight Road
Location Along Road 1 PAN ISLAND EXPRESSWAY TOWARDS AIRPORT TRAVELLING ON LANE 1			
Weather Raining	Road Surface Wet	Road Speed Limit	
Traffic Flow One Way	Traffic Control Not Controlled	Traffic Volume Moderate	
Type of Collision Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SHB8958D	Car			Silver	Slightly Damaged	1
SHC3708L	Car			Blue	Slightly Damaged	0
SLX6900U	Car	MERCEDES BENZ		Black	Slightly Damaged	1



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Rochor N.P.C.
11 Kampong Kapur Road SINGAPORE
208678
Tel No. 1800 2949999



T/20181212/2003

2 of 4

Report No. T/20181212/2003

CONTINUATION OF REPORT

Details of Person Involved

Any Pedestrian Involved No

No. of Pedestrians Injured NIL

Use of Pedestrian Crossing NA

Driver

Name	TAN HUNG KAI	ID No	S141168I
Related Vehicle	SHB8958D (Car)	Contact No	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class NIL Date of Expiry NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Driver

Name	EE HOE KEE	ID No	S1327285I
Related Vehicle	SHC3708L (Car)	Contact No	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class NIL Date of Expiry NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Driver

Name	FOK KAR LAM	ID No	S7870958H
Related Vehicle	SLX6900U (Car)	Contact No	87423935
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class 2B,2A,3 Date of Expiry: NIL
Date Treatment	11/12/2018	Date Discharge	11/12/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On the 11/12/2018 at about 1620hrs I picked up a passenger from Pipit road and headed to Changi Airport, while travelling alone PIE towards Airport on the 1st Lane the taxi in front SHB8958D of me applied its brake and braked his vehicle, I followed suite and braked my vehicle, however the vehicle behind SHC 3708L me did not stop in time and knocked into my vehicle causing my car to jerk forward resulting in my car hitting the front car.

I alighted from my vehicle to inspect the damage and discovered that the back of my car was damaged so much that my car boot unable to close and the left side of the bumper is left hanging almost touching the



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Rochor N.P.C.
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999



T20181212/2503

Page 4






Report No: T20181212/2503

CONTINUATION OF REPORT

ground, the damage to the front of my vehicle head light is broken and the front bumper is completely dislodged and the Mercedes logo is cracked

No ambulance came. I exchanged particulars with the other drivers and my passenger got another taxi to send him off. I drove my vehicle to the work shop and went to seek treatment at TTSH and was given 3 days of Medical leave and would have to go back for review

That's all

 POLICE FORCE		 T/2018/12/12/20000	
Police Station Of Origin Anchor N.P.C 111 Kampong Kapor Road SINGAPORE 208678 Tel No: 1800-2949999		Report No. T/2018/12/12/20000	
CONTINUATION OF REPORT			
Sketch Plan Informant is not able to provide sketch plan			
<p>IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474685 stating the <u>report number</u> as reference</p>			
Signature Of Officer Recording The Report A / Sgt 2 ANAND KUMAR S/O SASITARAN		Signature Of Informant 	
Signature Of Interpreter Not applicable		Date/Time 12/12/2018 00:32	
Officer In Charge Of Case TP / GIA / Staff Sgt WONG SIEU LUI Contact No- 66476151		Classification Of Case	
Authentication Stamp 			

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

11/12/2018

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR MERCEDES CLA (AMG) - SLX6900U

1pc	rear boot cover	R	\$ 1,530.00	✓
1pc	rear boot cover "MERCEDES" logo	R	\$ 180.00	✓
1pc	rear boot cover "CLA" emblem	R	\$ 65.00	✓
1pc	rear boot cover "180" emblem	R	\$ 65.00	✓
2pcs	rear boot cover hinge @\$130.00	R	\$ 260.00	X
1pc	rear boot cover inner lock	R	\$ 280.00	✓
1pc	rear boot cover inner lock cover	L	\$ 90.00	X
1pc	rear boot cover inner rubber	Dis/Br	\$ 185.00	✓
2pcs	rear taillamp @\$795.00	NIS CM	\$ 1,590.00	✓
2pcs	LH * rear taillamp lower bracket @\$95.00 also	NIS CM	\$ 190.00	✓
1pc	* rear taillamp LH panel	SL	\$ 450.00	X
1pc	rear bumper	R	\$ 1,810.00	✓
2pcs	rear bumper side retainer @\$100.00	NIS DIT	\$ 200.00	✓
3pc	* rear bumper parking sensor @\$220.00	Shor	\$ 660.00	✓
3pc	rear bumper parking sensor rubber @\$35.00	SL	\$ 70.00	X
1pc	rear bumper LH side cover	SL	\$ 155.00	X
1pc	rear bumper reinforcement	R	\$ 590.00	✓
1pc	rear bumper diffuse	R	\$ 520.00	✓
1pc	rear bumper diffuse lower lid	R	\$ 380.00	✓
1pc	rear bumper diffuse lower lid base	NIP R	\$ 185.00	✓
2pcs	* rear bumper lower centre bracket @\$65.00	R	\$ 130.00	✓
2pcs	rear bumper exhaust muffler @\$380.00 chrome	NIS R	\$ 760.00	✓
2pcs	* rear bumper exhuast muffler bracket @\$125.00	DIT	\$ 250.00	✓
1pc	rear bumper lower centre garnish	CM	\$ 185.00	✓
1pc	rear bumper towing cover	R	\$ 75.00	✓
1pc	rear end panel	R	\$ 950.00	✓
1pc	rear end panel inner garnish	NIS DIT	\$ 390.00	✓
1pc	rear float panel	R	\$ 1,550.00	X
1pc	rear RH fender	R	\$ 1,530.00	✓
2pcs	rear seat blet @\$1450.00	Im	\$ 2,900.00	✓
1pc	air bag control unit	R	\$ 2,850.00	✓
2pcs	* front headlamp @\$2850.00	NIS CM	\$ 5,700.00	✓
2pcs	front headlamp bracket @\$185.00	R	\$ 370.00	X
1pc	front bumper	R	\$ 2,200.00	✓
2pcs	front bumper side retainer @\$120.00	L	\$ 240.00	X
balance c/f			\$ 29,535.00	

Not Authorized
11/12/2018
830,000/-
Running After Paint
14 days

X

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

11/12/2018

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR MERCEDES CLA (AMG) - SLX6900U

balance c/f			\$ 29,535.00
2pcs	* front bumper centre parking sensor @\$220.00	Shang	\$ 440.00 2
2pcs	front bumper centre parking sensor rubber @\$35.00	Sh	\$ 70.00 X
2pcs	front bumper centre parking sensor garnish @\$85.00	o/s n/i	\$ 170.00 4
1pc	* front bumper parking sensor control unit	CM	\$ 1,950.00 2
1pc	front bumper number garnish	CM	\$ 155.00 1
2pcs	* front bumper side garnish @\$255.00	o/s DM	\$ 510.00 4
1pc	front bumper lower grille	Sh	\$ 285.00 X
1pc	front bumper lower spoiler	Sh	\$ 385.00 X
1pc	front bumper "MERCEDES" logo	Sh	\$ 165.00 1
1pc	* front bumper top bracket	CM	\$ 285.00 2
2pcs	front bumper top side bracket @\$85.00	Sh	\$ 170.00 X
1pc	front bumper top rubber	Sh	\$ 185.00 X
1pc	* front bumper reinforcement	Sh	\$ 580.00 2
2pcs	* front bumper reinforcement side bracket @\$285.00	Sh	\$ 570.00 2
1pc	front bumper centre sponge	CM	\$ 195.00 1
2pcs	front bumper side sponge @\$105.00	Sh	\$ 210.00 X
1pc	front bumper centre grille base	CM	\$ 780.00 1
1pc	front bumper centre grille garnish	CM	\$ 290.00 1
2pcs	front bumper centre grille chrome @\$195.00	Sh	\$ 390.00 1
1pc	front bumper centre grille logo	CM	\$ 180.00 1
1pc	front bumper centre grille logo base	CM	\$ 175.00 1
1pc	* front support panel	CM	\$ 980.00 2
2pcs	* front support panel side garnish @\$125.00	CM	\$ 250.00 2
1pc	* front radiator	B-TH	\$ 1,550.00 2
1pc	front radiator cowling	Sh	\$ 680.00 X
1pc	front radiator cowling fan	Sh	\$ 195.00 X
1pc	front radiator cowling fan motor	Sh	\$ 355.00 X
1pc	front air-con condenser	Sh	\$ 1,250.00 2
			\$ 42,935.00
less 10%			\$ 4,293.50
balance c/f			\$ 38,641.50

輝 陽 汽 車 有 限 公 司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

11/12/2018

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR MERCEDES CLA (AMG) - SLX6900U

	balance c/f			\$ 38,641.50	
2set	front & rear number plate & casing	<i>Rec No 151 B4</i>	s.nett	\$ 120.00	<i>90%</i>
1set	rear windscreen glass moulding	<i>mc</i>	s.nett	\$ 220.00	<i>✓</i>
1pc	* rear seat	<i>Return / cm</i>	s.nett	\$ 2,500.00	<i>2</i>
	* remove & refit radiator & coolant		\$	180.00	<i>50%</i>
	remove & refit air-con & gas		\$	150.00	<i>100%</i>
	remove & refit rear windscreen glass		\$	150.00	<i>120%</i>
	remove & refit rear cushion		\$	180.00	<i>120%</i>
	program parking sensor control unit & air bag control unit		\$	680.00	<i>320%</i>
	wiring		\$	180.00	<i>50%</i>
	tuffkote		\$	250.00	<i>90%</i>
	spray painting		\$	2,200.00	<i>1500%</i>
	labour charges		\$	2,000.00	<i>1800%</i>
	Total			<u>\$ 47,451.50</u>	

辉 陽 汽 車 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

11/12/2018

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR MERCEDES CLA (AMG) - SLX6900U

1pc	rear boot cover	B1	\$ 1,530.00	✓
1pc	rear boot cover "MERCEDES" logo	re	\$ 180.00	✓
1pc	rear boot cover "CLA" emblem	re	\$ 65.00	✓
1pc	rear boot cover "180" emblem	re	\$ 65.00	✓
2pcs	rear boot cover hinge @\$130.00	re	\$ 260.00	X
1pc	rear boot cover inner lock	re	\$ 280.00	✓
1pc	rear boot cover inner lock cover		\$ 90.00	?
1pc	rear boot cover inner rubber	Dis/Re	\$ 185.00	✓
2pcs	rear taillamp @\$795.00	NIS CM	\$ 1,590.00	✓
2pcs	rear taillamp lower bracket @\$95.00		\$ 190.00	?
1pc	rear taillamp LH panel		\$ 450.00	?
1pc	rear bumper	B1	\$ 1,810.00	✓
2pcs	rear bumper side retainer @\$100.00	NIS Dis	\$ 200.00	✓
3pc	rear bumper parking sensor @\$220.00		\$ 660.00	?
3pc	rear bumper parking sensor rubber @\$35.00		\$ 70.00	?
1pc	rear bumper LH side cover	re	\$ 155.00	X
1pc	rear bumper reinforcement	B1	\$ 590.00	✓
1pc	rear bumper diffuse	B2	\$ 520.00	✓
1pc	rear bumper diffuse lower lid	B2	\$ 380.00	✓
1pc	rear bumper diffuse lower lid base	NIP B2	\$ 185.00	X
2pcs	rear bumper lower centre bracket @\$65.00		\$ 130.00	?
2pcs	rear bumper exhaust muffler @\$380.00 chrome	NIS Re	\$ 760.00	✓
2pcs	rear bumper exhuast muffler bracket @\$125.00		\$ 250.00	?
1pc	rear bumper lower centre garnish	CM	\$ 185.00	✓
1pc	rear bumper towing cover	re	\$ 75.00	✓
1pc	rear end panel	B1	\$ 950.00	✓
1pc	rear end panel inner garnish	re Dis	\$ 390.00	✓
1pc	rear float panel	re	\$ 1,550.00	X
1pc	rear RH fender	B2	\$ 1,530.00	✓
2pcs	rear seat blet @\$1450.00	re	\$ 2,900.00	✓
1pc	air bag control unit	re	\$ 2,850.00	✓
2pcs	front headlamp @\$2850.00		\$ 5,700.00	?
2pcs	front headlamp bracket @\$185.00		\$ 370.00	?
1pc	front bumper	B2	\$ 2,200.00	✓
2pcs	front bumper side retainer @\$120.00	re	\$ 240.00	X

balance c/f

\$ 29,535.00



NIS First Capital
13/12/18
LCC

Not Authorized
1/12/18
Running After Paint
14 days

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

11/12/2018

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR MERCEDES CLA (AMG) - SLX6900U

	balance c/f		\$ 29,535.00	
2pcs	front bumper centre parking sensor @\$220.00		\$ 440.00	?
2pcs	front bumper centre parking sensor rubber @\$35.00		\$ 70.00	?
2pcs	front bumper centre parking sensor garnish @\$85.00	01/12/18	\$ 170.00	✓
1pc	front bumper parking sensor control unit		\$ 1,950.00	?
1pc	front bumper number garnish	CM	\$ 155.00	✓
2pcs	front bumper side garnish @\$255.00	1/12/18 X 01/12/18	\$ 510.00	
1pc	front bumper lower grille	SM	\$ 285.00	X
1pc	front bumper lower spoiler	SM	\$ 385.00	X
1pc	front bumper "MERCEDES" logo	MC	\$ 165.00	✓
1pc	front bumper top bracket		\$ 285.00	?
2pcs	front bumper top side bracket @\$85.00		\$ 170.00	?
1pc	front bumper top rubber	SM	\$ 185.00	X
1pc	front bumper reinforcement		\$ 580.00	?
2pcs	front bumper reinforcement side bracket @\$285.00		\$ 570.00	?
1pc	front bumper centre sponge	CM	\$ 195.00	✓
2pcs	front bumper side sponge @\$105.00		\$ 210.00	?
1pc	front bumper centre grille base	CM	\$ 780.00	✓
1pc	front bumper centre grille garnish	CM	\$ 290.00	✓
2pcs	front bumper centre grille chrome @\$195.00	MC	\$ 390.00	✓
1pc	front bumper centre grille logo	CM	\$ 180.00	✓
1pc	front bumper centre grille logo base	CM	\$ 175.00	✓
1pc	front support panel		\$ 980.00	?
2pcs	front support panel side garnish @\$125.00		\$ 250.00	?
1pc	front radiator		\$ 1,550.00	?
1pc	front radiator cowling		\$ 680.00	?
1pc	front radiator cowling fan		\$ 195.00	?
1pc	front radiator cowling fan motor		\$ 355.00	?
1pc	front air-con condenser	PC	\$ 1,250.00	✓
			<hr/>	
			\$ 42,935.00	
	less 10%		\$ 4,293.50	
	balance c/f		<hr/>	
			\$ 38,641.50	



輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

11/12/2018

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR MERCEDES CLA (AMG) - SLX6900U

	balance c/f			\$ 38,641.50
2set	front & rear number plate & casing	<i>Rec Red 1st 1st</i>	s.nett	\$ 120.00 <i>90sm</i>
1set	rear windscreen glass moulding	<i>m</i>	s.nett	\$ 220.00 <i>✓</i>
1pc	rear seat		s.nett	\$ 2,500.00 <i>7</i>
	remove & refit radiator & coolant		\$	180.00 <i>7</i>
	remove & refit air-con & gas		\$	150.00 <i>1001</i>
	remove & refit rear windscreen glass		\$	150.00 <i>1201</i>
	remove & refit rear cushion		\$	180.00 <i>1201</i>
	program parking sensor control unit & air bag control unit		\$	680.00 <i>3201</i>
	wiring		\$	180.00 <i>501</i>
	tuffkote		\$	250.00 <i>901</i>
	spray painting		\$	2,200.00 <i>15001</i>
	labour charges		\$	2,000.00 <i>18001</i>
	Total			<u>\$ 47,451.50</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18022426/Ktd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3708L	Veh. Inspected	SLX 6900U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008803MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	13/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ CLA180	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WDD1173422N463433	Colour	METALLIC BLACK	
Odometer	46311	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	CONTINENTAL	7 mm	
L/H Front Tyre	225/40 R18	CONTINENTAL	7 mm	
R/H Rear Tyre	225/40 R18	CONTINENTAL	7 mm	
L/H Rear Tyre	225/40 R18	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/12/2018	Inspection Date	13/12/2018	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 6900U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT COVER	BENT	1,530.00	1,530.00
1	REAR BOOT COVER "MERCEDES" LOGO	NECESSARY	180.00	180.00
1	REAR BOOT COVER "CLA" EMBLEM	NECESSARY	65.00	65.00
1	REAR BOOT COVER "180" EMBLEM	NECESSARY	65.00	65.00
2	REAR BOOT COVER HINGE @\$130.00	TO REPAIR SEE LABOUR	260.00	-
1	REAR BOOT COVER INNER LOCK	DENTED	280.00	280.00
1	REAR BOOT COVER INNER LOCK COVER	SERVICEABLE	90.00	-
1	REAR BOOT COVER INNER RUBBER	DISTORTED / DENTED	185.00	185.00
2	REAR TAILLAMP @\$795.00	N/S CRACKED	1,590.00	795.00
2	REAR TAILLAMP LOWER BRACKET @\$95.00	N/S CRACKED / O/S SERVICEABLE	190.00	95.00
1	REAR TAILLAMP LH PANEL	TO REPAIR SEE LABOUR	450.00	-
1	REAR BUMPER	BENT	1,810.00	1,810.00
2	REAR BUMPER SIDE RETAINER @\$100.00	N/S DISTORTED	200.00	100.00
3	REAR BUMPER PARKING SENSOR @\$220.00	SHORTED	660.00	660.00
3	REAR BUMPER PARKING SENSOR RUBBER @\$35.00	SERVICEABLE	70.00	-
1	REAR BUMPER LH SIDE COVER	SERVICEABLE	155.00	-
1	REAR BUMPER REINFORCEMENT	BENT	590.00	590.00
1	REAR BUMPER DIFFUSE	BROKEN	520.00	520.00
1	REAR BUMPER DIFFUSE LOWER LID	BROKEN	380.00	380.00
1	REAR BUMPER DIFFUSE LOWER LID BASE	NO SUCH PARTS	185.00	-
2	REAR BUMPER LOWER CENTRE BRACKET @\$65.00	BENT	130.00	130.00
2	REAR BUMPER EXHAUST MUFFLER CHROME @\$380.00	N/S DENTED	760.00	380.00
2	REAR BUMPER EXHAUST MUFFLER BRACKET @\$125.00	DISTORTED	250.00	250.00
1	REAR BUMPER LOWER CENTRE GARNISH	CRACKED	185.00	185.00
1	REAR BUMPER TOWING COVER	DENTED	75.00	75.00
1	REAR END PANEL	BENT	950.00	950.00
1	REAR END PANEL INNER GARNISH	MTG DISTORTED	390.00	390.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,550.00	-

Report Ref No. CS/FCI18022426/Ktd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR RH FENDER	BUCKLED	1,530.00	1,530.00
2	REAR SEAT BLET @\$1450.00	JAMMED	2,900.00	2,900.00
1	AIR BAG CONTROL UNIT	NECESSARY	2,850.00	2,850.00
2	FRONT HEADLAMP @\$2850.00	MTG CRACKED	5,700.00	5,700.00
2	FRONT HEADLAMP BRACKET @\$185.00	TO REPAIR SEE LABOUR	370.00	-
1	FRONT BUMPER	BUCKLED	2,200.00	2,200.00
2	FRONT BUMPER SIDE RETAINER @\$120.00	SERVICEABLE	240.00	-
2	FRONT BUMPER CENTRE PARKING SENSOR @\$220.00	SHORTED	440.00	440.00
2	FRONT BUMPER CENTRE PARKING SENSOR RUBBER @\$35.00	SERVICEABLE	70.00	-
2	FRONT BUMPER CENTRE PARKING SENSOR GARNISH @\$85.00	O/S DISTORTED	170.00	85.00
1	FRONT BUMPER PARKING SENSOR CONTROL UNIT	CRACKED	1,950.00	1,950.00
1	FRONT BUMPER NUMBER GARNISH	CRACKED	155.00	155.00
2	FRONT BUMPER SIDE GARNISH @\$255.00	O/S CRACKED / N/S SERVICEABLE	510.00	255.00
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	285.00	-
1	FRONT BUMPER LOWER SPOILER	SERVICEABLE	385.00	-
1	FRONT BUMPER "MERCEDES" LOGO	NECESSARY	165.00	165.00
1	FRONT BUMPER TOP BRACKET	CRACKED	285.00	285.00
2	FRONT BUMPER TOP SIDE BRACKET @\$85.00	TO REPAIR SEE LABOUR	170.00	-
1	FRONT BUMPER TOP RUBBER	SERVICEABLE	185.00	-
1	FRONT BUMPER REINFORCEMENT	BENT	580.00	580.00
2	FRONT BUMPER REINFORCEMENT SIDE BRACKET @\$285.00	BENT	570.00	570.00
1	FRONT BUMPER CENTRE SPONGE	CRACKED	195.00	195.00
2	FRONT BUMPER SIDE SPONGE @\$105.00	SERVICEABLE	210.00	-
1	FRONT BUMPER CENTRE GRILLE BASE	CRACKED	780.00	780.00
1	FRONT BUMPER CENTRE GRILLE GARNISH	CRACKED	290.00	290.00
2	FRONT BUMPER CENTRE GRILLE CHROME @\$195.00	NECESSARY	390.00	390.00
1	FRONT BUMPER CENTRE GRILLE LOGO	CRACKED	180.00	180.00
1	FRONT BUMPER CENTRE GRILLE LOGO BASE	CRACKED	175.00	175.00
1	FRONT SUPPORT PANEL	CRACKED	980.00	980.00

Report Ref No. CS/FCI18022426/Ktd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT SUPPORT PANEL SIDE GARNISH @\$125.00	CRACKED	250.00	250.00
1	FRONT RADIATOR	BENT / PUNCTURE	1,550.00	1,550.00
1	FRONT RADIATOR COWLING	SERVICEABLE	680.00	-
1	FRONT RADIATOR COWLING FAN	SERVICEABLE	195.00	-
1	FRONT RADIATOR COWLING FAN MOTOR	SERVICEABLE	355.00	-
1	FRONT AIR-CON CONDENSER	PUNCTURE	1,250.00	1,250.00
	LESS 10% DISCOUNT		-4,293.50	-3,532.00
			38,641.50	31,788.00
	<u>SPECIAL NETT ITEMS</u>			
2	SET FRONT & REAR NUMBER PLATE & CASING (SN)	REAR DENTED / FRONT BENT	120.00	90.00
1	SET REAR WINDSCREEN GLASS MOULDING (SN)	NECESSARY	220.00	220.00
1	REAR SEAT (SN)	DEFORMED / CRACKED	2,500.00	2,500.00
			2,840.00	2,810.00
	<u>LABOUR</u>			
	REMOVE & REFIT RADIATOR & COOLANT.		180.00	50.00
	REMOVE & REFIT AIR-CON & GAS.		150.00	100.00
	REMOVE & REFIT REAR WINDSCREEN GLASS.		150.00	120.00
	REMOVE & REFIT REAR CUSHION.		180.00	120.00
	PROGRAM PARKING SENSOR CONTROL UNIT & AIR BAG CONTROL UNIT.		680.00	320.00
	WIRING.		180.00	50.00
	TUFFKOTE.		250.00	90.00
	SPRAY PAINTING.		2,200.00	1,500.00
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF REAR BOOT COVER HINGE, REAR TAILLAMP LH PANEL, REAR FLOOR PANEL, FRONT HEADLAMP BRACKET AND FRONT BUMPER TOP SIDE BRACKET.		2,000.00	1,800.00
			5,970.00	4,150.00
	GRAND TOTAL		47,451.50	38,748.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			30,000.00

Report Ref No. CS/FCI18022426/Ktd3e2



Report Ref No. CS/FCI18022426/Ktd3e2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.