



# CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

EZ SWIFT CAR RENTAL & LEASING PTE LTD

12/12/2018

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

TPAXA.  
Joy.

Accident date: 11/12/2018

Estimated repair cost for vehicle no: SLW981E HONDA ACCORD 2.4 A '09

CHASSIS: MRHCP26308P020483

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Repair</i>		\$878.40 <i>+</i>
2	1	Rear Boot Lid Emblem Logo <i>2 New</i>		\$27.40 <i>✓</i>
3	1	Rear Boot Lid Accord Logo <i>1 New</i>		\$29.20 <i>✓</i>
4	1	Rear Boot Lid 2.4 I-Vtec Logo <i>1 New</i>		\$38.10 <i>✓</i>
5	1	Rear Boot Lid Number Plate Garnish <i>Ornate</i>		\$332.40 <i>✓</i>
6	1	Rear Boot Lid Inner Lock <i>2 New</i>		\$160.90 <i>+</i>
7	1	Rear Boot Lid Inner Rubber <i>1 New</i>		\$125.00 <i>+</i>
8	2	Rear Tail Lamp <i>Ornate</i>	\$395.20	\$790.40 <i>✓</i>
9	2	Rear Tail Lamp Lower Bracket <i>Not Nec</i>	\$17.50	\$35.00 <i>+</i>
10	1	Rear Bumper <i>Ornate</i>		\$709.20 <i>✓</i>
11	2	Rear Bumper Side Retainer <i>Not</i>	\$47.50	\$95.00 <i>✓</i>
12	1	Rear Bumper Reinforcement <i>Ornate Bent</i>		\$245.60 <i>✓</i>
13	4	Rear Bumper Reverse Sensor <i>Ornate 2 pieces</i>	\$226.40	\$905.60 <i>452.80</i>
14	4	Rear Bumper Reverse Sensor Handle <i>2 New</i>	\$15.50	\$62.00 <i>+</i>
15	4	Rear Bumper Reverse Sensor Handle Rubber Seal <i>1 New</i>	\$8.50	\$34.00 <i>+</i>
17	1	Rear End Panel <i>Repair</i>		\$487.40 <i>+</i>
18	1	Rear End Panel Top Garnish <i>Not</i>		\$197.70 <i>+</i>
19	1	Rear & Center Exhaust <i>Not</i>		\$1,241.70 <i>+</i>

Subtotal :- \$6,395.00

2720.10

2176.08



## Labour charges

To remove & refit rear reverse sensor

~~\$100.00~~ 60.

To remove & refit rear & center exhaust

~~\$380.00~~ 80.

To check wiring

~~\$60.00~~ 30

Tuff kote

\$150.00 x.

Panel beating

1470

~~\$1,400.00~~ 800

Spray painting

~~\$1,400.00~~ 700.

Subtotal :- \$3,490.00

Total:- \$9,885.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Adrian Ling  
L/s 13/12/18.

OS Day

total: 3646.08

L/s: 2.9K.

2.9K.  
OS Day