



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 13.12.2018

China Taiping Insurance (S) Pte Ltd
2 Anson Road #16-00
Springleaf Tower
Singapore 079909

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SMA1266J HONDA SHUTTLE (2017)

To Supply

1) 1pc	rear bumper <i>DE-</i>	\$	1,350.00
2) 1pc	rear bumper clip <i>re /</i>	\$	20.00
3) 1pc	rear bumper right tow hook cover ?	\$	26.50
4) 1pc	tail gate <i>BT /</i>	\$	1,380.00
5) 1pc	tail gate weatherstrip <i>out /</i>	\$	168.50
6) 1pc	tail gate "H" emblem <i>re /</i>	\$	38.00
7) 1pc	tail gate "Shuttle" emblem <i>re /</i>	\$	58.00
8) 1pc	tail gate "Hybrid" emblem <i>re /</i>	\$	75.00
9) 1pc	pocket, tailgate <i>CRA /</i>	\$	27.50
10) 1pc	tail gate lock <i>BT /</i>	\$	180.00
11) 1pc	rear glass top & lower moulding <i>re /</i>	\$	180.00
12) 1pc	rear end panel <i>BT /</i>	\$	685.00
13) 1pc	rear end panel top garnish <i>DE /</i>	\$	165.00
14) 1pc	rear floor panel <i>repair</i>	\$	1,250.00
15) 1pc	rear tool box ?	\$	285.00
16) 1pc	spooge tool lid <i>BT X</i>	\$	155.00

Sub total parts	\$	6,043.50
Less: 20% discount	\$	(1,208.70)
	\$	4,834.80

To supply S.nett Parts

1) 1set	floor panel sealant	\$	120.00 X
2) 1tube	rear glass sealant	\$	40.00 /

3) 1set reverse sensor

\$ ~~250.00~~ 200.00

Sub total S.Nett Parts \$ 410.00

L/charges

1) To tuff kote front portion

\$ ~~80.00~~ 60

2) To remove & replace rear glass

\$ 120.00

3) To transfer rear tail gate trim board, handle, mechanism parts

\$ ~~120.00~~ 80

4) To cut/ welding rear end panel, floor panel. Remove rear tailgate, rear bumper, rear end panel & floor panel. To alight & adjust rear tailgate & rear bumper.

\$ ~~1,400.00~~ 700

5) To putty, respray painting tailgate inlet & outer, rear end panel, floor floor panel & rear bumper. To polish

\$ ~~1,500.00~~ 800

Sub total L/charges \$ 3,220.00

Estimate Grand Total \$ 8,464.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resur

Hp 90010068

7 days

9/18

14/12/18 @ 0900hrs

Resurvy 34 part