



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS

Not about
the reason
the ph before body.
11/1/19 3 dy.

INDIA INTERNATIONAL INSURANCE PTE LTD 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Miglani Gaurav ADDRESS : 1 Amber Road #04-02 Singapore 439845 TEL : 90289214		WIP : 37370 EXCESS : DATE: 10-Dec-18	
VEH NO :	SMA7238B	DATE IN :		CONTACT PERSON :	JESS 8128 9802
CHASSIS NO :	JM6BN22A8J0204105	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	18-Jun-18	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MBPD8-50-221ABB	10/12	\$ 1,074.80
2	BRACKET CENTER	1	MKD53-50-251	11	\$ 5.10
3	RETAINER, SENSOR	4	MKD47-67-UC5A64	?	\$ 69.20
4	SENSOR CENTER, ULTRASONIC	2	MGMK6-67-UC1 64	?	\$ 344.40
5	SENSOR SIDE, ULTRASONIC	2	MKD47-67-UC1 64	?	\$ 387.80
6	TAPE PROTECTOR, SENSOR	3	MGS1D-50-EM1A	?	\$ 24.30
7	REAR REINFORCEMENT	1	MB45A-50-260	?	\$ 537.30
8	CLIP, REAR BUMPER	2	MGJ21-50-049	11	\$ 6.40
9	FASTENER, REAR BUMPER	4	MB45A-56-146A	11	\$ 11.20
10	RIVET, REAR BUMPER	4	MBBM4-50-355	11	\$ 16.80
11	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	11	\$ 10.00
12	GROMMET, REAR BUMPER	2	M9991-00-501	11	\$ 5.60
13	GASKET LHS, TAILLAMP	1	MBHN1-51-163	11	\$ 20.90
14	GASKET RHS, TAILLAMP	1	MBHN1-51-153	11	\$ 20.90
TOTAL PARTS					\$ 2,534.70
LESS 10%					\$ 253.47
TOTAL PARTS COST					\$ 2,281.23
Labour Description					
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.			660 \$ 1,980.00
2	MZ-SP-SFRT01	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND REAR END PANEL.			630 \$ 1,890.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.			200 \$ 660.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.			11X \$ 250.00

5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$	250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$	350.00
7		TO SUPPLY BRILA PREMIUM COATING.	200	NETT	\$ 800.00
8	MZ-BR-SUNDRI	SUNDRIES.	net 30	NETT	\$ 100.00
				TOTAL LABOUR	\$ - \$ 6,280.00
				TOTAL PARTS	\$ - \$ 2,281.23
				TOTAL	\$ - \$ 8,561.23
				LESS EXCESS	\$ - \$ -
				TOTAL AFTER EXCESS	\$ -
				GST 7%	\$ - \$ -
				GRAND TOTAL	\$ - \$ -

TRANS EUROKARS PTE LTD

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CODE:	I9104	I04	PAGE NO :	1
			INVOICE NO:	31001
			DEPT/POS ID:	N / 12
CUSTOMER:	Mr Miglani Gaurav		DATE IN	18/06/2
ADDRESS:	1 Amber Rd		DATE PRINTED:	25/06/2
	#04-02		JOB NO:	19170
	Singapore 439845		CSO/OP CODE:	PDI - 1
			TEL NO:	
MODEL:	MAZDA3 1.5L SDN DELUXE BLACK L		REGN NO:	SMA7238
CHASSIS NO:	JM6BN22A8J0204105		REGN DATE:	
ENGINE NO:	P520494915		MILEAGE:	3
DESCRIPTION:	P.D.I.		REQUISITION NO:	26121/1

MZ-PT M3 PETROL TOPPING
Std PDI Pkg IPM M3

MZ-PDI M PRE DELIVERY INSPECTION & INSTALL IU
Std PDI Pkg IPM M3

MZ-PV M3 POLISH A UNIT OF VEHICLE
Std PDI Pkg IPM M3

MZ-RP M3 SUPPLY 1 SET OF REGN PLATE
Std PDI Pkg IPM M3

MZ-IU M3 SUPPLY 1 UNIT OF IU
Std PDI Pkg IPM M3

MZ-SF M3 SUPPLY & INSTALL SOLAR FILM
SUBLET 135706

MZ-FVC M INSTALL FRONT & REAR VIDEO CAMERA

SUB M3 BRILA RED LINE BODY COATING
SUBLET 135707

GEN TO CHECK BRAKE CONDITION