

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3482G

DATE 13/12/2018 10:18

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 553.00
	Rear Bumper Clip 10 pcs			\$ 22.00
	SUB TOTAL			\$ 575.00
	LESS 20%			\$ 115.00
	DISCOUNTED TOTAL			\$ 460.00
	Rear Bumper Rubber Mat			\$ 50.00
				\$ 50.00
	Labour Charge			
	Panel Beating			\$ 400.00 ²⁰⁰
	Spray Painting Charge			\$ 300.00 ²⁰⁰
	Wiring Charge			\$ 30.00 ²⁰⁰
	Remove/Refix Reverse Sensor			\$ 80.00 ²⁰⁰
	TOTAL LABOUR			\$ 810.00
	ESTIMATE TOTAL			\$ 1,320.00

Kali/10/11/14

13/12/18 132h

2 hrs

4/3

At the Repair shop

KKK Auto Repairs hence notify the Rep of the following:

- To res - after spray painting
- To display damaged parts during survey
- Parts prices are subject to final survey
- Third party survey is on a "no" n
- No illegal modifications
- Supplementary item(s) must be is subject to final approval from insurance

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.