SME Motor Pte Ltd 1 Kaki Bukit Ave 6,#02-15/16/17/18 AutoBay @ Kaki Bukit Singapore

Claim Reference:

Assessment Number: G5001845

Version: SMEMOT01/1

Date Calculated: 12/12/2018 01:57

Full Report - V1

Registration: SKR5689E

Printed: 12/12/2018 09:54

Summary Information

Claim

Location:

Printed by:

Authorisation Status: Work Provider:

Singapore (SG) Gary Seah

Interim

MERCEDES

CLA Class

SKR5689E

December

Not Known

WDD1173442N115568

CLA 250

375 45

2014

AXA Insurance S'pore Pte

Ltd

OD

Currency:

Date of Incident:

Able to Authorise Repairs: Repairs Authorised:

Estimated Repair Time: Quote Due Date:

Actual Repair Days: Parts Ordered Date: Hire Car Start:

Hire Car End: Vehicle Collected: SGD

10/12/2018

TBA TBA

Claim Reference:

Policy Number: Other Reference:

Third Party: Insured Amount:

Under Warranty: Warranty Expired:

Vehicle Details

Vehicle

Manufacturer: Model:

Sub Model: Model Sheet Number:

Registration:

Registration Month:

Registration Year:

VIN Number: Odometer:

Colour:

Engine Number: Fuel Level:

%

Model Specs

FROM VIN N070761 **MODEL 2015** RAIN SENSOR

ELECT FOLDING MIRROR BI-XENON HEADLAMPS

HEADLAMP WASHER UNIT AMG LINE

SILL MLDG ILLUMINAT LEATHER STRG WHEEL PASS SEAT MEMORY

SEAT COMFORT PACKAGE ILLUM SUN VISOR

EMISSION/STD EURO 6 ECO START/STOP CRUISE CONTROL PARAMETER STEERING TYRES 225/40 WR 18

PAINTED GRILLE **ELECTRIC SUNROOF** AMG STYLING

ALU DESIGN PARTS A/C THERMATIC

DIPPING DOOR MIRROR AUDIO 20 CD CHANGER LIGHT-/VIEW PACKAGE

LEATHERETTE PAD MULTI FUNCT S-WHEEL S/WHEEL TIP SWITCHES DRIVER SEAT MEMORY ELECT LUMBAR ADJUST

MEDIA INTERFACE REARVIEW CAMERA STRATIFIED CHARGE ELECTRIC HORN

7 SPEED AUTOMATIC SPORTS SUSPENSION WHEELS 7.5J X 18 ALU

KNEE AIRBAG PARKTRONIC BASECOAT CLEAR

Vehicle Condition

Vehicle Status

Pre-Accident Condition:

Steering:

Brakes Pedal Travel: Place of Inspection:

Pre-Accident Damage:

Severity of Impact: Vehicle Status on Inspection: .

Date of Inspection:

12/12/2018

Tyres Condition:

SME Motor Pte Ltd

Claim Reference:

Assessment Number: GS001845

Version: SMEMOT01/1


Date Calculated: 12/12/2018 01:57

Full Report - V1 Registration: SKR5689E


Printed: 12/12/2018 09:54

Tread Depth LHF: Tread Depth LHR:

Damage Areas:



Tread Depth RHF: Tread Depth RHR: Direction of Impact:



Addresses

Cost Summary

۰	Marian 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
	Total Labour	\$342.00	-
	Total Paint/Material	\$99.47	
	Total Parts	\$3,536.50	
	Excess:	TBA	
	Grand Total Exc GST:	\$3,977.97	
	7 % GST:	\$278,46	
	Grand Total Inc GST:	\$4,256.43	

0.0HRS

Repair Information

LABOUR	Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR			
Repair /	•	Price/De	Dent = \$0.00/HR	
Guide Numbe	er Répair Details	1221	_	
61-1071 01	R + R FRONT LOWER ENGINE COMPARTMENT	5.0	Cost Price (\$) 22.50	
88-1102 01 88-1105 01	R + R FRONT BUMPER CPL DIS + ASS FRONT BUMPER	8.0 7.0	36.00 31.50	
88-1360 01	(BUMPER REMOVED) AFTER CHECK: RENEW PARTS IF NECESSARY		91,50	
	ADDITION TO DIS + ASS FRONT BUMPER (VEHICLE WITH PARK ASSISTANT)	3.0	13.50	
88-1355 01	ADDITION TO DIS + ASS FRONT BUMPER (VEHICLE WITH HEADLAMP WASHER SYSTEM)	2.0	9.00	
82-4800 01)	RENEW RIGHT HEADLAMP (BUMPER DETACHED)	5.0	22.50	
	UMFASST: HEADLAMP AND FOG LAMPS ADJUST			
82-4885 01	ADDITIONAL TO RENEW RIGHT HEADLAMP (VEHICLE WITH XENON HEADLAMP)	3.0	13.50	
88-3983 01	RENEW R/FR WING (BUMPER REMOVED/DETACHED)	8.0	36.00	
	INCLUDES: R/F WHEELHOUSE COVER CPL REMOVE AND REFIT			
97-2500 ZAX	CAVITY PROTECTION (ADD/MORK)	2.0		
97-2500 ZAX	APPLY RUST PROOFING ON R/F WING	2.0	9.00	
LAE	SOUR COST	2.0	9,00	
	Total Work Units	45.0		
	Corrosion Protection	1919		

Corrosion Protection External Labour

0,00

SME Motor Pte Ltd

Claim Reference:

Assessment Number: GS001845

Version: SMEMOT01/1

Date Calculated: 12/12/2018 01:57

Full Report - V1 Registration: SKR5689E Printed: 12/12/2018 09:54

Paint Labour 3,:		0.4HRS 4.5HRS 3.1HRS 7.6HRS	18.00 \$202.50 \$139.50 \$342.00
------------------	--	--------------------------------------	---

PAINT WORK	Time Ba	sis 10 WU = 1 HR. Price = \$4	5.00/HR
Gulde Number D	react thrigh		st Price (\$)
98-2615 01 R 98-1340 01 P	- BASECOAT CLEAR RONT BUMPER PAINTING STAGE I-M /F WING PAINTING STAGE I-M REPARATION WORK FOR TWO COAT PAINTING F FITTED BODY PARTS JR COST - PAINT	11.0	
T T T MATER T P	IME(PAINT) otal Work Units (10WU/HR) otal Paintwork Labour RIAL COST - PAINT otal Excluding Pearlescent Uplift earlescent Uplift @ 0.0% otal Paint Material Cost	0.0 31.0 3.1HRS	\$139.50 Cost Price \$99.47 \$0.00 \$99.47

Guide No. Qty Description		Provide Manager	Price	Valid: 01/06/2015
283 1 FRONT BUMPE 349 1 FRT BUMPER C 742 1 R/F WING 6 562 1 RIGHT HEADLA f: OEM Parts g: Original h: Secondhand p: Parallel	LAMPKIT MA	117 001 0001	96 09 09 09 09 (10 %)	ot. Price (\$) 1,150.00* 35.00* 430.00*
			(10 70)	

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Final Calculation	Total Extras	\$0.00
Total Parts		4.5
Labour		\$3,536.50
Total Panel/Mechanical Total Paintwork Corr Prot Internal 4 WU Total Labour	\$184.50 \$139.50 \$18.00	
Additional Costs	,	\$342.00
Corr Prot Materials External Total Paint/Material Costs Grand Total Excludes GST	\$0.00	\$99.47
GST @ 7 %		\$3,977.97
Grand Total Includes GST		\$278.46
22.25 (10.4		\$4,256.43

Assessment Notes

SME Motor Pte Ltd

Claim Reference:

Assessment Number: GS001845

Version: SMEMOT01/1

Date Calculated: 12/12/2018 01:57

Full Report - V1 Registration: SKR5689E Printed: 12/12/2018 09:54

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: