TOTH (Person): Stacey Ng	ASSIGNMENT (Office) ASSIGNMENT (AXA)	
stimuled Cost	Bill to:	12119 13119
OD TP/WS/TP RES/OD RES	/EVA/INV/MV7CS	
To Inspect Vehicle No.	SKR 5689 E	Insured:
it Workshop m/s	SME Motor	Tel: 6747 6106
of I kaki B	ukit 106 # 02-15	
Policy No:	Claim No:	S8M016E0
Sum Insured.	Excess:	+ 700-00
Make of Veh:		D.O.A. 10/12/2018
CA) REV / REP. / REV 24 HI	s mv: \$ 9sk	H.O.D. Endersement
Date/Time 9:200000 HIDIR	Person Contacted: Pei Yi	
Date/Time Action/Instruction	-) Estimate	
	- NA/INC 18 0/6 224 13	DUA: 28/8/2018
	150	
1412 18 Soud DEL 1	levised via smart of	aim
THE SENCE DIE!	CACCOL ALO SILINGLE	
a la		T claim Lynn soid Su

0.

ASM (AXA)

	ESIGNMENT
Date 14/12/18	Volt 16 5KR\$689E WHOM S/12 14
Estimated Cost	Type M. Car I M. Cycle I Bus I Van I Corry I Taxi I Prime Mover I
OD TP/WS/TP RES/OD RES/EVA/INV/MV	Truck/Trailer or CA
For Improced Verlando Nov SKR 5689E	Make Mer Benz CLAZED 1891
at Workshop miss SME Motor	Colour Whe Le A/C Insured / Std / NI / NA
1 Kaki Bukit Ave 6 # 02-15	Sp. Reading 62497 URadio Insured / Std / MI / NA
Insured 7	Eng/No
Policy No	1010 WDD 1173442N11556f
Claims No.	Gen. Cond/Good / Faix / Poor / Burnt
Sum Insured: Excesso ≠ 700 · 00	Steering: Isosafer / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Interfor / Jammed / Leaked / Burnt or
Make of Velt	Modi: Nii (S/Rim STD A/Rim or / 1 2 2 4
	Tyre Size: F: 225/40218
(Policy Condition)	R:
Remark: The veh had commenced its / N/S C	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYOTYOKO OF CON FINENTE
Ball or Market Value: 98	Front Rear .
IDAC Accident Rport: Compistent? Yes or No	P.Bal 6 mm R/Bal 6 mm
GULLER Seen: > Consistent? : Yes or No	L/Ball 6 mm L/Ball 6 mm
Est Repoirs: 3 days Res.: Yes or No	D.O.A. 10/14/18 D.O.I. 14/-1/18
Lum Sum /-3 / % 3 Val.: Yes or No	Survey held at
CA REV / REP. / 24 HRS PLY	Des. of Damages Frt / Rear / Q/S / N/S / U/C / Rooftop or
Vehicle: IN /	out 0/5 ff.
Date: Person Contacted	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction L7A 66638	· · · · · · · · · · · · · · · · · · ·
1 007 14	min 18
litel conficult fall back	335.27 Wile AHYIN . (Rad 0) 24/2/201
11/11 2 1/11/19 3/3	0 26/12/201
	/ED 2 0 DEC 2018
RECEIV	1/4/2
	27 .4.
Lonellous, File Pass to? : Prefi. Report	Days Of Repair: 3
: Final Report	Resurvey No. of Trip: 2 Survey Fee:
Cals/Dinc File Bullimit 607	Facesparianes
= 24/12- typist Add	
	Interview (\$) Photos
Report Format: SMART Claim	Tech lays (\$) ones .
Lump Sum / LB.1: (\$ 5335-27	Westend IS
	AND THE CONTRACTOR OF THE CONT

Menu



Re:SKR 5689E-SUPPLEMENTARY | Proceed to Auth

Type

Q Question

Message

Thanks

Reply

LKK AUTO CONSULTANTS PTE LTD (OD) .

Menu

New Message

Type *



Message

Subject *

SKR 5689E-SUPPLEMENTARY

Message *

Dear Stacey,

Please be informed that we have received supplementary \$1343.80 from repairer.Kindly refer IA uploaded.Thanks Veron

Cancel

Send



SECHIANE I, MILIEDAYA ERI PANESTRIAE PARK, NENGAPORE MIRAE TEL : INDI GANAME PAR : INDI 4256411

Immediate Advice

To: AXA Insurance Pte Ltd

Date: 20/12/2018

Survey details

Date of loss	10/12/2018	
Date of appointment	13/12/2018	
Date of survey	14/12/2018	
Location of survey	SME MOTOR PTE LTD	

Vehicle Details:

Claim Type:	Own Damage	
Vehicle number	SKR 5689E	
Make and Model	MERCEDES BENZ CLA250	
Date of registration	5/12/2014	
Excess	\$700	
Market Value	\$98,000.00	
Parf Rebate	\$66,638.00	
Nett Loss	\$31,362.00	

Repair details

		æ
Initial Estimate	And and the state of the state	ì
Indiana Estimate	\$5,335.27 (incl.supplementary \$1343.80)	
HUITIN ESTIMATE	133,333.£7 (IIICI,30)Picilicital 4 31343,001	3

Proposed/Revised repair cost:

Parts	\$4,480.30
"Check items (Estimated)	
Labour	\$854.97
Total	\$5,335.27 (incl.supplementary \$1343.80)
Lump Sum (Estimated)	

- 1		
н	Number of days of repair	3 days (net)
- 1	Namber of gays of repair	2 days (est)

Remarks:

The vehicle sustained damages at the o/s front portion.

Damages Consistent Repair Cost Economical

LKK AUTO CONSULTANTS PTE LTD (OD) - Menu

New	M	essa	ge
-----	---	------	----

Type * Message Subject * IA SUBMITTED FOR SKR 5689E Message * Dear Stacey, Please be informed that IA submitted. We have Authorize repair. Thanks Veron Chen

Cancel



SECRETANE S, 2001-25 PANA URE UNDESTREAL PARIS, SENSLAPCINE 40092A TEL.: (1905) 62563564 FAX (1905) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd

Date: 14/12/2018

Survey details

Date of loss	10/12/2018	
Date of appointment	13/12/2018	
Date of survey	14/12/2018	
Location of survey	SME MOTOR PTE LTD	

Vehicle Details:

Claim Type:	Own Damage	
Vehicle number	SKR 5689E	
Make and Model	MERCEDES BENZ CLA250	
Date of registration	5/12/2014	
Excess	\$700	
Market Value	\$98,000.00	
Parf Rebate	\$66,638.00	
Nett Loss	\$31,362.00	

Repair details

Initial Estimate	\$3,977.97	
Initial Estimate	133,377.37	

Proposed/Revised repair cost:

Parts	\$3,536.50
"Check items (Estimated)	
Labour	\$441.47
Total	\$3,977.97
Lump Sum (Estimated)	

Number of days of repair	3 days (est)

Remarks:

The vehicle sustained damages at the o/s front portion.

Damages Consistent Repair Cost Economical

We have authorise repair.



Service Request Details

Claim

58M016E0

Reference

None

Loss Date

December 10, 2018

Request Date

December 13, 2018

Due Date

December 20, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize



Vehicle Information

Incident Vehicle Registration #

SKR5689E

Make

MERCEDES

Jel VILE MUUI 655

(0)(0)

Primary Contact/Insured

LIJIAYI 40 FLORA DRIVE, #01-58 PALM ISLES, 506866, Singapore 97718257

Claim Handler

NG Stacey 6568804351 stacey.ng@axa.com.sg

Additional Instructions BASIC XS \$700

Messages Invoices History Documents Assessment Metrics Notes

New Message

RATAN BHOSALE Pragati

From:

pelying@smemotor.com.sg

Sent:

Thursday, December 13, 2018 2:03 PM

To:

SG AXA Insurance SM AXA SGP - Motor Survey

Subject:

OWN DAMAGE CLAIM FOR SKR5689E

Attachments:

SKR5689E AUDATEX.pdf; SKR5689E.pdf

Categories:

Pragati

Hi,

Kindly assist to create claim in smart claims.

Thanks

Regards, Pei Ying

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	8657E
Vehicle No.:	SKR5689E
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Dec 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CLA250
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	27092030446032
Chassis No.:	WDD1173442N115568
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$34,013.00
Original Registration Date:	05 Dec 2014
First Registration Date:	05 Dec 2014
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$29,619.00 14 Aug
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Dec 2024
PARF Rebate Amount: Intended COE Rebate Details	\$22,214.00
COE Expiry Date:	04 Dec 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$74,389.00
COE Rebate Amount:	\$44,424.00
Total Rebate Amount:	\$66,638.00

The information contained herein is correct as at 14 Dec 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

By the lodgement of this report to the insurers, you aforesaid.	ou hereby consent to the archiving of this report at the centre and to copies of the report being ma	de available
	ACCIDENT STATEMENT	
Date Of Report	12/12/2018 13:49	
Date Of Accident	10/12/2018 15:00	
Exact Location Of Accident	TAMPINES MALL CARPARK	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKR5689E	
Insured/Policyholder		
Name Of Registered Owner	LI JIAYI	
NRIC No	S8678657E	
Email Address	NOEMAIL	

Mobile Phone No (LOCAL) +65-97718257 Alternative Phone No. OFFICE-97718257

Vehicle Particulars

Manufacturer MERCEDES-BENZ

Model **CLA 250**

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number GA420841

Cover Note Number

Driver

Name of Driver LI JIAYI NRIC No S8678657E Date Of Birth 08/11/1986 Occupation INDOOR Date Of Driving Pass 08/02/2010

Driving Experience 8 YEARS AND 10 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-97718257

Fax Number

Contact Number OFFICE-97718257

EMail Address NOEMAIL Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLIDED INTO PROPERTY

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by NO

ambulance?

NO

Was any other material or property damaged? I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WANTED TO PARK INTO THE PARKING LOT WHEN MY VEHICLE'S FRONT RIGHT PORTION HIT INTO THE PILLAR.

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera?

Was there any audio recorded?

NO

NO

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- J. Please report carriedly the details of the accident to speed up the claims process.
- This Form must be completed by the Pulicyholder and far the Authorised Oriver
- information provided must be as standar and assurate as possible. Any will increpresentation or withholding of material facts may allow insurance companies to (spudible policy (lability
- The result and acceptance of this Euron by insurance companies is not an admission of policy liability on the part of the insurance
- 3 Any fand copering may be referred to the Police for investigation.
- 6 The explore will be forwarded by the mourers of the GIA Records Management Centre established by the General Insurance Accordance of Singapore (G(A) for archiving and that copies of this report will for a fee be made evallable upon application by
- 3. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Content under the Personal Data Protection Act (PDPA)

understand, acknowledge, agree and content that

- (a) My intures, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, discluse and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - III processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
 - [ii] investigating the accident and/or my claims;
 - fill carrying out and/or dealing with my instructions or responding to any enquiries by me.
 - [W] administering my claims lineluding the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclasure of certain personal data about me to bring about delivery of the same as well as on the reternal cover of envelopes/mail packages); and/or
 - (v) complying with applicable row in administering, processing, handling sind/or dealing with my claims (collectively the
- (b) all insurer(t) who have insured vehicle(s) implied in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Parposes; and
- my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or. against finctuding their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, medangation and management in present and all future claims.
- (if) The information so collected under (d) above may be shared / discloses.
 - (i) I is all visusers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(iii) Nir complyin with requirements under any regulations, laws or court orders.

"- cyfrolion's Signature

David R. Cone

Street's Signature

If driver is not the policyholder)

Date & Time.

Reporting Centry Personnel's Signature Name

NAIC/FIN NO.



Sketch Plan #3 Pg. 1

A *

	Owner of Venicle Number: SPR 55696
	a following has been advised to you way your workshop, SIND MOTOR PTE CIP through the
36.1	a following has been advised to you wa your workshop,
Pag	ase tick the applicable box if you had been advice on the content as seen below:
1	You had been advised by the workshop that in the case that you wish to claim against your own policy that is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframs from the day of occurrence.
	You had been advised by the workshop on the liability and merits of the case accordingly.
1	You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
4	There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
	There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare part; have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
1)	The estimated waiting time for the spare parts to arrive is The estimated arrival time does not include the repair period.
1	You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.
V	For vehicles below Three [3] years old, your insurance Company will use only genuine original parts to repair your vehicle.
	For vehicles above Three (3) years old, your insurance Company will be carrying out repairs using any combination of genuine original parts and/or original equipment manufacturer (OEM) parts.
1	You had been advised by the workshop of the Twelve (12) months warranty for <u>Own Damage</u> repairs on workmanship related to the accident.
1	For vehicles that are under warranty with a local distributor, you have been advised by the workshop to sheck with your local distributor on any effect to your warranty prior to making this Own Damage claim.
911	Others
igned ar	acknowledge by:
	£ 1

Name and signature of workthop personnel including company stamp

SME Motor Pte Ltd 1 Kaki Bukit Ave 6,#02-15/16/17/18 AutoBay @ Kaki Bukit Singapore

Claim Reference:

Assessment Number: GS001845

Version: SMEMOT01/1

Date Calculated: 12/12/2018 01:57

Full Report - V1

Registration: SKR5689E

Printed: 12/12/2018 09:54

SGD

TBA

10/12/2018

Summary Information

Claim

Location:

Printed by:

Authorisation Status:

Work Provider:

Claim Reference:

Policy Number: Other Reference:

Third Party: Insured Amount:

Under Warranty: Warranty Expired: Singapore (SG)

Gary Seah Interim

AXA Insurance S'pore Pte Repairs Authorised:

Ltd

OD

Currency:

Date of Incident:

Able to Authorise Repairs: TBA

Estimated Repair Time:

Ouote Due Date: Actual Repair Days: Parts Ordered Date: Hire Car Start: Hire Car End: Vehicle Collected:

Model Specs

MODEL 2015

AMG LINE

RAIN SENSOR

FROM VIN N070761

ELECT FOLDING MIRROR

BI-XENON HEADLAMPS

SILL MLDG ILLUMINAT

14/14/18 \$ 700 14/14/18 The photo Between

Vehicle Details

Vehicle

Model: Sub Model:

Model Sheet Number:

Registration:

Registration Month: Registration Year:

VIN Number:

Odometer:

Colour:

Engine Number: Fuel Level:

Manufacturer:

CLA Class CLA 250 375 45 SKR5689E

MERCEDES

December 2014

WDD1173442N115568

Not Known

LEATHER STRG WHEEL PASS SEAT MEMORY SEAT COMFORT PACKAGE

> ILLUM SUN VISOR EMISSION STD EURO 6 ECO START/STOP CRUISE CONTROL PARAMETER STEERING TYRES 225/40 WR 18

PAINTED GRILLE ELECTRIC SUNROOF AMG STYLING

Severity of Impact:

Vehicle Status on

Inspection:

ALU DESIGN PARTS A/C THERMATIC

DIPPING DOOR MIRROR AUDIO 20 CD CHANGER LIGHT-/VIEW PACKAGE HEADLAMP WASHER UNIT LEATHERETTE PAD MULTI FUNCT S-WHEEL S/WHEEL TIP SWITCHES DRIVER SEAT MEMORY ELECT LUMBAR ADJUST MEDIA INTERFACE REARVIEW CAMERA STRATIFIED CHARGE ELECTRIC HORN 7 SPEED AUTOMATIC

> SPORTS SUSPENSION WHEELS 7.53 X 18 ALU KNEE AIRBAG PARKTRONIC

BASECOAT CLEAR

12/12/2018

Vehicle Condition

Vehicle Status

Tyres Condition:

Pre-Accident Condition: Steering:

Brakes Pedal Travel: Place of Inspection: Pre-Accident Damage: XX Auto Consultants hence notify

the Repairer of the following:

- . To resurve a seforetatter spray painting + To disgline marriaged part(x) during resurve
- . Parts prices are subject to confirmation
- * Third party survey is on a 'Without Prejudi No migal mobilications) is allowed.
- Date of Inspection: + Supplementary (tam(x) must be recoveyed and

is subject to finiti approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

Audatex System Using Manufacturer Times

SME Motor Pte Ltd

Claim Reference:

Assessment Number: GS001845

Version: SMEMOT01/1


Date Calculated: 12/12/2018 01:57


Full Report - V1

Registration: SKR5689E


Printed: 12/12/2018 09:54

Tread Depth LHF: Tread Depth LHR:





Tread Depth RHF: Tread Depth RHR: Direction of Impact:



Addresses

Cost Summary

Total Labour	\$342.00
Total Paint/Material	\$99.47
Total Parts	\$3,536.50
Excess:	TBA
Grand Total Exc GST:	\$3,977.97
7 % GST:	\$278.46
Grand Total Inc GST:	\$4,256.43

0.0HRS

Repair Information

LABOUR	Time Basis 10 WU =	and the second s	1 = \$45.00/HR ent = \$0.00/HR
Repair /			Transfer Mesovice All Vision
Guide Numbe	er Repair Details	wu	Cost Price (\$)
61-1071 01	R + R FRONT LOWER ENGINE COMPARTMENT COVER	5.0	22,50
88-1102 01	R + R FRONT BUMPER CPL	8.0	36.00
88-1105 01	DIS + ASS FRONT BUMPER (BUMPER REMOVED)	7.0	31.50
88-1360 01	AFTER CHECK: RENEW PARTS IF NECESSARY ADDITION TO DIS + ASS FRONT BUMPER	3.0	13.50
88-1355 01	(VEHICLE WITH PARK ASSISTANT) ADDITION TO DIS + ASS FRONT BUMPER	2.0	9.00
	(VEHICLE WITH HEADLAMP WASHER SYSTEM)		
82-4800 01)	RENEW RIGHT HEADLAMP (BUMPER DETACHED)	5.0	22.50
	UMFASST: HEADLAMP AND FOG LAMPS ADJUST		
82-4885 01	ADDITIONAL TO RENEW RIGHT HEADLAMP (VEHICLE WITH XENON HEADLAMP)	3.0	13.50
88-3983 01	RENEW R/FR WING (BUMPER REMOVED/DETACHED)	8.0	36.00
	INCLUDES: R/F WHEELHOUSE COVER CPL		
07 2500 744	REMOVE AND REFIT	2.0	9.00
	CAVITY PROTECTION (ADD/WORK)		
97-2500 ZAX	- 1911 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2.0	9.00
LA	BOUR COST	45.0	
	Total Work Units Corrosion Protection	45.0	

Corrosion Protection External Labour

0.00

SME Motor Pte Ltd

Claim Reference:

Assessment Number: GS001845

Version: SMEMOT01/1

Date Calculated: 12/12/2018 01:57

Full Report - V1

Registration: SKR5689E

Printed: 12/12/2018 09:54

Corrosion Protection Internal Labour	0.4HRS	18.00
Sub Total	4.5HRS	\$202.50
Paint Labour	3.1HRS	\$139.50
Total Labour	7.6HRS	\$342.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$45.00/HR		
Guide Numbe	er Description	wu	Cost Price (\$)	
	- BASECOAT CLEAR			
98-1682 01	FRONT BUMPER PAINTING STAGE I-M	11.0		
98-2615 01	R/F WING PAINTING STAGE I-M	6.0		
98-1340 01	PREPARATION WORK FOR TWO COAT	PAINTING 14.0		
	OF FITTED BODY PARTS			
LAI	BOUR COST - PAINT			
	TIME(PAINT)	0.0		
	Total Work Units (10WU/HR)	31.0		
Total Paintwork Labour		3.1HRS	\$139.50	
MATERIAL COST - PAINT			Cost Price	
Total Excluding Pearlescent Uplift			\$99.47	
	Pearlescent Uplift @ 0.0%		\$0.00	
	Total Paint Material Cost		\$99.47	

	^	-	-
•	Д		•

					Pr	ice Val	lid: 01/06/2015
Guide I	No.Qty	Description	Part Number	Supplier		Bet.	Price (\$)
283	1	FRONT BUMPER Re-ege47	117 880 4840 9999)		0%	1,150.00*-
349	110	FRT BUMPER CLAMP KIT ALL	USE SINGLE PARTS			0%	35.00*
742	1	R/F WING Berf / BUE	117 881 0201			0%	430.00*
562	1	RIGHT HEADLAMP ASSY SER	117 906 6600			0%	_ 1,600.00*
f: OEM	Parts	707	Sub Total				\$3,215.00
g: Origi	nal		Mark Up From	m Cost	(10 %)		\$321.50
h: Seco	ndhand		Total Parts		Accessed to the		\$3,536.50
p: Paral	lel						Catherinal Scholaster

x: Exchange

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

	Total Extras	\$0.00
Final Calculation		
Total Parts		\$3,536.50
Labour		100
Total Panel/Mechanical	\$184.5	0 198
Total Paintwork	\$139.5	0
Corr Prot Internal 4 WU	\$18.0	00
Total Labour		\$342.00
Additional Costs		
Corr Prot Materials External	\$0.0	00
Total Paint/Material Costs	100.000	\$99.47
Grand Total Excludes GST		\$3,977.97
GST @ 7 %		\$278.46
Grand Total Includes GST		\$4,256.43

Assessment Notes

SME Motor Pte Ltd

Claim Reference:

Assessment Number: GS001845

Version: SMEMOT01/1

Date Calculated: 12/12/2018 01:57

Full Report - V1 Registration: SKR5689E

Printed: 12/12/2018 09:54

408933

Claim Reference:

Assessment Number: GS001845

Version: SMEMOT01/1

Date Calculated: 14/12/2018 07:10

Full Report - V1 Registration: SKR5689E

Printed: 14/12/2018 15:11

SGD

TBA

10/12/2018

Summary Information

Claim

Location:

Printed by:

Authorisation Status: Work Provider:

Claim Reference: Policy Number:

Other Reference:

Third Party: Insured Amount: Under Warranty: Warranty Expired: Singapore (SG)

LKK AUTO Interim

AXA Insurance S'pore Pte Repairs Authorised: Ltd

OD

Ouote Due Date: Actual Repair Days: Parts Ordered Date: Hire Car Start: Hire Car End: Vehicle Collected:

Estimated Repair Time:

Vehicle Details

Vehicle Manufacturer:

Model: Sub Model:

Model Sheet Number: Registration:

Registration Month:

Registration Year: VIN Number:

Odometer:

Colour: Engine Number:

Fuel Level:

MERCEDES CLA Class **CLA 250**

375 45 SKR5689E December

2014

WDD1173442N115568

Not Known

%

Model Specs

Currency:

Date of Incident:

Able to Authorise Repairs: TBA

FROM VIN N070761 **MODEL 2015** RAIN SENSOR

ELECT FOLDING MIRROR BI-XENON HEADLAMPS HEADLAMP WASHER UNIT

AMG LINE

SILL MLDG ILLUMINAT LEATHER STRG WHEEL PASS SEAT MEMORY SEAT COMFORT PACKAGE

ILLUM SUN VISOR EMISSION STD EURO 6 ECO START/STOP CRUISE CONTROL PARAMETER STEERING TYRES 225/40 WR 18 PAINTED GRILLE

ELECTRIC SUNROOF AMG STYLING

ALU DESIGN PARTS A/C THERMATIC

DIPPING DOOR MIRROR AUDIO 20 CD CHANGER LIGHT-/VIEW PACKAGE LEATHERETTE PAD MULTI FUNCT S-WHEEL S/WHEEL TIP SWITCHES

DRIVER SEAT MEMORY ELECT LUMBAR ADJUST MEDIA INTERFACE REARVIEW CAMERA STRATIFIED CHARGE ELECTRIC HORN 7 SPEED AUTOMATIC

SPORTS SUSPENSION

WHEELS 7.5J X 18 ALU KNEE AIRBAG PARKTRONIC BASECOAT CLEAR

Vehicle Condition

Vehicle Status

Pre-Accident Condition:

Steering:

Brakes Pedal Travel: Place of Inspection:

Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF:

Severity of Impact:

Vehicle Status on Inspection:

Date of Inspection:

12/12/2018

Tread Depth RHF:

Claim Reference:

Full Report - V1

Assessment Number: GS001845

Registration: SKR5689E


Version: SMEMOT01/1

Date Calculated: 14/12/2018 07:10


Printed: 14/12/2018 15:11

Tread Depth LHR:

Damage Areas:



Tread Depth RHR: Direction of Impact:



Addresses

Cost Summary

Total Labour	\$342.00
Total Paint/Material	\$99.47
Total Parts	\$3,536.50
Excess:	TBA
Grand Total Exc GST:	\$3,977.97
7 % GST:	\$278.46
Grand Total Inc GST:	\$4,256.43

Repair Information

LABOUR	Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/I Price/Dent = \$0.00/I				
Repair /		100000000000000000000000000000000000000			
Guide Numbe	r Repair Details	WU	Cost Price (\$)		
61-1071 01	R + R FRONT LOWER ENGINE COMPARTMENT COVER	5.0	22.50		
88-1102 01	R + R FRONT BUMPER CPL	8.0	36.00		
88-1105 01	DIS + ASS FRONT BUMPER (BUMPER REMOVED)	7.0	31.50		
	AFTER CHECK: RENEW PARTS IF NECESSARY				
88-1360 01	ADDITION TO DIS + ASS FRONT BUMPER (VEHICLE WITH PARK ASSISTANT)	3.0	13.50		
88-1355 01	ADDITION TO DIS + ASS FRONT BUMPER (VEHICLE WITH HEADLAMP WASHER SYSTEM)	2.0	9.00		
82-4800 01)	RENEW RIGHT HEADLAMP (BUMPER DETACHED)	5.0	22.50		
	UMFASST: HEADLAMP AND FOG LAMPS ADJUST				
82-4885 01	ADDITIONAL TO RENEW RIGHT HEADLAMP (VEHICLE WITH XENON HEADLAMP)	3.0	13.50		
88-3983 01	RENEW R/FR WING (BUMPER REMOVED/DETACHED) INCLUDES: R/F WHEELHOUSE COVER CPL	8.0	36.00		
	REMOVE AND REFIT				
97-2500 ZAX		2.0	9.00		
97-2500 ZAX		2.0	9.00		
	SOUR COST				
	Total Work Units Corrosion Protection	45.0			
	Corrosion Protection External Labour	0.0HRS	0.00		
	Corrosion Protection Internal Labour	0.4HRS	18.00		

Claim Reference:

Full Report - V1

Assessment Number: GS001845

Registration: SKR5689E

Version: SMEMOT01/1

Printed: 14/12/2018 15:11

Date Calculated: 14/12/2018 07:10

Sub Total	4.5HRS	\$202.50
Paint Labour	3.1HRS	\$139.50
Total Labour	7.6HRS	\$342.00

PAINT WORK		ime Basis 10 WU = 1 HR. Price	
Guide Number	Description	WU	Cost Price (\$)
	- BASECOAT CLEAR		
98-1682 01	FRONT BUMPER PAINTING STAGE I-M	11.0	
98-2615 01	R/F WING PAINTING STAGE I-M	6.0	
98-1340 01	PREPARATION WORK FOR TWO COAT F	PAINTING 14.0	
	OF FITTED BODY PARTS		
LAB	OUR COST - PAINT		
	TIME(PAINT)	0.0	
	Total Work Units (10WU/HR)	31.0	
	Total Paintwork Labour	3.1HRS	\$139.50
MAT	ERIAL COST - PAINT		Cost Price
	Total Excluding Pearlescent Uplift		\$99.47
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$99.47
PARTS		nego-control	

PARTS					Dri	ice Valid	1: 01/06/2015
Guide I 283	No.Qty	Description FRONT BUMPER	Part Number 117 880 4840 9999	Supplier	100	Bet. 0%	Price (\$) 1,150.00*
349	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS			0%	35.00*
742	1	R/F WING	117 881 0201			0%	430.00*
562	1	RIGHT HEADLAMP ASSY	117 906 6600			0%	1,600.00*
f: OEM	Parts		Sub Total				\$3,215.00
g: Origi	inal		Mark Up Fro	m Cost	(10 %)		\$321.50
h: Seco	ndhand		Total Parts				\$3,536.50

p: Parallel x: Exchange

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

	lotal Extras	\$0.00
Final Calculation		
Total Parts		\$3,536.50
Labour		
Total Panel/Mechanical	\$184.50	
Total Paintwork	\$139.50	
Corr Prot Internal 4 WU	\$18.00	
Total Labour		\$342.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Total Paint/Material Costs		\$99.47
Grand Total Excludes GST		\$3,977.97
GST @ 7 %		\$278.46
The state of the s		

Assessment Notes

Grand Total Includes GST

\$0.00

\$4,256.43

Claim Reference:

Full Report - V1

Assessment Number: GS001845

Registration: SKR5689E

Version: SMEMOT01/1

Printed: 14/12/2018 15:11

Date Calculated: 14/12/2018 07:10

408933

Claim Reference:

Assessment Number: GS001845

Version: SMEMOT01/2

Date Calculated: 20/12/2018 02:43

Full Report - V1

Registration: SKR5689E

Printed: 20/12/2018 10:45

SGD

TBA

10/12/2018

Summary Information

Claim

Location:

Printed by:

Authorisation Status:

Work Provider:

Claim Reference: Policy Number:

Other Reference: Third Party:

Insured Amount: Under Warranty: Warranty Expired: Singapore (SG)

LKK AUTO Interim

MERCEDES

CLA Class

SKR5689E

December

Not Known

WDD1173442N115568

CLA 250

375 45

2014

AXA Insurance S'pore Pte Repairs Authorised:

Ltd

OD

Estimated Repair Time:

Able to Authorise Repairs: TBA

Actual Repair Days: Parts Ordered Date: Hire Car Start: Hire Car End: Vehicle Collected:

Vehicle Details

Vehicle Manufacturer:

Model: Sub Model:

Model Sheet Number: Registration:

Registration Month:

Registration Year: VIN Number:

Odometer:

Colour: Engine Number:

Fuel Level:

%

Model Specs

Currency:

Date of Incident:

Ouote Due Date:

FROM VIN N070761 **MODEL 2015** RAIN SENSOR

ELECT FOLDING MIRROR BI-XENON HEADLAMPS HEADLAMP WASHER UNIT

AMG LINE

SILL MLDG ILLUMINAT LEATHER STRG WHEEL

PASS SEAT MEMORY SEAT COMFORT PACKAGE

ILLUM SUN VISOR EMISSION STD EURO 6 ECO START/STOP CRUISE CONTROL PARAMETER STEERING TYRES 225/40 WR 18

PAINTED GRILLE ELECTRIC SUNROOF AMG STYLING

ALU DESIGN PARTS A/C THERMATIC

DIPPING DOOR MIRROR AUDIO 20 CD CHANGER LIGHT-/VIEW PACKAGE LEATHERETTE PAD MULTI FUNCT S-WHEEL

S/WHEEL TIP SWITCHES DRIVER SEAT MEMORY ELECT LUMBAR ADJUST MEDIA INTERFACE REARVIEW CAMERA STRATIFIED CHARGE

ELECTRIC HORN 7 SPEED AUTOMATIC SPORTS SUSPENSION WHEELS 7.5J X 18 ALU

KNEE AIRBAG PARKTRONIC BASECOAT CLEAR

Vehicle Condition

Vehicle Status

Pre-Accident Condition: Steering:

Brakes Pedal Travel: Place of Inspection:

Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF:

Severity of Impact: Vehicle Status on

Date of Inspection:

Inspection:

12/12/2018

Tread Depth RHF:

Claim Reference:

Full Report - V1


Assessment Number: GS001845


Registration: SKR5689E Printed: 20/12/2018 10:45

Version: SMEMOT01/2

Date Calculated: 20/12/2018 02:43

Tread Depth RHR:





Addresses

LABOUR

Cost Summary

Total Labour	\$355.50
Total Paint/Material	\$99.47
Total Parts	\$4,480.30
Total of Additional Costs	\$400.00
Excess:	TBA
Grand Total Exc GST:	\$5,335.27
7 % GST:	\$373.47
Grand Total Inc GST:	\$5,708.74

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR

Repair Information

LABOUR	111112 22010 23 1113	Price/Dent = \$0.00/HR		
Repair /				
Guide Numbe	r Repair Details	wu	Cost Price (\$)	
54-1011 01	SHORT TEST	3.0	13.50	
	INCLUDES: CONNECT + DISCONNECT STAR			
	DIAGNOSIS,			
	PRINT DATA,			
	DELETE ERROR MEMORY			
61-1071 01	R + R FRONT LOWER ENGINE COMPARTMENT	5.0	22.50	
	COVER			
88-1102 01	R + R FRONT BUMPER CPL	8.0	36.00	
88-1105 01	DIS + ASS FRONT BUMPER	7.0	31.50	
	(BUMPER REMOVED)			
	AFTER CHECK: RENEW PARTS IF NECESSARY			
88-1360 01	ADDITION TO DIS + ASS FRONT BUMPER	3.0	13.50	
	(VEHICLE WITH PARK ASSISTANT)			
88-1355 01	ADDITION TO DIS + ASS FRONT BUMPER	2.0	9.00	
	(VEHICLE WITH HEADLAMP WASHER SYSTEM)			
82-4800 01)	RENEW RIGHT HEADLAMP	5.0	22.50	
	(BUMPER DETACHED)			
	UMFASST: HEADLAMP AND FOG LAMPS			
	ADJUST			
82-4885 01	ADDITIONAL TO RENEW RIGHT HEADLAMP	3.0	13.50	
	(VEHICLE WITH XENON HEADLAMP)			
88-3983 01	RENEW R/FR WING	8.0	36.00	
	(BUMPER REMOVED/DETACHED)			
	INCLUDES: R/F WHEELHOUSE COVER CPL			
	REMOVE AND REFIT			
97-2500 ZAX	CAVITY PROTECTION (ADD/WORK)	2.0	9.00	

Claim Reference:

Full Report - V1

Assessment Number: GS001845

Registration: SKR5689E

Version: SMEMOT01/2

Printed: 20/12/2018 10:45

Date Calculated: 20/12/2018 02:43

97-2500 ZAX	APPLY RUST PROOFING ON R/F WING	2.0	9.00
	OUR COST Total Work Units	48.0	
	Corrosion Protection Corrosion Protection External Labour Corrosion Protection Internal Labour Sub Total	0.0HRS 0.4HRS 4.8HRS	0.00 18.00 \$216.00
	Paint Labour Total Labour	3.1HRS 7.9HRS	\$139.50 \$355.50

PAINT WORK Tir		ne Basis 10 WU = 1 HR. Price	
Guide Numbe	r Description	WU	Cost Price (\$)
	- BASECOAT CLEAR		
98-1682 01	FRONT BUMPER PAINTING STAGE I-M	11.0	
98-2615 01	R/F WING PAINTING STAGE I-M	6.0	
98-1340 01	PREPARATION WORK FOR TWO COAT PA	AINTING 14.0	
	OF FITTED BODY PARTS		
LAB	OUR COST - PAINT		
	TIME(PAINT)	0.0	
	Total Work Units (10WU/HR)	31.0	
	Total Paintwork Labour	3.1HRS	\$139.50
MAT	TERIAL COST - PAINT		Cost Price
	Total Excluding Pearlescent Uplift		\$99.47
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$99.47

PARTS					Price	Valid: 01/06/2015
Guide No	o.Qty	Description	Part Number	Supplier	Be	et. Price (\$)
283	1	FRONT BUMPER	117 880 4840 999	9	09	6 1,150.00*
349	1	FRT BUMPER CLAMP KIT	USE SINGLE PART	S	09	6 35.00*
832 7	X	R/F W-ARCH LINER MTG	USE SINGLE PART	0.0 -	7745 09	6 28.00*(A)
742	1	R/F WING	117 881 0201		09	6 430.00*
9652	1	R/H-LAMP CONT UNIT	218 900 9303	short circuit	r 09	6 580.00* (A)
9650	1	R/H-LAMP LVL C-UNIT	222 900 3300	Short circu	rt 09	6 250.00* (A)
562	1	RIGHT HEADLAMP ASSY	117 906 6600		09	6 1,600.00*
f: OEM Pa	arts		Sub Total			\$4,073.00
g: Origina			Mark Up Fro	om Cost (10 %)	\$407.30
h: Secon			Total Parts			\$4,480.30
n: Daralle			104411414			

p: Parallel x: Exchange

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description		Betterment	Price
REPROGRAMME	SPECIALIST	0%	CPA \$400.00 ()
HEADLAMP		Total Extras	\$400.00

Final Calculation

\$4,480.30 **Total Parts**

Labour

\$198,00 Total Panel/Mechanical

Claim Reference:

Full Report - V1

Assessment Number: GS001845

Registration: SKR5689E

Version: SMEMOT01/2

Printed: 20/12/2018 10:45

Date Calculated: 20/12/2018 02:43

Total Paintwork \$139.50 Corr Prot Internal 4 WU \$18.00

Total Labour \$355.50

Additional Costs

Corr Prot Materials External \$0.00

Cost of Specialist \$400.00

Total of Additional Costs
Total Paint/Material Costs
\$99.47

Grand Total Excludes GST \$5,335.27 GST @ 7 % \$373.47

Grand Total Includes GST \$5,708.74

Assessment Notes

408933

Claim Reference:

Assessment Number: GS001845

Version: SMEMOT01/2

Date Calculated: 24/12/2018 07:26

SGD

TBA

10/12/2018

Full Report - V1 Registration: SKR5689E

Printed: 24/12/2018 15:26

Summary Information

Claim

Location:

Printed by:

Authorisation Status:

Work Provider:

Claim Reference:

Policy Number: Other Reference:

Third Party:

Insured Amount: Under Warranty: Warranty Expired: Singapore (SG)

LKK AUTO Interim

MERCEDES

CLA Class

SKR5689E

December

Not Known

WDD1173442N115568

CLA 250

375 45

2014

AXA Insurance S'pore Pte Repairs Authorised:

OD

Estimated Repair Time: Ouote Due Date:

Currency:

Date of Incident:

Able to Authorise Repairs: TBA

Actual Repair Days: Parts Ordered Date: Hire Car Start: Hire Car End: Vehicle Collected:

Vehicle Details

Vehicle Manufacturer:

Model: Sub Model:

Model Sheet Number:

Registration: Registration Month:

Registration Year:

VIN Number:

Odometer: Colour:

Engine Number:

Fuel Level:

%

Model Specs

FROM VIN N070761 **MODEL 2015** RAIN SENSOR

ELECT FOLDING MIRROR BI-XENON HEADLAMPS HEADLAMP WASHER UNIT

AMG LINE

SILL MLDG ILLUMINAT LEATHER STRG WHEEL PASS SEAT MEMORY

SEAT COMFORT PACKAGE ILLUM SUN VISOR EMISSION STD EURO 6 ECO START/STOP CRUISE CONTROL PARAMETER STEERING

TYRES 225/40 WR 18 PAINTED GRILLE ELECTRIC SUNROOF AMG STYLING

ALU DESIGN PARTS A/C THERMATIC

DIPPING DOOR MIRROR

AUDIO 20 CD CHANGER LIGHT-/VIEW PACKAGE LEATHERETTE PAD MULTI FUNCT S-WHEEL S/WHEEL TIP SWITCHES DRIVER SEAT MEMORY ELECT LUMBAR ADJUST MEDIA INTERFACE REARVIEW CAMERA

STRATIFIED CHARGE ELECTRIC HORN 7 SPEED AUTOMATIC SPORTS SUSPENSION WHEELS 7.5J X 18 ALU

KNEE AIRBAG PARKTRONIC BASECOAT CLEAR

Vehicle Condition

Vehicle Status

Pre-Accident Condition:

Steering:

Brakes Pedal Travel: Place of Inspection: Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF:

Severity of Impact:

Date of Inspection:

Vehicle Status on Inspection:

12/12/2018

Tread Depth RHF:

Claim Reference:

Full Report - V1

Assessment Number: GS001845


Registration: SKR5689E

Version: SMEMOT01/2


Printed: 24/12/2018 15:26

Date Calculated: 24/12/2018 07:26





Tread Depth RHR: Direction of Impact:



Addresses

Cost Summary

Total Labour	\$355.50
Total Paint/Material	\$99.47
Total Parts	\$4,480.30
Total of Additional Costs	\$400.00
Excess:	TBA
Grand Total Exc GST:	\$5,335.27
7 % GST:	\$373.47
Grand Total Inc GST:	\$5,708.74

Repair Information

LABOUR Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
Price/Dent = \$0.00/HR

Repair /		NAME OF TAXABLE PARTY.	
	r Repair Details	wu	Cost Price (\$)
54-1011 01	SHORT TEST	3.0	13.50
31 1011 01	INCLUDES: CONNECT + DISCONNECT STAR		
	DIAGNOSIS,		
	PRINT DATA,		
	DELETE ERROR MEMORY		
61-1071 01	R + R FRONT LOWER ENGINE COMPARTMENT	5.0	22.50
01 10/1 01	COVER		
88-1102 01	R + R FRONT BUMPER CPL	8.0	36.00
88-1105 01	DIS + ASS FRONT BUMPER	7.0	31.50
00 1103 01	(BUMPER REMOVED)		
	AFTER CHECK: RENEW PARTS IF NECESSARY		
88-1360 01	ADDITION TO DIS + ASS FRONT BUMPER	3.0	13.50
00 1500 01	(VEHICLE WITH PARK ASSISTANT)		
88-1355 01	ADDITION TO DIS + ASS FRONT BUMPER	2.0	9.00
00 1000 01	(VEHICLE WITH HEADLAMP WASHER SYSTEM)		
82-4800 01)	RENEW RIGHT HEADLAMP	5.0	22.50
02 1000 01,	(BUMPER DETACHED)		
	UMFASST: HEADLAMP AND FOG LAMPS		
	ADJUST		
82-4885 01	ADDITIONAL TO RENEW RIGHT HEADLAMP	3.0	13.50
	(VEHICLE WITH XENON HEADLAMP)		
88-3983 01	RENEW R/FR WING	8.0	36.00
	(BUMPER REMOVED/DETACHED)		
	INCLUDES: R/F WHEELHOUSE COVER CPL		
	REMOVE AND REFIT		
97-2500 ZAX	CAVITY PROTECTION (ADD/WORK)	2.0	9.00

Claim Reference:

Full Report - V1

Assessment Number: GS001845

Registration: SKR5689E

Version: SMEMOT01/2

Printed: 24/12/2018 15:26

Date Calculated: 24/12/2018 07:26

97-2500 ZAX	APPLY RUST PROOFING ON R/F WING	2.0	9.00
	BOUR COST		
=-0.7	Total Work Units	48.0	
	Corrosion Protection		
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.4HRS	18.00
	Sub Total	4.8HRS	\$216.00
Paint Labour		3.1HRS	\$139.50
	Total Labour	7.9HRS	\$355.50
PAINT WORK	Time Basis 10	WU = 1 HR. Price	= \$45.00/HR
	er Description	WU	Cost Price (\$)
	- BASECOAT CLEAR		
98-1682 01	FRONT BUMPER PAINTING STAGE I-M	11.0	
98-2615 01	R/F WING PAINTING STAGE I-M	6.0	
98-1340 01	PREPARATION WORK FOR TWO COAT PAINTING	14.0	
	OF FITTED BODY PARTS		
LAI	BOUR COST - PAINT		
	TIME(PAINT)	0.0	
	Total Work Units (10WU/HR)	31.0	
	Total Paintwork Labour	3.1HRS	\$139.50
MA	TERIAL COST - PAINT		Cost Price
	Total Excluding Pearlescent Uplift		\$99.47
	Pearlescent Uplift @ 0.0%		\$0.00
	· white a court of the court of		400 47

Guide No.Qty Description Part Number Supplier Bet. Price (\$) 283 1 FRONT BUMPER 117 880 4840 9999 0% 1,150.00* 349 1 FRT BUMPER CLAMP KIT USE SINGLE PARTS 0% 35.00* 832 1 R/F W-ARCH LINER MTG USE SINGLE PARTS 0% 28.00* 742 1 R/F WING 117 881 0201 0% 430.00* 9652 1 R/H-LAMP CONT UNIT 218 900 9303 0% 580.00* 9650 1 R/H-LAMP LVL C-UNIT 222 900 3300 0% 250.00* 562 1 RIGHT HEADLAMP ASSY 117 906 6600 0% 1,600.00* f: OEM Parts Sub Total \$4,073.00 g: Original Mark Up From Cost (10 %) \$407.30	PARIS	F2:			Pri	ice Valid	: 01/06/2015
349 1 FRT BUMPER CLAMP KIT USE SINGLE PARTS 0% 28.00* 832 1 R/F W-ARCH LINER MTG USE SINGLE PARTS 0% 28.00* 742 1 R/F WING 117 881 0201 0% 430.00* 9652 1 R/H-LAMP CONT UNIT 218 900 9303 0% 580.00* 9650 1 R/H-LAMP LVL C-UNIT 222 900 3300 0% 250.00* 562 1 RIGHT HEADLAMP ASSY 117 906 6600 0% 1,600.00* f: OEM Parts g: Original Mark Up From Cost (10 %) \$407.30	Guide	No.Qty	Description	7. 19. 27. 48. 19. 19. 19. 19. 19. 19. 19. 19. 19. 19		Bet.	Price (\$)
832 1 R/F W-ARCH LINER MTG USE SINGLE PARTS 0% 28.00* 742 1 R/F WING 117 881 0201 0% 430.00* 9652 1 R/H-LAMP CONT UNIT 218 900 9303 0% 580.00* 9650 1 R/H-LAMP LVL C-UNIT 222 900 3300 0% 250.00* 562 1 RIGHT HEADLAMP ASSY 117 906 6600 0% 1,600.00* f: OEM Parts g: Original Sub Total \$4,073.00	283	1.	FRONT BUMPER	117 880 4840 9999			and the second second second second second
832 1 R/F W-ARCH LINER MTG USE SINGLE PARTS 0% 28.00* 742 1 R/F WING 117 881 0201 0% 430.00* 9652 1 R/H-LAMP CONT UNIT 218 900 9303 0% 580.00* 9650 1 R/H-LAMP LVL C-UNIT 222 900 3300 0% 250.00* 562 1 RIGHT HEADLAMP ASSY 117 906 6600 0% 1,600.00* f: OEM Parts Sub Total \$4,073.00 g: Original Mark Up From Cost (10 %) \$407.30	349	+1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0%	35.00*
742 1 R/F WING 117 881 0201 0% 430.00* 9652 1 R/H-LAMP CONT UNIT 218 900 9303 0% 580.00* 9650 1 R/H-LAMP LVL C-UNIT 222 900 3300 0% 250.00* 562 1 RIGHT HEADLAMP ASSY 117 906 6600 0% 1,600.00* f; OEM Parts Sub Total \$4,073.00 g; Original Mark Up From Cost (10 %) \$407.30		1	R/F W-ARCH LINER MTG	USE SINGLE PARTS		0%	28.00*
9652 1 R/H-LAMP CONT UNIT 218 900 9303 0% 580.00* 9650 1 R/H-LAMP LVL C-UNIT 222 900 3300 0% 250.00* 562 1 RIGHT HEADLAMP ASSY 117 906 6600 0% 1,600.00* f: OEM Parts g: Original Sub Total Mark Up From Cost (10 %) \$4,07.30		1	A Participation of the Control of th			0%	430.00*
9650 1 R/H-LAMP LVL C-UNIT 222 900 3300 0% 250.00* 562 1 RIGHT HEADLAMP ASSY 117 906 6600 0% 1,600.00* f: OEM Parts g: Original Sub Total Mark Up From Cost (10 %) \$4,073.00		1				0%	580.00*
562 1 RIGHT HEADLAMP ASSY 117 906 6600 0% 1,600.00* f: OEM Parts g: Original Sub Total 4,073.00 Mark Up From Cost (10 %) \$407.30		1				0%	250.00*
f: OEM Parts g: Original Sub Total Mark Up From Cost (10 %) \$4,073.00 \$407.30		1		117 906 6600		0%	1,600.00*
g: Original Mark Up From Cost (10 %) \$407.30		Parts		Sub Total			\$4,073.00
±4.400.20		The second second			st (10 %)		\$407.30
	-			Total Parts			\$4,480.30
	p: Para	illel					
p: Parallel	v. Evel	2000					

x: Exchange

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

DARTS

Description		Betterment	Price
REPROGRAMME	SPECIALIST	0%	\$400.00
HEADLAMP		Total Extrac	\$400.00

Final Calculation

\$4,480.30 **Total Parts**

Labour

\$198.00 Total Panel/Mechanical

Total Paint Material Cost

\$99.47

Claim Reference:

Full Report - V1

Assessment Number: GS001845

Registration: SKR5689E

Version: SMEMOT01/2

Printed: 24/12/2018 15:26

Date Calculated: 24/12/2018 07:26

\$139.50

Total Paintwork Corr Prot Internal 4 WU

\$18.00

Total Labour

\$355.50

Additional Costs

Corr Prot Materials External

\$0.00

Cost of Specialist

\$400.00

Total of Additional Costs
Total Paint/Material Costs

\$400.00 \$99.47

Grand Total Excludes GST

\$5,335.27

GST @ 7 % Grand Total Includes GST \$373.47 \$5,708.74

Assessment Notes

LAUNCH

LAUNCH TECH (S) PTE LTD

INVOICE

DATE: 17/12/2018

Co Reg: 200812433G 9004, Tampines St. 93 #01-110 Singapore 528838 Phone 96185133

TO: July

COMMENTS OR SPECIAL INSTRUCTIONS:

		TOTAL
SON ON LINCE COO ING. FRONT,	\$400 E	\$400
HEADLAMP MODEC.		
(SKL 5689 E). MB 117.		
	SUBTOTAL	
	SALES TAX	
SH	IPPING & HANDLING	
	TOTAL DUE	= 400 -
	HEADLAMP MUDEL. (SKLS689E). MB 117.	HEADLAMP MODEL. (SKLSB9E)_MB117. SUBTOTAL SALES TAX SHIPPING & HANDLING

Make all cheques payable to Launch Tech (S) Pte Ltd
If you have any questions concerning this invoice, contact Vincent, +65 96185133

THANK YOU FOR YOUR BUSINESS!

10 KAK BUK 1 ROAD 1 #01 33 K3 HJUSTR AL BULDING 5 NGAPORE 415175. Tel 87476018 Fex 67449344 | Email Surcess m@gmail.com Co & Gs Reg No 1999048085

SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 /16 /17 /18 AUTOBAY SINGAPORE 417883

TAX INVOICE

Inv No. 18120122 Date : 14/12/2018

Page

2 1 of 1

5/1	V Item No.	Description	Qty	U/ Price	Amount
1		02-18 SKR5689E			
Z	A1179066600	HEADLAMP	1	1,600.00	1,600.00
3	A1178810201	FENDER	1	430.00	430.00
4.	A1178805840	BUMPER AMG FRT 1178804840	1	1,150.00	1,150.00
5	A0039909497	4MM PIN	7	4.00	28.00
5	A1249900492	39067 RIVET	10	3.50	35.00
7	A2229003300	CONTROL UNIT	1	250.00	250.00
8	A2189009303	CONTROL UNIT	1	580.00	580.00

Sub Total	4,073.00
GST 7%	285.11
Total	4,358.11

Customer's Signature