

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 6959D

DATE 11/12/2018 14:07

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 553.00
	Rear Bumper Clip 10 pcs			\$ 22.00
	SUB TOTAL			\$ 575.00
	LESS 20%			\$ 115.00
	DISCOUNTED TOTAL			\$ 460.00
	 Rear Bumper Rubber Mat			\$ 50.00
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Bumper Reverse Sensor			\$ 135.70
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00
				\$ 435.70
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Wiring Charge			\$ 30.00
	Remove/Refix Reverse Sensor			\$ 80.00
	TOTAL LABOUR			\$ 810.00
	ESTIMATE TOTAL			\$ 1,705.70

Kah (UK)

13/12/18 1425L

2 Pys.

L/s

Attn Repair pth

LKF Auto Consultants hence notify the Repairer of the following:

- To be away before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Total price is on a "Without Prejudice" basis
- No claim to be made by the Repairer
- Supplier and repair must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.