

Attn: Motor Claim Dept

Date:

Pages: 1 - 7

ACCIDENT REPAIR ESTIMATES

Our Ref:	
Type of Claim : Own Damage	Vehicle No. : SJR7880S
x 3rd Party	Make & Model : HYUNDAI HD AVANTE 1.6 A
Windscreen	Year of Manufacture : 2009
	Chassis No.
Ins Company : DIRECT ASIA INSURANCE	Engine No. : G4FC9U678125
Excess :	Policy No : <u>MT/00496543</u>
Date of Accident : 5/12/2018	Time of Accident : 1350 hrs
Suggested Days of Repair :2	In-house Vehicle Assessor
	Name : Cray Tan
Repair Estimates	
Parts (a) Cost / List Price Items	Signature :
	Contact No : 9766 1393
Plus/Less %	E- mail : 3,1878805
(b) Nett Price Items Less	the Repairer of the following: To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed
Total Repair Cost \$0.00	Supplementary :tern(s) must be resurveyed and is subject to final approval from Insurance Company
The above total will be subjected to 7% G.S.T.	Acknowledged by Repairer
Name of Surveyor : Tau Company : Tau Survey conducted on : 12	Signature: 1849 49 49 49 49 49 49 49 49 49 49 49 49 4
Remarks By Surveyor (a) The repair of this vehicle is authorized / is not auth	orized until further notice.
(b) Recommended Days of Repair :	day(s)
(c) Resurvey : Required / Not	Required After nepri.
(d) Excess :\$	
(e) Signature of surveyor :	Date: 29/17/68

VACCIDENT REPAIR ESTIMATES\F3

This is an initial estimate based on a visual inspection of the above mentioned vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the insurance company



Spare Parts

Vehicle No. :	SJR7880S	Submit By :	Cray Tan
Make & Model:	HYUNDAI AVANTE 1.6 (A)	Year Manufactur:	2009
Chassis No. : _	KMHDU41BR9U796971	Engine No. :	G4FC9U678125
		04/1:-4	

Cost / List

S/No	Part Description	Qty	Cost		Disposition by Surveyor
1	Reverse Sensor	1	\$240.00	S/N	200 ?
	LABOUR				
1	Labour to remove, putty and respray rear bumper		\$280.00		200 25
				Incari	
					Surveyor
				-3/9	
	Total amount:		\$520.00		
	rotal amount.		ψ320.00		
				- 01-	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.