

Y/P2962E.

TP EQ Cecilia.

Isuzu NPR85

JAANPR85HG7100194.

Rear Number Plate	30(SN) X
Rear Number Plate Bracket	85 X
Rear Undersides Frame . Best	1000(SN) 700(SN)
Taillamp x 02 RH wt	282 x 2 = 564 282
Taillamp Panel x 02 N/R	97 x 2 = 194 X
Rear Wooden Step Panel. cracked	550(SN) 280(SN)
Rear Wooden Chassis Member x 02 RH cracked	950 x 2 = 1900(SN) 700(SN)
Rear Rubber Stopper x 03 2 pieces unit	80 x 3 = 240(SN) 160(SN)
Tailgate x 02 Dent	1500 x 2 = 3000(SN) 2600(SN)
Tailgate Lock x 02 Best	280 x 2 = 560(SN) 500(SN)
Tailgate Lock Check x 02 Dent	50 x 2 = 100(SN) 60(SN)
Tailgate Lower Hinge x 02 N/R	250 x 2 = 500(SN) X
Advertisement Stickers New	1000(SN) 850(SN)

List: 282.

S.N: 5850

Ten 15% : 239.70

Panel Beating	1000 500
Spray Painting	1000 500
Wiring	50 30
To remove rear storage box	500 380
To repair and straighten chassis member	800. X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total 7499.70

L/S: 61K

C9 Xing

200