

ASS. REC. BY:

REF:

CS/ASM18022502/Ktd3⁹²

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Lynn Khong

of

ASM(CAXA)

Date/Time:

14/12/2018

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKX 5640M

Insured:

at Workshop m/s

BH Auto

Tel:

6559 8944

of

Blk 1, Sector C Sin Ming Ind. Est # 01-111

Policy No:

Claim No:

88M015XQ

Sum Insured:

Excess:

\$300.00

Make of Veh:

D.O.A.

9/12/2018

(Client's Record)

☒ CA / REV / REP. / REV 24 HRS

17.12.2018 @ 3.30pm

H.O.D. Endorsement:

Date/Time:

12.16pm @ 14/12/18

Person Contacted:

Jarelyn

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKX 5640M - x

12/12/18 - Pensed via smart claims

Part by Part \$3961.67 (Red: 3953.49; 49%)

REF: ASM (AXA)

ASSIGNMENT

From:

Date: 17/12/2018

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKX 5640M

at Workshop n/s: BH Auto

of: BLK1, sec. C 8th Ming Ind. Est # 01-111

Insured:

Policy No:

Claims No:

Sum Insured: Excess: \$300.00

(Client's Record)

Make of Veh: 330pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$62k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val: Yes or No

☒ CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKX 5640M Yr Regn: 12 15

Type: ☒ M. Car / ☐ M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel C.C. 1496

Colour: M. P. White A/C Insured / Std / NI / NA

Sp. Reading: 032920 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RUI 1104451

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R:

BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 2 mm R/Bal. 7 mm

L/Bal. 2 mm L/Bal. 7 mm

D.O.A. 9/12/18 D.O.I. 17/12/18

Survey held at

Des. of Damages: ☒ Frt / ☐ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/12 File pass to Customer

RECEIVED 29 JAN 2019

Date/Time, File Pass to?

1) 29/11 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$ 3961.67)

☐ Prel. Report☒ Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) S+RS St

) Photos

) Other:

TOTAL

200

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 29 January 2019 11:57 AM
To: 'BHAS - Moo Wen Zheng'; Kenneth Kong (LKKAUTO)
Cc: BHAS - Bernard Kee; BHAS - Jacelyn Loh; BHAS - Chan Yun Shi
Subject: RE: FINALIZE OD AXA SKX5640M DOA 09.12.2018

Dear Wen Zheng,

Confirm part by part \$3961.67, 4days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>
Sent: Tuesday, 29 January 2019 11:18 AM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>; Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Cc: BHAS - Bernard Kee <Bernard.kee@bhauto.com.sg>; BHAS - Jacelyn Loh <Jacelyn.loh@bhauto.com.sg>; BHAS - Chan Yun Shi <yunshi.chan@bhauto.com.sg>
Subject: RE: FINALIZE OD AXA SKX5640M DOA 09.12.2018

Dear Denise,

Report has been assigned in audatex.

Kindly assist.

Thank you.

Best Regards,
Wen Zheng



BH AUTO SERVICES PTE LTD

BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-111/113/115/117
SINGAPORE 575636 TEL: (65) 6559 8944 FAX: (65) 6269 2404
CO. REG. NO.: 200917512K GST REG. NO.: 200917512K

(W) +65-6559 8945 (F) +65-6269 2404 (HP) +65 9621 2084

(E) wenzheng.moo@bhauto.com.sg <http://www.bhauto.com.sg>



From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Tuesday, 29 January 2019 11:15 AM
To: BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; Kenneth Kong (LKKAUTO)



Service Request Details

Claim

S8M015XQ

Reference

None 

Loss Date

December 9, 2018

Request Date

December 14, 2018

Due Date

December 21, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKX5640M

Make

HONDA



Service Address

Blk 1 Sin Ming Industrial, , , 575636

Primary Contact/Insured

TANG KOK CHIEN

79D TOA PAYOH CENTRAL, #05-59, 314079, Singapore

98554768

mervin.tang@hotmail.com

Claim Handler

KHONG Lynn

68804892

lynn.khong@axa.com.sg

Additional Instructions

BH Auto OD Excess \$300

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

New Message



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

Date: 18/12/2018

To : AXA Insurance Pte Ltd

Survey details

Date of loss	9-Dec-18
Date of appointment	17-Dec-18
Date of survey	17-Dec-18
Location of survey	BH AUTO

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKX 5640M
Make and Model	HONDA VEZEL
Date of registration	17/12/2015
Excess	300.00
Market Value	\$62,000
Parf Rebate	\$46,543
Nett Loss	\$15,457

Repair details

Initial Estimate	\$7,915
------------------	---------

Proposed/Revised repair cost:

Parts	\$1,953
Check item	\$1,010
Labour	\$1,402
Total	\$4,365
Lump Sum(if applicable)	\$0

Number of days of repair	4
--------------------------	---

Remarks:

Damage consistent
Repair cost economical

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/12/2018 10:38
Date Of Accident	09/12/2018 11:20
Exact Location Of Accident	ALONG TOA PAYOH LORONG 6 TOWARDS LORONG 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX5640M
Insured/Policyholder	
Name Of Registered Owner	TANG KOK CHIEN
NRIC No	S7966319J
Email Address	MERVIN.TANG@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98554768
Alternative Phone No	OTHERS-98554768

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA28825/1
Cover Note Number	

Driver

Name of Driver	TANG KOK CHIEN
NRIC No	S7966319J
Date Of Birth	01/12/1979
Occupation	INDOOR
Date Of Driving Pass	16/12/2011
Driving Experience	6 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98554768
Fax Number	
Contact Number	OTHERS-98554768
Email Address	MERVIN.TANG@HOTMAIL.COM

Accident Sketch Plan

SKETCH PLAN



Top Road
Lansing 6
A-SK 5600M
B-SLP 8491L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 9 December 2017 approximately 11.20 am I was at the cross junction on Top Road Lansing 6 going into Lansing 2. The traffic light turned green to turn and the car in front of me, SLP 8491L Suzuki Vitara, started to move and I followed suit. The car suddenly stops and my car being into the car in front of me.

The right side headlamps drop from its location and some damage on the grill.

The car in front suffers damage at the back of the vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

10/12/17

9.00 PM

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NAC/7-12 No.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 6319J

Vehicle Details

Vehicle No.: SKX5640M
Vehicle to be Exported: No
Intended Deregistration Date: 10 Dec 2018
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X CVT
Primary Colour: White
Manufacturing Year: 2015
Engine No.: L15B4024453
Chassis No.: RU11104451
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$19,775.00
Original Registration Date: 17 Dec 2015
First Registration Date: 17 Dec 2015
Transfer Count: 0
Actual ARF Paid: \$9,775.00

Intended PARF Rebate Details
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 16 Dec 2025
PARF Rebate Amount: \$7,331.00

Intended COE Rebate Details
COE Expiry Date: 16 Dec 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$55,889.00
COE Rebate Amount: \$39,212.00
Total Rebate Amount: \$46,543.00

The information contained herein is correct as at 10 Dec 2018

OK



FREE Car Search **REWARDS MEMBERSHIPS**
Get at least **10% DISCOUNT** on all services from repair, warranty & servicing, grooming to car accessories

[Learn more](#)


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Cos Renewal Toyota Altis 1.6A



2.88% P.A. Lowest Interest @ GV
Cars Financing \$2000
Downpayment Monthly From
\$568
GV Credit Pte Ltd. StarAd

PRIME MOTOR & LEASING

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

18 vehicles

Honda Vezel

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Vezel		Any	Any	2015	Any	Any	Any	Available
	Honda Vezel	1.5A X	\$61,800	\$8,220 /yr	15-Nov-2015	1,496 cc	66,239 km	SUV	Available
1 Owner Only! Well Maintained. 100% Accident Free! Low Fuel Consumption! Electric Park Brake Button, Bluetooth Interface/Audio Aux/USB Port, Smart Key, LED Headlights, Auto Climate Control Aircon, Kno...									
Posted: 09-Dec-2018 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel	1.5A X	\$62,800	\$8,340 /yr	02-Dec-2015	1,496 cc	38,500 km	SUV	Available
Beautiful Mica Black, 1 Careful Owner, Under Warranty, Well Maintained, Seldom Used, Accident Free, Just Serviced, Undergone A 120 Points Safety Check By Our In House Mechanics Peace Of Mind! Can Loan...									
Jia Leong Trading Enterprise									
Posted: 06-Dec-2018 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel	1.5A X	\$59,800	\$7,990 /yr	04-Nov-2015	1,496 cc	42,000 km	SUV	Available
Low Mileage Done. Not LCR Stock. New Tires And Battery. \$3,000 Detailing Package, 7 More Sessions. 1 Transfer Count From Family. 100% Accident Free. Highest Trade In With High Loan, Balloon Loan, In H...									
Posted: 08-Dec-2018 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel	1.5A X	\$62,800	\$8,280 /yr	22-Dec-2015	1,496 cc	42,812 km	SUV	Available
100% Not A Private Hire Unit Assured, One Of The Cheapest And Lowest Depreciation Unit In The Market! Previous Owner Upgraded To A New Mercedes. Affordable And Worthy Buy SUV To Own. Fabulous Conditio...									
Posted: 07-Dec-2018 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Customise Leather Upholstery for Vezel Leather Wrapping Package for Honda Vezel X/G/Hybrid/X Hybrid. Your 1 stop interior leather wrapping solution. More info about this product								
	Honda Vezel	1.5A X	\$63,000	\$8,670 /yr	17-Sep-2015	1,496 cc	25,500 km	SUV	Available
Well Maintained, Priced To Sell, Please Call/Sms For More Info, No Dealers Please. White On Red Leather Interior, Low Mileage Done.									
Posted: 07-Dec-2018 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel	1.5A X	\$63,800	\$8,480 /yr	11-Dec-2015	1,496 cc	39,500 km	SUV	Available
1 Owner, Well Maintained, Low Mileage, Very Fuel Economy, Always Parked In Shelter At Home / Workplace. Price Negotiable, Please Call To Arrange For Viewing Grey Premium Full Leather Seats, Pioneer HU...									
Posted: 04-Dec-2018 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel	1.5A X	\$63,800	\$8,480 /yr	08-Dec-2015	1,496 cc	56,985 km	SUV	Available
Accredited Company! One Owner Only. Enjoy Low Interest Rate! Non Grab/Uber Unit. Low Mileage! As Good As New, Accident Free, Very Well Maintained, High OMV And CDE! Low Maintenance! Accident Free! Chea...									
Fu Ylap Motor Trading									
Posted: 03-Dec-2018 Tags: 2015 Honda Vezel, 2015 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									

Compare

BH AUTO
Sin Ming Industrial Est
Sector C
Singapore 575636

Claim Reference: OD049
Assessment Number: BAC00055
Version: BHAUTOSP/1
Date Calculated: 13/12/2018 07:34

Full Report - V1
Registration: SKX5640M
Printed: 13/12/2018 15:34

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	BH admin	Date of Incident:	09/12/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	OD049	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:	SKX5640M	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	Vezel
Sub Model:	BASE MODEL
Model Sheet Number:	HVE 01
Registration:	SKX5640M
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM MODEL 2015	ELECT FOLDING MIRROR
FOG LAMPS	SIDE FLASHER
LED HEADLAMP	CHROME DOOR HANDLES
REAR PARKING SYSTEM	1.5 LTR 88KW
WHEELS 7J X 16 ALLOY	SIDE AIRBAGS
HEAD AIRBAG	BASECOAT CLEAR

Not known
1-B.1
Resurvey B4 paint
Ex B300h

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on	
	Inspection:	
Brakes Pedal Travel:	Date of Inspection:	13/12/2018
Place of Inspection:		
Pre-Accident Damage:		

Tyres Condition:

Tread Depth LHF:

Tread Depth LHR:

Damage Areas:

Tread Depth RHF:

Tread Depth RHR:

Direction of Impact:

- KKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



Signature:

Date:

BH AUTO

Claim Reference: OD049
 Assessment Number: BAC00055
 Version: BHAUTOSP/1
 Date Calculated: 13/12/2018 07:34

Full Report - V1
 Registration: SKX5640M
 Printed: 13/12/2018 15:34



Primary Impact
 Secondary Impact

Addresses**Cost Summary**

Total Labour	\$837.00
Total Paint/Material	\$173.46
Total Parts	\$6,904.70
Excess:	TBA
Grand Total Exc GST:	\$7,915.16
7 % GST:	\$554.06
Grand Total Inc GST:	\$8,469.22

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
 Price/Dent = \$45.00/HR

Repair /**Guide Number Repair Details**

		WU	Cost Price (\$)
NO NUMBER	RENEW FRONT PANEL	32.0	144.00
8101A2 ZAX	RENEW FRONT BUMPER	17.0	76.50
813110)	RENEW RADIATOR GRILLE	3.0	13.50
812100	RENEW BONNET	11.0	49.50
	INCLUDES: R + R BONNET AND REQUIRED ATTACHED PARTS ASSEMBLE		
8121B6)	R + R L/BONNET SEAL	3.0	13.50
8121B7)	R + R R/BONNET HINGE	3.0	13.50
NO NUMBER	R + R BOTH FRONT WINGS (BUMPER REMOVED)	17.0	76.50
	INCLUDES: R + R FRONT HEADLAMPS, SILL COVER AND REQUIRED ATTACHED PARTS.		
NO NUMBER	R + R L/FRONT SCREEN FRAME AIR GRILLE	1.0	4.50
NO NUMBER	R + R R/FRONT SCREEN FRAME AIR GRILLE	1.0	4.50
7421B0)	R + R WASHER RESERVOIR	2.0	9.00
NO NUMBER	RUST PROOFING BODY SHELL PART	2.0	
NO NUMBER	ANTIRUST TREATMENT FOR BONNET	1.0	
NO NUMBER	RIGHT FRONT WING RUST PROOFING	1.0	
710100	R + R BATTERY	3.0	13.50
1211E1	R + R AIR FILTER INTAKE PIPE	2.0	9.00
114100)	R + R RADIATOR	10.0	45.00
1151A2)	R + R L/FAN MOTOR	1.0	4.50
1151A1)	R + R L/FAN BLADE	1.0	4.50
616100)	R + R CONDENSER	2.0	9.00
620020	DRAIN + REFILL AIR CONDITIONING	7.0	31.50

LABOUR COST

BH AUTO

Claim Reference: OD049
 Assessment Number: BAC00055
 Version: BHAUTOSP/1
 Date Calculated: 13/12/2018 07:34

Full Report - V1
 Registration: SKX5640M
 Printed: 13/12/2018 15:34

Total Work Units	120.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	11.6HRS	\$522.00
Paint Labour	7.0HRS	\$315.00
Total Labour	18.6HRS	\$837.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$45.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- BASECOAT CLEAR		
340	FRT BUMPER SUPPORT NEW PART PAINTING	8.0	
471	BONNET NEW PART PAINTING	21.0	
742	R/F WING NEW PART PAINTING	9.0	
1009	FRONT PANEL CPL SURFACE PAINT	6.0	
283	FRONT BUMPER NEW PART PAINT K1R	10.0	
LABOUR COST - PAINT			
TIME(PAINT)		54.0	
Preparation Main Work Metal		11.0	
Preparation Comp. Work Plastic		5.0	
Preparation Work Multi Layer Paint		0.0	
Total Work Units (10WU/HR)		70.0	
Total Paintwork Labour		7.0HRS	\$315.00
MATERIAL COST - PAINT			Cost Price
New Part Painting			\$91.85
New Part Painting - Plastic K1R			\$43.30
Surface-/Blend Paint			\$11.21
Material-Const Main Work Metal			\$18.10
Material-Const Comp. Work Plastic			\$9.00
Total Excluding Pearlescent Uplift			\$173.46
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$173.46

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
471	1	BONNET	60100T8NT00ZZ		0% Bu 430.00*
481	1	BONNET INSULATION	74141T7YT00		0% Sm 80.00* X
492	1	BONNET LOCK	74120T7WA01		0% R 70.00* X
1002	1	BONNET SEAL LH	Renew		0% Sm 22.00* X
1003	1	BONNET SEAL RH	Renew		0% Sm 22.00* X
4465	1	CONDENSER	80110T7YF01		0% Bu Bu 360.00* X
283	1	FRONT BUMPER	71101T8NT00ZZ		0% Bu 210.00* ✓
282	1	FRONT LOWER BUMPER	04712T7WA90		0% Sm 120.00* X
1009	1	FRONT PANEL CPL	60400T8NT00ZZ		0% R 370.00* X
391	1	FRONT SPOILER	71110T7A000		0% R 45.00* X
340	1	FRT BUMPER SUPPORT	71130T8NT00ZZ		0% Bu 200.00* X
1000	1	FRT NUMBER PLATE	Renew		0% Bu 35.00* ✓
410	1	GRILLE	71121T8NT50		0% Bu 185.00* 7
431	1	GRILLE BADGE	75700TA0A00		0% Bu 18.00* 7
427	1	GRILLE MOUNTING KIT	USE SINGLE PARTS		0% Bu 25.00* 7
475	1	L/BONNET HINGE	60170T8NT01ZZ		0% R 40.00* X
513	1	L/BONNET SEAL	74128T7JH00		0% Sm 22.00* X

BH AUTO

Claim Reference: OD049
Assessment Number: BAC00055
Version: BHAUTOSP/1
Date Calculated: 13/12/2018 07:34

Full Report - V1
Registration: SKX5640M
Printed: 13/12/2018 15:34

511	1	L/BONNET SEAL	74192T7JH00	0%	Sm	22.00*	X
343	1	L/BUMPER CORNER BRKT	71190T7A000	0%	Di	22.00*	X 30
345	1	L/F AIR DUCT	71116T8NT50	0%	Sm	23.00*	X
561	1	L/F HEADLAMP CPL	33150T7SE11	0%	Sm	920.00*	X
347	1	L/F MOULDING	71166T8NT00	0%	Sm	15.00*	X
319	1	L/F UPP BUMPER BRKT	71198T7A000	0%	Sm	15.00*	X
789	5	L/F WING CLAMP KIT	934050601608	0%	Sm	30.00*	X
7789	1	L/FAN MOTOR	1903051YZ01	0%	Sm	190.00*	X
7767	1	L/FAN SHROUD	1901551YZ01	0%	Sm	90.00*	X
435	1	L/GRILLE TRIM	71128T8NT00	0%	net	23.00*	X
415	1	L/RAD-GRILLE BRACKET	71152T7A000	0%	Sm	14.00*	X
7793	1	L/RADIATOR FAN	19020R1AA01	0%	Sm	65.00*	X
787	1	L/WING MOULDING	74157T7MH01	0%	Sm	40.00*	X
351	1	LOWER FRONT GRILLE	71103T7JH00	0%	Sm	60.00*	X
476	1	R/BONNET HINGE	60120T8NT01ZZ	0%	Sm	40.00*	X
514	1	R/BONNET SEAL	74121T7JH00	0%	Sm	22.00*	X
512	1	R/BOONET SEAL	74142T7JH00	0%	Sm	22.00*	X
344	1	R/BUMPER CORNER BRKT	71140T7A000	0%	30 Di	22.00*	X
346	1	R/F AIR DUCT	71111T8NT50	0%	Sm	23.00*	X
562	1	R/F HEADLAMP CPL	33100T7SE11	0%	Sm	920.00*	X
348	1	R/F MOULDING	71161T8NT00	0%	Sm	15.00*	X
320	1	R/F UPP BUMPER BRKT	71193T7A000	0%	Sm	15.00*	X
742	1	R/F WING	60210T8NT00ZZ	0%	Sm	190.00*	X
790	5	R/F WING CLAMP KIT	934050601608	0%	Sm	30.00*	X
436	1	R/GRILLE TRIM	71123T8NT00	0%	cm	23.00*	X
416	1	R/RAD-GRILLE BRACKET	71151T7JH00	0%	Sm	14.00*	X
788	1	R/WING MOULDING	74107T7MH01	0%	Sm	40.00*	X
413	1	RAD GRILLE BRACKET	71150T7JH00	0%	cm	18.00*	X
424	1	RAD GRILLE COVER	71122T8NT50	0%	cm	145.00*	X
7761	1	RADIATOR	1901052XZ01	0%	Sm	770.00*	X
1001	1	RADIATOR COOLANT	Renew	0%	Sm	50.00*	X
411	1	UP/CVR RADIAT GRILLE	71129T7JH00	0%	Sm	35.00*	X
1436	1	WASHER RESERVOIR	76841T8NT01	0%	Sm	50.00*	X
1437	1	W-SCREEN WASHER PUMP	76846TF0013	0%	Sm	50.00*	X
f: OEM Parts			Sub Total			\$6,277.00	
g: Original			Mark Up From Cost	(10 %)		\$627.70	
h: Secondhand			Total Parts			\$6,904.70	
p: Parallel							
x: Exchange							

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras

\$0.00

Final Calculation

Total Parts	\$6,904.70
Labour	
Total Panel/Mechanical	\$522.00 441.00
Total Paintwork	\$315.00 364.50
Total Labour	\$837.00
Total Paint/Material Costs	\$173.46 167.47
Grand Total Excludes GST	\$7,915.16
GST @ 7 %	\$554.06
Grand Total Includes GST	\$8,469.22

7964.66

BH AUTO

Claim Reference: OD049

Assessment Number: BAC00055

Version: BHAUTOSP/1

Date Calculated: 13/12/2018 07:34

Full Report - V1

Registration: SKX5640M

Printed: 13/12/2018 15:34

Assessment Notes

BH AUTO
Sin Ming Industrial Est
Sector C
Singapore 575636

Claim Reference: OD049
Assessment Number: BAC00055
Version: BHAUTOSP/1
Date Calculated: 22/01/2019 07:44

Full Report - V1
Registration: SKX5640M
Printed: 22/01/2019 15:45

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	BH admin	Date of Incident:	09/12/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	OD049	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:	SKX5640M	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	HONDA
Model:	Vezel
Sub Model:	BASE MODEL
Model Sheet Number:	HVE 01
Registration:	SKX5640M
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM MODEL 2015	ELECT FOLDING MIRROR
FOG LAMPS	SIDE FLASHER
LED HEADLAMP	CHROME DOOR HANDLES
REAR PARKING SYSTEM	1.5 LTR 88KW
WHEELS 7J X 16 ALLOY	SIDE AIRBAGS
HEAD AIRBAG	BASECOAT CLEAR

Vehicle Condition



Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	13/12/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	
Tread Depth LHR:	Tread Depth RHR:	
Damage Areas:	Direction of Impact:	

BH AUTO

Claim Reference: OD049
 Assessment Number: BAC00055
 Version: BHAUTOSP/1
 Date Calculated: 22/01/2019 07:44

Full Report - V1
 Registration: SKX5640M
 Printed: 22/01/2019 15:45



Primary Impact
 Secondary Impact

Addresses**Cost Summary**

Total Labour	\$805.50
Total Paint/Material	\$167.47
Total Parts	\$2,988.70
Excess:	TBA
Grand Total Exc GST:	\$3,961.67
7 % GST:	\$277.32
Grand Total Inc GST:	\$4,238.99

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR
 Price/Dent = \$45.00/HR

Repair /**Guide Number Repair Details**

		WU	Cost Price (\$)
8101A2 ZAX	RENEW FRONT BUMPER	17.0	76.50
813110)	RENEW RADIATOR GRILLE	3.0	13.50
812100	RENEW BONNET	11.0	49.50
	INCLUDES: R + R BONNET AND REQUIRED ATTACHED PARTS ASSEMBLE		
8101B1)	R + R FRONT BUMPER SUPPORT	2.0	9.00
7121B6)	R + R R/HEADLAMP (BUMPER REMOVED)	4.0	18.00
	INCLUDES: ADJUST HEADLAMP		
8131B5	R + R L/F WING MOULDING	2.0	9.00
NO NUMBER	RUST PROOFING BODY SHELL PART	2.0	
NO NUMBER	ANTIRUST TREATMENT FOR BONNET	1.0	
NO NUMBER	RIGHT FRONT WING RUST PROOFING	1.0	
616100)	R + R CONDENSER	2.0	9.00
620020	DRAIN + REFILL AIR CONDITIONING	7.0	31.50
0742	REPAIR R/F WING	15.0*	67.50
1009	REPAIR FRONT PANEL CPL	35.0*	157.50

LABOUR COST

Total Work Units	102.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	9.8HRS	\$441.00
Paint Labour	8.1HRS	\$364.50
Total Labour	17.9HRS	\$805.50

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$45.00/HR

BH AUTO

Claim Reference: OD049
 Assessment Number: BAC00055
 Version: BHAUTOSP/1
 Date Calculated: 22/01/2019 07:44

Full Report - V1
 Registration: SKX5640M
 Printed: 22/01/2019 15:45

Guide Number	Description	WU	Cost Price (\$)
	- BASECOAT CLEAR		
340	FRT BUMPER SUPPORT NEW PART PAINTING	8.0	
471	BONNET NEW PART PAINTING	21.0	
283	FRONT BUMPER NEW PART PAINT K1R	10.0	
742	R/F WING REPAIR PAINTING <50%	10.0	
1009	FRONT PANEL CPL SURFACE PAINT	6.0	
LABOUR COST - PAINT			
	TIME(PAINT)	55.0	
	Preparation Main Work Metal	21.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	81.0	
	Total Paintwork Labour	8.1HRS	\$364.50
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$75.85
	New Part Painting - Plastic K1R		\$43.30
	Surface-/Blend Paint		\$11.21
	Repair Painting		\$10.01
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$167.47
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$167.47

PARTS

				Price Valid: 01/06/2015		
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
471	1	BONNET	60100T8NT00ZZ	Bu	0%	430.00*
4465	1	CONDENSER	80110T7YF01		0%	385.00*
283	1	FRONT BUMPER	71101T8NT00ZZ		0%	210.00*
340	1	FRT BUMPER SUPPORT	71130T8NT00ZZ		0%	200.00*
1000	1	FRT NUMBER PLATE	Renew		0%	35.00*
410	1	GRILLE	71121T8NT50		0%	185.00*
431	1	GRILLE BADGE	75700TA0A00		0%	18.00*
427	1	GRILLE MOUNTING KIT	USE SINGLE PARTS		0%	25.00*
343	1	L/BUMPER CORNER BRKT	71190T7A000		0%	30.00*
435	1	L/GRILLE TRIM	71128T8NT00		0%	23.00*
787	1	L/WING MOULDING	74157T7MH01		0%	40.00*
344	1	R/BUMPER CORNER BRKT	71140T7A000		0%	30.00*
562	1	R/F HEADLAMP CPL	33100T7SE11		0%	920.00*
436	1	R/GRILLE TRIM	71123T8NT00		0%	23.00*
413	1	RAD GRILLE BRACKET	71150T7JH00		0%	18.00*
424	1	RAD GRILLE COVER	71122T8NT50		0%	145.00*
f: OEM Parts		Sub Total				\$2,717.00
g: Original		Mark Up From Cost		(10 %)		\$271.70
h: Secondhand		Total Parts				\$2,988.70
p: Parallel						
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Total Extras \$0.00

Final Calculation

Total Parts \$2,988.70

BH AUTO

Claim Reference: OD049
Assessment Number: BAC00055
Version: BHAUTOSP/1
Date Calculated: 22/01/2019 07:44

Full Report - V1
Registration: SKX5640M
Printed: 22/01/2019 15:45

Labour

Total Panel/Mechanical
Total Paintwork

\$441.00
\$364.50

Total Labour

\$805.50

Total Paint/Material Costs

\$167.47

Grand Total Excludes GST

\$3,961.67

GST @ 7 %

\$277.32

Grand Total Includes GST

\$4,238.99

Assessment Notes



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

TO: BH AUTO SERVICES PTE LTD

BLK 1, SECTOR C,
SIN MING INDUSTRIAL ESTATE
#01-111/113/115/117 S(575636)
WEN ZHENG

NO: HLI9060829

PAGE: 1

DATE: 28/12/2018

A/C CODE: LDBH111

TERMS: CR

P/O NO: 2603

Part No	Description	Location	Qty	Unit Price	Amount
H71140-T7A-000	344 FR.BPR.BEAM RH	H2J1	1	SIN 30.00	SIN 30.00
71190-T7A-000	343 FR.BPR.BEAM LH(T7J)	H2J1	1	30.00	30.00
H80110-T7A-J01	4465 A/CON CONDENSER	HU3-80	1	385.00	385.00
TOTAL QUANTITY:			3	TOTAL	SIN 445.00
				ADD GST @ 7%	31.15
				GRAND TOTAL	<u>SIN 476.15</u>

VEZEL SKX 5640 M

print:2 / MCNK / 28/12/2018 10:35:26 AM

LESMA: MCNK


as document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY





合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

TO: BH AUTO SERVICES PTE LTD

BLK 1, SECTOR C,
SIN MING INDUSTRIAL ESTATE
#01-111/113/115/117 S(575636)
SKX 5640 M

NO: HLI9060812

PAGE: 1

DATE: 26/12/2018

A/C CODE: LDBH111

TERMS: CR

P/O NO: 2600

Part No	Description	Location	Qty	Unit Price	Amount
H71121-T7A-000	410 FR.GRILLE	HU3-35	1	SIN 185.00	SIN 185.00
5700-S9A-G00	431 GRILLE EMBLEM(TA0)	HIM6	1	18.00	18.00
H91505-TM8-003	427 CLIP	HIP5	10	2.50	25.00
H71123-T7A-000	436 FR.GRIL LENS MLDG RH	HIFT1	1	23.00	23.00
H71128-T7A-000	435 FR.GRIL LENS MLDG LH	HIFT1	1	2.00 23	2.00 23
H71122-T7A-000	424 FR.GRILLE LENS	HU3-35	1	145.00	145.00
H71150-T7J-H00	413 FR.GRILLE GARNISH,RR.CTR	H2J3	1	18.00	18.00
H71130-T7A-000ZZ	340 FR.REINFORCEMENT(010ZZ)	HU3017-2	1	200.00	200.00
H74157-T7M-H01✓	787 FR.W/H ARCH PROT.LH	HU2R21S	1	40.00	40.00

TOTAL QUANTITY:

18

TOTAL

SIN 656.00

ADD GST @ 7%

45.92

GRAND TOTAL

SIN 701.92

EZEL

at / MCNK / 26/12/2018 4:19:53 PM

LES MAN: MCNK

s document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E

GOODS RECEIVED BY





合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

TO: BH AUTO SERVICES PTE LTD

BLK 1, SECTOR C,
SIN MING INDUSTRIAL ESTATE
#01-111/113/115/117 S(575636)
WEN ZHENG

NO: HLI9060796

PAGE: 1

DATE: 24/12/2018

A/C CODE: LDBH111

TERMS: CR

P/O NO: 2598

Part No	Description	Location	Qty	Unit Price	Amount
				<u>SIN</u>	<u>SIN</u>
H60100-T8N-T00ZZ	BONNET 471	HDS	1	430.00	430.00
..1101-T7J-H00ZZ	FR.BUMPER 283	HDS	1	210.00	210.00
H33100-T7S-E11	FR.HEADLAMP ASSY RH 562	HU3-58	1	920.00	920.00
TOTAL QUANTITY:			3	TOTAL	SIN 1,560.00
				ADD GST @ 7%	109.20
				GRAND TOTAL	<u><u>SIN 1,669.20</u></u>

EZEL
SKX 5640 M

27 Dec 2018

int / MCNK / 24/12/2018 10:27:53 AM

ALLESMAN: MCNK

this document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E

GOODS RECEIVED BY

SERVICE REQUESTS MESSAGES CLAIMS

<< Service Request Details

Claim

S6M015XQ

Reference

CS/ASM18022502K1d3s2 

Loss Date

December 9, 2018

Request Date

December 14, 2018

Due Date

December 14, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Finish the work

Complete Work

Move

Document Type

Document Sub Type

Upload Documents

Vehicle Information

Incident Vehicle Registration #

SKX5640M

Make

HONDA

Model

VEZEL 1.5

Blk

1

Sin

Ming Industrial, . .

Service Address

575636

Primary Contact/Insured

TANG KOK CHIEN
79D TOA PAYOH CENTRAL, #05-59, 314079, Singapore
98554768
mervin.tang@hotmail.com

Claim Handler

KHONG Lynn
68804892
lynn.khong@axa.com.sg

Additional Instructions

BH Auto OD Excess \$300

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Messages	Invoices	History	Documents	
Assessment	Metrics	Notes		

SERVICE REQUESTS MESSAGES CLAIMS

 Service Request Details

Claim	S8M015XQ	Actions		AW		
Reference		Next Step	Finish the work	Complete Work		
CS/ASM18022502Ktd3s2 		More				
Loss Date						
December 9, 2018						
Request Date						
December 14, 2018						
Due Date						
December 14, 2019						
Vendor Name						
LKK AUTO CONSULTANTS PTE LTD (OO)		Type of Loss				
Own Damage		Services				
Accelerated survey and authorize						
		Vehicle Information				
		Incident Vehicle Registration #	SKX5640M	Service Address		
		Make				
		HONDA	Model	Blk 1		
		VEZEL 1.5	Ming Industrial, ...	Sin 575636		
		Primary Contact/Insured				
		TANG KOK CHIEN				
		79D TOA PAYOH CENTRAL #05-59, 314079, Singapore				
		98554768				
		mervin.tang@hotmail.com				
		Claim Handler				
		KHONG Lynn				
		68804892				
		lynn.khong@axa.com.sg				
Additional Instructions		Messages	Invoices	History	Documents	
BH Auto OD Excess \$300		Assessment	Metrics	Notes		
CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary	
Workshop Details													
General Details				Workshop Details									
Involving		1 2015 HONDA VEZEL 1.5 (SX5640M)											
Date of Loss		December 9, 2018											
Time of Loss		11:20											
Loss Description		SX5640M (INSO) C/W REAR OF SLP8491L (TP)											
Comment													
		Total Rebate Amount		46543									
		Nett Loss Amount		\$15,457.00									
		Assigned Workshop		LKK AUTO CONSULTANTS PTE. LTD (OD)									
		Days of work completion		7									

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	SKXS640M	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	12/17/2015
Mileage	32920	Age of Vehicle	2
Driver Details			
CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	POST SURVEY INFORMATION
Manufacturing Year	2015	CATEGORY	FNOL INFORMATION
Make	HONDA	Driver Name	TANG KOK CHIEN
Model	VEZEL 1.5	Date of Birth	December 1, 1979
Type	VEZEL 1.5X CVT	Age	39
Type of Paint		Occupation	Unknown
Chassis No	RU11104451	Education Qualification	Other
Engine No	L15B4024453	Driving Experience	13
Engine Capacity	1496 cc	Driver License #	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *	12/17/2018		General condition	Good
Total Loss	Yes	No	Steering (Serviceable)	Yes No
Towing Charges	0		Footbrake (Serviceable)	Yes No
Voluntary Excess	0		Handbrake (Serviceable)	Yes No
Compulsory Excess	300		Engine Modification	Yes No
Young/Inexperienced/Unlicensed Driver Excess	0		Pre-accident condition	Good
Other Excess				

Tyre Condition

Age of Tyres		Spare wheel	
Front Tyre Size	215/60R16	Rear Tyre Size	215/60R16
Front left side	DUNLOP 2mm	Rear left side	DUNLOP 7mm
Front right side	DUNLOP 2mm	Rear right side	DUNLOP 7mm

SERVICE REQUESTSMESSAGESCLAIMS

Assessment Details

General & Workshop Details: Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

ADD

APPROVE

DENY

SUBMIT ALL

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1	1			BONNET (10%) (WCP)			Buckled	473				473	Reviewing	
	2	1			BONNET INSULATION (WCP)			Serviceable	0				0	Reviewing	
	3	1			BONNET LOCK (WCP)			Repair	0				0	Reviewing	
	4	1			BONNET SEAL LH (WCP)			Serviceable	0				0	Reviewing	
	5	1			BONNET SEAL RH (WCP)			Serviceable	0				0	Reviewing	
	6	1			CONDENSER (10%) (WCP)			Buckled	423.5				423.5	Reviewing	
	7	1			FRONT BUMPER (10%) (WCP)			Buckled	231				231	Reviewing	
	8	1			FRONT LOWER BUMPER (WCP)			Serviceable	0				0	Reviewing	
	9	1			FRONT PANEL CPL (WCP)			Repair	0				0	Reviewing	
	10	1			FRONT SPOILER (WCP)			Serviceable	0				0	Reviewing	

EDIT	S/N	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR / BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	25	1			L/FAN MOTOR (WCP)			Serviceable	0				0	Reviewing	
	26	1			L/FAN SHROUD (WCP)			Serviceable	0				0	Reviewing	
	27	1			L/GRILLE TRIM (10%) (WCP)			Necessary	25.3				25.3	Reviewing	
	28	1			L/RAD- GRILLE BRACKET (WCP)			Repair	0				0	Reviewing	
	29	1			L/RADIATOR FAN (WCP)			Serviceable	0				0	Reviewing	
	30	1			L/MING MOULDING (10%) (WCP)			Necessary	44				44	Reviewing	
	31	1			LOWER FRONT GRILLE (WCP)			Serviceable	0				0	Reviewing	
	32	1			RIBONNET HINGE (WCP)			Repair	0				0	Reviewing	
	33	1			RIBONNET SEAL (WCP)			Serviceable	0				0	Reviewing	
	34	1			RIBONNET SEAL (WCP)			Serviceable	0				0	Reviewing	
	35	1			R/BUMPER CORNER BRKT (10%) (WCP)			Damaged	33				33	Reviewing	
	36	1			R/F AIR DUCT (WCP)			Serviceable	0				0	Reviewing	
	37	1			R/F HEADLAMP CPL (10%) (WCP)			Cracked	1012				1012	Reviewing	
	38	1			R/F MOULDING (WCP)			Serviceable	0				0	Reviewing	

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TOTAL PANEL/MECHANICAL	441	0	0	Reviewing		
		2		TOTAL PAINTWORK	364.5	0	0	Reviewing		
		3		TOTAL PAINT / MATERIAL COSTS	167.47	0	0	Reviewing		

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
------	-------	------	--------	--------	---------	--------



DAYS OF REPAIR

1

Reviewing

4



SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Claim Amount \$3,661.67

Claim Amount \$3,661.67

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$2,988.70	\$2,988.70
Labour	\$972.97	\$972.97
Excess	-\$300.00	-\$300.00

Submit for Review