

Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s Complete
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 860k
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLF 08737 Yr Regn: 09, 16
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mit Lancer EX c.c. 1590
 Colour: n. Black A/C: Insured / Std / NI / NA
 Sp. Reading: 51237 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JMYPRCYIAGW 005852
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modl: NI / S/Rim / STD / R/Rim or _____
 Tyre Size: F: 205/60R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 7 mm Rear R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 11/12/18 D.O.I. 18/12/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
None N/S
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
19/12	File pass to Customer, EST not ready
11/01/19	Confirmed HS \$ 1,900/- @ 3 days with Kenneth. (\$ 2,971.26 Red. - 61%)

RECEIVED 11 JAN 2019

Date/Time, File Pass to?

11/01/19

: Prel. Report
 : Final Report

1) Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:

Transportation:

S - RS - SI

Photos

Others

TOTAL

135
50
50
20
255

Report Format :

Lump Sum / I.B.I: (\$ 1,900/- HS)

MOTOR SURVEY ASSIGNMENT

Date	13-12-2018	Our Ref No. D18008821MFSH
Accident Date	11-12-2018	Claim Type. Third Party
Insured Vehicle	SHB2251Z	Third Party Vehicle. SLF6873J
Survey Location	176 SIN MING DRIVE #03-14SIN MING AUTOCARE COMPLEX	
Contact Person.	LILY/LI HUI	
Contact No.	64550012/ 64550012	Fax No. 65073849
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	COMPLETE VMS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 20 December 2018 5:07 PM
To: 'Sithara'; 'CWS Motor Claims'
Cc: SUR; Admin-D (LKKAuto); assignments
Subject: RE: SURVEY ASSESSMENT - D18008821MFSH/1

Dear Sithara,

Please be informed that we have inspected the vehicle SLF 6873J on 18/12/2018.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 14 December 2018 10:51 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008821MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 13 December, 2018 5:41 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008821MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7306I
Vehicle Details	
Vehicle No.:	SLF6873J
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jan 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER EX 1.6 AT LED TAIL LAMP
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	4A92CJ8098
Chassis No.:	JMYSRCY1AGU005852
Maximum Power Output:	86.0 kW (115 bhp)
Open Market Value:	\$14,756.00
Original Registration Date:	06 Sep 2016
First Registration Date:	06 Sep 2016
Transfer Count:	2
Actual ARF Paid:	\$14,756.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Sep 2026
PARF Rebate Amount:	\$11,067.00
Intended COE Rebate Details	
COE Expiry Date:	05 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,503.00
COE Rebate Amount:	\$40,169.00
Total Rebate Amount:	\$51,236.00

The information contained herein is correct as at 11 Jan 2019

OK



Ks

COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
 176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
 (Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
 lily@completevms.com.sg ()
 lihui@completevms.com.sg ()

MUHAMMAD FAJAR ABDUL JALIL
 BLK 407 JURONG WEST STREET 42 #10-649
 SINGAPORE 640407

Estimate : ES006545

Attention : THE OWNER
 Contact : 98296981

Date : 18/12/2018
 Vehicle Num. : SLF6873J
 Make/Model : MITSUBISHI LANCER 1.6-2016
 Chassis/Eng# : JMYSRCY1AGU005852/4A92CJ8098
 Accident Date : 11/12/2018
 Claim No. :
 Reference :
 Policy No. :

Not Authorized
11/12/1900h
Resuming After Paint
3 days

S/N Quantity Particular Unit Price Amount S\$

1.	1	NETT ITEMS :		
2.	1	REAR BUMPER	815.00	✓
3.	6	REAR BUMPER TOP BRACKET	65.00	—
4.	2	REAR BUMPER CLIP		—
5.	1	REAR BUMPER SIDE RETAINER		X
6.	1	REAR BUMPER REINFORCEMENT	210.00	✓
7.	2	REAR BUMPER REFLECTOR L/H		✓
8.	1	REAR NUMBER PLATE LAMP		X
9.	1	REAR END PANEL		X
10.	1	REAR END PANEL TOP GARNISH		X
		REAR END PANEL BUZZER		✓
		Nett Total S\$:	2,781.40	
		10.00% Discount S\$:	278.14	
			2,503.26	
1.	1	SPECIAL NETT ITEMS :		
2.	1	REVERSE SENSOR SET	280.00	✓
3.	1	REAR NUMBER PLATE	25.00	✓
		REAR NUMBER PLATE HOLDER	33.00	✓
		Special Nett Total S\$:	338.00	
		LABOUR :		
		RUST PROOFING TREATMENT	100.00	X
		SPRAY PAINT DAMAGED AREA AFFECTED	950.00	✓
		TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS	950.00	✓
		Labour Total S\$:	2,030.00	

SingDollars : Four Thousand Eight Hundred Seventy-One & Cents Twenty-Six Only

Total S\$: 4,871.26

=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18022503/Ksbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-01-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 2251Z	Veh. Inspected	SLF 6873J
Policy No.		Coverage (\$)	0.00
Claim No.	D18008821MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	13/12/2018
2. Vehicle Particulars & Condition			
Make & Model	MITSUBISHI LANCER EX (A)	c.c	1590
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JMYSRCY1AGU005852	Colour	METALLIC BLACK
Odometer	51237	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	YOKOHAMA	7 mm
L/H Front Tyre	205/60 R16	YOKOHAMA	7 mm
R/H Rear Tyre	205/60 R16	YOKOHAMA	7 mm
L/H Rear Tyre	205/60 R16	YOKOHAMA	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/12/2018	Inspection Date	18/12/2018
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 6873J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (N)	BUCKLED / CRACKED	854.00	815.00
1	REAR BUMPER TOP BRACKET (N)	BENT	185.00	65.00
6	REAR BUMPER CLIP @\$6.00 (N)	NECESSARY	36.00	36.00
2	REAR BUMPER SIDE RETAINER @\$41.20 (N)	SERVICEABLE	82.40	-
1	REAR BUMPER REINFORCEMENT (N)	BENT	383.00	210.00
1	REAR BUMPER REFLECTOR L/H (N)	MTG CRACKED	65.00	65.00
2	REAR NUMBER PLATE LAMP @\$83.00 (N)	SERVICEABLE	166.00	-
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	663.00	-
1	REAR END PANEL TOP GARNISH (N)	SERVICEABLE	161.00	-
1	REAR END PANEL BUZZER (N)	CRACKED	186.00	186.00
	LESS 10% DISCOUNT		-278.14	-137.70
			2,503.26	1,239.30
SPECIAL NETT ITEMS				
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR NUMBER PLATE HOLDER (SN) }	BENT	33.00	45.00
1	REAR NUMBER PLATE (SN) }	BENT	25.00	-
			338.00	245.00
LABOUR				
	RUST PROOFING TREATMENT.	NOT NECESSARY	100.00	-
	SPRAY PAINT DAMAGED AREA AFFECTED.		980.00	450.00
	TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		950.00	450.00
	-		-	-
	-		-	-
	-		-	-
			2,030.00	900.00
GRAND TOTAL			4,871.26	2,384.30



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00
---	--	--	----------

Report Ref No. CS/FCI18022503/Ksbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.