

ASS. REC. BY:

REF:

CS/CTI18022518/Krd3n2

Special Instruction:

Surveyor

Meinen

Kenneth

ASSIGNMENT (Office)

From (Person):

Ong chin Kiat

of

CTI

Date/Time:

14/12/18 @ 2:16pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 7779C

Insured:

GBC 4400M

at Workshop m/s

Carplus Auto

Tel:

6451 6602

9748 1077

of

160 Sin Ming Drive # 04-06

Policy No:

DMCVSN/813271800

Claim No:

SNM18005783C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

2:27pm @ 14/12/18

Person Contacted:

Christine

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLD 7779C - NA/CTI18022452/K4

DOA: 12/12/18

GBC 4400M - NA/CTI18022452/K4

DOA: 12/12/18

1/1 Pm @ 3600 / email

3/1/19

@409pm LS \$3650 confirmed with Christine (Red 5351.47, 58b)

ASS. REC. BY:

REF:

C721

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5-6 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLD 7779C

Yr Regn:

06, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Hammer

C.G.

1986

Colour:

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

39405

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZSU 60

0074162

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

R:

225/85R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

5

mm

L/Bal.

7

mm

L/Bal.

5

mm

D.O.A.

12/12/18

D.O.I.

14/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/12 File pass to Catherine

RECEIVED 04 JAN 2019

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trlp:

1

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

merimen

Lump Sum / I.B.I. (\$

3850/-

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Dec 2018		14 Dec 2018 14:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	D'SWIFT, Co. Reg. No.: -		
Main Claimant:	CHAU TSZ HO, ID: S8070760F		
Vehicle Reg. No.:	SLD7779C	Date of Loss:	12/12/2018 18:00 - :59
Claim Type:	TP / SNM18D05783C02	Policy/Cover Note No.:	DMCVSN1813271800 (Comprehensive)
Vehicle Reg. No. (Insured):	GBC4400M	Policy No. (Claimant):	MT102281
		Excess:	S\$0.00
Repairer:	CARPLUS AUTO PTE LTD (HQ) 160 SIN MING DRIVE #04-06, SIN MING AUTOCITY, 575722 Sin Ming - Tel: 64516602		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/12/2018]		
Driver/Custodian (Insured):	LIM SI HONG, JASON (LIN SIHONG, JASON) (33 / Male), NRIC: S8533757B, Tel: +6598562844		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

(Draft)

MLHM18160655 / Lai Hui (Meng Kee) Motor Pte Ltd - Sin Ming
 ENTRY DATE & TIME: 13/12/2018 09:49
 SUBMITTED BY: [To Be Confirmed]

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 13/12/2018 09:49
 Date Of Accident 12/12/2018 18:50
 Exact Location Of Accident MCE TUNNEL ALONG TANJONG RHU
 Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLD7779C
Insured/Policyholder
 Name Of Registered Owner CHAU TSZ HO
 NRIC No S8070760F
 Email Address CHAUTSZHO@GMAIL.COM
 Mobile Phone No (LOCAL) +65-98458858
 Alternative Phone No Others-98458858

Vehicle Particulars

Manufacturer TOYOTA
 Model HARRIER
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company TOKIO MARINE INSURANCE SINGAPORE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number MT102281
 Cover Note Number

Driver

Name of Driver CHAU TSZ HO
 NRIC No S8070760F
 Date Of Birth 04/12/1980
 Occupation INDOOR
 Date Of Driving Pass 03/12/2007
 Driving Experience 11 YEARS AND 0 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-98458858
 Fax Number
 Contact Number OTHERS-98458858
 Email Address CHAUTSZHO@GMAIL.COM
 Address 17 PASIR RIS RIS
 #06-35

Postcode	518088
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : WANGELIN SUM WAN PING Gender: : Female

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC4400M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LIM SI HONG, JASON
NRIC/Passport Number	S8533757B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

A-SLO7779C

B-GB C44001



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MCE Tunnel along Tuiping Rd @ 6.49pm

12/201

I was driving along MCE Tunnel "Tuiping Rd" & it was congested. Due to the heavy traffic, I was driving at a really low speed I came to a stop when vehicle B suddenly hit on my back.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 13 DEC 2013

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

Poh Kwee Choo

NRIC/FIN No.:

S6840583A

CARPLUS**AUTO PTE LTD****ESTIMATE**

Not Authorized
L1 Imp 836001
Resurvey After Paint

5- days

96810663

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3, Anson Road #16-00

Springleaf Tower

Singapore 079909

Fax : 6224 7175

Attn: Claim Department

Date: 13.12.2018

OUR REF CP/121218/SLD7779C/18
VEHICLE NO SLD7779C
MODEL TOYOTA HARRIER 2.0 AUTO

PARTS

1 PC Rear Boot
 1 PC Rear Boot Emblem (Harrier)
 1 PC Rear Boot Glass Moulding
 1 PC Rear Boot Lock
 1 PC Rear Bumper *1381.50*
 2 PCS Rear L/R Bumper Retainer @ S\$98.80
 1 PC Rear Bumper Sponge
 1 PC Rear End Panel
 2 PCS Rear L/R Fender @ S\$1,306.40
 30 PCS Clips @ S\$3.21

15

Less: - 25%

Bu \$1,465.40 ✓
mc \$77.20 —
mc \$99.20 —
mc \$503.50 —
Bu \$1,832.50 ✓
old d.i \$197.60 ✓
cm \$125.50 ✓
R \$765.30 X
R \$2,612.80 X
mc \$96.30 ✓ *48.15*
 \$7,775.30
 \$1,943.83
 \$5,831.47

Rear Reverse Camera *Sense*
 Tuff Kote
 Check Wiring
 Sealant
 Dismantle & Refix Upholstery
 Dismantle & Refix Rear Glass

nd \$300.00 *SN 200m*
 \$80.00 *39*
 \$80.00 *201*
mc \$80.00 *405m*
 \$180.00 *60h*
 \$150.00 *1201*

LABOUR

Being labour to dismantle & renew the above mentioned parts
 Respray Painting

\$1,000.00 *5501*
 \$1,500.00 *10001*

Total**\$9,201.47**

If any further damaged are found upon dismantling,
 you will be advised accordingly.

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

160 Sin Ming Drive #04-06 Sin Ming AutoCity Singapore 575722
 Telephone : 6451 6602 • Facsimile : 6451 6902 • E-mail : carplus@singnet.com.sg

Company Regn. No. 200303611H

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18022518/KVD3N2

Date: 04/01/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1813271800
Claimant Vehicle No :	SLD7779C	Insured Vehicle No :	GBC4400M
Date of Loss:	12/12/2018	Nature of Claim:	TP
		Claim No:	SNM18D05783C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD7779C	Engine No:	3ZRB745358
Make & Model:	TOYOTA HARRIER, 2.0 (A)	Chassis No:	ZSU600074162
Reg. Date:	28/06/2016 (Man. Year: 2016)	Odometer:	39405 km
Colour:	Metallic Pearl White		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,211.47	3,089.44	3,122.03	50.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,990.00	1,780.00	1,210.00	40.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,201.47	4,869.44	4,332.03	47.08
Approved Total (Overridden) (\$\$)		3,850.00		
Nett Amount (\$\$)	9,201.47	3,850.00	5,351.47	58.16

INSPECTION

Date of Assignment:	14/12/2018	
Date Inspected:	14/12/2018	Inspected At:
		CARPLUS AUTO PTE LTD (HQ) 160 SIN MING DRIVE #04-06, SIN MING AUTOCITY Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2019)
Parts: M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLD7779C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	1,465.40 FL	*1,465.40 FL
2	1		*REAR BOOT EMBLEM (HARRIER)	Necessary	77.20 FL	*77.20 FL
3	1		*REAR BOOT GLASS MOULDING	Necessary	99.20 FL	*99.20 FL
4	1		*REAR BOOT LOCK	Dented	503.50 FL	*503.50 FL
5	1		*REAR BUMPER	Buckled	1,832.50 FL	*1,381.50 FL
6	1		*REAR L/R BUMPER RETAINER	O/s Distorted	197.60 FL	*98.80 FL
7	1		*REAR BUMPER SPONGE	Cracked	125.50 FL	*125.50 FL
8	1		*REAR END PANEL	Repair	765.30 FL	*- FL
9	2		*REAR L/R FENDER	Repair	2,612.80 FL	*- FL
10	1		*CLIPS (30 Pcs)	Necessary (15 Pcs only)	96.30 FL	*48.15 FL
11	1		*REAR REVERSE SENSOR	Dented	300.00 FS	*200.00 FS
12	1		*SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,155.30	4,039.25
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,943.83	949.81
Total Parts (\$\$)	6,211.47	3,089.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TUFF KOTE	New	80.00	30.00
2	CHECK WIRING	New	80.00	20.00
3	DISMANTLE & REFIX UPHOLSTERY	New	180.00	60.00
4	DISMANTLE & REFIX REAR GLASS	New	150.00	120.00
5	BEING LABOUR TO DISMANTLE & RENEW THE ABOVE MENTIONED PARTS	New	1,000.00	550.00
6	RESPRAY PAINTING	New	1,500.00	1,000.00
Gross Labour Cost (\$\$)			2,990.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >