















**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                              | Lab.Type | Repairer's      | Amount          |
|--------------------------------|----------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                          |          |                 |                 |
| 1                              | TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD,KNOCK & ALIGN      | New      | 1,600.00        | 520.00          |
| 2                              | TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA              | New      | 1,400.00        | 600.00          |
| 3                              | TO RUST PROOF ACCIDENT AFFECTED AREA                     | New      | 160.00          | 30.00           |
| 4                              | TO RNR STICKER ON ACCIDENT AFFECTED AREA                 | New      | 1,000.00        | -               |
| 5                              | TO RNR REAR BOOT MECHANISM                               | New      | 250.00          | 60.00           |
| 6                              | TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS            | New      | 400.00          | 80.00           |
| 7                              | TO RNR REVERSE SENSOR & CHECK FUNCTION                   | New      | 120.00          | 50.00           |
| 8                              | TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS               | New      | 200.00          | -               |
| 9                              | TO CHECK WIRING LAYOUT AND TAILLAMP FUNCTION             | New      | 120.00          | 20.00           |
| 10                             | TO DO DIAGNOSIS AND RESET,REPROGRAM OR CODING FAULT CODE | New      | 400.00          | -               |
| 11                             | TO DO CODING FOR TAILLAMP                                | New      | 600.00          | -               |
| <b>Gross Labour Cost (S\$)</b> |                                                          |          | <b>6,250.00</b> | <b>1,360.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >