

22/03/2007

ASS. REC. BY:

REF: CS/CTI18022530/Uvd3n2 Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time: 14/12/2018 @ 1:42pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8LX 7109G

Insured:

SKT 9267C

at Workshop m/s

Precise Auto

Tel:

67457367

of

1. Kaki Bukit Ave. 6 # 02-34 Autobay

Policy No:

DMPESN1825151800

Claim No:

SNM18D05750G02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 11/12/2018

CA / REV / REP. / REV 24 HRS / up

H.O.D. Endorsement:

Date/Time:

2:16pm @ 14/12/18

Person Contacted:

Yeu Hong

Vehicle:

IN / U?

Date/Time

Action/Instruction (✓) Estimate

8LX 7109G - CS/CTI18022455/Awb

DOA: 11/12/2018

SKT 9267C - NA/CTI18022386/24

DOA: 11/12/18

(08/11/13) wef

ASS. REC. BY: Merimen

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX 7109Gat Workshop m/s precise

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 41

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 12 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: Dep 13500

Date / Time Action / Instruction

police report 14/1/19 14/1/19next 1743814/1/19 confirmed 1/5 @ 16.00 with yan hee (Red 18, 214-80, 5590)

RECEIVED 15 JAN 2019

Veh No: SLX 7109G Yr Regn: 27/10/2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Mer Benz C180K c.c. 1597Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 72256 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2040452A421224

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45ZU17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 11/12/18 D.O.I. 14/1/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rpt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 12

1) _____

☐ : Final ReportResurvey No. of Trip: 2

Date/Time, File Return to?

2) 15/1 - typistAdd Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: merimenLump Sum / I.B.I. (\$) 16,500/-

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Dec 2018		14 Dec 2018 13:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	XU WEISHI , ID: S2724165D
Vehicle Reg. No.:	SLX7109G
Claim Type:	TP / SNM18D05750C02
Vehicle Reg. No. (Insured):	SKT9267C
Policy/Cover Note No.:	DMPCSN1825151800
Policy No. (Claimant):	DMPCSN3035201800
Excess:	S\$0.00
Repairer:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36, 417883 Kaki Bukit - Tel: 67457367
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/12/2018]
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Do you clean your
car fuel system?

c180

Price Range ▼

Depreciation ▼

2010 ▼

Vehicle Type ▼

Home » Used Cars » MS Carz » Mercedes-Benz C-Class C180K

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Mercedes-Benz C-Class C180K

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price	\$40,800	
Depreciation	\$12,920 /yr View models with similar depreciation	?
Reg Date	19-Nov-2010 (1yr 11mths 1day COE left)	
Manufactured	2010	?
Mileage	-	
Transmission	Auto	
Engine Cap	1,597 cc	
Road Tax	\$742 /yr	?
Power	115.0 kW (154 bhp) View specs of the Mercedes-Benz C-Class Saloon (2002-2006)	
Curb Weight	1,500 kg	?
Features	1.6L Inline 4 Cylinders Supercharged Engine, 5 Speed Automatic Transmission, Cruise Control, Auto Headlights, Electric Seat	
Accessories	Leather Seats, AMG Rims, Factory Fitted Audio System, Reverse Sensors And Camera, Fog Lamps, Auto Side Mirror Indicators. Retractable Mirrors.	
Description	Cheapest In Town! Getting A Safety, Superb Handling, Comfortable For You And Your Family! No Repair Needed. Is In A Very Good Condition. High Loan Available, High Trade In Welcome. Don't Miss. Come To Have A Ride. Call Or Text Our Sale For More Info Before It's Gone	
COE	\$34,001	?
OMV	\$31,893	?
ARF	\$31,893	?



Seller Information

Company

Address

Location

Contact Person(s)

Compare



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more

Home » Used Cars » Direct Owners » Mercedes-Benz C-Class C180 CGI

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Leasing



Mercedes-Benz C-Class C180 CGI

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price \$43,888

Depreciation \$13,430 /yr

View models with similar depreciation

Reg Date 12-Oct-2010

(1yr 9mths 24days COE left)

Manufactured 2010

Mileage -

Transmission Auto

Engine Cap 1,796 cc

Road Tax \$974 /yr

Power 115.0 kW (154 bhp)

View specs of the Mercedes-Benz C-Class Saloon (2002-2006)

Curb Weight 1,495 kg

Features 1.8L CGI Inline 4 Cylinder Turbocharged Engine, 156BHP, 250NM, 5 Speed Auto, 6 x SRS Airbags, 4 x ABS Disc Brakes, Cruise Control. 0 To 100Km/H: 8.5s.

Accessories 17" Original Alloy Wheels, Grey Leather Upholstery, 2 x Electric Seats, Retractable Side Mirrors, Reverse Camera And Sensors, Rear Knockdown Seats.

Description CGI Model. More Powerful Than Kompressor Model. Regularly Serviced Using Original Parts, 90% Parked In Shelter, 4 x New Tyres, 100% Stock Condition With No Modifications. Major Servicing Just Done! Owner Selling Due To Upgrade Price Slightly Negotiable Only. SMS/Whatsapp Only.

COE \$44,129

OMV \$38,917

ARF \$38,917



Seller Information

Contact Person(s)

Contact No.

Enquiry

USEFUL FORMS

» Indemnity form

» Receipt

» Ownership Transfer

Instructions on consumer deal

Compare




Wide selection of
Inchcape Certified
Pre-owned
LEXUS & TOYOTA

Christmas Sale

Free Tyre &
Service Credits
up to
\$3,000

Interest Rate
2.28%

Extended
Warranty
1yr



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5A



2.88%p.a Lowest Interest@GV
Cars Financing \$2000
Downpayment Monthly From
\$488
GV Credit Pte Ltd StarAd

PRIM
(CHENG YONG CREDIT)
With over 200 ur
to choose from,
all European to.

Browse by Category ▾

Sort by Da

7 vehicles

c180

Advanced S

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
Search Selection	c180		Any	Any	2010	Any	Any
	Mercedes-Benz C-Class C180 CGI		\$38,800	\$12,870 /yr	17-Jun-2010	1,796 cc	140,000
Consignment Unit, Getting A Safety, Superb Handling, Comfortable For You And Your Family! No Repair Needed. Is In A Very Loan Available, High Trade In Welcome. Don't Miss. Come To...							
Autotruster Traders Pte Ltd							
Posted: 16-Dec-2018 Tags: 2010 Mercedes-Benz C180, 2010 mercedes-benz c180, Mercedes-Benz C180, mercedes-benz c180, Mercedes-Benz, C180, c180, Used Mercedes-Benz							
	Mercedes-Benz C-Class C180K		\$40,800	\$12,920 /yr	19-Nov-2010	1,597 cc	-
Cheapest In Town! Getting A Safety, Superb Handling, Comfortable For You And Your Family! No Repair Needed. Is In A Very Loan Available, High Trade In Welcome. Don't Miss. Come To...							
Posted: 14-Dec-2018 Tags: 2010 Mercedes-Benz C180K, 2010 mercedes-benz c180k, Mercedes-Benz C180K, mercedes-benz c180k, Mercedes-Benz, C180K, c180k, Used Mercedes-Benz							
	Mercedes-Benz C-Class C180 CGI		\$39,800	\$12,310 /yr	12-Aug-2010	1,796 cc	-
1 Owner With Low Mileage Done. Very Well Maintained. Original Condition Since Day 1, 100% Accident Free. View To Appreciate It'll Be Gone Soon!							
Posted: 14-Dec-2018 Tags: 2010 Mercedes-Benz C180, 2010 mercedes-benz c180, Mercedes-Benz C180, mercedes-benz c180, Mercedes-Benz, C180, c180, Used Mercedes-Benz							
	Mercedes-Benz C-Class C180 CGI		\$43,888	\$13,430 /yr	12-Oct-2010	1,796 cc	-
CGI Model. More Powerful Than Kompressor Model. Regularly Serviced Using Original Parts, 90% Parked In Shelter, 4 x New Condition With No Modifications. Major Servicing Just Done! Own...							
Posted: 14-Dec-2018 Tags: 2010 Mercedes-Benz C180, 2010 mercedes-benz c180, Mercedes-Benz C180, mercedes-benz c180, Mercedes-Benz, C180, c180, Used Mercedes-Benz							

**GET YOUR
COE
REN**

Compare

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest in 2 days without effort! Enquire today.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4165D
Vehicle Details	
Vehicle No.:	SLX7109G
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Dec 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C180K
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	27191031330706
Chassis No.:	WDD2040452A421224
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$31,893.00
Original Registration Date:	27 Oct 2010
First Registration Date:	27 Oct 2010
Transfer Count:	2
Actual ARF Paid:	\$31,893.00 15546
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Oct 2020
PARF Rebate Amount:	\$17,541.00
Intended COE Rebate Details	
COE Expiry Date:	26 Oct 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$32,415.00
COE Rebate Amount:	\$6,021.00
Total Rebate Amount:	\$23,562.00

The information contained herein is correct as at 17 Dec 2018

OK

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

31-12-18

Date of Accident : 11-12-18

OUR REF : SLX 7109G/T/18

Xu Wei Shi
71 Hillview Ave
#09-04
Singapore 669570

Not Aclut
Maras
2/5 @ 16.500
12 July.
Date in/out: 11/12/18 to 26/12/18
14/12/18

ESTIMATE BILL ON VEHICLE NO. : SLX 7109G

MODEL : MERCEDES BENZ C180

CHASSIS NO: WDD2040452A421224

LIST ITEM

Front Bumper Fascia		<i>00/ee</i>	1,310.00	✓
Front Bumper Clips	12pcs @ 4.50	<i>rec</i>	54.00	✓
Front Bumper Reinforcement		<i>n</i>	588.00	X
Front Bumper Sponge		<i>nt</i>	146.00	X
Front Bumper Chrome Moulding	2pcs @ 78.00	<i>rec</i>	156.00	✓
Front Bumper Side Retainer		<i>best</i>	87.00	✓
Front Grille Assy		<i>one</i>	656.00	✓
Front Hook Inner Arch Bracket		<i>11</i>	38.00	X
Head Lamp Assy	2pcs @ 1083.00	<i>hd lamp</i>	2,166.00	✓
Front Number Plate Garnish		<i>70.00</i>	192.00	✓
Bonnet <i>1819</i>		<i>500</i>	1,935.00	✓
Bonnet Badge		<i>rec</i>	47.00	✓
Bonnet Hook		<i>800</i>	49.00	X
Bonnet Rubber Stopper	2pcs @ 9.00	<i>11</i>	18.00	X
Bonnet Catch		<i>11</i>	63.00	X
Front Support Centre Panel		<i>best</i>	144.00	✓
Front Centre Top Panel Garnish		<i>11</i>	124.00	X

Radiator Side Guard - N/S		11	122.00	X
Turbo Intercooler	1100	one	1,280.00	✓
Rear Bumper Fascia	1485.32	Dis	1,899.00	✓
Rear Bumper Side Retainer		Sub	90.00	✓
Rear Bumper Side Attachment		Sub	138.00	✓
Rear Bumper Center Retainer		NS	139.00	X
Rear Bumper Tow Cover		Tow	49.00	✓
Rear Bumper Chorme (Center)	145	Sub	195.00	✓
Rear Bumper Chorme (Side)	115x2x230	Sub	2,723.00	✓
Rear Bumper Reinforcement	645	Sub	670.00	✓
Rear Bumper Clips		Sub	45.00	✓
Tail Lamp Assy	585x2=1170	one	1,206.00	✓
Tail Lamp Sealant		11	80.00	X
Tail Lamp Side Garnish		11	90.00	X
Tail Lamp Side Garnish Clips		11	45.00	X
Tail Lamp Base Panel - LH		R	155.00	X
Rear Floor Panel Under Side Cover		11	288.00	X
Boot Lid	1520	Sub/Sec	1,578.00	✓
Boot Lid Hinge		11	299.00	X
Boot Lid Stopper		11	28.00	X
Boot Lid Lock		Two	285.00	✓
Boot Lid Lock Striker		11	28.00	X
Boot Lid Weather Stripe		Two	165.00	✓
Boot Lid Lock Garnish		one	55.00	✓
Boot Lid Insulator		11	253.00	X
Boot Lid Insulator Clips		11	32.00	X
Boot Lid Lock Cover		11	16.00	X

Boot Lid Badge		neu	47.00	✓
Boot Lid Emblem "C180"		neu	74.00	✓
Boot Lid Emblem "Kompressor" 102.00		neu	108.00	✓
Rear End Panel		30/300	1,084.00	✓
Rear End Panel Top Trim		7m	115.00	✓
Rear End Panel Top Trim Clips	4pcs @ 4.50	112	18.00	X
Rear Spare Tyre Panel null		neu	270.00	✓
Rear Spare Tyre Panel Sealant		neu	254.00	505.00 ✓
Rear Spare Tyre Board		wagel	308.00	✓
Exhaust Silencer 1422.50		10/1m	1,864.00	✓
Exhaust Silencer Hook	2pcs @ 82.00	neu	164.00	✓
Rear Fender Inner Trim Board	2pcs @ 180.00	del/10/11	360.00	✓
Rear Fender Inner Trim Board Clips	16pcs @ 4.50	112	72.00	X
Front Head Rest Cushion RH & LH	2pcs @ 887.00	R	1,774.00	X
Front Seat Belt RH & LH 745x2=1490	2pcs @ 1320.00	Acid	2,640.00	✓
Rear Seat Belt RH & LH	2pcs @ 567.00	Acid	1,134.00	✓
			30,012.00	2032382
Less Discount 10%:			3,001.20	
			27,010.80	

SPECIAL NETT ITEM

Front Number Plate	neu	45.00	20
Front Number Plate Casing	best	29.00	20
1927 Reverse Sensor	shud	480.00	280

LABOUR CHARGE

Towing	120.00	100
To check wiring system	100.00	30
To tuff coat affected areas	200.00	100
To remove & refix front seat head rest cushion & front & rear seat belt	450.00	200
To remove & refix interior upholstery	180.00	80

To remove & refix exhaust silencer & straighten exhaust center pipe	300.00	80
To remove & refix reverse sensor	150.00	50
To adjust chassis alignment on car O liner	380.00	X
To respray affected areas	2,200.00	1700
To reset electrical module system	450.00	100
To renew damaged parts, straighten & repair front rear fender, rear chassis member, rear floor panel & aligned all parts	2,500.00	1600
To remove & refix turbo intercooler	120.00	30

Total :	34,714.80
GST 7% :	2,430.04
AMOUNT DUE :	<u>37,144.84</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18022530/UVD3N2

Date: 16/01/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1825151800
Claimant Vehicle No :	SLX7109G	Insured Vehicle No :	SKT9267C
Date of Loss:	11/12/2018	Nature of Claim:	TP
		Claim No:	SNM18D05750C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX7109G	Engine No:	27191031330706
Make & Model:	MERCEDES-BENZ C180K, 1.6 (A)	Chassis No:	WDD2040452A421224
Reg. Date:	27/10/2010 (Man. Year: 2010)	Odometer:	122256 km
Colour:	Grey		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45ZR17	Rear Tyre Size:	225/45ZR17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	27,564.80	18,661.44	8,903.36	32.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,150.00	4,070.00	3,080.00	43.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	34,714.80	22,731.44	11,983.36	34.52
Approved Total (Overridden) (\$\$)		16,500.00		
(\$\$)	34,714.80	16,500.00	18,214.80	52.47
+ GST 7.00/7.00% (\$\$)	2,430.04	1,155.00	1,275.04	52.47
Nett Amount (\$\$)	37,144.84	17,655.00	19,489.84	52.47

INSPECTION

Date of Assignment:	14/12/2018		
Date Inspected:	14/12/2018	Inspected At:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36 Singapore 417883
Estimated Period of Repair:	12.0 days		

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2019)
Parts: 143	MERCEDES-BENZ C180K 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLX7109G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER FASCIA	Dented/Deformed	1,310.00 FL	*1,310.00 FL
2	12	*FRONT BUMPER CLIPS	Necessary	54.00 FL	*54.00 FL
3	1	*FRONT BUMPER REINFORCEMENT	Repair	588.00 FL	*- FL
4	1	*FRONT BUMPER SPONGE	Not fitted	146.00 FL	*- FL
5	2	*FRONT BUMPER CHROME MOULDING	Necessary	156.00 FL	*156.00 FL
6	1	*FRONT BUMPER SIDE RETAINER	Bent	87.00 FL	*87.00 FL
7	1	*FRONT GRILLE ASSY	Cracked	656.00 FL	*656.00 FL
8	1	*FRONT HOOK INNER ARCH BRACKET	Not Necessary	38.00 FL	*- FL
9	2	*HEAD LAMP ASSY	Holder Cracked	2,166.00 FL	*2,166.00 FL
10	1	*FRONT NUMBER PLATE GARNISH	Torn	192.00 FL	*192.00 FL
11	1	*BONNET	Buckled	1,935.00 FL	*1,819.00 FL
12	1	*BONNET BADGE	Necessary	47.00 FL	*47.00 FL
13	1	*BONNET HOOK	Serviceable	49.00 FL	*- FL
14	2	*BONNET RUBBER STOPPER	Not Necessary	18.00 FL	*- FL
15	1	*BONNET CATCH	Not Necessary	63.00 FL	*- FL
16	1	*FRONT SUPPORT CENTRE PANEL	Bent	144.00 FL	*144.00 FL
17	1	*FRONT CENTRE TOP PANEL GARNISH	Not Necessary	124.00 FL	*- FL
18	1	*RADIATOR SIDE GUARD-N/S	Not Necessary	122.00 FL	*- FL
19	1	*TURBO INTERCOOLER	Cracked	1,280.00 FL	*1,100.00 FL
20	1	*REAR BUMPER FASCIA	Distorted	1,899.00 FL	*1,485.32 FL
21	2	*REAR BUMPER SIDE RETAINER	Bent	90.00 FL	*90.00 FL
22	2	*REAR BUMPER SIDE ATTACHMENT	Bent	138.00 FL	*138.00 FL
23	1	*REAR BUMPER CENTER RETAINER	No such part	139.00 FL	*- FL
24	1	*REAR BUMPER TOW COVER	Torn	49.00 FL	*49.00 FL
25	1	*REAR BUMPER CHROME (CENTER)	Bent	195.00 FL	*145.00 FL
26	2	*REAR BUMPER CHROME (SIDE)	Necessary	2,723.00 FL	*230.00 FL
27	1	*REAR BUMPER REINFORCEMENT	Bent	670.00 FL	*645.00 FL
28	10	*REAR BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
29	2	*TAIL LAMP ASSY	Cracked	1,206.00 FL	*1,170.00 FL
30	2	*TAIL LAMP SEALANT	Not Necessary	80.00 FL	*- FL
31	2	*TAIL LAMP SIDE GARNISH	Not Necessary	90.00 FL	*- FL
32	10	*TAIL LAMP SIDE GARNISH CLIPS	Not Necessary	45.00 FL	*- FL
33	1	*TAIL LAMP BASE PANEL-LH	Repair	155.00 FL	*- FL
34	1	*REAR FLOOR PANEL UNDER SIDE COVER	Not Necessary	288.00 FL	*- FL
35	1	*BOOT LID	Bent/Buckled	1,578.00 FL	*1,520.00 FL
36	2	*BOOT LID HINGE	Not Necessary	299.00 FL	*- FL
37	2	*BOOT LID STOPPER	Not Necessary	28.00 FL	*- FL
38	1	*BOOT LID LOCK	Twisted	285.00 FL	*285.00 FL
39	1	*BOOT LID LOCK STRIKER	Not Necessary	28.00 FL	*- FL
40	1	*BOOT LID WEATHER STRIP	Twisted	165.00 FL	*165.00 FL
41	1	*BOOT LID LOCK GARNISH	Cut	55.00 FL	*55.00 FL
42	1	*BOOT LID INSULATOR	Not Necessary	253.00 FL	*- FL
43	8	*BOOT LID INSULATOR CLIPS	Not Necessary	32.00 FL	*- FL
44	1	*BOOT LID LOCK COVER	Not Necessary	16.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*BOOT LID BADGE	Necessary	47.00 FL	*47.00 FL
46	1		*BOOT LID EMBLEM C180	Necessary	74.00 FL	*74.00 FL
47	1		*BOOT LID EMBLEM KOMPRESSOR	Necessary	108.00 FL	*102.00 FL
48	1		*REAR END PANEL	Badly Dented	1,084.00 FL	*1,084.00 FL
49	1		*REAR END PANEL TOP TRIM	Twisted	115.00 FL	*115.00 FL
50	4		*REAR END PANEL TOP TRIM CLIPS	Not Necessary	18.00 FL	*- FL
51	1		*REAR SPARE TYRE PANEL WELL	Cracked	270.00 FL	*270.00 FL
52	1		*REAR SPARE TYRE BOARD	Warped	308.00 FL	*308.00 FL
53	1		*EXHAUST SILENCER	Dented/Twisted	1,864.00 FL	*1,422.50 FL
54	2		*EXHAUST SILENCER HOOK	Necessary	164.00 FL	*164.00 FL
55	2		*REAR FENDER INNER TRIM BOARD	Deformed/Torn	360.00 FL	*360.00 FL
56	16		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	72.00 FL	*- FL
57	2		*FRONT HEAD REST CUSHION RH & LH	Repair	1,774.00 FL	*- FL
58	2		*FRONT SEAT BELT RH & LH	Activated	2,640.00 FL	*1,490.00 FL
59	2		*REAR SEAT BELT RH & LH	Activated	1,134.00 FL	*1,134.00 FL
60	1		*REAR SPARE TYRE PANEL SEALANT	Necessary	228.60 FS	*50.00 FS
61	1		*FRONT NUMBER PLATE	Cracked	45.00 FS	*20.00 FS
62	1		*FRONT NUMBER PLATE CASING	Bent	29.00 FS	*20.00 FS
63	1		*SET REVERSE SENSOR	Shorted	480.00 FS	*280.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	30,540.60	20,693.82
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,975.80	2,032.38
Total Parts (\$\$)	27,564.80	18,661.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	120.00	100.00
2	TO CHECK WIRING SYSTEM	New	100.00	30.00
3	TO TUFF COAT AFFECTED AREAS	New	200.00	100.00
4	TO REMOVE & REFIX FRONT SEAT HEAD REST CUSHION & FRONT & REAR SEAT BELT	New	450.00	200.00
5	TO REMOVE & REFIX INTERIOR UPHOLSTERY	New	180.00	80.00
6	TO REMOVE & REFIX EXHAUST SILENCER & STRAIGHTEN EXHAUST CENTER PIPE	New	300.00	80.00
7	TO REMOVE & REFIX REVERSE SENSOR	New	150.00	50.00
8	TO ADJUST CHASSIS ALIGNMENT ON CAR O LINER	New	380.00	-
9	TO RESPRAY AFFECTED AREAS	New	2,200.00	1,700.00
10	TO RESET ELECTRICAL MODULE SYSTEM	New	450.00	100.00
11	TO RENEW DAMAGED PARTS, STRAIGHTEN & REPAIR FRONT REAR FENDER, REAR CHASSIS MEMBER, REAR FLOOR PANEL & ALIGNED ALL PARTS	New	2,500.00	1,600.00
12	TO REMOVE & REFIX TURBO INTERCOOLER	New	120.00	30.00
Gross Labour Cost (\$\$)			7,150.00	4,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >