

ASSIGNMENT (Office)

From Person: menmen

ehin lee feng

of

AIG

Date/Time

14/12/18 @ 4:05pm

Estimated Cost

Bill to:

(01) / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGY 5777U

Insured:

at Workshop m/s

First Auto works

Tel:

8292 5595

of

23 kaki Bukit Ave 4 # 04-01

Policy No:

Claim No:

Sum Insured:

Excess:

IA \$600/-

Make of Veh:

(Client's Record)

D.O.A 12/12/2018

CA / (REV) / REP. / REV 24 HRS

18/12/18 @ 11am over writing

H.O.D. Endorsement:

Date/Time:

5:32pm @ 14/12/18

Person Contacted:

Kelvin

Vehicle-INS (OUT)

Date/Time	Action/Instruction (✓) Estimate
	<u>SGY 5777U-X</u>
<u>14/12/18</u>	<u>@ 11:01 a.m. mandate requested authorize repair to Norsazari via menmen.</u>
<u>14/12/18</u>	<u>@ 11:00 a.m. revised IA to Norsazari via menmen.</u>
<u>14/12/18</u>	<u>@ 12:42 a.m. mandate approved by Lois cheng via menmen.</u>
<u>14/12/18</u>	<u>@ 15:42 p.m. revert authorize repair to Kelvin via menmen.</u>

REF: ALG

ASSIGNMENT

Date: 12/12/2018

Estimated Cost:

TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGY 57774

at Workshop no: First Autoworks

at: 23 Kaki Bukit Ave 4 #04-01

Insured:

Policy No:

Claims No:

Sum Insured: Excess: TBA \$600/-

(Client's Record)

Make of Veh: I am @ owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: TSK.

IDAC Accident Rpt: Consistent? Yes or No

QIA / PR Seen: Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SGY57774. Yr Regn: 2017 / July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Opel Astra. CC: 999

Colour: White. A/C: Insured / Std / NI / NA

Sp. Reading: 13743. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WOLBE6EASH673250

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17.

R: 225/45R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front		Rear	
R/Bal: 06 mm		R/Bal: 06 mm	
L/Bal: 06 mm		L/Bal: 06 mm	
D.O.A:		D.O.A: 18/12/18.	

Survey held at: 1st Autowork.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision



Date / Time	Action / Instruction
	ALG.
28/01/19	Confirmed P/P \$14,928.50 @ 5 days with Adrian. (\$ 16,359.60 Red - 53%)

RECEIVED 10 JUN 2019

Date/Time, File Name (in): 10/06/19

By: Typist

Date/Time, File Return to:

Report Format:

Lump Sum / LB I: (\$ 16,359.60 P/P)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

200
11
211


Add Fee:

- Site Insp (\$)
- Interview (\$)
- Tech. Invs (\$)
- Weekend (\$)

TRAN

- SGY5777U - OPEL ASTRA - AIG - DOA 12-12-2018 - OWN DAMAG...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 14/12/2018 4:05:24 PM

Attachments:  SGY5777U_PG2.jpg  SGY5777U_ESTIMATE.jpg
 SGY5777U_PG1.jpg  GIA REPORT_SGY 5777 U.PDF.pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Vincent Sim [mailto:vincent.sim@alpinemotors.sg]
Sent: Friday, December 14, 2018 2:59 PM
To: AIG SGP, Claims-Survey
Subject: fw: SGY5777U - OPEL ASTRA - AIG - DOA 12-12-2018 - OWN DAMAGED CLAIM

Regards,
Vincent Sim- Claims Dept

vincent.sim@alpinemotors.sg

65113022 ext 343

From: "Vincent Sim" <vincent.sim@alpinemotors.sg>
Sent: Friday, December 14, 2018 2:46 PM
To: aigsp_claimssurvey@aig.com
Cc: leewengkeong@gmail.com, "suhaimi@alpinemotors.sg" <suhaimi@alpinemotors.sg>, "Kelvin Chew"

<Kelvin.chew@alpinemotors.sg>

Subject: SGY5777U - OPEL ASTRA - AIG - DOA 12-12-2018 - OWN DAMAGED CLAIM

Dear Sir/Madam,

Hereby attached estimate of the above for your survey team ,

kindly call to make appointment as the owner is **still driving the vehicle** , **we have to make arrangement for him to come in one day in advance** .

Survey to be carried out at ;

Person in charge :-

Suhaimi , Kelvin – 82925595 H/P.

68441985 – office phone

E-mail ;

suhaimi@alpinemotors.sg

Kelvin.chew@alpinemotors.sg

Add;

First Autoworks Pte Ltd

23, Kaki Bukit Ave 4

#04-01 (South Wing)

singapore 415933

(Vicom Building)

tel; 6844-1985

Regards,

Vincent Sim- Claims Dept

vincent.sim@alpinemotors.sg

65113022 ext 343 ,

H/P 92478842

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted

by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 7493J

Vehicle Details

Vehicle No.: SGY5777U
Vehicle to be Exported: Yes
Intended Deregistration Date: 13 Dec 2018
Vehicle Make: OPEL
Vehicle Model: ASTRA HB 1.0 AT
Primary Colour: White
Manufacturing Year: 2017
Engine No.: B1170487HRXX0952
Chassis No.: W0LBE6EA5HG113250
Maximum Power Output: 77.0 kW (103 bhp)
Open Market Value: \$19,298.00
Original Registration Date: 10 Jul 2017
First Registration Date: 10 Jul 2017
Transfer Count: 0
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 09 Jul 2027
PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 09 Jul 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$42,801.00
COE Rebate Amount: \$34,240.00
Total Rebate Amount: \$37,990.00

The information contained herein is correct as at 13 Dec 2018

OK

FREE VALUATION
 Let us tell you how much your car can sell for!
No obligations and it's FREE!

How much is my car worth?



Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

View 3 Year's Old Reasonable Sports Rides 1.0A



2 Year's Old Reasonable Sports Rides 1.0A
 Cars From Only \$2000
 Reasonable Sports Rides
 1700
 GV Credit Pte Ltd

CERTIFIED PRE-OWNED MERCEDES-BENZ

Browse by Category

Sort by Date Posted 20 results/page

7 vehicles

opel astra

Advanced Search

Image	Model	Price	Depreciation	Year Used	Eng Cap	Mileage	Veh Type	Status
Search Selection								
	opel astra	Any	Any	2017	Any	Any	Any	Available
	Opel Astra Sports Tourer 1.0A	\$72,800	\$8,250 /yr	22-Jun-2017	999 cc	24,600 km	Stationwagon	Available
Opel Astra Sport Tourer 1.0A TurboCharged Engine. Very Fuel Economic With Low Road Tax! 100% Accident Free With 5 Years Unlimited Mileage Warranty From Auto Germany For Your Peace Of Mind! Original Pa...								
Posted: 10-Dec-2018 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel								
	Opel Astra Sports Tourer 1.0A	\$76,955	\$8,270 /yr	20-Oct-2017	999 cc	22,000 km	Stationwagon	Available
Opel Astra Sport Tourer 1.0A TurboCharged Engine. Comes With Additional \$5000 Option For Intellilux Headlamp. Very Fuel Economic With Low Road Tax. 100% Accident Free With Valid Warranty From Auto Ger...								
Posted: 08-Dec-2018 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel								
	Opel Astra Sports Tourer 1.0A	\$76,000	\$8,590 /yr	03-Jul-2017	999 cc	26,000 km	Stationwagon	Available
Down Payment \$7,600 Only! From \$1,090/Month. Single Owner Unit! Maintained By Agent With Warranty Till 2022. Deep Sky Blue Exterior With Black Interior. Great Fuel Economy. Low Maintenance With Low Ro...								
Audax Auto Pte Ltd								
Posted: 04-Dec-2018 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel								
	Opel Astra 1.4A	\$83,900	\$8,960 /yr	08-Jun-2017	1,399 cc	43,000 km	Hatchback	Available
Look No Further! Genuine Mileage With 1 Owner! Best Value For Your Money. Direct Owner's Beautiful White. Jun'2017 Opel Astra HB 1.4 AT(LED) With Grey Leather Upholstery. Selling Due To Upgrading To N...								
Posted: 28-Nov-2018 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel								
	The Opel Astra 1.0 is an acquired taste The Opel Astra 1.0 has the same furnish and finish as its 1.4-litre counterpart and has an amusing Easytronic gearbox, which may divide opinions. Read this article							
	Opel Astra 1.4A Turbo (OPC)	\$67,000	\$6,980 /yr	19-Jun-2017	1,399 cc	19,000 km	Hatchback	Available
Beautiful Original Power Red Colour. 5 Years Warranty And 5 Years Free Servicing. German Built Quality. Neat Looking Dashboard. Sporty Exterior And Spacious Interior.5 Star Euro NCAP Safety Rating. Lo...								
Posted: 23-Nov-2018 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel								
	Opel Astra Sports Tourer 1.0A	\$81,000	\$8,790 /yr	26-Oct-2017	999 cc	21,500 km	Stationwagon	Available
Ideal Car For Family With 2 Young Kids. Single Owner. Maintained By Agent With Warranty Till 2022 And 3 More Free Servicing By Agent. Deep Sky Blue Exterior With Black Interior. Many Functions And Gre...								
Carro								
Posted: 20-Nov-2018 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel								
	Opel Astra 1.0A (OPC)	\$80,000	\$8,970 /yr	04-Aug-2017	999 cc	16,000 km	Hatchback	Available
Stylish, Comfortable And Performance-driven. Schedule A Test Drive Today. Viewing Is Strictly By Appointment Only.								
Carro								
Posted: 12-Nov-2018 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel								

Compare

Search criteria, to get email alerts whenever a match is found.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 8 February 2019 10:17 AM
To: 'Kelvin.chew@alpinemotors.sg'
Cc: 'suhaimi@alpinemotors.sg'; 'SUR'
Subject: RE: SGY 5777U OD (AIG)

Dear Kelvin,

Confirmed final fig \$14,928.50 (part by part) @ 5 days of repairs before excess \$600/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kelvin Chew [mailto:Kelvin.chew@alpinemotors.sg]
Sent: Tuesday, 29 January 2019 9:50 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: suhaimi@alpinemotors.sg
Subject: RE: SGY 5777U OD (AIG)

Hi Shirley,

please ignore the previus mail.
attach is the latest finalize report.
part by part \$14,928.50 before excess \$600.00 @ 5 working days.
kindly please check & confirm with me.
thanks.

from,
kelvin chew
8292 5595

From: "Kelvin Chew" <Kelvin.chew@alpinemotors.sg>
Sent: 28 January 2019 17:51
To: "Shirley Hiew (LKK Auto)" <ShirleyHiew@lkkauto.com>
Cc: "vincent.sim@alpinemotors.sg" <vincent.sim@alpinemotors.sg>, "suhaimi@alpinemotors.sg" <suhaimi@alpinemotors.sg>
Subject: RE: SGY 5777U OD (AIG)

Hi Shirley,

attach is finalize report.
part by part \$14,935.70 before excess \$600.00 @ 5 working days.

kindly please check & confirm with me.
thanks.

from,
kelvin chew
8292 5595

From: "Shirley Hiew (LKK Auto)" <ShirleyHiew@lkkauto.com>
Sent: 28 January 2019 10:37
To: "Kelvin.chew@alpinemotors.sg" <Kelvin.chew@alpinemotors.sg>
Cc: "vincent.sim@alpinemotors.sg" <vincent.sim@alpinemotors.sg>, "suhaimi@alpinemotors.sg" <suhaimi@alpinemotors.sg>
Subject: RE: SGY 5777U OD (AIG)

Hi Kelvin,

As spoken, please refer to the attachment.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Wednesday, 19 December 2018 3:42 PM
To: Kelvin.chew@alpinemotors.sg
Cc: vincent.sim@alpinemotors.sg; suhaimi@alpinemotors.sg
Subject: SGY 5777U OD (AIG)

Dear Kelvin,

As instructed by our client, please proceed to repair the insured vehicle **SGY 5777U (Excess \$ 600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 19 December 2018 3:42 PM
To: 'Kelvin.chew@alpinemotors.sg'
Cc: 'vincent.sim@alpinemotors.sg'; 'suhaimi@alpinemotors.sg'
Subject: SGY 5777U OD (AIG)

Dear Kelvin,

As instructed by our client, please proceed to repair the insured vehicle **SGY 5777U (Excess \$ 600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SGY5777U (0764797494SG)**
OD
Dec 12 2018 5:00PM
[LEE WENG KEONG]
Auto Germany Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 01/02/2019 14:10 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$14928.50) - SGY5777U - Claim Handler: Mohd Zawaye, Norsazani

Approved:14928.50.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SGY5777U (0764797494SG)**

OO
Dec 12 2018 5:00PM
[LEE WENG KEONG]
Auto Germany Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 19/12/2018 12:42 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10541.00) - SGY5777U - Claim Handler: Mohd Zawaye, Norsazani

Approved:10541.00:Re-inspection REQUIRE on hidden parts and supplementary parts

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Zawaye, Norsazani

Date: 29 Jan 2019

Preliminary Advice

Vehicle No	: SGY5777U	Accident Date	: 12/12/2018
Make	: OPEL ASTRA	Policy No.	: 1800066896
Assignment Date	: 14/12/2018	Excess	: S\$600.00
Date of Inspection	: 18/12/2018	Est. Duration of Repair	: 5 days
Inspection At	: Auto Germany Pte Ltd (HQ) 7 Ubi Close., Alpine Centre Singapore 408604		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,788.10
Revised Amount	:S\$	14,928.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,928.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	75,000.00
COE / PARF Rebate	:S\$	37,990.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,010.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: **AIG Asia Pacific Insurance Pte. Ltd.**
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: **LKK Auto Consultants Pte Ltd**
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: **Mohd Zawaye, Norsazani**

Date: 19 Dec 2018

Preliminary Advice

Vehicle No	: SGY5777U	Accident Date	: 12/12/2018
Make	: OPEL ASTRA	Policy No.	: 1800066896
Assignment Date	: 14/12/2018	Excess	: S\$600.00
Date of Inspection	: 18/12/2018	Est. Duration of Repair	: 5 days
Inspection At	: First Autoworks Pte Ltd (HQ) 23 KAKI BUKIT AVE 4 #04-01 SOUTH WING Singapore 415933		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,788.10
Revised Amount	:S\$	10,540.10
Check Items (Estimated)	:S\$	6,246.60
Total	:S\$	16,786.70
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	75,000.00
COE / PARF Rebate	:S\$	37,990.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,010.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/12/2018 19:01
Date Of Accident	12/12/2018 17:15
Exact Location Of Accident	WEST COAST HIGHWAY OPPOSITE HAW PAR VILLA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGY5777U
Insured/Policyholder	
Name Of Registered Owner	LEE WENG KEONG
NRIC No	S7027493J
Email Address	LEEWENGKEONG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98556680
Alternative Phone No	OTHERS-98556680

Vehicle Particulars

Manufacturer	OPEL
Model	ASTRA 1.0

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800066896
Cover Note Number	

Driver

Name of Driver	LEE WENG KEONG
NRIC No	S7027493J
Date Of Birth	05/08/1970
Occupation	INDOOR
Date Of Driving Pass	28/06/1993
Driving Experience	25 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98556680
Fax Number	
Contact Number	OTHERS-98556680
Email Address	LEEWENGKEONG@GMAIL.COM

Address	118 CLEMENTI STREET 13 #12-87 SINGAPORE
Postcode	120118
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX5113R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/12/2018 19:01
Date Of Accident	12/12/2018 17:15
Exact Location Of Accident	WEST COAST HIGHWAY OPPOSITE HAW PAR VILLA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGY5777U
Insured/Policyholder	
Name Of Registered Owner	LEE WENG KEONG
NRIC No	S7027493J
Email Address	LEEWENGKEONG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98556680
Alternative Phone No	OTHERS-98556680

Vehicle Particulars

Manufacturer	OPEL
Model	ASTRA 1.0

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800066896
Cover Note Number	

Driver

Name of Driver	LEE WENG KEONG
NRIC No	S7027493J
Date Of Birth	05/08/1970
Occupation	INDOOR
Date Of Driving Pass	28/06/1993
Driving Experience	25 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98556680
Fax Number	
Contact Number	OTHERS-98556680
Email Address	LEEWENGKEONG@GMAIL.COM

Address	118 CLEMENTI STREET 13 #12-87 SINGAPORE
Postcode	120118
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX5113R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Facts Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information (as set out in this Form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in the accident (all insurers) who have insured my vehicle(s) involved in the accident (shall be collectively referred to as the "Insurers"), my insurer's designated firm, the Ministry/Authority of Singapore and any relevant government agency/authority (collectively referred to as the "Government")
 - (i) processing, handling and/or dealing with my claim/including the settlement of the claim and any associated investigations relating to the claim;
 - (ii) investigating the accident and/or my claim;
 - (iii) carrying out and/or dealing with my subscription or responding to any enquiries by me;
 - (iv) administering my claim (including the handling of correspondence, statements, medical reports or notes of visit, court proceedings, disclosure of certain personal data which are to bring about closure of the case or end of the relevant course of investigation/assessment); and/or
 - (v) complying with applicable law or administering, enforcing, handling and/or dealing with my shared data/related to the "Program".
- (b) all insurers who have insured vehicle(s) involved in this accident and the Insurer's designated firm, may/are permitted to collect, use, disclose and/or process my Personal Information (as set out in this Form) for purposes such as:
 - (i) my Personal Information may/also be disclosed by any of the Insurers and/or GIA to their third party service providers (including their insurer/law firms) which may be third parties of Singapore, for use or work of the above purposes;
 - (ii) my Personal Information will also be collected and used by my insurer/insurers and/or the Insurer's designated firm, investigation and management in present and all future claims;
 - (iii) My Information is collected under (a) above may be shared with:
 - (i) to all Insurers and/or any other third parties that exist in existing, investigating, settling or managing claim, litigation, law enforcement and government agencies/authorities (as may be required for the purposes stated);
 - (ii) My complying with requirements under the regulations, laws or court orders.


Policyholder's Signature
Date & Time:
13/12/2018
11:35


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stopped at traffic junction beside Harbour Drive and I was in west coast Highway.

When traffic light turns green, I started to move. The van (GX5113R) did a sudden stop as the vehicle in front turn left into Harbour Drive.

I could not brake in time and bumped into GX5113R. No damage to GX5113R but the driver took my IC just in case his van's bumper dropped.

I did not take the driver's particulars but I have video footage.


The accident happened around Dec 12th 2018 at 1716 hrs.

DECLARATION

I/We declare the foregoing particulars are true in every respect. Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.


 Policyholder's Signature
 Date & Time:
 13/12/2018
 11:35


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.: Permen



AIG

CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : LEE WENG KEONG
 Period of Insurance : 10 Jul 2018 To 09 Jul 2019
 Engine No. : B1170457HRXX0952
 Chassis No. : WOLBE6EASHG113250

Vehicle No. : SGY5777U
 Policy No. : 1800065806
 Endorsement No. :
 Issued Date : 18 Jun 2018

ABOUT THE COVER

Make/Model	OPEL Astra 1.0 Turbo	Sum Insured	Market Value	First Year of Registration	2017
Engine Capacity/Tonnage	999.00 CC	Off Peak Car	No	Insuring with COE/PARF	Yes
Driver Restriction	NA				

Person or Classes of Persons Entitled to Drive*

is The Policyholder
 is Any other person who is driving on the Policyholder's order or with holder's permission.
 This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.
 You have to pay an additional sum of \$2,000 as "Young and Inexperienced Driver Excess" ("YIDE") if you are or your Authorized Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and not for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, sports racing, reliability trial or speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Limits of Loss 150000 - 180000 Optional

* Limitations mentioned hereunder by Section 9 of the Motor Vehicles (Third-Party Rules and Compensation) Act (Cap. 140) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0; Own Damage - \$500; Theft - \$0; Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen - \$100

Named Driver and Excess (where applicable)

LEE WENG KEONG - \$500 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/Authorized Repairers (for claims related repairs):
 Any accident repairs to the vehicle must be carried out by one of our Authorized Repairers within the first 2 years of the first registration of the vehicle in Singapore. You have the option of having the accident repairs carried out at the Sole Agent's workshop.
 For other approved Reporting Centres/Authorized Repairers, please contact our 24-hour accident emergency helpline at +65 6586 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from Google or Google Play.



Ms Cheong
 Hp: 9851 5488

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

*Please verify carefully that the policy to which this Certificate of Insurance refers is issued in accordance with the provisions of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third-Party Rules) Rules, 1929 (Malaysia).

9500939000

INSMART (INSURANCE) AGENCY PTE
 NO 1 KARAI BURST ROAD 1 #02-27 ENTERPRISE ONE,
 SINGAPORE 415334
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

INSMART (INSURANCE) AGENCY PTE LTD
 寶安(保險)代理私人有限公司

No. 1 Karai Burst Road | #02-27 Enterprise One Singapore 415334
 Tel: 6642 0821 Fax: 6642 0285, 6642 7883
 Email: cheong@insmart.sg Website: www.insmart.sg

Print

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORIZED REPRESENTATIVE



Date :13/12/2018

Reference: OPEL
Make: ASTRA

To Whom It May Concern

Dear Sir,

RE: VEHICLE .: SGY5777U
CHASSIS NO.: W0LBE6EA6HG178768
ENGINE NO.: B1171667HRXX0471

Name of insured .: LEE WENG KEONG
Date of accident.: 12/12/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET <i>new</i>	\$ 1,758.00
2	1	FRT BONNET LOCK	\$ 312.00
3	1	FRT BONNET LOCK CABLE	\$ 277.00
4	1	FRT BONNET HINGE LH	\$ 186.00
5	1	FRT BONNET HINGE RH	\$ 186.00
6	4	FRT BONNET STOPED	\$ 40.00
7	1	FRT BUMPER <i>Distorted</i>	\$ 1,994.00
8	1	FRT BUMPER LOW LIP RH <i>2nd</i>	\$ 156.00
9	1	FRT BUMPER LOW LIP LH <i>1st</i>	\$ 156.00
10	10	FRT BUMPER CLIP <i>new</i>	\$ 65.00
11	1	FRT BUMPER SIDE RETAINER LH - GUIDE <i>?</i>	\$ 136.00
12	1	FRT BUMPER SIDE RETAINER LH - UPP <i>?</i>	\$ 106.00
13	1	FRT BUMPER SIDE RETAINER RH - GUIDE	\$ 136.00
14	1	FRT BUMPER SIDE RETAINER RH - UPP	\$ 106.00
15	1	FRT BUMPER BRACKET LH <i>incl</i>	\$ 192.00
16	1	FRT BUMPER BRACKET RH <i>incl</i>	\$ 192.00
17	1	FRT BUMPER UNDER DUST COVER <i>new</i>	\$ 290.00
18	1	FRT BUMPER BRACKET TOP CENTRE <i>2nd</i>	\$ 198.00
19	1	FRT BRACE BRACKET CENTRE <i>Best</i>	\$ 229.00
20	1	FRT BRACE BRACKET RH <i>?</i>	\$ 118.00
21	1	FRT BRACE BRACKET LH <i>?</i>	\$ 118.00
22	1	FRT BUMPER SPONGE <i>incl</i>	\$ 254.00
23	1	FRT BUMPER REINFORCEMENT UPP (metal) <i>Best</i>	\$ 798.00
24	1	FRT BUMPER REINFORCEMENT LOW (firbe) <i>?</i>	\$ 374.00
25	2	FRT BUMPER PARKING SENSOR <i>?</i>	\$ 544.00
26	2	FRT BUMPER PARKING SENSOR SEAL <i>new</i>	\$ 24.00
27	1	FRT BUMPER PARKING SENSOR WIRE HARNESS <i>new</i>	\$ 394.00
28	1	FRT GRILLE ASSY <i>incl</i>	\$ 800.00
29	1	FRT GRILLE LOGO <i>incl</i>	\$ 160.00

30	1	FRT LOW CENTRE GRILLE <i>new</i>	\$	202.00	+
31	1	RH HEADLAMP <i>3 pced</i>	\$	820.00	✓
32	1	LH HEADLAMP	\$	820.00	✓
33	1	LH FOG LAMP	\$	434.00	+
34	1	LH FOG LAMP COVER	\$	120.00	+
35	1	RH FOG LAMP <i>new</i>	\$	434.00	+
36	1	RH FOG LAMP COVER	\$	120.00	+
37	1	FRT FENDER LH <i>Repair</i>	\$	682.00	+
38	1	FRT FENDER INNERSHIELD LH <i>3 pced</i>	\$	138.00	+
39	10	FENDER INNERSHIELD CLIP	\$	65.00	+
40	1	FRT FENDER RH <i>Repair</i>	\$	682.00	+
41	1	FRT FENDER INNERSHIELD RH <i>new</i>	\$	138.00	+
42	1	RADIATOR SUPORT PANEL TOP GARNISH RH <i>3 pced</i>	\$	152.00	✓
43	1	RADIATOR SUPORT PANEL TOP GARNISH LH	\$	152.00	✓
44	1	RADIATOR SUPORT PANEL TOP <i>Repair</i>	\$	334.00	+
45	1	FRT HEADLAMP PANEL RH <i>Repair</i>	\$	160.00	+
46	1	RADIATOR	\$	1,424.00	✓
47	1	RADIATOR COOLANT <i>new</i>	\$	164.00	✓
48	1	RADIATOR FAN ASSY <i>new</i>	\$	1,806.00	✓
49	1	RADIATOR TOP BRACKET LH	\$	124.00	?
50	1	RADIATOR TOP BRACKET RH	\$	124.00	?
51	1	RADIATOR BRACKET LOWER LH	\$	162.00	?
52	1	RADIATOR BRACKET LOWER RH	\$	162.00	?
53	1	A/C CONDENSER	\$	730.00	?
54	1	A/C CONDENSOR AIR GUIDE TOP CENTRE	\$	158.00	?
55	1	A/C CONDENSER AIR GUIDE RH	\$	134.00	?
56	1	A/C CONDENSER AIR GUIDE LH	\$	138.00	?
57	1	A/C PIPE (comp to cooling coil)	\$	934.00	+
58	1	A/C PIPE (cooling coil to condenser)	\$	916.00	+
59	1	A/C AMBIENT SENSOR <i>new</i>	\$	317.00	+
60	1	INTERCOOLER, TURBOCHARGER AIR GUIDE	\$	514.00	+
61	1	INTERCOOLER, TURBOCHARGER	\$	1,060.00	+
62	1	INTERCOOLER HOSE(turbo to intercooler), INLET <i>3 pced</i>	\$	302.00	+
63	1	INTERCOOLER HOSE(intercooler to throttle body), OUTLET <i>3 pced</i>	\$	292.00	+
64	1	ENGINE AIR INTAKE DUCT	\$	166.00	?
65	1	FRT ARLARM SIREN RH <i>3 pced</i>	\$	420.00	+
66	1	FRT ARLARM SIREN BRACKET RH <i>new</i>	\$	60.00	+

Parts Total: \$ 25,859.00
Less 10%: \$ 2,585.90
Total : \$ 23,273.10

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair /replacement parts.	\$ 3,250.00

1950

<u>2</u>	Carry out spray painting on affected area, FRT BUMPER, FRT RH FENDER, FRT SUPORT PANEL, FRT LH FENDER, FRT BONNET, FRT DOOR RH, FRT DOOR LH	\$ 3,850.00	1650
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 220.00	180
<u>4</u>	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 600.00	?
<u>5</u>	To remove and refix radiator and conduct pressure test	\$ 180.00	?
<u>6</u>	To conduct diagnostic check	\$ 350.00	?

Labour Total : \$ 8,450.00

Others

Other Description

No.		Price (SGD)
1	FRT NUMBER PLATE <i>amber</i>	\$ 65.00

Other Total: \$ 65.00

TOTAL: \$ 31,788.10

GST (7%): \$ 2,225.17

GRAND TOTAL : \$ 34,013.27

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Advisor

*Adrian King
R/P 18/12/18*

05 days

*All Authorised,
Excess: TBA.*

LKY Auto Consultants hence notify the Repairer of the following:

- To resurvey ~~before~~ after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementing item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:



Date :13/12/2018

To Whom It May Concern

Dear Sir,

RE: VEHICLE .: SGY5777U
CHASSIS NO.: W0LBE6EA6HG178768
ENGINE NO.: B1171667HRXX0471

Name of insured .: LEE WENG KEONG
Date of accident.: 12/12/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET <i>new</i>	\$ 1,758.00
2	1	FRT BONNET LOCK	\$ 312.00
3	1	FRT BONNET LOCK CABLE	\$ 277.00
4	1	FRT BONNET HINGE LH	\$ 186.00
5	1	FRT BONNET HINGE RH	\$ 186.00
6	4	FRT BONNET STOPED	\$ 40.00
7	1	FRT BUMPER <i>Distorted</i>	\$ 1,994.00
8	1	FRT BUMPER LOW LIP RH <i>new</i>	\$ 156.00
9	1	FRT BUMPER LOW LIP LH <i>new</i>	\$ 156.00
10	10	FRT BUMPER CLIP <i>new</i>	\$ 65.00
11	1	FRT BUMPER SIDE RETAINER LH - GUIDE <i>new</i>	\$ 136.00
12	1	FRT BUMPER SIDE RETAINER LH - UPP <i>new</i>	\$ 106.00
13	1	FRT BUMPER SIDE RETAINER RH - GUIDE	\$ 136.00
14	1	FRT BUMPER SIDE RETAINER RH - UPP	\$ 106.00
15	1	FRT BUMPER BRACKET LH <i>could</i>	\$ 192.00
16	1	FRT BUMPER BRACKET RH <i>could</i>	\$ 192.00
17	1	FRT BUMPER UNDER DUST COVER <i>new</i>	\$ 290.00
18	1	FRT BUMPER BRACKET TOP CENTRE <i>new</i>	\$ 198.00
19	1	FRT BRACE BRACKET CENTRE <i>Best</i>	\$ 229.00
20	1	FRT BRACE BRACKET RH <i>Best</i>	\$ 118.00
21	1	FRT BRACE BRACKET LH <i>Best</i>	\$ 118.00
22	1	FRT BUMPER SPONGE <i>could</i>	\$ 254.00
23	1	FRT BUMPER REINFORCEMENT UPP (metal) <i>Best</i>	\$ 798.00
24	1	FRT BUMPER REINFORCEMENT LOW (firbe) <i>could</i>	\$ 374.00
25	2	FRT BUMPER PARKING SENSOR <i>new</i>	\$ 544.00
26	2	FRT BUMPER PARKING SENSOR SEAL <i>new</i>	\$ 24.00
27	1	FRT BUMPER PARKING SENSOR WIRE HARNESS <i>new</i>	\$ 394.00
28	1	FRT GRILLE ASSY <i>could</i>	\$ 800.00
29	1	FRT GRILLE LOGO <i>could</i>	\$ 160.00

30	1	FRT LOW CENTRE GRILLE	Ab new Cracked	\$	202.00	✓
31	1	RH HEADLAMP	3 covered	\$	820.00	✓
32	1	LH HEADLAMP		\$	820.00	✓
33	1	LH FOG LAMP		\$	434.00	+
34	1	LH FOG LAMP COVER		\$	120.00	+
35	1	RH FOG LAMP	new	\$	434.00	+
36	1	RH FOG LAMP COVER		\$	120.00	+
37	1	FRT FENDER LH	Repair	\$	682.00	+
38	1	FRT FENDER INNERSHIELD LH	3 new	\$	138.00	+
39	10	FENDER INNERSHIELD CLIP		\$	65.00	+
40	1	FRT FENDER RH	Repair	\$	682.00	+
41	1	FRT FENDER INNERSHIELD RH	new	\$	138.00	+
42	1	RADIATOR SUPORT PANEL TOP GARNISH RH	3 new	\$	152.00	✓
43	1	RADIATOR SUPORT PANEL TOP GARNISH LH		\$	152.00	✓
44	1	RADIATOR SUPORT PANEL TOP	Repair	\$	334.00	+
45	1	FRT HEADLAMP PANEL RH	Repair	\$	160.00	+
46	1	RADIATOR	3 new	\$	1,424.00	2
47	1	RADIATOR COOLANT	new	\$	164.00	✓
48	1	RADIATOR FAN ASSY	new	\$	1,806.00	7.
49	1	RADIATOR TOP BRACKET LH	Not New	\$	124.00	2
50	1	RADIATOR TOP BRACKET RH	Not New	\$	124.00	2
51	1	RADIATOR BRACKET LOWER LH	Not New	\$	162.00	2
52	1	RADIATOR BRACKET LOWER RH	Not New	\$	162.00	2
53	1	A/C CONDENSER	3 new	\$	730.00	2
54	1	A/C CONDENSOR AIR GUIDE TOP CENTRE	Cracked	\$	158.00	2
55	1	A/C CONDENSER AIR GUIDE RH	Cracked	\$	134.00	2
56	1	A/C CONDENSER AIR GUIDE LH	Cracked	\$	138.00	2
57	1	A/C PIPE (comp to cooling coil)	3 new	\$	934.00	+
58	1	A/C PIPE (cooling coil to condenser)		\$	916.00	+
59	1	A/C AMBIENT SENSOR	new	\$	317.00	+
60	1	INTERCOOLER, TURBOCHARGER AIR GUIDE	Cracked	\$	514.00	2
61	1	INTERCOOLER, TURBOCHARGER	3 new Not new	\$	1,060.00	2
62	1	INTERCOOLER HOSE(turbo to intercooler), INLET	3 new	\$	302.00	+
63	1	INTERCOOLER HOSE(intercooler to throttle body), OUTLET	new	\$	292.00	+
64	1	ENGINE AIR INTAKE DUCT	3 new	\$	166.00	2
65	1	FRT ARLARM SIREN RH	3 new	\$	420.00	+
66	1	FRT ARLARM SIREN BRACKET RH	new	\$	60.00	+

Parts Total: \$ 25,859.00

Less 10%: \$ 2,585.90

Total: \$ 23,273.10

Labour

Labour Description

No.	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. \$ 3,250.00 1950

2	Carry out spray painting on affected area, FRT BUMPER, FRT RH FENDER, FRT SUPORT PANEL, FRT LH FENDER, FRT BONNET, FRT DOOR RH, FRT DOOR LH	\$ 3,850.00	1650
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 220.00	180
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 600.00	2
5	To remove and refix radiator and conduct pressure test	\$ 180.00	7.120
6	To conduct diagnostic check	\$ 350.00	x

Labour Total : \$ 8,450.00

Others

Other Description

No.		Price (SGD)
1	FRT NUMBER PLATE <i>amber</i>	\$ 65.00

Other Total: \$ 65.00

TOTAL: \$ 31,788.10
 GST (7%): \$ 2,225.17
 GRAND TOTAL : \$ 34,013.27

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Advisor

Adrian King
R/P 18/12/18

05 days
Not Authorised
Excess : TBA.

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to market fluctuation • Third party survey is on a "Without Prejudice" basis • No illegal modifications allowed • Supplementary items must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer: Signature: Date:</p>

FINALIZE

AIG ASIA PACIFIC INSURANCE PTE LTD

OST Ref. No: 20-000274-2

Vehicle No: 8QYE777U
 Chassis No: WOLBESEAHG178788
 Engine No: B1171967H9000471
 Date of accident: 12/12/2018

Invoice No:

Invoice Date:

DESCRIPTION	AMOUNT	SGD
-------------	--------	-----

Parts

No.	Qty	Description	Price (SGD)
1	1	FRT BUMPER	\$ 1,994.00
2	5	FRT BUMPER CLIP	\$ 50.00
3	1	FRT BUMPER SIDE RETAINER LH - GUIDE	\$ 136.00
4	1	FRT BUMPER SIDE RETAINER LH - UPP	\$ 106.00
5	1	FRT BUMPER SIDE RETAINER RH - GUIDE	\$ 136.00
6	1	FRT BUMPER SIDE RETAINER RH - UPP	\$ 106.00
7	1	FRT BUMPER BRACKET LH	\$ 192.00
8	1	FRT BUMPER BRACKET RH	\$ 192.00
9	1	FRT BUMPER BRACKET TOP CENTRE	\$ 198.00
10	1	FRT BRACE BRACKET CENTRE	\$ 229.00
11	1	FRT BRACE BRACKET RH	\$ 118.00
12	1	FRT BRACE BRACKET LH	\$ 118.00
13	1	FRT BUMPER SPONGE	\$ 254.00
14	1	FRT BUMPER REINFORCEMENT UPP (metal)	\$ 798.00
15	1	FRT BUMPER REINFORCEMENT LOW (fibre)	\$ 374.00
16	1	FRT GRILLE ASSY	\$ 890.00
17	1	FRT GRILLE LOGO	\$ 160.00
18	1	FRT LOW CENTRE GRILLE	\$ 202.00
19	1	RH HEADLAMP	\$ 820.00
20	1	LH HEADLAMP	\$ 820.00
21	1	RADIATOR SUPORT PANEL TOP GARNISH RH	\$ 152.00
22	1	RADIATOR SUPORT PANEL TOP GARNISH LH	\$ 152.00
23	1	RADIATOR	\$ 1,424.00
24	1	RADIATOR COOLANT	\$ 164.00
25	1	A/C CONDENSER	\$ 730.00
26	1	A/C CONDENSER AIR GUIDE TOP CENTRE	\$ 158.00
27	1	A/C CONDENSER AIR GUIDE RH	\$ 134.00
28	1	A/C CONDENSER AIR GUIDE LH	\$ 138.00
29	1	INTERCOOLER TURBOCHARGER AIR GUIDE	\$ 314.00
30	1	ENGINE AIR INTAKE DUCT	\$ 166.00

Supplementary

1			
---	--	--	--

Total: \$ 11,518.00
Less 10%: \$ 1,151.80
Parts Total: \$ 10,366.20

Labour

No.		Price (SGD)
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIRED / REPLACEMENT PARTS.	\$ 1,950.00
2	Carry out spray painting on affected area, FRT BUMPER, FRT RH FENDER, FRT SUPORT PANEL, FRT LH FENDER, FRT BONNET, FRT DOOR RH, FRT DOOR LH	\$ 1,650.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	\$ 180.00
4	TO REMOVE AND REFIT AIRCON CONDENSOR , VACUUM , REFILL AND CHECK AIR CON GAS SYSTEM	\$ 600.00
5	To remove and refix radiator and conduct pressure test	\$ 120.00

Labour Total: \$ 4,500.00

Other

No.		Price (SGD)
1	FRONT NUMBER PLATE WITH CASING	\$ 65.00

Other Total: \$ 65.00

Total: \$ 14,928.50
Excess: \$ 600.00
GST (7%): \$ 1,003.00
Grand Total: \$ 15,331.50

Yours Faithfully,

Ketrin Chew
Service Advisor
Tel: 68441985 Fax: 68445185

Please check and finalize with me



SATISFACTION NOTE

I LEE WENG KEONG IC NO : S7027493J hereby certified that Vehicle No :SGY5777U had been carried out to my entire Satisfaction &I agree that for the discharge of the repair from Auto Germany Pte Ltd for S600+GST 7%~\$642.00 being payment of the insurance excess by Auto Germany Pte Ltd shall be in full discharge of all claims In respect of the damage to this vehicle which resulting from an accident which occurred on or about the day of 12-12-2018

Date

26/1/2019

Signature

[Handwritten Signature]

IC NO & Name

S7027493J
Lee Weng Keong



AUTO GERMANY PTE LTD
 7, 131 Clinic, Alpha Centre, S40864

TAX INVOICE

AIG ASIA PACIFIC INSURANCE PTE LTD
 78, SHENTON WAY, AIG BUILDING
 #07-18
 SINGAPORE 379120

OST Ref. No: M280234824

Vehicle No: SGYS777U
 Chassis No: WJLBEREAGHQ178788
 Engine No: S1171667HROK0471
 Date of accident: 12/12/2018

Invoice No: CGI-ASC-15/R010236

Invoice Date: 12-3-2019

DESCRIPTION	AMOUNT	SGD
No. Description		
3 Carry out part by part repair on accident vehicle corresponding to supply of spare parts, labour and spray painting charges	\$	14,328.50

Total: \$ 14,328.50
 Excess: \$ 800.00
 Less Excess: \$ 14,328.50
 GST (7%): \$ 1,003.00
 Grand Total: \$ 15,331.50

Yours Faithfully,



Vincent Sim
 Claims Dept
 Tel: 85113022 ext 343

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO 'Auto Germany Pte Ltd'
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Dec 2018		14 Dec 2018 17:44 Edit Adj Rpt	S\$14,928.50 Edit Estimates	S\$14,928.50 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	LEE WENG KEONG , ID: S7027493J, Tel: +6598556680, Email: LEEWENGKEONG@GMAIL.COM								
Vehicle Reg. No.:	SGY5777U	Date of Loss:	12/12/2018 17:00 - :59 [17 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 0764797494SG	Policy/Cover Note No.:	1800066896 (Comprehensive)						
		Excess:	S\$600.00						
Repairer:	Auto Germany Pte Ltd (HQ) 7 Ubi Close., Alpine Centre, 408604 Kaki Bukit - Tel: 6511 3025								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/12/2018]								
Driver/Custodian:	LEE WENG KEONG (48 / Male), NRIC: S7027493J, Tel: +6598556680 Email: LEEWENGKEONG@GMAIL.COM								
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail						
<ul style="list-style-type: none"> AIG_SG (01/02/2019): Alert - Adj Mandate Approved (S\$14928.50) - SGY5777U - Claim Handler: Mohd Zaway... AIG_SG (19/12/2018): Alert - Adj Mandate Approved (S\$10541.00) - SGY5777U - Claim Handler: Mohd Zaway... AIG_SG (18/12/2018): SGY5777U / OD / 12/12/2018 / Coverage & Excess update 									
ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGY5777U (0764797494SG)
 OD
 Dec 12 2018 5:00PM
 [LEE WENG KEONG]
 Auto Germany Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View	View in Browser <input type="checkbox"/>
Assessment Reports			1 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/12/18 11:00	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
2	29/01/19 09:57	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
2	19/12/18 10:16	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
4	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
5	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
6	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
7	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
8	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
9	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
10	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
11	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
12	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
13	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
14	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
15	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
16	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
17	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
18	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
19	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
20	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
21	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
22	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
23	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
24	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
25	19/12/18 10:16	General View	Load JPG	<input checked="" type="checkbox"/>
26	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
27	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
28	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
33	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
35	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
62	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
63	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
64	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
65	29/01/19 09:53	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/12/18 10:13	ESTIMATE.pdf	Load PDF	
2	19/12/18 10:13	DRIVING & INS CERT.pdf	Load PDF	
3	29/01/19 09:54	ESTIMATE MARKED.pdf	Load PDF	
4	10/06/19 14:36	Workshop Invoice	Load PDF	
5	10/06/19 14:36	Discharge Voucher	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	13/12/18 11:41	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/12/18 19:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	12/12/18 19:01	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
----	--------------	-----------------------------------	-----------	-------

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	13/12/18 11:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	13/12/18 11:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	13/12/18 11:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	13/12/18 11:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	13/12/18 11:37	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Progressive Car Care Pte Ltd (HQ)	Thumbnail	Print
1	13/12/18 11:40	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	13/12/18 11:40	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	13/12/18 11:41	CI	 Load JPG	<input checked="" type="checkbox"/>
4	13/12/18 11:41	DRIVER NRIC & LICENSE	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG18022539/ASD3E2

Date: 10/06/2019

REFERENCE

Insured/Claimant:	LEE WENG KEONG	Policy No:	1800066896	
Date of Loss:	12/12/2018	Nature of Claim:	OD	Claim No: 0764797494SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGY5777U	Engine No:	B1170487HRXX0952
Make & Model:	OPEL ASTRA, 999cc HB (A)	Chassis No:	W0LBE6EA5HG113250
Reg. Date:	10/07/2017 (Man. Year: 2017)	Odometer:	13743 km
Colour:	White		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$75,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,338.10	10,428.50	12,909.60	55.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,450.00	4,500.00	3,950.00	46.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,788.10	14,928.50	16,859.60	53.04
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	31,188.10	14,328.50	16,859.60	54.06
+ GST 7.00/7.00% (S\$)	2,183.17	1,003.00	1,180.17	54.06
Nett Amount (S\$)	33,371.27	15,331.50	18,039.77	54.06

INSPECTION

Date of Assignment:	14/12/2018		
Date Inspected:	18/12/2018	Inspected At:	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING) SINGAPORE 415933

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Not Necessary	1,758.00 FL	*- FL
2	1		*FRT BONNET LOCK	Not Necessary	312.00 FL	*- FL
3	1		*FRT BONNET LOCK CABLE	Not Necessary	277.00 FL	*- FL
4	1		*FRT BONNET HINGE LH	Not Necessary	186.00 FL	*- FL
5	1		*FRT BONNET HINGE RH	Not Necessary	186.00 FL	*- FL
6	4		*FRT BONNET STOPED	Not Necessary	40.00 FL	*- FL
7	1		*FRT BUMPER	Distorted	1,994.00 FL	*1,994.00 FL
8	1		*FRT BUMPER LOW LIP RH	Not Necessary	156.00 FL	*- FL
9	1		*FRT BUMPER LOW LIP LH	Not Necessary	156.00 FL	*- FL
10	10		*FRT BUMPER CLIP	Necessary	65.00 FL	*30.00 FL
11	1		*FRT BUMPER SIDE RETAINER LH - GUIDE	Necessary	136.00 FL	*136.00 FL
12	1		*FRT BUMPER SIDE RETAINER LH - UPP	Necessary	106.00 FL	*106.00 FL
13	1		*FRT BUMPER SIDE RETAINER RH - GUIDE	Necessary	136.00 FL	*136.00 FL
14	1		*FRT BUMPER SIDE RETAINER RH - UPP	Necessary	106.00 FL	*106.00 FL
15	1		*FRT BUMPER BRACKET LH	Cracked	192.00 FL	*192.00 FL
16	1		*FRT BUMPER BRACKET RH	Cracked	192.00 FL	*192.00 FL
17	1		*FRT BUMPER UNDER DUST COVER	Not Necessary	290.00 FL	*- FL
18	1		*FRT BUMPER BRACKET TOP CENTRE	Damaged	198.00 FL	*198.00 FL
19	1		*FRT BRACE BRACKET CENTRE	Bent	229.00 FL	*229.00 FL
20	1		*FRT BRACE BRACKET RH	Bent	118.00 FL	*118.00 FL
21	1		*FRT BRACE BRACKET LH	Bent	118.00 FL	*118.00 FL
22	1		*FRT BUMPER SPONGE	Cracked	254.00 FL	*254.00 FL
23	1		*FRT BUMPER REINFORCEMENT UPP (METAL)	Bent	798.00 FL	*798.00 FL
24	1		*FRT BUMPER REINFORCEMENT LOW (FIRBE)	Cracked	374.00 FL	*374.00 FL
25	2		*FRT BUMPER PARKING SENSOR	Not Necessary	544.00 FL	*- FL
26	2		*FRT BUMPER PARKING SENSOR SEAL	Not Necessary	24.00 FL	*- FL
27	1		*FRT BUMPER PARKING SENSOR WIRE HARNESS	Not Necessary	394.00 FL	*- FL
28	1		*FRT GRILLE ASSY	Cracked	800.00 FL	*800.00 FL
29	1		*FRT GRILLE LOGO	Cracked	160.00 FL	*160.00 FL
30	1		*FRT LOW CENTRE GRILLE	Cracked	202.00 FL	*202.00 FL
31	1		*RH HEADLAMP	Cracked	820.00 FL	*820.00 FL
32	1		*LH HEADLAMP	Cracked	820.00 FL	*820.00 FL
33	1		*LH FOG LAMP	Not Necessary	434.00 FL	*- FL
34	1		*LH FOG LAMP COVER	Not Necessary	120.00 FL	*- FL
35	1		*RH FOG LAMP	Not Necessary	434.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*RH FOG LAMP COVER	Not Necessary	120.00 FL	*- FL
37	1		*FRT FENDER LH	Repair	682.00 FL	*- FL
38	1		*FRT FENDER INNERSHIELD LH	Not Necessary	138.00 FL	*- FL
39	10		*FENDER INNERSHIELD CLIP	Not Necessary	65.00 FL	*- FL
40	1		*FRT FENDER RH	Repair	682.00 FL	*- FL
41	1		*FRT FENDER INNERSHIELD RH	Not Necessary	138.00 FL	*- FL
42	1		*RADIATOR SUPORT PANEL TOP GARNISH RH	Deformed	152.00 FL	*152.00 FL
43	1		*RADIATOR SUPORT PANEL TOP GARNISH LH	Deformed	152.00 FL	*152.00 FL
44	1		*RADIATOR SUPORT PANEL TOP	Repair	334.00 FL	*- FL
45	1		*FRT HEADLAMP PANEL RH	Repair	160.00 FL	*- FL
46	1		*RADIATOR	Dented	1,424.00 FL	*1,424.00 FL
47	1		*RADIATOR COOLANT	Necessary	164.00 FL	*164.00 FL
48	1		*RADIATOR FAN ASSY	Not Necessary	1,806.00 FL	*- FL
49	1		*RADIATOR TOP BRACKET LH	Not Necessary	124.00 FL	*- FL
50	1		*RADIATOR TOP BRACKET RH	Not Necessary	124.00 FL	*- FL
51	1		*RADIATOR BRACKET LOWER LH	Not Necessary	162.00 FL	*- FL
52	1		*RADIATOR BRACKET LOWER RH	Not Necessary	162.00 FL	*- FL
53	1		*A/C CONDENSER	Dented	730.00 FL	*730.00 FL
54	1		*A/C CONDENSOR AIR GUIDE TOP CENTRE	Cracked	158.00 FL	*158.00 FL
55	1		*A/C CONDENSER AIR GUIDE RH	Cracked	134.00 FL	*134.00 FL
56	1		*A/C CONDENSER AIR GUIDE LH	Cracked	138.00 FL	*138.00 FL
57	1		*A/C PIPE (COMP TO COOLING COIL)	Not Necessary	934.00 FL	*- FL
58	1		*A/C PIPE (COOLING COIL TO CONDENSER)	Not Necessary	916.00 FL	*- FL
59	1		*INTERCOOLER, TURBOCHARGER AIR GUIDE	Cracked	514.00 FL	*514.00 FL
60	1		*INTERCOOLER, TURBOCHARGER	Not Necessary	1,060.00 FL	*- FL
61	1		*INTERCOOLER HOSE (TURBO TO INTERCOOLER), INLET	Not Necessary	302.00 FL	*- FL
62	1		*INTERCOOLER HOSE (INTERCOOLER TO THROTL BODY), OUTLET	Not Necessary	292.00 FL	*- FL
63	1		*ENGINE AIR INTAKE DUCT	Deformed	166.00 FL	*166.00 FL
64	1		*FRT ARLARM SIREN RH	Not Necessary	420.00 FL	*- FL
65	1		*FRT ARLARM SIREN BRACKET RH	Not Necessary	60.00 FL	*- FL
66	1		*FRT NUMBER PLATE	Cracked	65.00 FS	*65.00 FS
67	1		*A/C AMBIENT SENSOR	Not Necessary	317.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,924.00	11,580.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,585.90	1,151.50
Total Parts (\$\$)	23,338.10	10,428.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	3,250.00	1,950.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA, FRT BUMPER, FRT RH FENDER, FRT SUPORT PANEL, FRT LH FENDER, FRT BONNET, FRT DOOR RH, FRT DOOR LH	New	3,850.00	1,650.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	220.00	180.00
4	TO REMOVE AND REFIT AIRCON CONDENSOR, VACUUM, REFILL AND CHECK AIR CON GAS SYSTEM	New	600.00	600.00
5	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	180.00	120.00
6	TO CONDUCT DIAGNOSTIC CHECK	New	350.00	0.00
Gross Labour Cost (S\$)			8,450.00	4,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >