

ASS. REC. BY:

REF

CS/CT18022559/ Gsd3

Special Instruction:

Surveyor
MeimenGuo Qing
Elaine Cheong

ASSIGNMENT (Office)

From (Person):

of

CT1

Date/Time:

14/12/18 4:16pm

Estimated Cost:

Bill to:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 9433 U

Insured:

SJM 6138 K

at Workshop m/s:

BW Workshop

Tel:

66920125

of

30 ubi Road 4

Policy No:

DMPCSN1832111800

Claim No:

SNM18 D05620C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/11/2018

CA / REV / REP. / REV 24 HRS

up

19.12.2018 @ 11am

H.O.D. Endorsement:

Date/Time:

10:01am @ 14/12/18

Person Contacted:

syahrah

Vehicle IN ☒ OUT

Date/Time

Action/Instruction (✓) Estimate

GBF 9433 U - X

SJM 6138 K - CS / AV1109019623 / Rbrl

Dot: 25/05/2021

XmL

REF: C11

C72374

ASSIGNMENT

Date: 19/12/18

Estimated Cost

OD (1) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBF 94334

at Workshop m/s: BW workshop
of: 30 ubi Road 4

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bat. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up'

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No

GBF94334

Y Reg: 20 Apr 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna

CC 2982

Colour:

white

A/C Insured / Std / NI / NA

Sp. Reading

83245

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KDY2318028002

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

155 R15

R:

185 R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Plan Kack (Ch)

Front

Rear

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

D.O.I.

19-12-18

Survey held at

w/s

11AM

Des. of Damages: Frt / Rear / D/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

15/8

Finalized \$ 2600 with Yvonne
owner change w/s to 2-one
(\$ 5,281.35 Red - 67%)

16/8/2019

RECEIVED 19 AUG 2019

Date/Time, File Pass to?

1) 19/12/18
Type 4

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation

\$ + P.S. \$

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$ 2.600/- 1/5)

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Dec 2018		14 Dec 2018 16:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	ANG CHEE BENG, ID: S7347138I		
Main Claimant:	EVERGREEN 96 DESIGN CONSTRUCTION PTE LTD, Co. Reg. No.: 201207237H		
Vehicle Reg. No.:	GBF9433U	Date of Loss:	30/11/2018 16:00 - :59
Claim Type:	TP / SNM18D05620C02	Policy/Cover Note No.:	DMPCSN1832111800 (Comprehensive)
Vehicle Reg. No. (Insured):	SJM6138K	Policy No. (Claimant):	DMCPHQ18-001520
		Excess:	S\$0.00
Repairer:	Bw Workshop Services Pte Ltd (HQ) 30 UBI ROAD 4, 408615 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/12/2018]		
Driver/Custodian (Insured):	ANG CHEE BENG (44 / Male), NRIC: S7347138I		
Adj Asg. Remarks:	EST \$7721.55 , CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7237H
Vehicle Details	
Vehicle No.:	GBF9433U
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 DIESEL TURBO M/T 2WD LORRY
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1KD2681179
Chassis No.:	KDY2318028002
Maximum Power Output:	-
Open Market Value:	\$32,499.00
Original Registration Date:	20 Apr 2017
First Registration Date:	20 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$1,625.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Apr 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$45,906.00
COE Rebate Amount:	\$38,250.00
Total Rebate Amount:	\$38,250.00

The information contained herein is correct as at 20 Dec 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/12/2018 10:42
Date Of Accident	30/11/2018 16:30
Exact Location Of Accident	PIE TOWARDS CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF9433U
Insured/Policyholder	
Name Of Registered Owner	EVERGREEN 96 DESIGN CONSTRUCTION PTE LTD
Co Reg No	201207237H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-94508987

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA-3.0 D TURBO M/T 2WD (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ18-001520
Cover Note Number	

Driver

Name of Driver	MARIMUTHU NATARAJAN
NRIC No	G7317748R
Date Of Birth	07/06/1979
Occupation	OUTDOOR
Date Of Driving Pass	16/06/2008
Driving Experience	10 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84297521
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	C/O 6 YISHUN INDUSTRIAL STREET 1 #05-12 NORTHVIEW BIZHUB SINGAPORE
Postcode	768160
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : SUJAN GENDER: : MALE
Passenger 2	NAME: : SARAVANAN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM6138K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKM4538R

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SGN2489D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

MARIMUTHU NATARAJAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

GBF9433U

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

SUJAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

GBF9433U

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 3

Name	SARAVANAN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	GBF9433U
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claim and any necessary investigations relating to the claim;
 - (ii) investigating the accident and/or my claim;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claim (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims collectively the "Purposes";
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Person's Signature
Name:
NRIC/PIN No:

permen

Sketch Plan #2

SKETCH PLAN

<p>PIE TO Changi Airport</p>	<p>Vehicle</p> <p>A - G8F 9433U</p> <p>B - SJM 6138K</p> <p>C - SKM 4538R</p> <p>D - SGN 2489D</p> <p>Legend</p> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> Vehicle </div> <div style="text-align: center;"> Motorcycle </div> </div>
------------------------------	---

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 30/11/2018, Around 4:30pm. I was driving along PIE towards Changi Airport. My lorry is on lane 2. Suddenly, that was a car B SJM 6138K swerve his car from lane 1 to lane 2 and collided onto my lorry. The car B also involve accident with another 2 cars.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 Please be advised that your insurer may have a fourteen (14) days class period to make the claim against your policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature
 Date & Time:



Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

perman

BW WORKSHOP SERVICES PTE LTD

30 UBI ROAD 4

SINGAPORE

Singapore 408615

6289 8800

workshop@bw.com.sg

GST Registration No. : 201504834E

Company Registration No. 201504834E



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATES NO. 1017**DATE 06/12/2018****ESTIMATES****ADDRESS**

CHINA TAIPING INSURANCE

(SINGAPORE) PTE LTD

CHINA TAIPING INSURANCE

(SINGAPORE) PTE LTD

VEHICLE NO.

GBF9433U

MILEAGE

NA

MAKE & MODEL

TOYOTA DYNA

ACTIVITY	QTY	RATE	AMOUNT
FRT BUMPER <i>Repair X</i>	1	721.10	721.10
FRT DRIVER DOOR <i>/ BT</i>	1	1,530.10	1,530.10
FRT SIGNAL RH <i>/ mis</i>	1	75.60	75.60
FRT HEADLAMP RH <i>/ SCR</i>	1	659.10	659.10
STEP GARNISH <i>X NN</i>	1	231.60	231.60
LOWER ARM <i>X</i>	1	487.40	487.40
UPPER ARM <i>X</i>	1	791.50	791.50
TYRE RH <i>/ Be</i>	1	150.00	150.00
REAR CANVAS <i>/ TN</i>	1	250.00	250.00
DOOR STICKER <i>/ ent</i>	1	50.00	50.00
Labour Charges STD	1	2,270.00	2,270.00

100

Labour Charges STD

- TO REPAIR FRT DOOR, BUMPER AND REPLACE ACCIDENT PORTION \$800.00 *400*
- TO RESPRAY PAINT ON ACCIDENT PORTION \$800.00 *600*
- TO CHECK REAR WIRING \$50.00 *30*
- TO TUFF-KOTE \$150.00 *60*
- TO REMOVE & TRANSFER SIDE MIRROR \$80 *40*
- TO REMOVE & TRANSFER DOOR WINDSCREEN GLASS \$80.00 *40*
- TO REMOVE & TRANSFER DOOR POWER WINDOW MOTOR \$60.00 *20*
- TO REMOVE & REPLACE LOWER ARM, UPPER ARM \$250.00 *X NN*

wheel Alignment report. - 60.

NETS & Cash only.

Our Bank Details:-

Name of Bank : UOB

Account Name : BW Workshop Services Pte Ltd

Account Number :356-305-177-7

5 Days. 2/12/18
part by part.
before paint photos.

Gino Gino.
19/12/18

Please feel free to contact us again if you have any queries on our quotation.
This quotation is valid for 7 days ONLY.

We look forward to seeing you again.

SUBTOTAL
GST TOTAL
TOTAL

7,216.40
505.16

SGD 7,721.56

Accepted By

Accepted Date

NETS & Cash only.

Our Bank Details:-

Name of Bank : UOB

Account Name : BW Workshop Services Pte Ltd

Account Number :356-305-177-7



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

ESTIMATE

Evergreen 96 Design Construction Pte Ltd
6 Yishun Industrial Street 1 #05-12 Northview
Bizhub Singapore 768160

Contact : 94508987

Code : C101876

Date in : 24/01/2019

Vehicle Num. : GBF9433U

Model : Toyota Dyna 3.0 Diesel Turbo M/T
2WD Lorry

Chassis/Eng# : KDY2318026002/1KD2681179

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
Front Bumper <i>X Repair</i>	1	721.10	721.10
Front Corner Panel Bracket RH <i>X NN</i>	1	56.80	56.80
Front Corner Panel RH <i>/ Cut</i>	1	202.30	202.30
Front Door Hinge RH <i>/ BT</i>	1	90.30	90.30
Front Door Mechanism Lock RH <i>X</i>	1	180.00	180.00
Front Door Regulator Motor RH <i>X NN</i>	1	761.90	761.90
Front Door Regulator RH <i>X</i>	1	444.10	444.10
Front Door RH <i>/ BT</i>	1	1530.10 <i>1380</i>	1,530.10 <i>989.6</i>
Front Door Signal Lamp RH <i>/ M's</i>	1	75.60	75.60
Front Door Step Garnish RH <i>X NN</i>	1	231.60	231.60
Front Door Weather Strip RH <i>/ TN</i>	1	90.00	90.00
Front Headlamp RH <i>/ Sup</i>	1	659.10	659.10 <i>616</i>
Front Lower Arm RH <i>X</i>	1	487.40	487.40
Front Upper Arm RH <i>X NN</i>	1	791.50	791.50
Subtotal before discount <i>2454.2</i>			6,321.80 <i>2563.8</i>
Percentage discount 25%			1,580.45 <i>1547.65</i>
Sub-total 1 <i>25% 1840.65</i>			4,741.35 <i>10</i>
Front Door 'Company Detail' Sticker (SN) <i>/ Cut</i>	1	50.00	50.00



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

Front Door Company Logo Sticker (SN) / ABC	1	200.00	200.00	50
Front Tyre RH (SN) / Cut	1	280.00	100	280.00
Rear Canvas (SN) / TV	1	250.00		250.00
				80
				240
Subtotal before discount			780.00	
Percentage discount 0%			0.00	
Sub-total 2			780.00	
Parts-total			5,521.35	

LABOUR

Description	Price
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	30 80.00
To diagnose, replace and/or repair to rectify front door electrical system for proper functioning	60 100.00
To remove, reinstall front door window glass. (to FR)	X 80.00
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	X 250.00
To conduct computerise wheel alignment and adjustments	60 100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	600 800.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	400 800.00
To apply anti-rust chemical (Tuff-Kote) on repaired and replaced panel.	60 150.00
Labour Total	2,360.00
Parts & Labour Total	7,881.35

page 2

Guo Qian P.

5 Days

2997.85 3290.65

20%: 2400 2600

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Lump sum repair - After repair photos

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118022559/GSD3N2

Date: 19/08/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1832111800
Claimant Vehicle No :	GBF9433U	Insured Vehicle No :	SJM6138K
Date of Loss:	30/11/2018	Nature of Claim:	TP
		Claim No:	SNM18D05620C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF9433U	Engine No:	1KD2681179
Make & Model:	TOYOTA DYNA, 3.0 D TURBO M/T 2WD (M)	Chassis No:	KDY2318028002
Reg. Date:	20/04/2017 (Man. Year: 2016)	Odometer:	83245 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	185R13
Front Left Side:	Hankook 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,521.35	2,080.65	3,440.70	62.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,360.00	1,210.00	1,150.00	48.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,881.35	3,290.65	4,590.70	58.25
Approved Total (Overridden) (\$\$)		2,600.00		
(\$\$)	7,881.35	2,600.00	5,281.35	67.01
+ GST 7.00/7.00% (\$\$)	551.69	182.00	369.69	67.01
Nett Amount (\$\$)	8,433.04	2,782.00	5,651.04	67.01

INSPECTION

Date of Assignment:	14/12/2018	
Date Inspected:	19/12/2018 Inspected At:	BW WORKSHOP SERVICES PTE LTD 30 UBI ROAD 4 SINGAPORE 408615 REPAIRER: Z-ONE AUTOMOTIVE PTE LTD
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Aug 2019)	
Parts:	N/A	TOYOTA DYNA 3.0 D TURBO M/T 2WD (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF9433U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	721.10 FL	*- FL
2	1		*FRONT CORNER PANEL BRACKET RH	Not Necessary	56.80 FL	*- FL
3	1		*FRONT CORNER PANEL RH	Cut	202.30 FL	*202.30 FL
4	1		*FRONT DOOR HINGE RH	Bent	90.30 FL	*90.30 FL
5	1		*FRONT DOOR MECHANISM LOCK RH	Not Necessary	180.00 FL	*- FL
6	1		*FRONT DOOR REGULATOR MOTOR RH	Not Necessary	761.90 FL	*- FL
7	1		*FRONT DOOR REGULATOR RH	Not Necessary	444.10 FL	*- FL
8	1		*FRONT DOOR RH	Bent	1,530.10 FL	*1,380.00 FL
9	1		*FRONT DOOR SIGNAL LAMP RH	Missing	75.60 FL	*75.60 FL
10	1		*FRONT DOOR STEP GARNISH RH	Not Necessary	231.60 FL	*- FL
11	1		*FRONT DOOR WEATHER STRIP RH	Torn	90.00 FL	*90.00 FL
12	1		*FRONT HEADLAMP RH	Scratched	659.10 FL	*616.00 FL
13	1		*FRONT LOWER ARM RH	Not Necessary	487.40 FL	*- FL
14	1		*FRONT UPPER ARM RH	Not Necessary	791.50 FL	*- FL
15	1		*FRONT DOOR COMPANY DETAIL STICKER	Cut	50.00 FS	*10.00 FS
16	1		*FRONT DOOR COMPANY LOGO STICKER	Necessary	200.00 FS	*50.00 FS
17	1		*FRONT TYRE RH	Cut	280.00 FS	*100.00 FS
18	1		*REAR CANVAS	Torn	250.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,101.80	2,694.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,580.45	613.55
Total Parts (\$\$)	5,521.35	2,080.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING (TO FR)	New	80.00	30.00
2	TO DIAGNOSE,REPLACE AND/OR REPAIR TO RECTIFY FRONT DOOR ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	100.00	60.00
3	TO REMOVE,REINSTALL FRONT DOOR WINDOW GLASS (TO FR)	New	80.00	0.00
4	TO REMOVE,CHANGE FRONT SUSPENSION PARTS,ABSORBER,LOWER ARM,KNUCKLE ARM,WHEEL BEARING,BEARING HUB,DRIVE SHAFT,ANTI-ROLL BAR,TOP-ARM AND STEERING RACK AND PINION	New	250.00	0.00
5	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT AND ADJUSTMENTS	New	100.00	60.00
6	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	800.00	600.00
7	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	800.00	400.00
8	TO APPLY ANTI-RUST CHEMICAL (TUFF-KOTE) ON REPAIRED AND REPLACED PANEL	New	150.00	60.00
Gross Labour Cost (\$\$)			2,360.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >