

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 18 Dec 2018

Preliminary Advice

Insured Vehicle No	: SBF300D		
TP Vehicle No	: SGT2338A	Accident Date	: 12/12/2018
Make	: TOYOTA HARRIER	Assignment Date	: 14/12/2018
Date of Inspection	: 17/12/2018	Est. Duration of Repair	: 4 days
Inspection At	: CP Motors Pte Ltd (HQ) BLK 34 #01-126, SIN MING DRIVE Singapore 575708		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,787.46
Revised Amount	:S\$	4,178.53
Check Items (Estimated)	:S\$	174.96
Total	:S\$	4,353.49
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP