

ASS. REC. BY:

REF: CS/SMO18022564/Kvd3nk

Special Instruction:

Surveyor
Meimer

ASSIGNMENT (Office)

From (Person):

Chan Shu Hui Agnes

SMO

Date/Time: 14/12/18 @ 3:47pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGT 2338A

Insured: SBF 300D

at Workshop m/s:

CP Motors

Tel: 82018103

of

Blk 94 # 01-126

Policy No:

D18MTPV01000179

Claim No:

CMTD1805532

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 12/12/18

CA / REV / REP. / REV 24 HRS

b up

H.O.D. Endorsement:

Date/Time: 10:20am @ 17/12/18

Person Contacted:

Thomas

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	Inspr: 160 Sh Ming Drive # 05-05
	SGT 2338A - X
	SBF 300D - X
18/12/18	@ 15:22 p.m. revised IA to Agnes Chan via meimer
27/12/18	@ 138pm Final fig \$ 4086.97 confirmed with Thomas (Red 1700-49, 29/12)

ASS. REC. BY:

REF:

Soh /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGT 2338 A

Yr Regn:

03, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy / Itanic

c.c

1998

Colour:

H. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

11441

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTE ZB 3G14 20J 001333

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/55R18

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

12/12/18

D.O.I.

17/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/12

Mileage to Garage

RECEIVED 27 DEC 2018

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 21/12 - typist

Report Format:

Lump Sum / I.B.I. (\$) :

merimen

4086.97

Days Of Repair:

4

Resurvey No. of Trlp:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

250
10
260

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 18 Dec 2018

Preliminary Advice

Insured Vehicle No	: SBF300D	Accident Date	: 12/12/2018
TP Vehicle No	: SGT2338A	Assignment Date	: 14/12/2018
Make	: TOYOTA HARRIER	Est. Duration of Repair	: 4 days
Date of Inspection	: 17/12/2018		
Inspection At	: CP Motors Pte Ltd (HQ) BLK 34 #01-126, SIN MING DRIVE Singapore 575708		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,787.46
Revised Amount	:S\$	4,178.53
Check Items (Estimated)	:S\$	174.96
Total	:S\$	4,353.49

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Dec 2018		14 Dec 2018 15:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TEO CHIN WEN, ID: S8007586C		
Main Claimant:	YIP LAI HA, ID: S1303257B		
Vehicle Reg. No.:	SGT2338A	Date of Loss:	12/12/2018 18:00 - :59
Claim Type:	TP / CMTD1805532	Policy/Cover Note No.:	D18MTPV01000179 (Comprehensive)
Vehicle Reg. No. (Insured):	SBF300D	Policy No. (Claimant):	
		Excess:	
Repairer:	CP Motors Pte Ltd (HQ) BLK 34 #01-126, SIN MING DRIVE, 575708 Sin Ming - Tel:		
Handling Insurer:	Sampo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/12/2018]		
Adj Asg. Remarks:	Please assign to Mr Kenneth Kong to conduct the survey.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/12/2018 18:44
Date Of Accident	12/12/2018 18:20
Exact Location Of Accident	BRADDELL ROAD TO CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGT2338A
Insured/Policyholder	
Name Of Registered Owner	YIP LAI HA
NRIC No	S1303257B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98178033
Alternative Phone No	OFFICE-98178033

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	0
Cover Note Number	CN881950

Driver

Name of Driver	YIP LAI HA
NRIC No	S1303257B
Date Of Birth	23/08/1958
Occupation	INDOOR
Date Of Driving Pass	12/03/1984
Driving Experience	34 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98178033
Fax Number	
Contact Number	OFFICE-98178033
EMail Address	NOEMAIL

Address	48 SELETAR GREEN WALK
Postcode	805265
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NICOLE NG
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBF300D
Vehicle Make/Model/Colour	VOLKSWAGEN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time: /


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: /


 Reporting Centre Personnel's Signature
 Name: B/12 @ 10 AM
 NRIC/FIN No.: /



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 12/12/18 at about 1830 hrs, I was travelling along Braddell Rd towards CTE. While approaching the bus stop, bus (SB3 8462) front was already out from the bus stop. I slow down to give way for the bus. Suddenly SBF 300D knock onto the rear of my car.

~~Repair~~ at other workshop.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Company Chop (if applicable)

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



13/18 E 10th

CP MOTORS PTE LTD

160 Sin Ming Drive #05-05 Sin Ming Auto City
Singapore 575722

Tel No. : 64571357 Fax No. : 64595357

Tax Reg. No. : 201535864N Buss. Reg. No. : 201535864N

C/O CP Motors Pte Ltd
160 Sin Ming Drive #05-05
Sin Ming Auto City S 575722

Attention : Motor Claim Department

Contact : 82018103

Not Authorized
Resurvey By 1.B.1
4 days

Estimate : ES000110

Date : 17/12/2018
Vehicle Num. : SGT2338A
Make/Model : Toyota Harrier M Grade-2018
Chassis/Eng# : JTEZB3GH20J001333/8ARZ109573
Accident Date : 12/12/2018
Claim No. :
Reference : T/P Claim Against Somp
Policy No. : CN881950

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|-----|-------|---------------------------|--|--|
| | | LIST ITEMS : | | |
| 1. | 1 pc | Rear Windscreen Moulding | | |
| 2. | 1 pc | Tailgate | | |
| 3. | 1 pc | Tailgate Emblem | | |
| 4. | 1 pc | Tailgate Emblem | | |
| 5. | 1 pc | Rear Bumper | | |
| 6. | 1 pc | Rear Bumper Sponge | | |
| 7. | 1 pc | Rear Bumper Side Retainer | | |
| 8. | 8 pcs | Rear Bumper Clip | | |
| 9. | 1 pc | Rear Bumper Lower | | |
| 10. | 1 pc | Rear Bumper Reflector | | |
| 11. | 1 pc | Reverse Sensor | | |

List TotalS\$:
25.00% Discount S\$:

<i>Re</i>	188.06	✓
<i>Re</i>	1,834.28	✓
<i>Re</i>	99.50	✓
<i>Re</i>	81.23	✓
<i>Bu</i>	792.44	✓
	152.45	?
<i>Re</i>	85.29	✓
5.00 <i>Re</i>	40.00	✓
<i>cm</i>	485.87	✓
	80.83	?
<i>Re</i>	250.00	✓
	4,089.95	
	1,022.49	
	3,067.46	

- | | | | | |
|----|------|----------------------|--|--|
| | | SPECIAL NETT ITEMS : | | |
| 1. | 1 pc | Sealant | | |
| 2. | 1 pc | Inner Seal | | |

Special Nett Total S\$:

LABOUR :
Remove/refix rear windscreen

<i>Re</i>	40.00	✓
<i>Re</i>	40.00	20.00
	80.00	

120.00 ✓

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CP MOTORS PTE LTD

160 Sin Ming Drive #05-05 Sin Ming Auto City
Singapore 575722

Tel No. : 64571357 Fax No. : 64595357

Tax Reg. No. : 201535864N Buss. Reg. No. : 201535864N

C/O CP Motors Pte Ltd
160 Sin Ming Drive #05-05
Sin Ming Auto City S 575722

Attention : Motor Claim Department

Contact : 82018103

Estimate : ES000110

Date : 17/12/2018

Vehicle Num. : SGT2338A

Make/Model : Toyota Harrier M Grade-2018

Chassis/Eng# : JTEZB3GH20J001333/8ARZ109573

Accident Date : 12/12/2018

Claim No. :

Reference : T/P Claim Against Sompoo

Policy No. : CN881950

S/N	Quantity	Particular	Unit Price	Amount S\$
		Transfer Tailgate Mechanism	120.00	60h
		Rust Proof Damaged Parts	60.00	30h
		To Install Parking Sensor To New Bumper	120.00	60h
		Check rear wiring	20.00	—
		To straighten tailgate hinges, rear end panel, luggage boot floor panel, right rear fender include replacement of parts.	1,000.00	500h
		Spray paint on tailgate, rear end panel, luggage boot floor panel, right rear fender & rear bumper.	1,200.00	500h
		Labour Total S\$:	2,640.00	

E. & O.E.

Total S\$: 5,787.46

=====


for CP MOTORS PTE LTD

CP MOTORS PTE LTD

160 Sin Ming Drive #05-05 Sin Ming Auto City

Singapore 575722

Tel No. : 64571357 Fax No. : 64595357

Tax Reg. No. : 201535864N Buss. Reg. No. : 201535864N

C/O CP Motors Pte Ltd
160 Sin Ming Drive #05-05
Sin Ming Auto City S 575722

Attention : Motor Claim Department

Contact : 82018103

Estimate : ES000110

Date : 17/12/2018
Vehicle Num. : SGT2338A
Make/Model : Toyota Harrier M Grade-2018
Chassis/Eng# : JTEZB3GH20J001333/8ARZ109573
Accident Date : 12/12/2018
Claim No. :
Reference : T/P Claim Against Sompco
Policy No. : CN881950

S/N Quantity Particular Unit Price Amount S\$

		LIST ITEMS :		
1.	1 pc	Rear Windscreen Moulding		188.06 ✓
2.	1 pc	Tailgate	1712.19	1,834.28
3.	1 pc	Tailgate Emblem		99.50
4.	1 pc	Tailgate Emblem		81.23
5.	1 pc	Rear Bumper		792.44
6.	1 pc	Rear Bumper Sponge		152.45
7.	1 pc	Rear Bumper Side Retainer		85.29
8.	8 pcs	Rear Bumper Clip	5.00	40.00
9.	1 pc	Rear Bumper Lower		485.87
10.	1 pc	Rear Bumper Reflector		80.83
11.	1 pc	Reverse Sensor		250.00
		List Total S\$:	3,771.38	4,089.95
		25.00% Discount S\$:	942.84	1,022.49
			2,828.54	3,067.46

		SPECIAL NETT ITEMS :		
1.	1 pc	Sealant		40.00
2.	1 pc	Inner Seal		40.00
		Special Nett Total S\$:		80.00
		LABOUR :		
		Remove/refix rear windscreen		120.00

03061
62
63
64
65

CONTINUE / ...

CP MOTORS PTE LTD

160 Sin Ming Drive #05-05 Sin Ming Auto City
Singapore 575722

Tel No. : 64571357 Fax No. : 64595357

Tax Reg. No. : 201535864N Buss. Reg. No. : 201535864N

C/O CP Motors Pte Ltd
160 Sin Ming Drive #05-05
Sin Ming Auto City S 575722

Attention : Motor Claim Department

Contact : 82018103


Estimate : ES000110

Date : 17/12/2018
Vehicle Num. : SGT2338A
Make/Model : Toyota Harrier M Grade-2018
Chassis/Eng# : JTEZB3GH20J001333/8ARZ109573
Accident Date : 12/12/2018
Claim No. :
Reference : T/P Claim Against Somp
Policy No. : CN881950

S/N	Quantity	Particular	Unit Price	Amount S\$
		Transfer Tailgate Mechanism	120.00	60h
		Rust Proof Damaged Parts	60.00	30h
		To Install Parking Sensor To New Bumper	120.00	60h
		Check rear wiring	20.00	—
		To straighten tailgate hinges, rear end panel, luggage boot floor panel, right rear fender include replacement of parts.	1,000.00	500h
		Spray paint on tailgate, rear end panel, luggage boot floor panel, right rear fender & rear bumper.	1,200.00	500h
		Labour Total S\$:	2,640.00	

E. & O.E.

Total S\$: 5,787.46
=====


for CP MOTORS PTE LTD

Parts - 2,838.54
SIN - 60.00
Labour - 1,290.00
4,178.54

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18022564/KVD3N2

Date: 28/12/2018

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPV01000179
Claimant Vehicle No :	SGT2338A	Insured Vehicle No :	SBF300D
Date of Loss:	12/12/2018	Nature of Claim:	TP
		Claim No:	CMTD1805532

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGT2338A	Engine No:	8ARZ109573
Make & Model:	TOYOTA HARRIER, 2.0 (A)	Chassis No:	JTEZB3GH20J001333
Reg. Date:	15/03/2018 (Man. Year: 2018)	Odometer:	11441 km
Colour:	Metallic Violet		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,147.46	2,796.97	350.49	11.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,640.00	1,290.00	1,350.00	51.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,787.46	4,086.97	1,700.49	29.38
+ GST 7.00/7.00% (S\$)	405.12	286.09	119.03	29.38
Nett Amount (S\$)	6,192.58	4,373.06	1,819.52	29.38

INSPECTION

Date of Assignment:	14/12/2018	
Date Inspected:	17/12/2018	Inspected At:
		160 SIN MING DRIVE# 05-05 REPAIRER:CP Motors Pte Ltd (HQ) BLK 34 #01-126, SIN MING DRIVE Singapore 575708

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2018)
Parts: M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGT2338A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	188.06 FL	*188.06 FL
2	1		*TAILGATE	Bent	1,834.28 FL	*1,712.19 FL
3	1		*TAILGATE EMBLEM	Necessary	99.50 FL	*99.50 FL
4	1		*TAILGATE EMBLEM	Necessary	81.23 FL	*81.23 FL
5	1		*REAR BUMPER	Buckled	792.44 FL	*792.44 FL
6	1		*REAR BUMPER SPONGE	Serviceable	152.45 FL	*- FL
7	1		*REAR BUMPER SIDE RETAINER	Serviceable	85.29 FL	*- FL
8	8		*REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
9	1		*REAR BUMPER LOWER	Cracked	485.87 FL	*485.87 FL
10	1		*REAR BUMPER REFLECTOR	Serviceable	80.83 FL	*- FL
11	1		*REVERSE SENSOR	Scratched	250.00 FL	*250.00 FL
12	1		*SEALANT	Necessary	40.00 FS	*40.00 FS
13	1		*INNER SEAL	Necessary	40.00 FS	*20.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	4,169.95	3,709.29
- List Item Discount on L Items 25.00/25.00% (S\$)	1,022.49	912.32
Total Parts (S\$)	3,147.46	2,796.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE/REFIX REAR WINDSCREEN	New	120.00	120.00
2	TRANSFER TAILGATE MECHANISM	New	120.00	60.00
3	RUST PROOF DAMAGED PARTS	New	60.00	30.00
4	TO INSTALL PARKING SENSOR TO NEW BUMPER	New	120.00	60.00
5	CHECK REAR WIRING	New	20.00	20.00
6	TO STRAIGHTEN TAILGATE HINGES, REAR END PANEL, LUGGAGE BOOT FLOOR PANEL, RIGHT REAR FENDER INCLUDE REPLACEMENT OF PARTS	New	1,000.00	500.00
7	SPRAY PAINT ON TAILGATE, REAR END PANEL, LUGGAGE BOOT FLOOR PANEL, RIGHT REAR FENDER & REAR BUMPER	New	1,200.00	500.00
Gross Labour Cost (\$\$)			2,640.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >