

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 19 December 2018 11:31 AM
To: 'daryl tan'
Cc: SUR
Subject: RE: GBD 7545D OD (EQI)

Dear Chuan,

As instructed by our client, please proceed at repair cost not exceeding \$15,000.00 (inclusive supplementary) to repair the insured vehicle **GBD 7545D (Excess \$ 500/-)** on lump Sum basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: daryl tan [mailto:daryltankc@gmail.com]
Sent: Wednesday, 19 December 2018 11:18 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: Re: GBD 7545D OD (EQI)

Dear Shirley,

We will proceed with repairs based on lump sum not exceeding \$15000.00

Regards
Chuan

On Wed, 19 Dec 2018, 11:13 Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Dear Mr. Kiat/Mr. Chuan,

As spoken, kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 15,000.00 on lump sum basis.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)