



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

TP INSURER: India International Insurance Pte Ltd (HQ)
Comfort Transportation Pte Ltd

Singapore

Claimant Insurer: MS First Capital Insurance Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP016122018
Policy No:		Date of Loss:	14/12/2018
Vehicle Reg. No.:	SH2440H	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	G JEFERY KAPOOR		

Make/Model:	TOYOTA COROLLA AXIO, 1.5 HYBRID CVT (A)	Vehicle Reg. Date:	19/05/2017
Vehicle Colour:	YELLOW/BLACK	Chassis No:	NKE1657128790
Engine No:	1NZR357816		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		

*not adjust
make
2/5 2350/17/12/18
3 day.
while Mr. After repair*

Description of Accident/Loss: ON 14.12.2018 AT ABOUT 0145HRS, I WAS DRIVING MY VEHICLE (A: SH2440H) ALONG TERMINAL 2 TAXI PICK UP. WHILE VEHICLES AHEAD STOPPED, I FOLLOWED SUIT. SUDDENLY, I FELT AN IMPACT FROM BEHIND AND REALIZED THAT VEHICLE (B: SHD3154D) HAD HIT ONTO REAR PORTION. VEHICLE A (SH2440H): NO PASSENGER ON BOARD. VEHICLE B (SHD3154D): NO PASSENGER ON BOARD.

Present Location: TAN LIM MOTOR PTE LTD (DEFU)

COST OF CLAIMS	Amount
Parts	3,950.97
Miscellaneous Items	10.00
Labour	1,350.00
Paintwork Labour	850.00
Towing	0.00
Gross Total (\$\$)	6,160.97
+ GST 7.00% (\$\$)	431.27
Nett Amount (\$\$)	6,592.24

This claim is handled by: OW CAYMEN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Dec 2018)

Parts: 143 TOYOTA COROLLA AXIO 1.5 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Tan Lim Motor Pte Ltd/SH2440H/14/12/2018 11:55

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*bootlid <i>2</i>	25.00	0.00	*710.00 FL <i>X</i>
2	1		*bootlid Axio badge <i>2</i>	25.00	0.00	*68.00 FL <i>—</i>
3	1		*bootlid Corolla badge <i>2</i>	25.00	0.00	*47.40 FL <i>—</i>
4	1		*bootlid centre emblem badge <i>2</i>	25.00	0.00	*59.80 FL <i>—</i>
5	1		*bootlid lock <i>X</i>	25.00	0.00	*88.90 FL <i>—</i>
6	1		*bootlid lock stricker <i>11</i>	25.00	0.00	*25.30 FL <i>X</i>
7	1		*bootlid weatherstrip <i>2</i>	25.00	0.00	*187.10 FL <i>—</i>
8	1		*bootlid outer chrome garnish <i>11</i>	25.00	0.00	*285.00 FL <i>X</i>
9	1		*o/s rear lamp <i>2</i>	25.00	0.00	*572.00 FL <i>—</i>
10	4		*rear lmap clip holder <i>11</i>	25.00	0.00	*50.00 FL <i>X</i>
11	1		*rear end panel <i>2</i>	25.00	0.00	*594.40 FL <i>X</i>
12	1		*rear end panel inner trim <i>11</i>	25.00	0.00	*198.50 FL <i>X</i>
13	1		*rear bumper <i>20/2</i>	25.00	0.00	*1,209.00 FL <i>—</i>
14	2		*rear bumper bracket <i>11</i>	25.00	0.00	*86.70 FL <i>X</i>
15	2		*rear bumper side retainer <i>34 115 65.10</i>	25.00	0.00	*192.20 FL <i>115</i>
16	2		*rear bumper side holder <i>115 15.50</i>	25.00	0.00	*31.00 FL <i>115</i>
17	10		*rear bumper clips <i>2</i>	25.00	0.00	*43.00 FL <i>—</i>
18	2		*rear license plate lamp <i>11</i>	25.00	0.00	*113.00 FL <i>X</i>
19	1		*rear license plate <i>11</i>	0	0.00	*80.00 FS <i>X</i>
20	1		*rear bumper parking sensor <i>11 117</i>	0	0.00	*450.00 FS <i>X</i>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,091.30
- List Item Discount on L Items (S\$)	1,140.33
Total Parts (S\$)	3,950.97

Tan Lim Motor Pte Ltd/SH2440H/14/12/2018 11:55. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-2355-80
252
1766.85

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	Putty and spray painting of the affected portion.	New	850.00
<u>Labour Items</u>			
2	To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	New	150.00
3	To rust-proofing of the affected areas.	New	120.00
4	To check electrical lighting concerned.	New	60.00
5	To reinstall of rear bumper parking sensor.	New	120.00
6	Panel beating, knocking and straighten the both rear fender, remove and renewal of parts, adjust and realign the same.	New	900.00
Gross Labour Cost (S\$)			2,200.00

Tan Lim Motor Pte Ltd/SH2440H/14/12/2018 11:55. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Defu Lane 10 Singapore 539216
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@tlmotor.com.sg www.tlmotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

2956.85
2164