

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 49442
Date Estimated : 14/12/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Hitachi Capital Asia Pacific Pte. Ltd.
111 Somerset Road
#14-05 Tripleone Somerset

Singapore 238164

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SKP5676C	LE00803	31/07/2014	X3 sDrive20	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLADDING BUMPER FRT (PDC/SCHWARZ) * <i>sea</i>	246.20	1.00		246.20
# RIGHT SUPPORT * <i>bt</i>	184.80	1.00		184.80
# EXPANDING RIVET * <i>ru</i>	1.35	20.00		27.00

Total Labour :	
Total Parts :	458.00
Total Labour & Parts :	458.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 49442
Date Estimated : 14/12/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -

Hitachi Capital Asia Pacific Pte. Ltd.
111 Somerset Road
#14-05 Tripleone Somerset

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 238164

REGN. NO.	CHASSI S NO.	REGN. DATE	MODEL	M LEAGE
SKP5676C	LE00803	31/07/2014	X3 sDrive20	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments, front RH fender and attachments, RH spray nozzle include knocking out dents caused by the accident	1700.00		1,700.00 ✓
To spray paint front bumper and front RH fender	1730.00		1,730.00 ✓
To check electrical wiring systems at the front section for proper function	150.00		150.00 ✓
To carry out body cavity preservation (Per panel)	100.00		100.00 ✓
To replace RH LED technology headlight include programming and conducting tests for proper function	408.00		408.00 ✓
Sundries	150.00		150.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT RH FENDER	804.50	1.00		804.50 ✓
RH MOUNT FOR SIDEWALL/HEADLIGHT	57.05	1.00		57.05 ✓
# CLADDING BUMPER FRT (PDC/SCHWARZ) *	246.20	1.00		246.20 (S) ✓
FRT BUMPER PANEL PRIMED	1,335.40	1.00		1,335.40 ✓
# RIGHT SUPPORT *	184.80	1.00		184.80 (S) ✓
# EXPANDING RIVET *	1.35	20.00		27.00 (S) ✓
FRT RH WHEEL ARCH COVER	179.75	1.00		179.75 ✓
SPRAY NOZZLE RH	159.85	1.00		159.85 ✓
RH HEADLIGHT LED TECHNOLOGY	3,682.05	1.00		3,682.05 ✓
DECOUPLING RING PDC TORQUE CONVERTE	5.05	1.00		5.05 ✓
ULTRASONIC SENSOR (SCHWARZ)	236.85	1.00		236.85 ✓

SUPPLEMENTARY ITEMS

Total Labour :	4,238.00
Total Parts :	6,918.50
Total Labour & Parts :	11,156.50
Deduction for Excess :	0.00
Total Repair Costs less Excess:	11,156.50
GST @7%:	780.96
Grand Total :	11,937.46

Vic (LKKAuto)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Thursday, 21 March, 2019 7:06 PM
To: Rasul (LKKAuto); SUR; CS A Team; Mei Kwan (LKKAuto)
Subject: FINAL REPORT / SKP5676C
Attachments: Final Report SKP5676C_2.pdf; Final Report SKP5676C.pdf

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 4,238.00
Total Parts : 6,918.50
Total Labour & Parts : 11,156.50

Repair days: 7

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."