

INS. CASE OWNER:

June Tay

CC6, CT1 180

2538, Afa302

LKK:

IDAC:

Surveyor:

LUP

DOI:

ASSIGNMENT

Date / Time

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

Name of Insured :

Insured Tel No. :

Excess Sec II :SS

Is driver the owner?

( YES / (NO) )

Nature of Accident :

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SMD 8050C



INSRS:

WSP:

Tel :

Liability :

RMKS:

Hiap Hong



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date / Time

24/12

CPK

11/12/19

SMD 8050C } N/A line 100, 2509/104 ; DOA: 14/12/18  
YL 246ZSpoke to PIC, confirmed BOLA 27, informed TP claim and  
HIP issue. They agree to settle and remove HIP issue.  
Send letter to OI.

file pass to type mandate report

Atta copy photo

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 11/1/2019

After call ltr to OI: 11/1/2019

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

5/3/2019

Sent By:

CPK

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$ 5,800.00 ( 6 days) Reduction: 56.07 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

11/4/2019

Confirm with

Mr Chua

Email ☒ Call ☐

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia :

Repair Cost:

S\$ 5,800.00

Loss of Rental (LOR):

S\$ - ( days)

Loss of Use (LOU):

S\$ 800.00 (\$100.00 x 8 days)

Loss of Income (LOI):

S\$ - (\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

S\$ -

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent )

Legal Cost

S\$ -

Total:

S\$ 6,600.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Payee 1:

S\$ 6,600.00

Name 1:

Hiap Hong Motor Repair

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$400.00

COPY SENT  
15/4/19

REF:

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMD80S0C. Yr Regn 2018 / Sept

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Freed. Hybrid cc 1796.

Colour:

Grey.

A/C:

Insured / Std / NI / NA

Sp. Reading

31101.

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GB71072488

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

185/65R15

R:

185/65R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

14/12/18.

Survey held at

Payu Ubi.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Chrim Hiap Hong.

\$13,203.50

1/51 \$5,800.00 (Rediff 7,403.50 / 56.01%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ )

Add Fee:

☐

Site Insp (\$ )

☐

Interview (\$ )

☐

Tech. Invs (\$ )

☐

Weekend (\$ )



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: SNM18D05828/C02  
Our ref: CC6/CTI18022577/Afa3

Date: 05.03.2019

The Motor Claims Department  
M/s CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Dear Sirs,

**PRELIMINARY ADVICE OF VEHICLE NO.**


**SMD 8050C**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14/12/2018 at the premises of M/s Hiap Hong Motor Repair and have the following to report:-

Workshop Estimate Amount	: S\$	13,073.50
Revised Estimate Amount	: S\$	5,800.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:  
The vehicle sustained damages at the  
Rear Portion



Comments/Present Status:  
Damages Consistent  
Estimated normal period for repairs: 6.0 days

Yours faithfully,

ADRIAN LING  
Licensed Appraiser

Transaction ref 20180904163430802690

Please check that the owner and vehicle details are correct:

1. Name	: TAN TION HUA
2. Identification No. Type	: Singapore NRIC
3. Identification No.	: S1315016H
4. Country/Region	: -
5. Registered Address	: APT BLK 401 JURONG WEST STREET 42 #11-537 SINGAPORE 640401
6. Mailing Address	: -
7. Vehicle Registration No.	: SMD8050C
8. Effective Date of Ownership	: 04 Sep 2018
9. Original Registration Date	: 04 Sep 2018
10. First Registration Date	: 04 Sep 2018
11. Vehicle Type	: Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover
12. Vehicle Scheme	: Normal
13. Attachment 1	: No Attachment
14. Attachment 2	: -
15. Attachment 3	: -
16. Vehicle Make	: HONDA
17. Vehicle Model	: FREED HYBRID 1.5G AUTO
18. Year of Manufacture	: 2018
19. Primary Colour	: Grey
20. Secondary Colour	: -
21. Passenger Capacity	: 6
22. Chassis/Trailer Chassis No.	: GB71072488 / -
23. Propellant/Emission Standard	: Petrol-Electric / Euro VI
24. Engine No./Motor No.	: LEB5606963 / H14087196
25. Engine Capacity(cc)/Power Rating(kW)	: 1496 / 22.0
26. Maximum Power Output(kW/bhp)	: 101.0 / 135
27. Unladen Weight(kg)	: 1430
28. Maximum Laden Weight(kg)	: 1815
29. Open Market Value	: \$24,745.00
30. PARF Eligibility	: Yes
31. PARF Eligibility Expiry Date	: 03 Sep 2028
32. Minimum PARF Benefit	: \$8,321.00

TP Chin

SMD8050C.

Bob Kim

Honda Freed Hybrid.

GB71072488.

Rees Bumper Defend.	1180.20 ✓
Rees Bumper Clips. <sup>new</sup>	30 ✓
Rees Bumper Side Holder x 02 <sup>new</sup>	53.8 x 2 = 107.60 ✓
Rees Bumper Side Reflector x 02 <sup>new</sup>	163.4 x 2 = 326.80 X.
Reverse Sensor Dmgd.	280 ( <del>80</del> ) 2w/sn
Rees End Panel Repair	623.20 X
Rees End Panel Top Garnish. <sup>defd</sup>	115.60 ✓
Rees End Panel Sealant, <sup>new</sup>	60 (sn) X.
Taillamp x 02 <sup>cracked</sup>	494.1 x 2 = 988.20 ✓
Tailgate Distorted.	1207.90 ✓
Tailgate Lock Damaged	242.30 ✓
Tailgate Weatherstripe <sup>at</sup>	198.20 ✓
Tailgate Chrome Moulding <sup>cracked</sup>	247.80 ✓
Tailgate Reflector x 02 <sup>cracked</sup>	380.5 x 2 = 761 ✓
Tailgate Inner Trim Board <sup>cracked</sup>	345 ✓
Tailgate Inner Trim Board Clips. <sup>new</sup>	30 ✓

67438

# SMD8050C.

Tailgate Pocket Handle	schud	3540	✓
Tailgate Wiper Motor	XL ner	264.80	X.
Tailgate Glass Moulding	} ner	124.60	✓
Tailgate Glass Sealant		60(SN)	✓
Handle Logo	} ner	35.60	✓
Freed Emblem		45.80	✓
Hybrid Emblem		5040	✓
Rees Fender Inner Trim Board x02	MP ner	345x2-680	X
Rees Fender Inner Trim Board Clips	not ner	60	X.
Rees Exhaust Pipe	} MP ner	880.10	X
Rees Exhaust Mounting		36.40	X.
Rees Camera	cruld MP ner	<del>680(SN)</del> 350(SN)	
Rees Number Plate Lamp x02.		33.2x2=6640	X.
<del>Floor Panel Top Covers</del>			

3029.7

SM D8050C.

Panel Beating.	<del>1200</del> 750
Spray Painting.	<del>1200</del> 700
Wiring.	<del>50</del> 30
To underseal.	150 X
To remove reverse sensor	<del>100</del> 50
To remove camera.	<del>100</del> 50
To remove upholstery.	<del>150</del> 60
To transfer tailgate fittings.	<del>150</del> 80
To remove tailgate glass.	<del>180</del> 120
To remove exhaust pipe.	150. X

hist: 5745.70  
un 20/: 4556.56  
S.N: 810.

Labour: 1840.  
total: 7246.56  
r/s: 5.8K  
068mp

5.8K

068mp

3430

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

13203-50.

## Mei Kwan (LKKAUTO)

---

**From:** Lucas Lee <lucas.lee@sg.cntaiping.com>  
**Sent:** Friday, 21 December, 2018 1:32 PM  
**To:** Mei Kwan (LKKAUTO)  
**Cc:** Irene Tay  
**Subject:** RE: Direct Settlement - Accident Involving YL246Z (OI : CTI - SNM18D05828C02) AND SMD8050C (TP : LKK REF - CC6/CTI18022577/Afa3) on 14/12/2018  
**Attachments:** MSNH18162120-YL246Z.pdf  
**Categories:** HMK

Dear Sir,

Case Handler : Irene Tay

Lucas Lee  
Claims Department (Motor)  
**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Direct (65) 6389 6181  
Fax (65) 6222 7175/6224 7478  
Email: [lucas.lee@sg.cntaiping.com](mailto:lucas.lee@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]  
**Sent:** Monday, 17 December, 2018 3:13 PM  
**To:** Claims Dept of CTI  
**Cc:** Irene Tay; Lucas Lee; Poh Kin (LKKAUTO); CS A Team; Admin A  
**Subject:** Direct Settlement - Accident Involving YL246Z (OI : CTI - TBA) AND SMD8050C (TP : LKK REF - CC6/CTI18022577/Afa3) on 14/12/2018

**CTI ref:** TBA  
**LKK REF:** CC6/CTI18022577/Afa3

Dear Sir / Madam,



**Poh Kin (LKKAuto)**

---

**From:** Poh Kin (LKKAuto)  
**Sent:** Friday, 22 March 2019 3:48 PM  
**To:** 'hiap.hong.motor@gmail.com'  
**Cc:** Admin A  
**Subject:** ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. YL 246Z AND SMD 8050C  
ALONG UPPER CHANGI ROAD EAST ON 14.12.2018

**Importance:** High

**WITHOUT PREJUDICE**

**SAVE AS TO COSTS**

Our Ref: CC6/CTI18022577/Afa3  
Your Ref: SMD 8050C

Dear Sir/Madam,

**ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. YL 246Z AND SMD 8050C ALONG UPPER CHANGI  
ROAD EAST ON 14.12.2018**

We refer to the above matter.

Towards an amicable settlement and without admission of liability to our Insured's part, we have instruction from our Principal to offer settlement as below:

1. Cost of Repair	S\$ 5,800.00
2. Loss of Use (\$60.00 x 8days)	<u>S\$ 480.00</u>
	<b><u>S\$ 6,280.00</u></b>

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

## Poh Kin (LKKAUTO)

---

**From:** Poh Kin (LKKAUTO)  
**Sent:** Tuesday, 5 March 2019 7:35 PM  
**To:** claimsdept@sg.cntaiping.com  
**Cc:** irene.tay@sg.cntaiping.com; Admin A  
**Subject:** RE: Direct Settlement - Accident Involving YL246Z (OI : CTI - SNM18D05828C02) AND SMD8050C (TP : LKK REF - CC6/CTI18022577/Afa3) on 14/12/2018  
**Attachments:** LKK Survey Photo.pdf; Preliminary Advice dated 05.03.2019.pdf; TP Estimate-Marked.pdf  
**Importance:** High

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SMD 8050C

We have not authorized repairs.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition


Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Mei Kwan (LKKAUTO)  
**Sent:** Monday, 17 December 2018 3:13 PM  
**To:** claimsdept@sg.cntaiping.com  
**Cc:** irene.tay@sg.cntaiping.com; Lucas Lee <lucas.lee@sg.cntaiping.com>; Poh Kin (LKKAUTO) <pohkin@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** Direct Settlement - Accident Involving YL246Z (OI : CTI - TBA) AND SMD8050C (TP : LKK REF - CC6/CTI18022577/Afa3) on 14/12/2018

**CTI ref: TBA**

**Poh Kin (LKKAUTO)**

---

**From:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
**Sent:** Thursday, 11 April 2019 3:50 PM  
**To:** Poh Kin (LKKAUTO); Admin A  
**Cc:** Irene Tay; Alfred Toh; Hsiao Tong (LKKAUTO)  
**Subject:** RE: <Urgent> <Seek Mandate> Direct Settlement - Accident Involving YL 246Z (OI: SNM18D05828C02/6) and SJZ 3192D (TP : LKK REF - CC6/CTI18022577/Afa3) on 14/12/2018

LKK REF - CC6/CTI18022577/Afa3  
CTI REF - SNM18D05828C02/6 (YL246Z)

Dear Poh Kin

We refer to your email pertaining to the above matter.

Please proceed to resolve the property damage claim at \$6,600.00 (all in)

**Best Regards**

**Alfred Toh**  
**Senior Executive**  
**Claims Department**  
**China Taiping Insurance (Singapore) Pte. Ltd.**  
**3 Anson Road #XX-00 Springleaf Tower Singapore 079909**  
**DID : (65) 6389 6183**  
**FAX: (65) 6224 7478**

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Poh Kin (LKKAUTO) [mailto:pohkin@lkkauto.com]  
**Sent:** Thursday, 11 April, 2019 3:15 PM  
**To:** Alfred Toh <alfred.toh@sg.cntaiping.com>  
**Cc:** Irene Tay <irene.tay@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** FW: <Urgent> <Seek Mandate> Direct Settlement - Accident Involving YL 246Z (OI: SNM18D05828C02/6) and SJZ 3192D (TP : LKK REF - CC6/CTI18022577/Afa3) on 14/12/2018  
**Importance:** High

**WITHOUT PREJUDICE**

**Our Ref:** CC6/CTI18022577/Afa3  
**Your Ref:** SNM18D05828C02

Dear Mr Alfred,

**ROAD TRAFFIC ACCIDENT INVOLVING NOS. YL 246Z (OI) AND SMD 8050C (TP) ALONG UPPER CHANGI ROAD EAST ON 14/12/2018**

We refer to the above matter and your mandate approval dated 22<sup>nd</sup> March 2019.

## Poh Kin (LKKAUTO)

**From:** Poh Kin (LKKAUTO)  
**Sent:** Thursday, 11 April 2019 3:15 PM  
**To:** 'Alfred Toh'  
**Cc:** 'irene.tay@sg.cntaiping.com'; Admin A  
**Subject:** FW: <Urgent> <Seek Mandate> Direct Settlement - Accident Involving YL 246Z (OI : CTI - SNM18D05828C02) and SJZ 3192D (TP : LKK REF - CC6/CTI18022577/Afa3) on 14/12/2018

**Attachments:** LKK Adjustment report.pdf; LKK Inspection report.pdf; LKK resurvey photo- after repair.pdf; LKK resurvey Photo.pdf; LKK Survey Photo.pdf; TP LOD\_ SMD 8050C.pdf; RE: <Urgent> <Seek Mandate> Direct Settlement - Accident Involving YL 246Z (OI : CTI - SNM18D05828C02) and SJZ 3192D (TP : LKK REF - CC6/CTI18022577/Afa3) on 14/12/2018; TP GIA.pdf

**Importance:** High

### WITHOUT PREJUDICE

Our Ref: CC6/CTI18022577/Afa3  
Your Ref: SNM18D05828C02

Dear Mr Alfred,

### ROAD TRAFFIC ACCIDENT INVOLVING NOS. YL 246Z (OI) AND SMD 8050C (TP) ALONG UPPER CHANGI ROAD EAST ON 14/12/2018

We refer to the above matter and your mandate approval dated 22<sup>nd</sup> March 2019.

We hereby re-seek mandate as TP counter proposal for loss of use + Income for \$100.00 per day, given a point of view that the vehicle is used for **Private Hire**.

The summary is as follows: -

	Amount Claimed	Amount Revised	TP counter propo
1. Cost of Repair	\$13,203.50	\$ 5,800.00	\$ 5,800.00
2. Loss of Use	\$ 1,200.00 (\$150.00 x 8 days)	\$ 480.00 (\$60.00 x 8 days)	\$ 800.00(\$100.
Total	\$14,403.50	\$ 6,280.00	\$ 6,600.00

We here by re-seek your approval to offer Third Party repairer "Hiap Hong Motor Repair" at \$ 6,600.00 (all-in).

**\*\*6 days recommendation for repair + PRI/downtime + weekends = 8 days**

Enclosed here with all the relevant documents for your perusal.

For your approval please.

## Poh Kin (LKKAUTO)

---

**From:** Alfred Toh <alfred.toh@sg.cntaiping.com>  
**Sent:** Friday, 22 March 2019 2:38 PM  
**To:** Poh Kin (LKKAUTO); Admin A  
**Cc:** Irene Tay; Alfred Toh; Chee So Chow  
**Subject:** RE: <Urgent> <Seek Mandate> Direct Settlement - Accident Involving YL 246Z (OI : CTI - SNM18D05828C02) and SJZ 3192D (TP : LKK REF - CC6/CTI18022577/Afa3) on 14/12/2018  
**Attachments:** image001.jpg

Dear Poh Kin

We refer to your emails pertaining to the above matter.

Please proceed to resolve the property damage claim at @6,280.00.

We await your payment advice to enable Irene to act accordingly.

Best Regards

Alfred Toh

---

From: Poh Kin (LKKAUTO) <pohkin@lkkauto.com>  
Sent: Friday, March 22, 2019 2:06 PM  
To: Claims Dept of CTI  
Cc: Irene Tay; Alfred Toh; Admin A  
Subject: RE: <Urgent> <Seek Mandate> Direct Settlement - Accident Involving YL 246Z (OI : CTI - SNM18D05828C02) and SJZ 3192D (TP : LKK REF - CC6/CTI18022577/Afa3) on 14/12/2018

WITHOUT PREJUDICE

Our Ref: CC6/CTI18022577/Afa3

Your Ref: SNM18D05828C02

## Poh Kin (LKKAUTO)

---

**From:** Poh Kin (LKKAUTO)  
**Sent:** Tuesday, 12 March 2019 4:15 PM  
**To:** 'claimsdept@sg.cntaiping.com'  
**Cc:** 'irene.tay@sg.cntaiping.com'; 'Alfred Toh'; Admin A  
**Subject:** <Urgent> <Seek Mandate> Direct Settlement - Accident Involving YL 246Z (OI : CTI - SNM18D05828C02) and SJZ 3192D (TP : LKK REF - CC6/CTI18022577/Afa3) on 14/12/2018  
**Attachments:** LKK Adjustment report.pdf; LKK Inspection report.pdf; LKK resurvey photo- after repair.pdf; LKK resurvey Photo.pdf; LKK Survey Photo.pdf; TP LOD\_ SMD 8050C.pdf  
**Importance:** High

### WITHOUT PREJUDICE

Our Ref: CC6/CTI18022577/Afa3  
Your Ref: SNM18D05828C02

Dear Sir/madam,

### ROAD TRAFFIC ACCIDENT INVOLVING NOS. YL 246Z (OI) AND SMD 8050C (TP) ALONG UPPER CHANGI ROAD EAST ON 14/12/2018

We refer to the above matter.

Liability: Insured Driver collided into the rear of third party vehicle. Liability is down against our insured.

We did clarify with Insured(PIC) the nature of the accident and They agree to settle and aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer "**Hiap Hong Motor Repair**" at **\$ 6,280.00 (all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair	\$13,203.50	\$ 5,800.00
2. Loss of Rental	\$ 1,200.00 (\$150.00 x 8 days)	\$ 480.00 (\$60.00 x 8 days)
Total	\$14,403.50	\$ 6,280.00

**\*\*6 days recommendation for repair + PRI/downtime + weekends = 8 days**

Enclosed here with all the relevant documents for your perusal.

**For your approval please.**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18022577/Afa3n2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 16-04-2019



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YL 246Z	Veh. Inspected	SMD 8050C
Policy No.	DMCVSN1826541800	Coverage (\$)	0.00
Claim No.	SNM18D05828C02	Excess (\$)	0.00
Assign From		Assign Date	14/12/2018

## 2. Vehicle Particulars & Condition

Make & Model	HONDA FREED HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GB71072488	Colour	GREY
Odometer	31101	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	185/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	185/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	185/65 R15	YOKOHAMA	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	14/12/2018	Inspection Date	14/12/2018
Survey held at	51 UBI AVE 1 #01-25 PAYA UBI IND PARK S (408933)		
Repairer	HIAP HONG MOTOR REPAIR		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 8050C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DEFORMED	1,180.20	1,180.20
1	REAR BUMPER CLIPS	NECESSARY	30.00	30.00
2	REAR BUMPER SIDE HOLDER @\$53.80	NECESSARY	107.60	107.60
2	REAR BUMPER SIDE REFLECTOR @\$163.40	NOT NECESSARY	326.80	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	623.20	-
1	REAR END PANEL TOP GARNISH	DEFORMED	115.60	115.60
2	TAILLAMP @\$494.10	CRACKED	988.20	988.20
1	TAILGATE	DISTORTED	1,207.90	1,207.90
1	TAILGATE LOCK	DAMAGED	242.30	242.30
1	TAILGATE WEATHERSTRIPE	CUT	198.20	198.20
1	TAILGATE CHROME MOULDING	CRACKED	247.80	247.80
2	TAILGATE REFLECTOR @\$380.50	CRACKED	761.00	761.00
1	TAILGATE INNER TRIM BOARD	CRACKED	345.00	345.00
1	TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	30.00	30.00
1	TAILGATE ROCKET HANDLE	DEFORMED	35.40	35.40
1	TAILGATE WIPER MOTOR	NOT NECESSARY	264.90	-
1	TAILGATE GLASS MOULDING	NECESSARY	124.60	124.60
1	HONDA LOGO	NECESSARY	35.60	35.60
1	FREED EMBLEM	NECESSARY	45.90	45.90
1	HYBRID EMBLEM	NECESSARY	50.40	50.40
2	REAR FENDER INNER TRIM BOARD @\$345.00	NOT NECESSARY	690.00	-
1	REAR FENDER INNER TRIM BOARD CLIPS	NOT NECESSARY	60.00	-
1	REAR EXHAUST PIPE	NOT NECESSARY	880.10	-
1	REAR EXHAUST MOUNTING	NOT NECESSARY	36.40	-
2	REAR NUMBER PLATE LAMP @\$33.20	NOT NECESSARY	66.40	-
	LESS 20% DISCOUNT		-	-1,149.14
			8,693.50	4,596.56
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	60.00	-

Report Ref No. CC6/CTI18022577/Afa3n2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE GLASS SEALANT (SN)	NECESSARY	60.00	60.00
1	REAR CAMERA (SN)	CRACKED	680.00	550.00
			1,080.00	810.00
	<b>LABOUR</b>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		1,200.00	750.00
	SPRAY PAINTING.		1,200.00	700.00
	WIRING.		50.00	30.00
	TO UNDERSEAL.	NOT NECESSARY	150.00	-
	TO REMOVE REVERSE SENSOR .		100.00	50.00
	TO REMOVE CAMERA.		100.00	50.00
	TO REMOVE UPHOLSTERY.		150.00	60.00
	TO TRANSFER TAILGATE FITTINGS.		150.00	80.00
	TO REMOVE TAILGATE GLASS.		180.00	120.00
	TO REMOVE EXHAUST PIPE.	NOT NECESSARY	150.00	-
			3,430.00	1,840.00
<b>GRAND TOTAL</b>			<b>13,203.50</b>	<b>7,246.56</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,800.00</b>

Report Ref No. CC6/CTI18022577/Afa3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV No. AC1903345  
INV Date 16/04/2019  
Reference CC6/CTI18022577/Afa3n2  
Code CTI



#### PROFESSIONAL SERVICE FEE

Vehicle No. SMD 8050C  
Insured Veh. YL 246Z  
Claim No. SNM18D05828C02  
Policy No. DMCVSN1826541800  
Accident Date 14/12/2018  
Inspection Date 14/12/2018

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

*HYN*