

HUI WANG ENTERPRISE PTE LTD

Blk 5 Defu Lane 10 #01-576 Singapore 539186
Telephone: 62864541 Fax: 62810647

Estimate

Date: 17/12/2018 Model: TOYOTA HIACE
Vehicle No: GV2003E Acc.Date: 12/12/2018

QTY	DESCRIPTION	PRICE
	REAR TAIL GATE <i>505.00 1245.10</i>	1,650.00
	REAR WINDSCREEN MOULDING <i>nei 502 99.305.1</i>	198.60
	REAR TAIL GATE WEATHER STRIP <i>7m</i>	296.50
	REAR TAIL GATE INNER TRIM PANEL <i>1</i>	325.80
	REAR TAIL GATE OUTER LOCK <i>100/1m</i>	360.26
	REAR TAIL GATE INNER LOCK MECHANISM <i>1m</i>	325.70
	REAR TAIL GATE LOCK CATCH LOWER <i>11</i>	61.10
	REAR BUMPER <i>3m</i>	380.10
	REAR END PANEL <i>305.00</i>	750.60
	SPARE TYRE BRACKET <i>1</i>	398.50
		4,747.16
	LESS 25%	3,560.37
	NETT	
	REAR TAIL GATE TOYOTA EMBLEM <i>1050 nei</i>	68.50
	LESS 10%	61.65
	SPECIAL NETT <i>25</i>	
	70KPH STICKER <i>nei</i>	30.00
	LICENSE PLATE <i>11</i>	30.00
	REAR END PANEL TOPPER <i>11</i>	150.00
		210.00
	LABOUR TO PANEL BEAT/ WELD/ STRAIGHTEN AFFECTED PARTS	1,200.00
	LABOUR TO TRANSFER REAR TAILGATE LOCK MECHANISMS	80.00
	LABOUR TO TRANSFER REAR WINDSCREEN	80.00
	WIRING	30.00
	RUST PROOFING	90.00
	SPRAY PAINTING	800.00
		2,280.00
	Total	6,112.02
	Gst 7%	427.84
	Grand Total	6,539.86

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

9-3426-76
2570.07
S.N - 109.30
126m - 1710
4389.37
1255 202
3571.49