

# OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date:	14 DECEMBER 2018	Third Party Insurer:	LONPAC
Vehicle No:	SLE4865B	Third Party Veh No:	SLR630U
Model:	TOYOTA AQUA	Date of Accident:	10 DECEMBER 2018
Chassis:	NHP102519646 – 2016		

## ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		<i>Bu</i> \$408.31
2	REAR BUMPER REINFORCEMENT	1		\$278.40
3	REAR BUMPER REINFORCEMENT BRACKET RH	1		<i>Bu</i> \$115.70
4	REAR BUMPER CLIPS	10	\$5.78	<i>Bu</i> \$57.80
SUB TOTAL				\$860.21
LESS 25%				-\$215.05
PARTS TOTAL				\$645.16

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER REVERSE SENSOR	1 SET		<i>Bu</i> \$280.00
S/N TOTAL				\$280.00

### LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

*2001*  
\$300.00

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

*2201*  
\$400.00

TO TUFF KOTE / ANTI-RUST

*2201*  
\$60.00 X

TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR

\$60.00 *501*

LABOUR TOTAL \$820.00

ONG / PEI TING

*Not Authorised*  
**TOTAL \$1,745.16**

*2 days*  
LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: