



Poh Kin

Section A - Accident Details

Registration Number	SHB5395Y
Case Reference Number	TAX/12/18/2050
Registration Date	30/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	CHAN NGIAN HEONG
Type of Accident	Head to Rear
Accident Date and Time	11/12/2018 1:45 PM
Accident Reported Date and Time	11/12/2018 3:28 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24099221
Special Instruction to ARC, if any	TP
Prepared Date and Time	12/12/2018 12:35 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Total Price

P/P 42353.05/- Selaya

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,214.00	\$400.00
Total Spray Cost	\$1,856.00	\$580.00
Total Spare Part Cost	\$5,345.44	\$1,283.05
Total Other Cost	\$940.00	\$90.00
TOTAL COST	\$9,355.44	\$2,353.05 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	8.0	5.0
Prepared / Adjusted By	Zhi Yang Phua	Hwee Jie (LKK) / QBE
ARC / Surveyor Sign Off Date	12/12/2018 1:11 PM	13/12/2018 4:18 PM
Signature		
Remarks	Initial estimates = 6 days Request number of days to extend 2 days	P/P photo before paint, supplementary item pls send e-mail to : naz@lkkauto.com (91803151)

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1903-0229	Invoice Number	
Quotation Date	13.03.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$1,014.00	\$300.00
TO REPAIR REAR END PANEL	\$200.00	\$100.00
Total Labour	\$1,214.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY SPOILER	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$80.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$200.00	\$100.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,856.00	\$580.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$940.00	\$90.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace
		75571470 10	TAIL GATE MOULDING GLASS, BACK DOOR	0.00	\$29.70	0.00	\$0.00	Replace	Not Given
		58307470 90	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Check
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace

52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check	X	nn
75573471 10	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$29.90	0.00	\$0.00	Replace	Not Given	X	nn
52592470 40	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X	nn
76801471 10A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$891.20	100.00	\$0.00	Replace	Repair	R	
67005474 40	TAIL GATE PANEL SUB- ASSY, BACK DOOR	1.00	\$929.60	100.00	\$0.00	Replace	Repair	R	
	SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X	nn
52169470 20	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace		
	SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X	nn
	STICKER SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace		
75403480 10	EMBLEM SUB-ASSY REAR	1.00	\$46.30	25.00	\$34.73	Replace	Replace		
75575470 51	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$19.70	0.00	\$0.00	Replace	Not Given	X	nn
52565479 00	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	X	nn
52566479 00	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	X	nn
52462470 10	PAD, RR BUMPER, RH & LH, 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace		
75442471 30	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace		
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace		
89997301 00	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Check	X	
75574470 40	TAIL GATE MOULDING LOWER GLASS, BACK	0.00	\$29.90	0.00	\$0.00	Replace	Not Given	X	
52576470 40	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Check	X	nn
56117501 40	TAIL GATE DAM, BACK DOOR GLASS UPPER	0.00	\$27.90	0.00	\$0.00	Replace	Not Given	X	
52591470 50	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given		
52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace		
52575470 40	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given	X	nn
	NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given	X	nn
76085479 16	SPOILER SUB-ASSY, REAR	0.00	\$1,322.10	0.00	\$0.00	Replace	Not Given	X	nn
52462470 30	PAD, RR BUMPER, RH & LH, 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace		
	SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X	nn
52462470 20	PAD, RR BUMPER, RH & LH, 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace		
52191470 30	SEAL, RR BUMPER ARM, RH & LH	2.00	\$11.00	25.00	\$16.50	Replace	Replace		
75441470 90	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace		
Total			\$6,449.00		\$1,043.95				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023470 30	REAR BUMPER REINFORCEMENT	1.00	\$318.80	25.00	\$239.10	Replace	Replace
Total					318.80		239.10		

BT

1283.05
+ 400.00
+ 670.00

2353.05