



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyotasingapore.com.sg

Toyota Bodycare Centre

17 Ubi Road 4

Singapore 409611

Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	S1000021 / ICEQI1	Ms Chua Lay Leng 442 Ang Mo Kio Avenue 10 #08-1189 Singapore 560442 Mobile: 98427252
	Document No 0	
	Document Date 10/12/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	C2	2RE171R	19/01/2016	SKZ3189C	0	17430 7DS/SKZ3189C/07121:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104540556	1ZRX535588	30	Sam San Joi	07/12/2018 14.00	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-GBF3971Y ACC DATE:07/12/2018 DRIVE IN:07/12/2018 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				30.00
2	S	BP-SUBLET DRILL HOLE & INSTALL REAR REVERSE SENSOR				154.00
3	S	BP-SUBLET CHECK LIGHTING & CONDUCT WATER LEAK TEST				154.00
4	S	BP-SUBLET SEALANT - REAR END PANEL				80.00
5	S	BP-SUBLET REMOVE & INSTALL REAR COMPARTMENT CARPET , GARNISH A TRIMMING TO ASSIST REPAIR				308.00
6	B	BP-ECU TO RESET ECU AND REPROGRAMME				134.00
7	S	BP-SUBLET REPLACE REAR BUMPER, REAR BUMPER, REINFORC EMENT, ETC STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				3080.00
8	S	BP-SUBLET RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS				2024.00
9	1	S52159-0Z904 COVER, RR BUMPER	1.00	546.10		546.10
10	2	S52563-02250 RETAINER, RR BUMPER L	1.00	59.00		59.00
11	3	S52576-02140 RETAINER, RR BUMPER L	1.00	107.20		107.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TAKE ALL INFORMATION INTO

3824378

TO SECURITY GUARD

3824378

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 10/12/2018
TIME 08:36

VEHICLE NO SKZ3189C
CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no : 6631 1188

Account Detail	Account No	Customer Detail
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	S1000021 / ICEQI1	Ms Chua Lay Leng 442 Ang Mo Kio Avenue 10 #08-1189 Singapore 560442 Mobile: 98427252
	Document No 0	
	Document Date 10/12/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	C2	2RE171R	19/01/2016	SKZ3189C	0	17430 .7DS/SKZ3189C/07121:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104540556	1ZRX535588	30	Sam San Joi	07/12/2018 14.00	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	4	S52562-02250 RETAINER, RR BUMPER R	1.00	59.00		59.00
13	5	S52575-02140 RETAINER, RR BUMPER R	1.00	107.20		107.20
14	6	S52161-0K040 CLIPS	10.00	4.00		40.00
15	7	S52182-02160 ARM, RR BUMPER, OUTE	1.00	66.90		66.90
16	8	S52181-02190 ARM, RR BUMPER, OUTE	1.00	66.90		66.90
17	9	S58307-02380 PANEL, LAMP LOWER	1.00	657.20		657.20
18	0	S58387-02240 PLATE, RR FLOOR	1.00	237.30		237.30
19	1	S64771-02390 CO COVER, SPARE WHEEL	1.00	262.10		262.10
20	2	S64401-02B61 PANEL SUB-ASSY, LUGG	1.00	717.50		717.50
21	3	S64461-02220 WEATHERSTRIP, LUGGAG	1.00	172.40		172.40
22	4	S64600-02080 LOCK ASSY, LUGGAGE C	1.00	391.60		391.60
23	5	S64621-06080 STRIKER, LUGGAGE COM	1.00	15.00		15.00
24	6	S75431-02090 LUGGAGE COMP EMBLEM,	1.00	60.40		60.40
25	7	S75442-02330 EMBLEM, SYMBOL	1.00	40.20		40.20
26	8	S75442-02340 EMBLEM, SYMBOL	1.00	44.70		44.70
27	9	S81560-02780 LAMP ASSY, RR COMB LH	1.00	372.50		372.50
28	0	S81550-02780 LAMP ASSY, RR COMB RH	1.00	372.50		372.50
29	1	T89997-30070 ELECTRICAL ANTENNA,	1.00	162.80		162.80
30	2	SPZ061-12021 76 BACK SENSOR 1F9 310A	1.00	159.75		159.75

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 4,718.25	10,682.25
		Labour 164.00	GST 7.00%
		Materials 5,800.00	747.76
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	Amount Due 11,430.01

PLEASE SIGN AND KEEP FOR YOUR RECORD

3824379

TO SECURITY GUARD

3824379

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 10/12/2018
TIME 08:36

VEHICLE NO SKZ3189C

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors