

Surveyor: M1A ASSIGNMENT 4/1/19 Date / Time: 17/12/18 (Register / Ex. Exemption):

Pre-assign / CCU / FTE
 Insured Vehicle No.: XBS156 G
 Name of Insured: Yishun Tony Pte
 Insured Tel No.: HP: 14/12/18
 Excess Sec II :SS D.O.A.: 14/12/18
 Is driver the owner? (YES / NO) Nature of Accident:
 If NO, Driver Name / Age: OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
 Driver Tel No.: (V/L: YES / NO) Insured Liability: % Final ? Yes / No

SLL2008K

INSRS: WSP: pml. Tel: Liability: RMKS:
 INSRS: WSP: Tel: Liability: RMKS:
 INSRS: WSP: Tel: Liability: RMKS:
 INSRS: WSP: Tel: Liability: RMKS:

Date/Time	STAGE	DATE / PIC
18/12/18	Non-Reporting ltr (1st): 17/12/18	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call Ot:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA :	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: S\$ (days) Reduction: % Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: Confirm with: Email ☐ Call ☐

Final Liability: % 0 (Agreed / Assessed) BOLA S/N No.: 15
 Repair Cost: S\$ TP CHARGED UPON 447 CID
 Loss of Rental (LOR): S\$ (days)
 Loss of Use (LOU): S\$ (\$ x days)
 Loss of Income (LOI): S\$ (\$ x days)
 LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]
 GIA/LTA Search: S\$
 Medical: S\$
 Disbursement: S\$ (e.g. Tow/ Independent)
 Legal Cost: S\$
 Total: S\$ Global Sum S\$:
 1) Claim status: Normal/Reject/Private Settle
 2) Report Format: TP
 3) Survey fee: 250

FINAL PAYMENT Date/Time: Confirm with: Email ☐ Call ☐

Payee 1: S\$ Name 1:
 Payee 2: (Strike if N.A.) S\$ Name 2:
 Payee 3: (Strike if N.A.) S\$ Name 3:

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401669M GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438100
Tel. 63190888 (AfterSales)
Fax. 63449772319, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796501 (AfterSales)
64796524 (Motorrad)

Due 27/12

→ 4/1/2019

2pm
Survey only

GST REG. NO : M2 - 0020081 - X

ESTIMATE

15 DEC 2018

Estimate No. : b1 49452
Date Estimated : 15/12/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Jonas Chua Ghee Seng
1 Sian Tuan Avenue

Singapore 588267

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLL2008K	0R99827	20/01/2017	X3 sDrive20	0

DESCRIPTION

Replacing rear bumper panel and attachments, rework
bootlid, etc to knock out dents caused by the accident

VALUE

1770 2,550.00

Spray rear bumper, bootlid

1805 2,006.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

Sundries

? 150.00

Total Labour 1: 4,883.00

DESCRIPTION

RR BUMPER CARRIER ECE
RR LH BUMPER MIDDLE MOUNTING
RR RH BUMPER MIDDLE MOUNTING
RR BUMPER LH MOUNT
RR BUMPER RH MOUNT
TRIM PANEL BUMPER RR BOTTOM (M)
RR BUMPER TRIM BUMPER PRIMED PDC (
REAR RH REFLECTOR
DECOUPLING RING PDC TORQUE CONVERTE
BUMPER PDC SENSOR (SCHWARZ)

QTY	PRIC	VALUE
1	756.50	756.50
1	137.75	137.75
1	137.75	137.75
1	192.15	192.15
1	192.15	192.15
1	258.00	258.00
1	1,625.30	1,625.30
1	36.10	36.10
4	5.05	20.20
1	236.85	236.85

Total Parts : 3,592.75

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438188
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/319 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 49452
Date Estimated : 15/12/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLL2008K	OR99827	20/01/2017	X3 sDrive20	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 4/1/19 Excess S\$ _____Surveyor's Name Tan Jiah Sign [Signature]Surveyor's Tel 9744745 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No [X] PML Yes / No _____Surveyor's E-mail tanjiah@lkkauto.comNo. of Working Days Recommend 4 - 5 days

Labour 1	:	4,883.00
Parts	:	3,592.75
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	593.30
Grand Total	:	9,069.05

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



Pls proceed to reject claim based on TP video

Type

🔗 Question

Message

TP was encroaching lane while OI was travelling straight.

Reply

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Tuesday, 4 June 2019 11:15 AM
To: PBSP
Cc: Chua Kee Sin
Subject: RE: REQ FOR DIRECT SETTLEMENT - SLL2008K & XB5156G ON 14/12/2018 *** LKK REF: CC4/ASM18022585/ea3
Attachments: OI SKETCH PLAN.pdf

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

We attached here with a copy of our insured's accident statement for your easy reference.

Our principal has reiterated that the accident was caused due to the entire negligence of your client cut into our insured lane and collided with our insured vehicle.

We are of the opinion that liability is not in your client's favor.

Under such a circumstances, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's claim.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simeдарby.com.sg>
Sent: Thursday, 3 January 2019 2:29 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Chua Kee Sin <chua.kee.sin@simeдарby.com.sg>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Subject: Re: REQ FOR DIRECT SETTLEMENT - SLL2008K & XB5156G ON 14/12/2018 *** LKK REF: CC4/ASM18022585/ea3

Dear Catherine

ok, 3pm appointment.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 3 January 2019 2:10 PM
To: PBSP; assignments
Cc: Chua Kee Sin; Asher Sng (LKKAuto)
Subject: RE: REQ FOR DIRECT SETTLEMENT - SLL2008K & XB5156G ON 14/12/2018 *** LKK REF: CC4/ASM18022585/ea3

Dear Caroline,

Kindly assist arrange survey at 3pm.

Best Regards,
Catherine Chong | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]
Sent: Thursday, 3 January, 2019 2:01 PM
To: assignments <assignments@lkkauto.com>
Cc: Chua Kee Sin <chua.kee.sin@simedarby.com.sg>; Asher Sng (LKK Auto) <AsherSng@lkkauto.com>
Subject: Fw: REQ FOR DIRECT SETTLEMENT - SLL2008K & XB5156G ON 14/12/2018 *** LKK REF: CC4/ASM18022585/ea3

Dear Sirs

Please assist to arrange survey tomorrow at 2pm.

***Owner waiting.

Thank you.

Regards,

Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Sent: Thursday, 3 January 2019 11:59 AM
To: PBSP
Cc: 甯瑤 ©; assignments
Subject: RE: REQ FOR DIRECT SETTLEMENT - SLL2008K & XB5156G ON 14/12/2018 *** LKK REF: CC4/ASM18022585/ea3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Caroline,

We refer to our tele-conversation.

Please kindly assist to arrange your client to survey first.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18022585/T1ea3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:PETER			Date : 12-06-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XB 5156G	Veh. Inspected	SLL 2008K	
Policy No.	GA288158	Coverage (\$)	0.00	
Claim No.	S8M016R2	Excess (\$)	0.00	
Assign From		Assign Date	17/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. X3	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBAWY920100R99827	Colour	BLACK	
Odometer	37001	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/50 R18	DUNLOP	6 mm	
L/H Front Tyre	245/50 R18	DUNLOP	6 mm	
R/H Rear Tyre	245/50 R18	DUNLOP	6 mm	
L/H Rear Tyre	245/50 R18	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/12/2018	Inspection Date	04/01/2019	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 2008K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN) (CONSISTENT)	* CHECK	150.00	-
1	RR BUMPER CARRIER ECE (SN) (CONSISTENT)	NOT NECESSARY	756.50	-
1	RR LH BUMPER MIDDLE MOUNTING (SN) (CONSISTENT)	NOT NECESSARY	137.75	-
1	RR RH BUMPER MIDDLE MOUNTING (SN) (CONSISTENT)	* CHECK	137.75	-
1	RR BUMPER LH MOUNT (SN) (CONSISTENT)	NOT NECESSARY	192.15	-
1	RR BUMPER RH MOUNT (SN) (CONSISTENT)	* CHECK	192.15	-
1	TRIM PANEL BUMPER RR BOTTOM (M) (SN) (CONSISTENT)	* CHECK	258.00	-
1	RR BUMPER TRIM BUMPER PRIMED PDC (SN) (CONSISTENT)	DEFORMED	1,625.30	1,625.30
1	REAR RH REFLECTOR (SN) (CONSISTENT)	CRACKED	36.10	36.10
4	DECOUPLING RING PDC TORQUE CONVERTE (SN) (CONSISTENT)	NECESSARY	20.20	20.20
1	BUMPER PDC SENSOR (SCHWARZ) (SN) (CONSISTENT)	* CHECK	236.85	-
			3,742.75	1,681.60
LABOUR				
	REPLACING REAR BUMPER PANEL AND ATTACHMENTS, REWORK BOOTLID ,ETC TO KNOCK OUT DENTS CAUSED BY THE ACCIDENT.		2,550.00	1,770.00
	SPRAY REAR BUMPER ,BOOTLID .		2,006.00	1,805.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
			4,733.00	3,725.00
GRAND TOTAL			8,475.75	5,406.60
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$974.75 NETT)				5,406.60

Report Ref No. CC4/ASM18022585/T1ea3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim	584016R2
Reference	CC4/ASM18022585/T16a3d2
Loss Date	14 December 2018
Report Date	17 Dec 2018 9:13:26 AM
Request Date	30 May 2019
Due Date	
Vendor Name	LKX AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pending verification - Direct Settlement

Vehicle Information	Incident Vehicle Registration #	5LL2009K
	Make	TPVD BMW
	Model	X3
	Service Address	
	Primary Contact/Insured	
		YISHUN TOWING PTE LTD 4015 ANG MO KIO IND PARK 1, #01-502, 569631, Singapore 64588480 SHARONTAN@HSTRADE.COM.SG
	Claim Handler	
	ANG Yvonne	656804461 yvonne.ang@aaa.com.sg

```

    graph TD
      A[Wait for: Approve Invoice] --> B[Send Invoice]
  
```

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
----------	----------	---------	-----------	------------	---------	-------

Document Type	Document SubType

+ Unlabeled Dexamethasone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Accident Statement	Reports & Statement		Martinez	

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1 (6).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	14 June 2019
 LKKInspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 June 2019
 LKKAdjustment1a (3).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 June 2019
 LKK PHOTO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 June 2019
 TP ESTIMATE - MARKED.pdf	Reports & Statement	GIA Report	LKK AUTO CONSULTANTS PTE LTD (TP)	10 January 2019
 TP Video (realized).avi	Evidence	Video	WANG Peter	18 December 2018
 EMAIL TP P9Lmg	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	17 December 2018
 Ltr to Insured -non reporting.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	17 December 2018