

ASS. REC. BY:

REF: CS / FCL18022588 / Tivlon2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

CWS Joanne Tong

of

FCL

Date/Time: 17/12/2018 338pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJX 1259U

Insured:

SHD 8557S

at Workshop m/s

Li Sheng

Tel:

8398 7469

of

Blk K Pandan Loop #01-18

Policy No:

Claim No:

018008871MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13.12.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WPI'

13.12.2018 @ morning

H.O.D. Endorsement:

Date/Time:

17.12.2018 351pm

Person Contacted:

Mr. Toh

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate.

SJX 1259U - CCB / AIG15011440 / Ang32

DUA: 03072015

SHD 8557S - CS / FCL18010787 / Kth3n2

DUA: 10062018

19/12/18

Email preli revised to FCL

4/1/19

LS \$2100 confirmed by email (Recd 5387.83, 727)

REF: *Tanji*

REF: *ECI*

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *35X12594* Yr Regn: *2010 May*
 Type: *Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: *Toyota Vios* C.C. *1497*
 Colour: *Black* A/C: Insured / Std / NI / NA
 Sp Reading: *157359* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *MR05344980516649*
 Gen. Cond: *Good* / Fair / Poor / Burnt
 Steering: *Inorder* / Jammed / Leaked / Burnt or
 Brake: *Inorder* / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: *155/60R15*
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front		Rear
R/Bal. <i>6</i> mm		R/Bal. <i>6</i> mm
L/Bal. <i>6</i> mm		L/Bal. <i>6</i> mm
D.O.A.		D.O.I. <i>18/12/18</i>

Survey held at *Lisheng Daxuan Corp*
 Des. of Damages: *Frnt* / Rear / O/S / N/S / U/C / Rooftop or

Nea n/s
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 07 JAN 2019

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) *4/1 - typist*

Report Format : *CWS*

Lump Sum / I.B.I: (\$) *21000*

Days Of Repair: *5*

Resurvey No. of Trip: *1*

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:
 Transportation
) S + RS SI
) Photos
) Others

145
50
50
40
TOTAL
285



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18008871MFSH

Our ref: CS/FCI18022588/T1vb

Date: 19/12/2018

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO SJX 1259U


We thank you for your instruction on 17/12/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18/12/2018 at the premises of M/s LI SHENG AUTOMOBILE TRADING and have the following to report:-

Workshop Estimate Amount	: S\$7,487.83
Revised Estimate Amount	: S\$2,655.12
"Check" Items Amount	: S\$
Total	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear n/s portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

MOTOR SURVEY ASSIGNMENT**Date** 17-12-2018**Our Ref No.** D18008871MFSH**Accident Date** 13-12-2018**Claim Type.** Third Party**Insured Vehicle** SHD8557S**Third Party Vehicle.** SJX1259U**Survey Location** BLK K #01-18 PANDAN LOOP**Contact Person.** TOH KHAR KIAN**Contact No.** 83987469/ 0**Fax No.** 67744885**Survey Type** WITHOUT PREJUDICE:**Appointed Surveyor** LKK AUTO CONSULTANTS PTE LTD**Contact Person** NA**Fax No.** 68416315**Contact Number.** NA**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST**Cc : Workshop** LI SHENG AUTOMOBILE TRADING**Attention.** NIL**Cc : TP Solicitor** NA**TP Solicitor Fax No.** NA**Officer Incharge** JOANNEY**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Khar Kian Toh <tohkk_90@hotmail.com>
Sent: Friday, 4 January 2019 12:04 PM
To: Veron Chen (LKKAUTO); SUR
Cc: Taufikh (LKKAUTO); Richard Toh Chin Huat
Subject: RE: Finalize for vehicle SJX1259U lumpsum \$2124.00 with 5 repair days

Hi Veron,

Confirm the offer Lump Sum as \$2100.

Thanks.

Best Regards,
Toh Khar Kian



Li Sheng Automobile Trading
18 Pandan Loop #01-18 Singapore 128236 (Blk K)
Mobile: (65) 83987469 | Fax: 67744885
Email : tohkk_90@hotmail.com

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Thursday, 3 January, 2019 4:06 PM
To: Khar Kian Toh <tohkk_90@hotmail.com>; SUR <sur@lkkauto.com>
Cc: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Richard Toh Chin Huat <lishengauto@yahoo.com.sg>
Subject: RE: Finalize for vehicle SJX1259U lumpsum \$2124.00 with 5 repair days

Dear Khar Kian,

WITHOUT PREJUDICE

Offer Lump Sum \$2100 @ 5 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Khar Kian Toh <tohkk_90@hotmail.com>
Sent: Wednesday, 2 January 2019 4:20 PM
To: SUR <sur@lkkauto.com>

Cc: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Richard Toh Chin Huat <lishengauto@yahoo.com.sg>

Subject: Finalize for vehicle SJX1259U lumpsum \$2124.00 with 5 repair days

Dear Sir/Madam,

The above attachment is the after paint photo, and finalize estimate.

Kindly Assist to Finalize for vehicle SJX1259U lump sum \$2124.00 with 5 repair days.

Please check and revert.

Thanks

Best Regards,
Toh Khar Kian



Li Sheng Automobile Trading
18 Pandan Loop #01-18 Singapore 128236 (Blk K)
Mobile: (65) 83987469 | Fax: 67744885
Email : tohkk_90@hotmail.com

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 19 December 2018 1:26 PM
To: 'CWS Motor Claims'
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008871MFSH/1, SJX 1259U
Attachments: SJX 1259U PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJX 1259U
Date of survey: 18/12/2018
Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 17 December 2018 3:55 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008871MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that repairer agreed survey on 18.12.2018.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 17 December, 2018 3:38 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008871MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-18 S(128236)

MS FIRST CAPITAL INSURANCE LIMITED

Your Ref Vehicle No:
(SHD8557S-TP)

Date: 14/12/2018
Vehicle No: 9JK1259U
Model: TOYOTA VIOS E
Date of loss: 13/12/2018
Our ref: LSA276TJS
Year: 2010

Qty	Description	List Price	Remarks
1.00	REAR TOYOTA ENBLEM	\$ 45.31	u✓
1.00	REAR "VIOS" ENBLEM	\$ 45.66	u✓
1.00	REAR "E" ENBLEM	\$ 40.82	u✓
1.00	REAR LHS FENDER	REPAIR	
1.00	REAR RHS FENDER	REPAIR	
1.00	REAR TAILGATE	\$ 588.69	Ry
1.00	REAR TAILGATE CENTER GARNISH	\$ 256.60	X
1.00	REAR TAILGATE LOCK	\$ 98.24	X } un
1.00	REAR TAILGATE WEATHER STRIP	\$ 228.60	X } un
2.00	REAR TAIL LAMP	\$ 424.50	LH-COR RH X 210-25
1.00	REAR BUMPER	\$ 397.31	de✓
4.00	REAR BUMPER RETAINER	\$ 259.06	u✓
10.00	REAR BUMPER CLIP	\$ 50.00	u✓
1.00	REAR END PANEL	\$ 539.23	Ry
1.00	REAR LEFT REFLECTOR	\$ 764.2	u✓
1.00	REAR TYRE BAY	REPAIR	
	REAR LH fender inner shield - \$68.10		
	TOTAL:	\$ 3,050.44	1194.93.
	LESS 25%:	\$ 762.61	896.20.
		\$ 2,287.83	

S/NET

Qty	Description	Unit Price	Remarks
2.00	REVERSE SENSOR	\$ 200 280.00	u✓
1.00	END PANEL SEALANT	\$ 150.00	X un
	TOTAL:	\$ 430.00	200.

LABOUR AND PAINT

Qty	Description	Unit Price	Remarks
1.00	LABOUR FOR REPAIR ON AFFECTED AREA	\$ 1,500.00	600
1.00	SPRAY PAINT ON AFFECTED AREA	\$ 1,300.00	700 800
1.00	CHECK WIRING	\$ 120.00	30
1.00	APPLY RUST PROOF ON AFFECTED PANEL	\$ 180.00	30
1.00	TO REMOVE AND REFIT REVERSE SENSOR	\$ 100.00	30
1.00	SUNDARIES ncl	\$ 50.00	20 1510
		\$ 3,250.00	
	TOTAL:	\$ 4,770.00	2606.20
	SUBTOTAL:	\$ 7,487.83	1157 2100

Estimate prepared by: TOH KHAR KIAN

5967.83

6018.90

Estimate

MS FIRST CAPITAL INSURANCE LIMITED

Your Ref Vehicle No:
(SHD8557S-TP)

Telephone : 83987469

tohkk_90@hotmail.com



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-18 S(128236)

Date: 14/12/2018
Vehicle No: SJX1259U
Model: TOYOTA VIOS E
Date of loss: 13/12/2018
Our ref: LSA276TJS
Year: 2010


19/12/18

Tanpin 97445749
'AP'
14/12/18 @ 3pm
Champion
Resurvey after repair
serv@lkkauto.com
5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-18 S(128236)

MS FIRST CAPITAL INSURANCE LIMITED

Your Ref Vehicle No:
(SHD85575-TP)

Date: 14/12/2018
Vehicle No: SJX1259U
Model: TOYOTA VIOS E
Date of loss: 13/12/2018
Our ref: LSA276TJS
Year: 2010

Qty	Description	List Price	Remarks
1.00	REAR TOYOTA ENBLEM	\$ 45.31	u✓
1.00	REAR "VIOS" ENBLEM	\$ 45.66	u✓
1.00	REAR "E" ENBLEM	\$ 40.82	u✓
1.00	REAR LHS FENDER	REPAIR	
1.00	REAR RHS FENDER	REPAIR	
1.00	REAR TAILGATE	\$ 588.69	Ry
1.00	REAR TAILGATE CENTER GARNISH	\$ 256.60	X
1.00	REAR TAILGATE LOCK	\$ 98.24	X
1.00	REAR TAILGATE WEATHER STRIP	\$ 228.60	X
2.00	REAR TAIL LAMP	\$ 424.50	LH-cry RH X
1.00	REAR BUMPER	\$ 397.31	de✓
4.00	REAR BUMPER RETAINER	\$ 259.06	de✓
10.00	REAR BUMPER CLIP	\$ 50.00	u✓
1.00	REAR END PANEL	\$ 539.23	Ry
1.00	REAR LEFT REFLECTOR	\$ 76.42	u✓
1.00	REAR TYRE BAY	REPAIR	
TOTAL:		\$ 3,050.44	\$1126.83
LESS 25%:		\$ 762.61	less 25% \$ 281.70
		\$ 2,287.83	\$845.13

S/NET

Qty	Description	Unit Price	Remarks
2.00	REVERSE SENSOR	\$ 200 280.00	M✓
1.00	END PANEL SEALANT	\$ 150.00	X
TOTAL:		\$ 430.00	\$200

LABOUR AND PAINT

Qty	Description	Unit Price	Remarks
1.00	LABOUR FOR REPAIR ON AFFECTED AREA	\$ 1,500.00	600 700
1.00	SPRAY PAINT ON AFFECTED AREA	\$ 1,300.00	700 800
1.00	CHECK WIRING	\$ 120.00	30
1.00	APPLY RUST PROOF ON AFFECTED PANEL	\$ 180.00	30
1.00	TO REMOVE AND REFIT REVERSE SENSOR	\$ 100.00	30
1.00	SUNDARIES	\$ 50.00	20
		\$ 3,750.00	
TOTAL:		\$ 4,770.00	\$1610

SUBTOTAL: \$ 7,487.83

Estimate prepared by: TOH KHAR KIAN

Estimate

MS FIRST CAPITAL INSURANCE LIMITED

Your Ref Vehicle No:
(SHD8557S-TP)

Telephone : 83987469

shd8557s@msfi.com

Part = \$1126.83
less 25% = \$ 281.70
\$ 845.13
S/ Net = \$ 200.00
\$1045.13
Labour \$ 1610.00
\$ 2655.13
Lump sum 20%
\$ 2124.00



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-15 S(128236)

Date: 14/12/2018
Vehicle No: SJX1259U
Model: TOYOTA VIOS E
Date of loss: 13/12/2018
Our ref: LSA276TJS
Year: 2010

Tanpin 97445749
'wp'
14/12/18 @ 3pm
Crompton
Meeting after repair
src@lsheng.com
5 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18022588/T1vbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 08-01-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8557S	Veh. Inspected	SJX 1259U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008871MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	17/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	MR053HY9305161649	Colour	BLACK	
Odometer	157359	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/12/2018	Inspection Date	18/12/2018	
Survey held at	LI SHENG AUTOMOBILE TRADING BLK 1, PANDAN LOOP, #01-16 SINGAPORE 128219.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 1259U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TOYOTA EMBLEM	NECESSARY	45.31	45.31
1	REAR "VIOS" EMBLEM	NECESSARY	45.66	45.66
1	REAR "E" EMBLEM	NECESSARY	40.82	40.82
1	REAR LHS FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR RHS FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	588.69	-
1	REAR TAILGATE CENTER GARNISH	NOT NECESSARY	256.60	-
1	REAR TAILGATE LOCK	NOT NECESSARY	98.24	-
1	REAR TAILGATE WEATHERSTRIP	NOT NECESSARY	228.60	-
2	REAR TAILLAMP	N/S CRACKED / O/S NOT NECESSARY	424.50	212.25
1	REAR BUMPER	DEFORMED	397.31	397.31
4	REAR BUMPER RETAINER	NECESSARY	259.06	259.06
10	REAR BUMPER CLIP	NECESSARY	50.00	50.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	539.23	-
1	REAR LEFT REFLECTOR	TORN	76.42	76.42
1	REAR TYRE BAY (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR LH FENDER INNER SHIELD	TORN	68.10	68.10
	LESS 25% DISCOUNT		-779.64	-298.73
			2,338.90	896.20
<u>SPECIAL NETT ITEMS</u>				
2	REVERSE SENSOR (SN)	TORN	280.00	200.00
1	END PANEL SEALANT (SN)	NOT NECESSARY	150.00	-
1	SUNDARIES (SN)	NECESSARY	50.00	20.00
			480.00	220.00

Report Ref No. CS/FCI18022588/T1vbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	LABOUR FOR REPAIR ON AFFECTED AREA.INCLUSIVE OF THE REPAIR OF REAR LHS FENDER,REAR RHS FENDER,REAR TAILGATE,REAR END PANEL AND REAR TYRE BAY.		1,500.00	600.00
	SPRAY PAINT ON AFFECTED AREA.		1,300.00	800.00
	CHECK WIRING.		120.00	30.00
	APPLY RUST PROOF ON AFFECTED PANEL.		180.00	30.00
	TO REMOVE AND REFIT REVERSE SENSOR.		100.00	30.00
			3,200.00	1,490.00
	GRAND TOTAL		6,018.90	2,606.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00

Report Ref No. CS/FCI18022588/T1vbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng.AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.