

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1428/2018/PH
Date : 17-Dec-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle : SCV 6812 H

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Choy Pow Chai
Address : 54 Chuan Garden
Singapore 558567
Telephone : HP +65 96700019
Type of Claim : Third party Claims
Policy No. : 2100391231-04
Vehicle No : **SDD 3322 H**
Model Code : Audi Q5 2.0 TFSI Qu
Model / Year : Oct-14
Engine No : CNC 042541
Chassis No : WAUZZZ8R7EA090296
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 14-Dec-18
Place of Accident : M'sia custom towards Singapore custom

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDD 3322 H .

S/n	Nature of Jobs		Estimated Charges
1	To remove and reinstall rear parking aid.Check function.	S/N \$	280.00
2	To remove and reinstall rear lid's convenience lock system,wire harness for tail lights and rear wiper system.	S/N \$	480.00
3	To renew rear windscreen.	S/N \$	480.00
4	To dismantle and renew rear bumper and rear lid.Inspect end panelling for further damages.Re-organize crash management components.Reinstall all parts removed.	\$	2,100.00
5	To respray rear bumper,rear lower spoiler,rear lid and rear hinges.	\$	2,500.00
6	To remove and renew rhs rear exhaustr silencer and centre exhaust silencer.To align to position.	\$	480.00
7	To carry out diagnostic check	S/N \$	192.00
TOTAL LABOUR CHARGES		:	\$ 6,320.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDD 3322 H .

		<u>Damaged Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/Nett</u>	
1	REAR BUMPER	\$	1,430.00
2	REAR BUMPER FIXING PARTS	\$	143.00
3	REAR BUMPER TAIL LIGHT - RH	\$	265.00
4	REAR BUMPER GUIDE SECTION - LH/RH	2 \$	92.00
5	REAR BUMPER GROMMET	2 \$	20.00
6	REAR BUMPER SPOILER	\$	749.00
7	REAR REINFORCEMENT	\$	571.00
8	REAR REINFORCEMENT BRACKET - LH/RH	2 \$	368.00
9	REAR BUMPER SENSOR	\$	211.00
10	REAR BUMPER SENSOR	\$	196.00
11	REAR LID	\$	3,844.00
12	REAR LID ATTACHMENT PARTS	\$	106.00
13	REAR LID HINGE	2 \$	400.00
14	REAR LID STRUT	2 \$	209.00
15	GASKET FOR FLAP	\$	176.00
16	SEAL -UPPER	\$	63.00
17	STRIKER PLATE WITH MOTOR FOR POWER LATCH	\$	802.00
18	REAR LID LOCK	\$	157.00
19	PUSH BUTTON FOR ELECTRIC LID LOCK ACTUATOR	\$	159.00
20	SEAL FOR PUSH BUTTON	\$	14.00
SUB TOTAL SPARE PARTS		:	\$ 9,975.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDD 3322 H .

		<u>Damaged Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/Nett</u>	
21	REAR LID STOP BUFFER	2 \$	48.00
22	GUARD PLATE - INNER	\$	54.00
23	LOCKING CLIP	2 \$	41.00
24	1 SET FIXING PARTS FOR SPOILER	\$	147.00
25	PACKING ADHESIVE	\$	15.00
26	Q5' EMBLEM	\$	83.00
27	2.0T' EMBLEM	\$	83.00
28	QUATTRRO' EMBLEM	\$	83.00
29	AUDI LOGO	\$	108.00
30	REAR WINDSCREEN	\$	1,020.00
31	PRIMER	2 \$	38.00
32	REAR SILENCER - RH	\$	883.00
33	DUAL CLIP	\$	47.00
34	BRACKET - LH / RH REAR	2 \$	100.00
35	CENTRE SILENCER	\$	875.00
36	DUAL CLIP	\$	52.00
37	DUAL CLIP	2 \$	93.00
38	BRACKET - LH / RH FRONT	2 \$	78.00
39	TRIM FOR REAR CROSS PANEL - PLASTIC/STAINLESS STEEL	\$	301.00
40	SUNDRIES	\$	800.00
TOTAL SPARE PARTS		:	\$ 14,924.00
TOTAL LABOUR CHARGES		:	\$ 6,320.00
GRAND TOTAL		:	\$ 21,244.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant