



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
NOR ZAMZARINA BINTE KAMIS  BLK 651 WOODLANDS RING RD #10-452 SINGAPORE 730651  Contact No Mobile: 96958477	Cust No/Name	/MS NOR ZAMZARINA BINTE KAMIS
	Reg No/Reg Date	SKW7727P / 16/11/201
	Date In/Mileage	/ 0
	Chassis No	JMYSRCY1AFU005526
	Engine No	4A92CC0513
	Make/Model	MIT/LANCER EX 1.6 GLS 4 A/T (M34)
	Colour/Trim	U01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	13/12/2018/ 16:42	TLC	442 / CocoLu	34229			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1375 2200.00
RENEW REAR BUMPER, BOOTLID, REPAIR REAR END PANEL								60. 100.00
E PNT88000								bt ✓ 50.00
REMOVE & INSTALL PARKING SENSOR								✓ 40.00
M SUNDRY								1260 1680.00
REAR BUMPER PLATE WITH FRAME								rw ✓ 220.00
M SUNDRY								✓ 20.00
APPLY SEALANT FOR ACCIDENT PORTION								✓ 200.00
E PNT98000								ne ✓ 40.00
SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL								✓ 20.00
M SUNDRY								100 200.00
SUPPLY PARKING SENSOR								de ✓ 852.00
A 54900099								we ✓ 17.00
CHECK WIRING & ELECTRICAL SYSTEM								we ✓ 17.00
A 54900099								bt ✓ 231.00
CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM								bt ✓ 13.00
M SUNDRY								✓ 90.00
C&C LOGO								bt ✓ 760.00
M SUNDRY								ry ✓ 92.00
Sundry								ry ✓ 92.00
E PNT88000								✓ 182.00
REMOVE & INSTALL REVERSE CAMERA								? 74.00
M	FACE,RR BUMPER			1.00	852.00	00.00		
M	BRKT,R/BMPR FACE SUPT,RH			1.00	17.00	00.00		
M	BRKT,R/BMPR FACE SUPT,LH			1.00	17.00	00.00		
M	REINFORCEMENT,RR BUMPER			1.00	231.00	00.00		
M	BRACKET,LICENSE PLATE LAMP			1.00	13.00	00.00		
M	REINFORCEMENT,RR BUMPER			1.00	90.00	00.00		
M	PANEL,TRUNK LID			1.00	760.00	00.00		
M	HINGE,TRUNK LID,RH			1.00	92.00	00.00		
M	HINGE,TRUNK LID,LH			1.00	92.00	00.00		
M	WEATHERSTRIP,TRUNK LID			1.00	182.00	00.00		
M	LATCH,TRUNK LID			1.00	74.00	00.00		

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
NOR ZAMZARINA BINTE KAMIS  BLK 651 WOODLANDS RING RD #10-452 SINGAPORE 730651  Contact No Mobile: 96958477	Cust No/Name	/MS NOR ZAMZARINA BINTE KAMIS
	Reg No/Reg Date	SKW7727P / 16/11/201
	Date In/Mileage	/ 0
	Chassis No	JMYSRCY1AFU005526
	Engine No	4A92CC0513
	Make/Model	MIT/LANCER EX 1.6 GLS 4 A/T (M34)
	Colour/Trim	U01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	13/12/2018/ 16:42	TLC	442 / CocoLu	34229
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M MARK,THREE-DIA		1.00	51.00	00.00	51.00
M MARK,LANCER		1.00	54.00	00.00	54.00
M SWITCH,TRUNK LID OPENER		1.00	67.00	00.00	67.00
M RETAINER,DOOR LOCK CYL		1.00	5.00	00.00	5.00
M TRIM,TRUNK ROOM RR END		1.00	164.00	00.00	164.00
M LAMP ASSY,TAIL,RH		1.00	191.00	00.00	191.00
M LAMP ASSY,TAIL,LH		1.00	191.00	00.00	191.00
M LAMP AS,HIGH MOUNTED STOP		1.00	369.00	00.00	369.00
M LAMP ASSY,LICENSE PLATE		1.00	35.00	00.00	35.00
M REFLECTOR LH		1.00	36.00	00.00	36.00
M REFLECTOR RH		1.00	36.00	00.00	36.00

Estimate

SURVEYOR NAME: Tay Hin 92495744SURVEYOR SIGNATURE: [Signature]DATE: WP' 26/6/19 @ 4:15pmREMARKS: Repair before part 4.sure the car is ready  
6 days

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm &amp; accepted by

	Nett	8,389.00
7% GST on	8389.00	587.23
<b>Total Payable</b>		<b>8,976.23</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.