

15/07/2018

ASS. REC. BY:

REF:

C/AIG18022608/NC

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Priscilla Sim

of

AIG.

Date/Time:

10/12/2018

Estimated Cost:

Bill to:

OD+TP+WS+TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No:

SAY1669A

Insured:

at Workshop n/s

Tel:

of

Policy No:

Claim No:

175622882686

Sum Insured:

Excess:

Make of Veh:

D.O.A

28/11/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SAY1669A-X

50019

Reply all |

Bryan Ang (LKKAuto)

Mon 10/12/2018 2:32 PM

To: Naz (LKKAuto); **assignments**

Cc: Sim, Priscilla-LK <Priscilla-LK.Sim@aig.com>; **SUR**

Inbox

gia.pdf
961 KB

Download

Action Items

Dear Naz

Please follow up on this fire investigation. To check for any modifications also. Please call owner and check where is the vehicle.

Dear Assignment Team

Please record that case assign to Naz.

Best Regards,

Bryan Ang

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: bryanang@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sim, Priscilla-LK <Priscilla-LK.Sim@aig.com>

Sent: Monday, 10 December 2018 2:27 PM

To: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: OD / 17562288265G / SGY 1669A

Hi Bryan

Kindly conduct investigation pertaining the cause of fire to the vehicle and/or any breach of policy terms & conditions.

Priscilla Sim LK

Senior Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1755 | Fax +(65) 6835 7416

priscilla-lk.sim@aig.com | www.aig.com.sg

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 28/11/2018 12:11
Date Of Accident 28/11/2018 03:15
Exact Location Of Accident CLEMETI LOOP
Country/State of Loss SINGAPORE

Vehicle @
176 Sin Ming Drive
#05-08

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGY1669A
Insured/Policyholder
Name Of Registered Owner POH JUN WEN GERALD
NRIC No S8944453E
Email Address GERALDPOHJUNWEN@HOTMAIL.COM
Mobile Phone No (LOCAL) +65-92710036
Alternative Phone No Others-92710036

LAI HUAT MOTOR

Vehicle Particulars

Manufacturer SUBARU
Model IMPREZA WRX 2.5

Exact Purpose for which vehicle was being used at time of accident PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 1800109573
Cover Note Number

Driver

Name of Driver POH JUN WEN GERALD
NRIC No S8944453E

Date Of Birth	06/12/1989
Occupation	INDOOR
Date Of Driving Pass	23/06/2009
Driving Experience	9 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92710036
Fax Number	
Contact Number	OTHERS-92710036
Email Address	GERALDPOHJUNWEN@HOTMAIL.COM
Address	BLK 443A BUKIT BATOK WEST AVENUE 8 #08-831
Postcode	651443
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	FIRE, EXPLOSION OR LIGHTNING
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties FIRE

Vehicle Category NA/UNKNOWN

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date: 22 Nov 2018

12/2/18

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Poh Kwee Choo
NRIC/IN No.: S8840563A

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I left home at 3.15am from 443A Bukit Barrow West Ave 8 heading towards 328 Clementi. When I exited the expressway at Clementi Ave 6, I sharp pedal and immediately turned off into Clementi Loop. I stop the car and check right when I stopped, I switched off the engine and flames immediately came out from the bonnet. There was an EMS crew nearby with his fire extinguisher and he was not able to put out the fire, I called 995 at the same time as well.

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature

Date & Time:
20 NOV 2019

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name: Poh Kwee Choo
NRIC/FIN No.: S0840583A

CERTIFICATE OF INSURANCE



CERTIFICATE OF INSURANCE

AUTOVALUE PRIVATE VEHICLE

Name of Policyholder : Poh Jun Wen Gerald
Period of Insurance : 18 Sep 2018 To 17 Sep 2019
Engine No. : EJ25D120089
Chassis No. : JF1GDGKD37G071365

Vehicle No. : SGY1666A
Policy No. : 1800109573
Endorsement No. :
Issued Date : 17 Sep 2018

ABOUT THE COVER

Make/Model	SUBARU IMPREZA WRX 2.5			Sum Insured	Market Value	First Year of Registration	2007
Engine Capacity/Tonnage	2.457.00 CC			Off Peak Car	No	Insuring with COE/PAF	No
Driver Restriction	NA						
Person or Classes of Persons Entitled to Drive*							

At the Policyholder's option:
 (1) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will extend to the Policyholder or any authorized driver only if the driver meets the specified age condition.
 You have to pay an additional sum of \$2,000 as "Young and Inexperienced Driver Excess" ("YIDE") if You are or Your Authorized Driver (named or unnamed) is under the age of 25 and/or has less than 3 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for local, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, public display, liability trial or speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Taxis.

Loss of Use 15000 - 15000 Optional

* Limitations imposed by Section 6 of the Motor Vehicle (Third Party Risk and Compensation) Act (Cap. 196) and Section 55 of the Road Transport Act, 1987 (Malaysia), and not to be included under these headings.

EXCESS

Section 1
 Fire - \$0; Own Damage - \$2000; Theft - \$0; Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Jun Wen Gerald Poh - \$2000 (Own Damages)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Any accident repairs to the vehicle must be carried out by one of our Authorized Repairers.
 For other approved Reporting Centres/Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 8228 8288. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download AIG SG from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan : SPEED CREDIT PTE LTD

We hereby certify that the policy in which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicle (Third Party Risk and Compensation) Act (Cap. 196), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicle (Third Party Risk) Rules, 1989 (Malaysia).

3506A12000

MULTI-URVES AGENCIES

AIG BUILDING 78 SHENTON WAY #07-18

SINGAPORE 078120 AYEP-NONLIFE

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. P. N. L.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORIZED REPRESENTATIVE

400009

18 Sep 2018 11:45 AM AIG Building, 78 Shenton Way (T: +65 8478 3000) www.aig.com.sg

AIG Asia Pacific Insurance Pte. Ltd.

DRIVER'S NRIC + DRIVING LICENCE

REPUBLIC OF SINGAPORE
IDENTITY CARD NO S8944453E



POH JUN WEN, GERALD
(FU JUNWEN)
傅俊文

DOB 08-12-1989 W

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LIC

License Number S8944453E



POH JUN WEN, GERALD
(FU JUNWEN)

Birth Date 08 Dec 1989
Issue Date 23 Jun 2008

001754624A

Barcode

IDENTITY CARD NO S8944453E



DOB 08-12-1989

APT 604 433A BAYVIEW WEST AVENUE 2 #08-011
SINGAPORE 651442

00044453E Date 23/06/08

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 3 Motor Cars > 3000kg with > 7 passengers, exclusive of the driver, and other motor vehicles < 2500kg

08-12-1989

00044453E

AP/23A

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Vehicle Information		Driver Information	
Make/Model	Year/Color	Name	License No.
Insurance	Registration	Address	City/State/Zip
Engine No.	Chassis No.	Phone	Signature
Inspector's Name		Date	

Witness Information		Notes	
Name	Signature		
Name	Signature		
Name	Signature		
Officer's Name		Officer's Signature	
Officer's Title		Officer's Department	

Accident Photo



A black and white photograph showing the interior of a vehicle, likely a car, with the front end heavily damaged. The dashboard and front seats are visible, and the front of the car is crumpled and twisted.

CHASSIS NUMBER





	☐ Subaru Impreza WRX 2.5M (COE till 11/2027)	\$71,800	\$8,180 /yr	03-Nov-2007	2,457 cc	-	Sports	Available
Well Maintained 1 Owner WRX (Renewed Coe Become 2). Serviced And Maintained By Reputable Subaru Workshop. No Repairs Needed! Owner Reluctant Sale As Due For Upgrade. Trade In And Loans Available! Call...								
								
☐ Subaru Impreza WRX 2.5M (COE till 11/2027)	\$79,800	\$8,880 /yr	05-Nov-2007	2,457 cc	-	Sports	Available	
No Dekitting. Looking For Someone Who Appreciates To Take Over. Heavily Invested In Both Time And Money. Over \$50k In Parts. Lots Of Customisation. Most Parts New With Receipts. Way Too Many Parts To ...								
								
☐ Subaru Impreza WRX 2.5M (OPC) (COE till 03/2027)	\$56,800	\$6,900 /yr	07-Mar-2007	2,457 cc	-	Sports	Available	
Free Conversion To Normal Plate. 100% Guaranteed Accident Free, 1 Owner, \$20K Worth Of Accessories, Tip Top Condition, Extremely Well Maintained By Car Enthusiast Owner! Remapped ECU, 80% Loan At 3.1%...								

Make & Model : Price : Depreciation : Reg : Eng : Mileage : Veh : Status :

For old advertisements, view Expired ads

20 results/page

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details	
Vehicle No.:	SGY1669A
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	SUBARU
Vehicle Model:	2.5 WRX
Chassis No.:	JF1GDGKD37G071365
Propellant:	Petrol
Engine No.:	EJ2519314L
Engine Capacity:	2457 cc
Maximum Power Output:	169.0 kW (226 bhp)
Maximum Laden Weight:	1860 kg
Unladen Weight:	1405 kg
Year Of Manufacture:	2007
Original Registration Date:	18 Sep 2007
Lifespan Expiry Date:	-
COE Category:	E - Open Category
PQP Paid:	\$50,355.00
COE Expiry Date:	17 Sep 2027
Road Tax Expiry Date:	17 Mar 2019
Inspection Due Date:	17 Sep 2019
Intended Transfer Date:	11 Dec 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4453E
Vehicle Details	
Vehicle No.:	SGY1669A
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Dec 2018
Vehicle Make:	SUBARU
Vehicle Model:	2.5 WRX
Primary Colour:	Blue
Manufacturing Year:	2007
Engine No.:	EJ2519314L
Chassis No.:	JF1GDGKD37G071365
Maximum Power Output:	169.0 kW (226 bhp)
Open Market Value:	\$16,955.00
Original Registration Date:	18 Sep 2007
First Registration Date:	18 Sep 2007
Transfer Count:	5
Actual ARF Paid:	\$18,651.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 Sep 2027
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$50,355.00
COE Rebate Amount:	\$44,144.00
Total Rebate Amount:	\$44,144.00

The information contained herein is correct as at 11 Dec 2018

OK

Enquiry on Vehicle Recall - Vehicle Specific

* ONLY INFORMATION ON VEHICLE RECALLS SUBMITTED FROM 9 APRIL 2007 IS AVAILABLE

Vehicle Details															
Owner ID Type:	Singapore NRIC														
Owner ID:	4453E														
Vehicle Details															
Vehicle Registration number:	SGY1669A														
Make:	SUBARU														
Vehicle Model:	2.5 WRX														
Engine No.:	EJ2519314L														
Chassis No.:	JF1GDGKD37G071365														
Recall Details															
1	<table> <tr> <td>Recall No.:</td><td>R2015070133</td></tr> <tr> <td>Manufacturer Recall Date:</td><td>21 May 2015</td></tr> <tr> <td>Estimated Completion Year of Recall:</td><td>2017</td></tr> <tr> <td>Brief Description (As Provided by Motor Dealer):</td><td> The subject vehicles are equipped with front passenger air bag SPI inflators, which are described on Part 573 Defect Information Report (NHTSA Recall No. 15E-041) reported by Takata on May 18, 2015. The propellant wafers in some of the subject inflators may experience an alteration over time, which could potentially lead to over-aggressive in the event of an air bag deployment. Takata is aware of a potential issue associated with the inflator body internal tape seals on some SPI inflators. During its investigation, Takata observed a small no. of tape seal leaks in SPI inflators manufactured prior to 2007. These leaks were discovered during leak testing in 2004, as part of the Takata returned-inflator evaluation program. Leaks have been found in SPI inflators returned from several of the vehicle manufacturers. Such leak can increase the potential for moisture to reach the main propellant wafers. In the event of a crash necessitating deployment of the passenger side frontal air bag, the subject propellant wafers could cause the inflator to rupture with fragments striking and potentially seriously injuring the vehicle occupants. </td></tr> <tr> <td>Date Rectified:</td><td>-</td></tr> <tr> <td colspan="2">For more details, contact MOTOR IMAGE ENTERPRISES PTE LTD</td></tr> <tr> <td>Hotline Information:</td><td> SUBARU SERVICE CENTRE TOA PAYOH BRANCH at 67038101 SUBARU SERVICE CENTRE LENG KEE BRANCH at 67038163 </td></tr> </table>	Recall No.:	R2015070133	Manufacturer Recall Date:	21 May 2015	Estimated Completion Year of Recall:	2017	Brief Description (As Provided by Motor Dealer):	The subject vehicles are equipped with front passenger air bag SPI inflators, which are described on Part 573 Defect Information Report (NHTSA Recall No. 15E-041) reported by Takata on May 18, 2015. The propellant wafers in some of the subject inflators may experience an alteration over time, which could potentially lead to over-aggressive in the event of an air bag deployment. Takata is aware of a potential issue associated with the inflator body internal tape seals on some SPI inflators. During its investigation, Takata observed a small no. of tape seal leaks in SPI inflators manufactured prior to 2007. These leaks were discovered during leak testing in 2004, as part of the Takata returned-inflator evaluation program. Leaks have been found in SPI inflators returned from several of the vehicle manufacturers. Such leak can increase the potential for moisture to reach the main propellant wafers. In the event of a crash necessitating deployment of the passenger side frontal air bag, the subject propellant wafers could cause the inflator to rupture with fragments striking and potentially seriously injuring the vehicle occupants.	Date Rectified:	-	For more details, contact MOTOR IMAGE ENTERPRISES PTE LTD		Hotline Information:	SUBARU SERVICE CENTRE TOA PAYOH BRANCH at 67038101 SUBARU SERVICE CENTRE LENG KEE BRANCH at 67038163
Recall No.:	R2015070133														
Manufacturer Recall Date:	21 May 2015														
Estimated Completion Year of Recall:	2017														
Brief Description (As Provided by Motor Dealer):	The subject vehicles are equipped with front passenger air bag SPI inflators, which are described on Part 573 Defect Information Report (NHTSA Recall No. 15E-041) reported by Takata on May 18, 2015. The propellant wafers in some of the subject inflators may experience an alteration over time, which could potentially lead to over-aggressive in the event of an air bag deployment. Takata is aware of a potential issue associated with the inflator body internal tape seals on some SPI inflators. During its investigation, Takata observed a small no. of tape seal leaks in SPI inflators manufactured prior to 2007. These leaks were discovered during leak testing in 2004, as part of the Takata returned-inflator evaluation program. Leaks have been found in SPI inflators returned from several of the vehicle manufacturers. Such leak can increase the potential for moisture to reach the main propellant wafers. In the event of a crash necessitating deployment of the passenger side frontal air bag, the subject propellant wafers could cause the inflator to rupture with fragments striking and potentially seriously injuring the vehicle occupants.														
Date Rectified:	-														
For more details, contact MOTOR IMAGE ENTERPRISES PTE LTD															
Hotline Information:	SUBARU SERVICE CENTRE TOA PAYOH BRANCH at 67038101 SUBARU SERVICE CENTRE LENG KEE BRANCH at 67038163														

JASMA

日本自動車マフラー協会 登録認定書

表示番号: 03511023

製品番号: 31006-CF001

製作社名: 株式会社・ケー・エス

車名: スバル インプレッサ

製品構成: 2 分割

登録番号: 03511023

適応型式:

GH-GDF
TA-GDG
6H-6DBエンジン型式: EJ25
EJ25
EJ20

FONG MUI GARAGE

NAME OF OWNER:

Kim Young Li Kheng

PMAET 2545

C.M.O.

VAAC: 200

SGP 20740

本製品は、自動車メーカーの製作した、上記車両の標準仕様車に對し国土交通省令で定める、道路運送車両の保安基準第3条（最低地上高）第30条（騒音防止装置）第31条（排気管、燃費のあるガス、有害なガス等の発煙防止装置）の基準への適合性に対し、JASMA基準に適合する商品として、当該車両への装着に對し、車両検査の対象品として基準を満たす商品であることを認めます。当協会にて認定した商品は、当協会が指定する表示番号を明記したプレートが目視確認しやすい位置に容易に外れない方法により取り付けられています。この商品は標準仕様車における自動車製作メーカー純正部品との交換を前提としたものであり、その他の改造を行ったときにその適合性を保証するものではありません。

- 上記記載製品装着時には、自動車検査証（車検証）と共に大切に保管し、必要に応じて整備点検等の際は本書をご提示下さい。
- 裏面の所定記入欄が空欄ですと、本書は有効となりません。未記入の場合には、すぐにお買上げ販売店へお申し出下さい。
- 本書は再発行は致しませんので、紛失しないよう大切に保管して下さい。又、裏面の注意書き内容をご確認ください。

上記製品に対するお問い合わせ窓口

お問い合わせ先: TEL 0544-29-1100

ご注意

12 JUN 2017

- 本書（登録認定書）は、表面に記載されている車両に對して装着された場合のみ有効です。それ以外の車両に装着された場合は、製造・販売元及び当協会では対応いたしません。
- 製品の取り付けには各部のクリアランスが保てるように注意してください。特に制動関係・駆動関係・燃料関係・その他諸般に注意してください。
- 燃費計（キヤタライザー等）の取り付けは法律で禁止されています。絶対に取り外して走行しないようにお願いいたします。
- 製品本体がタイプ切斷、消音器の破損、排気管の破損、エンジン等の故障、パイプの切斷、溶接部の破損等を生じないよう、苦慮して、正しい取り付け方法を厳格に守ってください。
- 日本自動車マフラー協会認定品として、JASMA規格に適合したプレート（JASMA規格）を取り付けられています。必ずこの項目をご確認ください。
- 製品の型式とマフラーの型式とが一致していることを必ず確認してください。VAAC: 200
- 本製品は自動車メーカーの標準仕様車に對しての取り付けに關して、道路運送車両の保安基準に對して適合性を認定するものであり、他の製品との組み合わせや他社での改造・販売元にお問合せのうえ、ご確認いただきますようお願い致します。取り付けや適合性などの不明な点がありましたら、当協会に電話でお問い合わせください。その旨が伝わり、マフラーの適合型式及びマフラーメーカーの指定した適合車両と装着する本車が一致していることを確認してください。
- マフラーは消耗品です。正しい使用方法を守り、自己責任において定期的に点検してください。経年劣化や使用状況・使用期間等により、本来の性能が損なわれた場合、他社製製品を販売・譲渡・中古販売・取扱い請用者自動車購入等により取得した場合には、本書（登録認定書）の有効性は消滅いたします。速やかで指定整備工場等に交換してください。また、ご使用中に法定点検（車検）を行なう際、次の項目に該当した場合には、一般品としてご使用はできません。
 1. 音圧40dBの定められた値以上になっている
 2. 排気管やマフラーに腐食・破損・変形等の形状変化がある
 3. 排気管やマフラーと地面のクリアランスが標準規格等の経年劣化や交換により基準値以下になっている
 4. 道路運送車両法、保安基準第3条により、検査実施要項で定める最低地上高の基準を満たさないものは検査に合格しません
- 本製品は車両検査の対象品として協会が定めるJASMA基準への適合性に対して認定したものであり、製品の品質に對して保証するものではありません。製造本体の品質と同等に品質はメーカー直轄となり、製造物責任法（平成6年法律第85号）に定められた、当該製造物を製造した者の責任となります。製造元となる方と協会の関係は、製造物責任法第2条（定義）第3項「当該製造物の製造者としての責任を負っていること」として詳細をご確認ください。その他に不明な点は、本書をお手元にご用意のうえお問い合わせ窓口へご連絡ください。

不安だと思ったら、まず、当会にご連絡を（日曜・金曜）

※販売店の方へ、必ず下欄に販売店・社判を押印して下さい。

※お客様へ、必ずお名前・ご住所をご記入下さい。

日本自動車マフラー協会

〒229-1134 神奈川県相模原市下九沢2140-101

TEL 042-700-2112 FAX 042-700-1115

お買上げ年月日	取付時車両走行距離	お名前	様
年 月 日	km	TEL ()	
販売店	店名・住所・電話	ご住所	

10 Sin Ming Drive Singapore 575701
Hotline: 1800 - CALL LTA (1800 - 2255 582)
FAX: (65) 6553 5329

Date: 12 JUN 2012

VIR No.:201206128695V0

Mr/Ms/Messrs
NG YUU SUI
APT BLK 103 SERANGOON NORTH AVENUE 1
#08-769
SINGAPORE 550103

Dear Sir/Madam

INSPECTION ACKNOWLEDGEMENT LETTER

EXHAUST SYSTEM

Vehicle Registration No: SGY1669A

Chassis No: JF1GDGKD37G071365

Engine No: EJ25D120089

Applicant: NG YUU SUI

This is to acknowledge that your vehicle has passed the inspection on 12 JUN 2012.

The accessory details are as follows:

Make :HKS

Model Name :HKS

EEC/ECE/JASMA/JMCA Number.:0

Type Number: 31006-CF001

Thank you for presenting the above vehicle for inspection.

Registrar of Vehicles



VT_IC_ACK08_LTR

VICOM (Sin Ming) 385 Sin Ming Drive, Singapore 575718

Tel: 6458 4555

www.edge-tuning.com

Block 176 Sin Ming Drive #05-08 Sin Ming Autocare Singapore 575721

Tel: +65 6458 4300 / Fax: +65 6458 4336

(Business/GST Registration No. 200600805K)

TAX INVOICE

Ref : P18-0014702

Date : 21 Aug 2018

M/s : Gerald Poh

Mileage : 249,713KM

Contact No. : 92710036

Car reg. : SGY1669A

Vehicle : Subaru WRX

Staff

Chassis No. : JF1GDGKD37G071365

Description	Quantity	Unit Price	Amount incl GST
Labour to remove splitter	1	\$40.00	\$40.00
Total (SGD)			\$40.00

Total before GST	GST Rate	GST Amount
\$37.38	7%	\$2.62

Address

- Goods sold are non-returnable / refundable.
- It is hereby agreed and understood that all non-DEM modifications to your car are done at your request and Edge Tech Pte Ltd will not accept any responsibilities and/or liabilities whatsoever and however arising therefrom.
 - Some Products sold are intended for race use only and not for street use and are therefore not legal for street use.
 - No warranty is provided on all parts sold unless otherwise stated. In the case where warranty is provided, warranty shall be provided only on the specified part. Damage incurred to other parts will not be covered by this warranty.
 - All cheques should be crossed and made payable to "Edge Tech Pte Ltd".
 - Invoice is only valid when payment has been acknowledged.
 - If payment is not made upon collection of vehicle, any outstanding or overdue invoice(s) will be subjected to late payment interest at a rate of 2% per month.
 - Upon the Customer signing below, the Customer is deemed to have acknowledged receipt of the vehicle and/or goods and services stated and the Customer confirms that the vehicle has been inspected by the Customer and found to be in good order and condition.

E & O E
Edge Tech

Jobsheet no.

18-06466

Customer Signature

EDGE TECH

www.edge-tuning.com

Block 176 Sin Ming Drive #05-08 Sin Ming Autocare Singapore 575721

Tel: +65 6458 4300 / Fax: +65 6458 4336

(Business/GST Registration No. 200600805K)

TAX INVOICE

Ref : P18-0014961

Date : 21 Sep 2018

M/s Gerald Poh

Mileage : 249,101KM

Contact No. : 92710036

Car reg. : SGY1669A

Vehicle : Subaru WRX

Staff :

Chassis No. : JF1GDGKD37G071365

Description	Quantity	Unit Price	Amount incl GST
Inspection fee	1	\$110.00	\$110.00
Supply and change timing belt set (racing belt)	1	\$900.00	\$900.00
Supply and install Cosworth head gaskets	1	\$450.00	\$450.00
Labour to remove and reinstall engine	1	\$700.00	\$700.00
Supply new engine block	1	\$4,200.00	\$4,200.00
Total (SGD)			\$6,360.00

Total before GST	GST Rate	GST Amount
\$5,943.93	7%	\$416.07

Note

- Goods sold are non-refundable / refundable.
- It is hereby agreed and understood that all non-OEM modifications to your car are done at your request and Edge Tech Pte Ltd will not accept any responsibilities and/or liabilities whatsoever and however arising therefrom.
 - Some Products sold are intended for race use only and not for street use and are therefore not legal for street use.
 - No warranty is provided on all parts sold unless otherwise stated. In the case where warranty is provided, warranty shall be provided only on the specified part. Damage incurred to other parts will not be covered by this warranty.
 - All cheques should be crossed and made payable to 'Edge Tech Pte Ltd'.
 - Invoice is only valid when payment has been acknowledged.
 - If payment is not made upon collection of vehicle, any outstanding or overdue invoice(s) will be subjected to late payment interest at a rate of 2% per month.
 - Upon the Customer signing below, the Customer is deemed to have acknowledged receipt of the vehicle and/or goods and services stated and the Customer confirms that the vehicle has been inspected by the Customer and found to be in good order and condition.

E & OE
Edge Tech

Customer Signature

EDGE TECH

www.edge-tuning.com

Block 176, Sin Ming Drive #05-08 Sin Ming Autocare Singapore 575721

Tel: +65 6458 4300 / Fax: +65 6458 4336

(Business/GST Registration No. 200600805K)

TAX INVOICE

Ref : P18-0014989

Date : 26 Nov 2018

M/s : Gerald Poh

Mileage : 251,164KM

Contact No. : 92710036

Car reg. : SGY1669A

Vehicle : Subaru WRX

Staff : Hoong

Chassis No. : JF1GDGKD37G071365

Description	Quantity	Unit Price	Amount incl GST
Fuchs Mineral 15W40 engine oil servicing (2/6)	4.5	\$12.00	\$54.00
Oil filter	1	\$21.00	\$21.00
Total (SGD)			\$75.00

Total before GST	GST Rate	GST Amount
\$70.09	7%	\$4.91

Note


- Goods sold are non-returnable / refundable
- It is hereby agreed and understood that all Non-OEM modifications to your car are done at your request and Edge Tech Pte Ltd will not accept any responsibilities and/or liabilities whatsoever and however arising therefrom.
- Some Products sold are intended for race use only and not for street use and are therefore not legal for street use.
- No warranty is provided on all parts sold unless otherwise stated. In the case where warranty is provided, warranty shall be provided only on the specified part. Damage incurred to other parts will not be covered by this warranty.
- All cheques should be crossed and made payable to "Edge Tech Pte Ltd".
- Invoice is only valid when payment has been acknowledged.
- If payment is not made upon collection of vehicle, any outstanding or overdue invoice(s) will be subjected to late payment interest at a rate of 2% per month.
- Upon the Customer signing below, the Customer is deemed to have acknowledged receipt of the vehicle and/or goods and services stated and the Customer confirms that the vehicle has been inspected by the Customer and found to be in good order and condition.

E. & O.E.
Edge Tech

Jobsheet no:

18-06735

Customer Signature



Auto
Consultants
Pte Ltd

STATEMENT

PARTICULARS

Name : POH JUN WEN, GERALD (FU JUNWEN)
 NRIC / Passport No. : S8944453E
 Address : BLK 443A BUKIT BARU WEST AVENUE 8 #08-831
SC 651443
 Telephone : (R) _____ (O) _____
 (HP) 97710036
 Sex / Age : M (29)
 Occupation / Name of Company : UNEMPLOYED
 Nationality : INDONESIAN

Recorded By : MUHD NAZIL Date : 14/12/18 Time: 1600
 Place Recorded: ADDRESS AS ABOVE
 Language Spoken: ENGLISH Interpreted By: N/A

FACTS OF CASE:


I am the owner and driver of vehicle S69 1669A which caught fire on 28/11/18 at 0315 hours at Clementi Loop. I was from home and was heading to BLK 328 Clementi Ave 3 to a 24 hour fish shop to get fish food. I took the PIE towards Changi and exited at Clementi Ave 6. After I exited I smelled a strong petrol smell from the interior of my car. So I turned right into Clementi Loop and switched off the engine. The fire started at the left side of the bonnet before I came to a stop. I exited the car and opened the bonnet. By then the fire was too big. I grabbed my fire extinguisher from the front passenger seat, I sprayed at the left side of the bonnet but the fire kept on out. So I dialed 995. An EMS personnel who was nearby came to my aid. He took a fire extinguisher from his vehicle but he sprayed it at the front left wheel protector instead of the bonnet where the fire started.

The SCDF arrived within 6 minutes together with the police. Firefighters took less than a minute to put out the fire. 2 firebikes and 2 pumps arrived. Police took my statement and

Signed: gh S8944453E

Recorded by: gh

MUHD NAZIL
LKK AUTO



Auto
Consultants
Private Ltd

STATEMENT

I assisted the SCDF with their preliminary investigations. They allowed me to buy my car after 1 and a half hours. I called my insurance broker to inform him of the incident. I called James Tsimmy and the tow truck arrived an hour later. My car was towed to my workshop, Edge Tech located at Blk 110, Sin Ming Drive #05-08, Sin Ming Autocare S(S75721). I hitched a ride with the towing personnel. I then met my friend who fetched me from the workshop. I made an insurance report at Lai Hui Motor Pte. Ltd. on the same day at 1211 hours.

I bought my car secondhand in 2016 with about slightly more than 9 year left of COE. I renewed my COE for 9 years on 18 September 2017. I got the car from a direct owner for about \$8,000. The bucket seats, steering wheel, pioneer DVD player, in vehicle recording device were changed by me. The struts on the undercarriage, bonnet and chassis, gauges, speed and RPM boost meter, control box for the inter cooler, inter cooler, controller for the gauges, intercooler, HKS after market exhaust, mid pipe and muffler, 18 inch rims, tyres, 4 after market speakers, 2 tweeters, 1 active subwoofer came with the car.

I went for a vehicle inspection at STA Sin Ming for in July 2018 but the personnel said the engine number looked like it was tampered with. So STA informed the LTA and I was made to be interviewed by the LTA investigating officer. He gave me 2 options: either change the whole engine block to an approved street legal type for my car model or scrap the car. So I chose to get a new engine block from Edge Tech and got it fitted on 21 September 2018. After installation, I was supposed to run in the engine for approximately 3000 km. I was running in the engine for about 500 km when the incident happened. I went for servicing on 26/11/18, 2 days before the fire. To change the engine oil and oil filter.

Since the last servicing I did not experience any mechanical or technical, electrical issues with the car till the incident occurred.

I wish to state that I was not under the influence of alcohol or under any medication that cause drowsiness and impair my ability to drive.

I hereby wish to affirm that the above statement is true and correct at the time it was written.

Signed:  5894453E

Recorded by: 

MUHD NAZIL
LKK AUTO-