

ASS. REC. BY:

REF:

CS/C7118022609 / TTB⁵⁷

Special Instruction:

Survivor:

Maimed

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTL

Date/Time:

17/12/2018 4:38pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 5817m

Insured:

YP 67C

at Workshop m/s

ASM Automotive

Tel:

of

No. 2 Kwong Min Road

Policy No:

OMCVSN 31134 01802

Claim No:

SNM18D05582C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/12/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

18-12-2018

H.O.D. Endorsement:

Date/Time:

17-12-2018 5:10pm

Person Contacted:

Jadyn

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBC 5817m - (C4) / A11 13025344 / A11392

DFA 051213

YP 67C - X

Part by Part \$5128.50 (Red: 2280', 30%)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Dec 2018		17 Dec 2018 16:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SCANTECH MARINE PTE LTD, Co. Reg. No.: 199203043D		
Main Claimant:	OCEANO ELECTRICAL TRADING PTE LTD		
Vehicle Reg. No.:	GBC5817M	Date of Loss:	28/11/2018 14:00 - :59
Claim Type:	TP / SNM18D05582C02	Policy/Cover Note No.:	DMCVSN3113401802 (Comprehensive)
Vehicle Reg. No. (Insured):	YP67C	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Asm Automotive Services Kwong Min Rd (HQ) No. 2 Kwong Min Road, 628705 Pioneer - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hul Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/12/2018]		
Adj Asg. Remarks:	EST \$7408.50, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/12/2018 14:33
Date Of Accident	28/11/2018 14:40
Exact Location Of Accident	ALONG PIONEER ROAD NORTH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC5817M
Insured/Policyholder	
Name Of Registered Owner	OCEANO ELECTRICAL TRADING PTE LTD
Co Reg No	200005830N
Email Address	CATHERINE_LIM@OCEANO.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-63345229

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150 MANUAL 3SEATER-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SI18V03096/VCV/R01
Cover Note Number	

Driver

Name of Driver	NORAKMAL BIN MASNON
NRIC No	S7400469E
Date Of Birth	18/01/1974
Occupation	OUTDOOR
Date Of Driving Pass	08/05/2007
Driving Experience	11 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96846162
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name NORAKMAL BIN MASNON

Approximate Age

Injuries Sustain

Injured person in which vehicle? GBC5817M

Were seat belts worn?


Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- Refer to the police report T/2015003/0161 -

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Police Report



**SINGAPORE
POLICE FORCE**



T/20181203/2161

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

CONTINUATION OF REPORT

2 of 3

Report No: T/20181203/2161

Driver			
Name	NORAKMAL BIN MASNON	ID No.	S7400469E
Related Vehicle	GBC5817M (Lorry)	Contact No.	96846162
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	28/11/2018	Date Discharge	NIL
No. of Days granted Medical Leave	09	Degree of Injury	Slight

Brief Details.

On 28/11/2018 at about 1440hrs, I was travelling along pioneer road north towards Jalan Buroh back to my office before entering the roundabout, I came to a stop at the roundabout to make a check before I proceed. Subsequently before I know it, a vehicle collided to the rear of my vehicle which cause my vehicle to lunge forward. I then alighted my vehicle and immediately contacted my office to inform them the accident I had, thus I also called for police assistance.

Subsequently I was too groggy and unable to walk properly due to incident, I sat down along the side of the road to wait for the authorities to be here. No threat or assault took place. Subsequently I was conveyed to Ng Teng Fong Hospital and got myself 9 days of MC.



ASM Automotive Services Pte Ltd

No 2, Kwong Min Road, Singapore 628705
Tel: 6265 0980 / 6265 8806 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C



FROM : Jaclyn Lai
TEL. NO. : 6265-0980 / 9236-8218
EMAIL : jaclynlai@asmauto.com.sg

TO : China Taiping Insurance (Sg) P/L
ATTN : Motor Claim Department
TEL. NO. : 6389-6111 (main)
EMAIL : claimsdept@sg.cntaiping.com

CC : Oceano Electrical Trading Pte Ltd
ATTN : Ms. Catherine

DATE : 14.12.2018

VEHICLE NO. : GBC 5817 M
MODEL NO. : TOYOTA DYNA 150 MANUAL
CHASSIS NO. : JTFAT35YX0K202254
ENGINE NO. : 1KD2276189
LTA REG DATE : 13-Mar-13

CLAIM TYPE : Third Party - YP 67 C
D.O.A : 28.11.2018
CLAIM REF NO. : asm/AC18128/JL

Quotation for Accident Repair

S/N	SPARE PARTS (SPECIAL NETT)	QUANTITY	UNIT PRICE	AMOUNT
1	Rear door complete set, including ~ hinge x 2pcs ~ locking device full set ~ interior protective plywood	2	\$ 750.00	\$ 1,500.00 <i>bt</i>
2	Deck body rear frame	1	\$ 480.00	\$ 480.00 <i>bt</i>
3	Tailamp, LH & RH	2	\$ 30.00	\$ 60.00 <i>com</i>
4	Rear number plate	1	\$ 15.00	\$ 15.00 <i>bt</i>
5	70km/h sticker	1	\$ 3.50	\$ 3.50 <i>new</i>
SUB-TOTAL :				\$ 2,058.50

LABOUR CHARGES

1	Panel beat front cabin rear end panel (right side), realignment front cabin.	\$ 800.00
2	To dismantle damaged door, cut, replace and re-weld rear frame, knock and straighten underbar. Realign rear box.	\$ 2,500.00
3	Half lift-up rear box to knock and straighten chassis.	\$ 1,500.00
4	Spray painting	\$ 550.00

TOTAL LABOUR : \$ 5,350.00

GRAND TOTAL : \$ 7,408.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Kah 97495749
12/12/18 @ 1415
Resurvey new parts
7 days
surp@lkkauto.com



ASM Automotive Services Pte Ltd

No 2, Kwong Min Road, Singapore 628705
Tel: 6265 0980 / 6265 8806 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C



FROM : Jaclyn Lai
TEL. NO. : 6265-0980 / 9236-8218
EMAIL : jaclynlai@asmauto.com.sg

TO : China Taiping Insurance (Sg) P/L
ATTN : Motor Claim Department
TEL. NO. : 6389-6111 (main)
EMAIL : claimsdept@sg.cntaiping.com

CC : Oceano Electrical Trading Pte Ltd
ATTN : Ms. Catherine

DATE : 14.12.2018

VEHICLE NO. : GBC 5817 M
MODEL NO. : TOYOTA DYNA 150 MANUAL
CHASSIS NO. : JTFAT35YX0K202254
ENGINE NO. : 1KD2276189
LTA REG DATE : 13-Mar-13

CLAIM TYPE : Third Party - YP 67 C
D.O.A : 28.11.2018
CLAIM REF NO. : asm/AC18128/JL

Quotation for Accident Repair

S/N	SPARE PARTS (SPECIAL NETT)	QUANTITY	UNIT PRICE	AMOUNT
1	Rear door complete set, including ~ hinge x 2pcs ~ locking device full set ~ interior protective plywood	2	\$ 750.00	\$ 1,500.00 <i>bt</i>
2	Deck body rear frame	1	\$ 480.00	\$ 480.00 <i>Rx? bt</i>
3	Tailamp, LH & RH	2	\$ 30.00	\$ 60.00 <i>cm</i>
4	Rear number plate	1	\$ 15.00	\$ 15.00 <i>bt</i>
5	70km/h sticker	1	\$ 3.50	\$ 3.50 <i>re</i>
SUB-TOTAL :				\$ 2,058.50 <i>1578.50</i>

LABOUR CHARGES

1	Panel beat front cabin rear end panel (right side), realignment front cabin.	\$ 800.00
2	To dismantle damaged door, cut, replace and re-weld rear frame, knock and straighten underbar. Realign rear box.	\$ 2,500.00
3	Half lift-up rear box to knock and straighten chassis.	\$ 1,500.00
4	Spray painting	\$ 550.00
TOTAL LABOUR :		\$ 5,350.00

GRAND TOTAL : \$ 7,408.50

Finalise with Jackie
\$ 5128.50
7 days
24/12/18

Resuming
24/12/18

Tanah 97495749 \$ 5128.50
12/12/18 @ 1415
Resuming new parts
7 days
See 2 photos for repair

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Dec 2018		17 Dec 2018 16:38 Edit Adj Rpt	S\$5,128.50 Edit Estimates	S\$5,128.50 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SCANTECH MARINE PTE LTD, Co. Reg. No.: 199203043D		
Main Claimant:	OCEANO ELECTRICAL TRADING PTE LTD		
Vehicle Reg. No.:	GBC5817M	Date of Loss:	28/11/2018 14:00 - :59 [68 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D05582C02	Policy/Cover Note No.:	DMCVSN3113401802 (Comprehensive)
Vehicle Reg. No. (Insured):	YP67C	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Asm Automotive Services Kwong Min Rd (HQ) No. 2 Kwong Min Road, 628705 Pioneer - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 27/12/2018]		
Adj Asg. Remarks:	EST \$7408.50, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBC5817M (SNM18D05582C02)**
[YP67C]

TP

OCEANO ELECTRICAL TRADING PTE LTD

Nov 28 2018 2:00PM

[SCANTECH MARINE PTE LTD]

Asm Automotive Services Kwong Min Rd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	29/11/18 13:35	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	29/11/18 13:33	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	29/11/18 13:33	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	29/11/18 13:33	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	29/11/18 13:33	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/01/19 10:42	General View	Load JPG	☒
2	02/01/19 10:42	General View	Load JPG	☒
3	02/01/19 10:42	General View	Load JPG	☒
4	02/01/19 10:42	General View	Load JPG	☒
5	02/01/19 10:42	General View	Load JPG	☒
6	02/01/19 10:42	General View	Load JPG	☒
7	02/01/19 10:42	General View	Load JPG	☒
8	02/01/19 10:42	General View	Load JPG	☒
9	02/01/19 10:42	General View	Load JPG	☒
10	02/01/19 10:42	General View	Load JPG	☒
11	02/01/19 10:42	General View	Load JPG	☒
12	02/01/19 10:42	General View	Load JPG	☒
13	02/01/19 10:42	General View	Load JPG	☒
14	02/01/19 10:42	General View	Load JPG	☒
15	02/01/19 10:42	General View	Load JPG	☒
16	02/01/19 10:42	General View	Load JPG	☒
17	02/01/19 10:42	General View	Load JPG	☒
18	02/01/19 10:42	General View	Load JPG	☒
19	02/01/19 10:42	General View	Load JPG	☒
20	02/01/19 10:42	General View	Load JPG	☒
21	02/01/19 10:42	General View	Load JPG	☒
22	02/01/19 10:42	General View	Load JPG	☒
23	02/01/19 10:42	General View	Load JPG	☒
24	02/01/19 10:42	General View	Load JPG	☒
25	02/01/19 10:42	General View	Load JPG	☒
26	02/01/19 10:42	General View	Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
27	02/01/19 10:42	General View	 Load JPG	✓
28	02/01/19 10:42	General View	 Load JPG	✓
29	02/01/19 10:42	General View	 Load JPG	✓
30	02/01/19 10:42	General View	 Load JPG	✓
31	02/01/19 10:42	General View	 Load JPG	✓
32	02/01/19 10:42	General View	 Load JPG	✓
33	02/01/19 10:42	General View	 Load JPG	✓
34	02/01/19 10:42	General View	 Load JPG	✓
35	02/01/19 10:42	General View	 Load JPG	✓
36	02/01/19 10:42	General View	 Load JPG	✓
37	02/01/19 10:42	General View	 Load JPG	✓
38	02/01/19 10:42	General View	 Load JPG	✓
39	02/01/19 10:42	General View	 Load JPG	✓
40	02/01/19 10:42	General View	 Load JPG	✓
41	02/01/19 10:42	General View	 Load JPG	✓
42	02/01/19 10:42	General View	 Load JPG	✓
43	02/01/19 10:42	General View	 Load JPG	✓
44	02/01/19 10:42	General View	 Load JPG	✓
45	02/01/19 10:42	General View	 Load JPG	✓
46	02/01/19 10:42	General View	 Load JPG	✓
47	02/01/19 10:42	General View	 Load JPG	✓
48	02/01/19 10:42	General View	 Load JPG	✓
49	02/01/19 10:42	General View	 Load JPG	✓
50	02/01/19 10:43	Reinspection Photo	 Load JPG	✓
51	02/01/19 10:43	Reinspection Photo	 Load JPG	✓
52	02/01/19 10:43	Reinspection Photo	 Load JPG	✓
53	02/01/19 10:43	Reinspection Photo	 Load JPG	✓
54	02/01/19 10:43	Reinspection Photo	 Load JPG	✓
55	02/01/19 10:43	Reinspection Photo	 Load JPG	✓
56	02/01/19 10:43	Reinspection Photo	 Load JPG	✓
57	02/01/19 10:43	Reinspection Photo	 Load JPG	✓
58	02/01/19 10:43	Reinspection Photo	 Load JPG	✓
59	02/01/19 10:43	Reinspection Photo	 Load JPG	✓
60	02/01/19 10:43	Reinspection Photo	 Load JPG	✓
61	02/01/19 10:43	Reinspection Photo	 Load JPG	✓
62	02/01/19 10:43	Reinspection Photo	 Load JPG	✓
63	02/01/19 10:43	Reinspection Photo	 Load JPG	✓
64	02/01/19 10:43	Reinspection Photo	 Load JPG	✓
65	02/01/19 10:43	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/12/18 16:36	REPAIR EST	 Load PDF	
2	17/12/18 16:36	TP GIA	 Load PDF	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	29/11/18 13:32	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	29/11/18 13:33	POLICE REPORT [Linked Accident Report Documents]	 Load TIF	
3	29/11/18 13:33	IC,CI,DL [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

				View	View in Browser ▼
Assessment Reports				1 per page ▼	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	29/11/18 13:35	Accident Statement		Load HTM	
Photos/Images				3 per page ▼	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	29/11/18 13:33	Accident Photo		Load JPG	☒
2	29/11/18 13:33	Accident Photo		Load JPG	☒
3	29/11/18 13:33	Accident Photo		Load JPG	☒
4	29/11/18 13:33	Accident Photo		Load JPG	☒
Documentation				1 per page ▼	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	29/11/18 13:32	Sketch Plan		Load TIF	
2	29/11/18 13:33	POLICE REPORT		Load TIF	
3	29/11/18 13:33	IC,CI,DL		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118022609/T1TBS2

Date: 02/01/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN3113401802

Claimant Vehicle No: GBC5817M Insured Vehicle No: YP67C

Date of Loss: 28/11/2018 Nature of Claim: TP Claim No: SNM18D05582C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBC5817M**

Make & Model: TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M) Engine No: 1KD2276189

Reg. Date: 13/03/2013 (Man. Year: 2013) Chassis No: JTFAT35YX0K202254

Colour: Silver Odometer: 203677 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/ R15 Rear Tyre Size: 155/ R12 (D)

Front Left Side: LINAM 6 mm Rear Left Side: LINAM 6/6 mm

Front Right Side: LINAM 6 mm Rear Right Side: LINAM 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,058.50	1,578.50	480.00	23.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,350.00	3,550.00	1,800.00	33.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,408.50	5,128.50	2,280.00	30.78
+ GST 7.00/7.00% (S\$)	518.60	359.00	159.60	30.78
Nett Amount (S\$)	7,927.10	5,487.50	2,439.60	30.78

INSPECTION

Date of Assignment: 17/12/2018

Date Inspected: 18/12/2018 Inspected At: Asm Automotive Services Kwong Min Rd (HQ)
No. 2 Kwong Min Road
Singapore 628705

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Jan 2019)	
Parts:	N/A	TOYOTA DYNA 150 MANUAL 3SEATER 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC5817M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR DOOR COMPLETE SET, INCLUDING HINGE X 2PCS, LOCKING DEVICE FULL SET AND INTERIOR PROTECTIVE PLYWOOD	Bent	1,500.00 F	*1,500.00 F
2	1		*DECK BODY REAR FRAME	Repair	480.00 F	*- F
3	2		*TAILAMP, LH & RH	Cracked	60.00 F	*60.00 F
4	1		*REAR NUMBER PLATE	Bent	15.00 F	*15.00 F
5	1		*70KM/H STICKER	Necessary	3.50 F	*3.50 F
F=Franchise part.						
				Total Parts (S\$)	2,058.50	1,578.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT FRONT CABIN REAR END PANEL (RIGHT SIDE), REALIGNMENT FRONT CABIN.	New	800.00	750.00
2	TO DISMANTLE DAMAGED DOOR, CUT, REPLACE AND RE-WELD REAR FRAME, KNOCK AND STRAIGHTEN UNDERUN BAR. REALIGN REAR BOX.	New	2,500.00	2,000.00
3	HALF LIFT-UP REAR BOX TO KNOCK AND STRAIGHTEN CHASSIS.	New	1,500.00	400.00
4	SPRAY PAINTING.	New	550.00	400.00
Gross Labour Cost (S\$)			5,350.00	3,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >